

ASS. REC. BY:

REF: CS3/EQI18000437/Wb's

Special Instruction:

change 2 days

Survivor:

ASSIGNMENT (Office)

From (Person): Elaine Cheong of EQI Date/Time: 8/11/18 @ 1:22pm

Estimated Cost: Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLC 8702Y Insured: GW 3487E

at Workshop m/s Allswell Motor Tel: 6679 1146

of 25 Defu Lane 9

Policy No: DMCPHQ17-000736

Claim No:

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 31/10/17

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time: 2:18pm @ 08/11/17 Person Contacted: Yanyee

Vehicle IN (OUT)

| Date/Time | Action/Instruction (X) Estimate |
|-----------|-----------------------------------|
| | SLC 8702Y - X |
| | GW 3487E - X |
| | |
| | |
| | |
| | |
| | |

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No. SLC 8702 Y

at Workshop mis All well

of 25 John Lane 9

Insured _____

Policy No. _____

Claims No. _____


Sum Insured _____ Excess _____

(Client's Record)

Make of Veh. _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| | |
|---|-----|
|  | |
| N/S | O/S |
| | |

Bal. or Market Value.

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

| | | | |
|---------------|------|------|-----------|
| Est. Repairs: | days | Res: | Yes or No |
|---------------|------|------|-----------|

| | | | |
|-----------|----|----|------------------|
| Item Sum: | 12 | 96 | 3 Val: Yes or No |
|-----------|----|----|------------------|

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLC 87024 Regn

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: Toyota Wish AC 1798

Colour: Black AC Insured / Std / Nil / NA

Sp. Reading: 148292 T. Radio Insured / Std / Nil / NA

Eng No

C.No: JT066 20W0050426

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / Si. Rim / STD A/Rim or

Tyre Size: F: 195 / 65 R15
R: 195 / 65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or FIRENZA (F) / CR

Front: R/Bal. 4 mm L/Bal. 4 mm D.O.A. _____

Rear: R/Bal. 4 mm L/Bal. 4 mm D.O.A. _____

Survey held at: Allswell @ 1233pm

Des. of Damages (Frt / Rear / O/S / N/S / U/C / Rooftop or

Des. of Damages ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

| Date / Time | Action / Instruction |
|-------------|----------------------|
|-------------|----------------------|

10/1/18 Accident Report Not Given

Range - \$2900 - \$3900

2) Dams

RECEIVED 0-4-APR 2010

DataTime File Path:

03042018

Day's Time File Return is

Report Format :

Lump Sum / I.B.H. (\$)

☐: Prelim. Report

☐: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: Site Insc \$

Site Insc 3

Interplay 15

Tech. Inv. 12

Week 18 18

Survey Fee

© 2004 Blackwell Publishing Ltd, *Journal of Internal Medicine* 255: 103–110

11-12-2013 11:11:11

Nivitha (LKK Auto)

From: Elaine Cheong <elaine.cheong@eqinsurance.com.sg>
Sent: Monday, 8 January 2018 1:22 PM
To: 'assignments'
Subject: FW: FW: SLC8702Y Accident 31.12.2017 - 3rd party claim against EQ Insurance insured GW3487E
Attachments: GW3487E.PDF; TP -SLC8702Y.pdf

Our ref : GW3487E
TP ref : SLC8702Y
Policy No. : DMCPHQ17-000736

Dear All,

Please refer to the email below.

Kindly proceed to survey the third party vehicle.

We enclosed the following documents for your perusal:

- Insured, GW3487E – GIA report
- TP repair estimate, SLC8702Y – GIA report

Please acknowledge receipt. Thank you.

Regards,

Elaine Cheong
Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of



From: OOI, Ben [mailto:ben@allswellmotor.com.sg]
Sent: Monday, January 08, 2018 11:26 AM
To: Elaine Cheong
Cc: Edmund Ng; Mark Mark; account5 leasing
Subject: Re: FW: SLC8702Y Accident 31.12.2017 - 3rd party claim against EQ Insurance insured GW3487E

Dear Elaine,

Please get LKK to do the survey and we will do a direct settlement with EQ Insurance as soon as possible.

Thanks in advance...

Truly

OOI, Ben

Allswell Motor Traders
25, Defu Lane 9
Singapore 539266
Office: +65 6679 1146
Mobile: +65 9147 8545
Email: ben@allswellmotor.com.sg

On Mon, Jan 8, 2018 at 11:05 AM, Elaine Cheong <elaine.cheong@eqinsurance.com.sg> wrote:

WITHOUT PREJUDICE

Dear Ben,

We refer to your email of 06.01.2018.

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please revert within 2 working days if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

| | |
|---|--|
| 1) AJAX Inspection Services Pte Ltd Tel: 6255 0808 Fax: 6849 9155 | 2) Automobile Inspection Services Pte Ltd Tel: 6286 0155 Fax: 6284 1539 Contact Person: Sophia |
| 3) LBS Automotive Appraisal Pte Ltd L.B.S. Auto Consultants Pte Ltd Tel: 6281 6690 / 62832866 Fax: 6281 8748 Contact Person: Amy/ Grace | 4) Priority Services Tel: 62934822 Fax: 62963283 Contact Person: Hui Lian |

| | |
|--|---|
| <p>5) RT Appraisal Pte Ltd</p> <p>Tel: 67486076</p> <p>Fax: 67480361</p> <p>Contact Person: Ricky Teng</p> | <p>6) LKK Auto Consultants Pte Ltd</p> <p>Tel: 6256-3561</p> <p>Fax: 6741-4108</p> |
| <p>7) Kelvin Automotive Appraising Services</p> <p>Tel: 81825263</p> <p>Fax: 67461148</p> <p>Contact Person: Kelvin</p> | <p>8) Automotive Appraiser & Surveying Services</p> <p>Tel: 96623655</p> <p>Fax: 67655662</p> <p>Contact Person: Mr Chee</p> |
| <p>9) JP Knights Pte Ltd</p> <p>Tel: 63450068</p> <p>Fax: 63445328</p> <p>Contact Person: Edna Lee</p> | |

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Regards,

Elaine Cheong

Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

From: Janet Tan
Sent: Monday, January 08, 2018 9:25 AM
To: Elaine Cheong
Cc: ben@allswellmotor.com.sg; Edmund Ng; Mark Mark; account5 leasing
Subject: FW: SLC8702Y Accident 31.12.2017 - 3rd party claim against EQ Insurance insured GW3487E

Elaine,

Fyna. Thank you.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road, #17-00 Tower Block, MND Complex, Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg



A Member of Citystate



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

From: OOI, Ben [<mailto:ben@allswellmotor.com.sg>]
Sent: Saturday, January 6, 2018 10:41 AM
To: Janet Tan <janet.tan@eqinsurance.com.sg>
Cc: Edmund Ng <edmund@allswellmotor.com.sg>; Mark Mark <mark@allswellmotor.com.sg>; account5 leasing <account5@allswellmotor.com.sg>
Subject: SLC8702Y Accident 31.12.2017 - 3rd party claim against EQ Insurance insured GW3487E

Dear Janet (Claims Department)

We are the owner of the vehicle **SLC8702Y** and your insured vehicle **GW3487E** came in contact with our vehicle at the material time.

Before we proceed to repair our damaged vehicle, please let us know within 2 working days till **09.01.2018** whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you, we will proceed repair without any more reference to you.

Thank you in advance.

Truly

OOI, Ben

Allswell Motor Traders

25, Defu Lane 9

Singapore 539266

Office: [+65 6679 1146](tel:+6566791146)

Mobile: [+65 9147 8545](tel:+6591478545)

Email: ben@allswellmotor.com.sg


**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT | | | |
|--|------------------------|---|-------------------------|
| EQ INSURANCE COMPANY LTD | | Ref: | CS3/EQI18000437/Wbs2 |
| 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110 | | Date: | 10-04-2018 |
| | | Code: | EQI |
| 1. Policy Particulars :- (THIRD PARTY CLAIM) | | | |
| Insured Veh. | GW 3487E | Veh. Inspected | SLC 8702Y |
| Policy No. | DMCPHQ17-000736 | Coverage (\$) | 0.00 |
| Claim No. | | Excess (\$) | 0.00 |
| Assign From | ELAINE CHEONG | Assign Date | 08/01/2018 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | TOYOTA WISH | c.c | 1798 |
| Engine No. | HIDDEN | Year of Reg. | |
| Chassis No. | JTDGG20W00J004263 | Colour | BLACK |
| Odometer | 148292 KM | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | GOOD | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | 195/65R15 | FIRENZA | 4 mm |
| L/H Front Tyre | 195/65R15 | FIRENZA | 4 mm |
| R/H Rear Tyre | 195/65R15 | FIRENZA | 4 mm |
| L/H Rear Tyre | 195/65R15 | FIRENZA | 4 mm |
| 4. Description of Damages | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. | |  | |
| 5. General Information | | | |
| Accident Date | 31/12/2017 | Inspect Date / Time | 10/01/2018 (12:33 PM) |
| Survey held at | 25 DEFU LANE 9 | | |
| Repairer | ALLSWELL MOTOR TRADERS | | |
| 5a. Remarks | | | |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,900-\$3,900 | | | |
| 5b. Estimate Days of Repair | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 3 Working Days | |

Report Ref No. CS3/EQI18000437/Wbs2

Inspected By

WILSON TEO CHENG MING

Automotive Assessor

K.K.LAU CPT (RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.