

22/03/2002

ASS. REC. BY:

REF: CS3/CTI18000442/Acd301

Special Instruction:

Survivor:
Minim

Adrian

ASSIGNMENT (Office)

From (Person):

Juel Goh

of

CTI

Date/Time:

08/01/2018 @ 1:32pm

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

XD 793P

Insured:

YN 8088A

at Workshop m/s

SE Automobile

Tel:

6745 7367

of 1 kaki Bkt Ave 6 #02-34/36

Policy No:

DMCVSN1536431702

Claim No:

SNM18D00093C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

03/01/2018

CA / REV / REP. / REV 24 HRS

'up'

09/01/2017 @ Morning

H.O.D. Endorsement:

Date/Time:

2:54pm @ 08/01/17

Person Contacted:

Aine

Vehicle IN OUT

| Date/Time | Action/Instruction |
|-----------|-------------------------------------|
| | (+) Estimate. |
| | XD 793P - NJA / MGA 08013454 / T147 |
| | YN 8088A - X |
| 17/3/19 | Submit PPS. |
| | Dismantle: 11/1/2018 |
| | After repair: 23/1/2018 |

D.O.A.: 29/04/2008

...CLAIM SUBFOLDER...(New Assignment)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--|---------|---------------|-------------|--|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 05 Jan 2018 | | 08 Jan 2018 13:32 Assign | | | | New Assignment Cancel Case |

| | | | | |
|------|-----------|---------------|-----------|--------------------------|
| Main | Reference | Claim Details | Documents | Show All |
|------|-----------|---------------|-----------|--------------------------|

CLAIM SUBFOLDER DETAILS [Created by insurer]

| | | | |
|-----------------------------|---|------------------------|----------------------------------|
| Insured: | NG HUI TENG (HUANG HUITING), ID: S75352061 | | |
| Main Claimant: | THONG HUAT BROTHERS LOGISTICS PTE LTD, Co. Reg. No.: 199305098W | | |
| Vehicle Reg. No.: | XD793P | Date of Loss: | 03/01/2018 17:00 - :59 |
| Claim Type: | TP / SNM18D00093C02 | Policy/Cover Note No.: | DMCVSN1536431702 (Comprehensive) |
| Vehicle Reg. No. (Insured): | YN8088A | Policy No. (Claimant): | MT20170926 |
| | | Excess: | S\$0.00 |
| Repairer: | SE Automobile System (HQ) 1 Kaki Bukit Avenue 6, #02-34/36, 417883 Kaki Bukit - Tel: | | |
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh] | | |
| Claimant's Insurer: | Great American Insurance Company (HQ) - Tel: 6804 6047 | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/01/2018] | | |
| Driver/Custodian (Insured): | NG KIM NGEE (HUANG JINGYI) (40 / Male), NRIC: S7708468A, Tel: +6596408359 | | |
| Adj Asg. Remarks: | NO ESTIMATE, W/O SJE CASE. | | |

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|---|---|---------------------------|---|
| CHINA TAIPING INSURANCE (S) PTE LTD | | Ref : CS/CT118000442/Aqd3 | |
| 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909 | | Date : 08-01-2018 |  |
| | | Code : CTI | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | YN 8088A | Veh. Inspected | XD 793P |
| Policy No. | DMCVSN1536431702 | Coverage (\$) | 0.00 |
| Claim No. | SNM18D00093C02 | Excess (\$) | 0.00 |
| Assign From | MERIMEN (JOEL GOH) | Assign Date | 08/01/2018 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | c.c 0 | | |
| Engine No. | HIDDEN | Year of Reg. | |
| Chassis No. | Colour | | |
| Odometer | Steering | | |
| Brakes | Modification | | |
| General | | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |
| 4. Description of Damages | | | |
| | | | |
| 5. General Information | | | |
| Accident Date | 03/01/2018 | Inspection Date | |
| Survey held at | SE AUTOMOBILE SYSTEM NO.1 KAKI BUKIT AVE 6 #02-36 SINGAPORE 417883 | | |
| 5a. Remarks | | | |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

| ACCIDENT STATEMENT | |
|--|---------------------------------------|
| Date Of Report | 04/01/2018 12:13 |
| Date Of Accident | 03/01/2018 17:10 |
| Exact Location Of Accident | SENOKO WAY |
| Country/State of Loss | SINGAPORE |
| DETAILS OF OWN VEHICLE | |
| Vehicle Registration Number | XD793P |
| Insured/Policyholder | |
| Name Of Registered Owner | THONG HUAT BROTHERS LOGISTICS PTE LTD |
| Co Reg No | 199305098W |
| Email Address | SUSAN@THBLOGISTICS.COM.SG |
| Mobile Phone No | |
| Alternative Phone No | OFFICE-62898801 |
| Vehicle Particulars | |
| Manufacturer | MITSUBISHI |
| Model | FP517DR2RDEB |
| Exact Purpose for which vehicle was being used at time of accident | WORK |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | COMMERCIAL VEHICLE |
| Insurance Company | |
| Name of Insurance Company | GREAT AMERICAN INSURANCE COMPANY |
| Type Of Coverage | THIRD PARTY |
| Fleet Policy | NO |
| Policy Number | |
| Cover Note Number | MT20170926 |
| Driver | |
| Name of Driver | ONG GUAN HOCK |
| NRIC No | S1135747D |
| Date Of Birth | 20/03/1955 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 29/01/1973 |
| Driving Experience | 44 YEARS AND 11 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-98233929 |
| Fax Number | |
| Contact Number | |
| EMail Address | NOEMAIL |

| | |
|---|----------------------------------|
| Address | BLOCK 642C PUNGGOL DRIVE #14-365 |
| Postcode | 823642 |
| Was driver an employee of the Insured's Company | YES |
| If No, Relationship of the Driver with the Insured | |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|----------------------------|
| Type Of Accident | COLLISION - MAJOR/MINOR RD |
| Weather Conditions | RAINING |
| Road Surface | WET |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles involved in the accident | 2 |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

I WAS TRAVELLING ALONG SENOKO WAY, VEHICLE B, YN8088A DROVE OUT FROM FACTORY, HIT ONTO MY VEHICLE FRONT RIGHT HAND PORTION. NO ONE WAS INJURED.

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|--------------------|
| Vehicle Registration Number | YN8088A |
| Vehicle Make/Model/Colour | |
| Details Of Properties | |
| Vehicle Category | COMMERCIAL VEHICLE |
| Name of Driver | NG KIM GHEE |
| NRIC/Passport Number | S7708468A |
| Contact Number | 96408359 |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | 1 |

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 4/1/18 1035hrs



Driver's Signature

(if driver is not the policyholder)

Date & Time: 4/1/18 1035hrs

[Signature]

Reporting Centre Personnel's Signature


Name: Cassandra

NRIC/FIN No.: 63229391W



Accident Sketch Plan

SKETCH PLAN



DCA: 3-1-2018

A: XD793P

B: 4N8088A


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along Senoko way, Vehicle B, 4N8088A drove out from factory,
hit onto my vehicle front right hand portion.


No one was injured.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

3 

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: Cassandra
NRIC/FIN No.: 632293914

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|--|-------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Company |
| Owner ID: | 5098W |
| Vehicle Details | |
| Vehicle No.: | XD793P |
| Vehicle to be Exported: | No |
| Intended De-registration Date: | 10 Jan 2018 |
| Vehicle Make: | MITSUBISHI |
| Vehicle Model: | FP517DR2RDEB |
| Primary Colour: | White |
| Manufacturing Year: | 2006 |
| Engine No.: | 6D24383636 |
| Chassis No.: | FP517DA06177 |
| Maximum Power Output: | - |
| Open Market Value: | \$59,479.00 |
| Original Registration Date: | 04 Sep 2006 |
| First Registration Date: | 04 Sep 2006 |
| Transfer Count: | 1 |
| Actual ARF Paid: | \$2,974.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | No |
| PARF Eligibility Expiry Date: | - |
| PARF Rebate Amount: | \$0.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 31 Aug 2021 |
| COE Category: | C - Goods Vehicle & Bus |
| COE Period(Years): | 5 |
| PQP Paid: | \$23,127.00 |
| COE Rebate Amount: | \$16,835.00 |
| Total Rebate Amount: | \$16,835.00 |
| Message | |
| Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle. | |

The information contained herein is correct as at 10 Jan 2018

I/we declare the foregoing particulars are true to every respect


Policyholder's Signature / Date & Time *[Signature]* 13/11/2012 8:20am

Driver's Signature (if driver is not the policyholder) / Date & Time *[Signature]* 13/11/2012 8:20am

Witnessed by Reporting Centre Personnel *[Signature]*

Declaration

I was travelling straight towards Euro's and then suddenly vehicle B cut into my lane because vehicle B went to pick up a passenger from the right side the vehicle B driver offer to repair outside his workshop.



Sketch Plan

A - SF06336
B - SAC 6937

- Please report correctly the details of the accident to speed up the claims process.
- The form must be completed by the Policyholder and/or the Authorized Driver.
- Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The form and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insured companies.
- Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available as stated.

IMPORTANT NOTICE

SKETCH PLAN

Sketch Plan



ANNOUNCING Hamilton Autohub Pte Ltd as sgCarMart Premium Dealer 2018



HAMILTON
— AUTOHUB PTE LTD —

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Year Coe Renewal Toyota Vios 1.5a



\$2500 Downpayment Monthly
From \$580 Onwards. Lowest
3.68%P.A@GV Car Financing
GV Credit Pte Ltd StarAd



Browse by Category ▼

3 vehicles

mitsubishi fp51

Sort by Date Posted ▼

20 results/page ▼

Advanced Search 🔍

| | Make | Model | Price | Depreciation | Reg Date | Eng Cap | Mileage | Veh Type | Status |
|--|-----------------|--|----------|--------------|------------------|-----------|---------|----------|-----------|
| Search Selection | MITSUBISHI FP51 | | Any | Any | > 10 year(s) old | Any | Any | Any | Available |
| | Mitsubishi | FP51 (COE till 09/2027) | \$88,800 | \$9,120 /yr | 31-Dec-2007 | 12,882 cc | - | Truck | Available |
| Fuel Type: Diesel 1 Owner Only. Powerful And Durable Mitsubishi Prime Mover. New Paintwork. Posted: 01-Jan-2018 Tags: 2007 Mitsubishi FP51, Mitsubishi FP51, Mitsubishi, FP51, Used Mitsubishi | | | | | | | | | |
| | Mitsubishi | Fuso Super Great FP51 (COE till 10/2022) | \$65,800 | \$6,730 /yr | 17-Dec-2007 | 12,882 cc | - | Truck | Available |
| Fuel Type: Diesel 1 Owner Only. Powerful And Durable Mitsubishi Prime Mover. New Paintwork. Clean Interior. Posted: 19-Dec-2017 Tags: 2007 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Used Mitsubishi | | | | | | | | | |
| | Mitsubishi | Fuso Super Great FP51 (COE till 11/2022) | \$65,800 | \$13,520 /yr | 22-Nov-2007 | 12,882 cc | - | Truck | Available |
| Fuel Type: Diesel 1 Owner Only. Mitsubishi Prime Mover. Powerful Engine. New Paintwork. Well Maintained By Previous Owner. Can Renew Another 5 Year COE After Current COE Expires. Posted: 05-Dec-2017 Tags: 2007 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Used Mitsubishi | | | | | | | | | |

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view **Expired ads**

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used MITSUBISHI FP51, MITSUBISHI FP51 Singapore, used MITSUBISHI FP51 Singapore, used MITSUBISHI FP51, used vehicles Singapore or even buy used MITSUBISHI FP51 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--|--|--|------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
| Main | 05 Jan 2018 | | 08 Jan 2018 13:32 Edit Adj Rpt | S\$0.00 Edit Estimates | S\$0.00 View Rpt | | Pending for Survey Report Cancel Case |

| | | | | |
|-------------|------------------|----------------------|------------------|--------------------------|
| Main | Reference | Claim Details | Documents | Show All |
|-------------|------------------|----------------------|------------------|--------------------------|

CLAIM SUBFOLDER DETAILS [Created by insurer]

| | | | |
|-----------------------------|--|------------------------|---|
| Insured: | NG HUI TENG (HUANG HUITING) , ID: S7535206I | | |
| Main Claimant: | THONG HUAT BROTHERS LOGISTICS PTE LTD , Co. Reg. No.: 199305098W | | |
| Vehicle Reg. No.: | XD793P | Date of Loss: | 03/01/2018 17:00 - :59 [135 Months and 30 Days From LTA Reg Date (Man Yr)] |
| Claim Type: | TP / SNM18D00093C02 | Policy/Cover Note No.: | DMCVSN1536431702 (Comprehensive) |
| Vehicle Reg. No. (Insured): | YN8088A | Policy No. (Claimant): | MT20170926 |
| | | Excess: | S\$0.00 |
| Repairer: | SE Automobile System (HQ) 1 Kaki Bukit Avenue 6, #02-34/36, 417883 Kaki Bukit - Tel: | | |
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh] | | |
| Claimant's Insurer: | Great American Insurance Company (HQ) - Tel: 6804 6047 | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 17/01/2018] | | |
| Driver/Custodian (Insured): | NG KIM NGEE (HUANG JINGYI) (40 / Male) , NRIC: S7708468A, Tel: +6596408359 Email: NOEMAIL | | |
| Adj Asg. Remarks: | NO ESTIMATE, W/O SJE CASE. | | |

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

Claim Documents

***XD793P (SNM18D00093C02)
[YN8088A]**

TP









































THONG HUAT BROTHERS LOGISTICS PTE LTD

Jan 3 2018 5:00PM

[NG HUI TENG (HUANG HUITING)]

SE Automobile System















| Upload Documents | | Upload Photos | Compose New Letter | View View in Browser | |
|----------------------------------|-----------------|---|------------------------------------|---|-------------------------------------|
| Assessment Reports | | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | Jin Auto Services Pte Ltd (Defu) | | Thumbnail | Print |
| 1 | 04/01/18 14:05 | Accident Statement | 1 | Load HTM | |
| Photos/Images | | | | 3 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | Jin Auto Services Pte Ltd (Defu) | | Thumbnail | Print |
| 1 | 04/01/18 12:28 | Accident Photo [Linked Accident Report Documents] | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 2 | 04/01/18 12:29 | Accident Photo [Linked Accident Report Documents] | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 3 | 04/01/18 12:29 | Accident Photo [Linked Accident Report Documents] | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 4 | 04/01/18 12:29 | Accident Photo [Linked Accident Report Documents] | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 5 | 04/01/18 12:29 | Accident Photo [Linked Accident Report Documents] | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 6 | 04/01/18 12:29 | Accident Photo [Linked Accident Report Documents] | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 7 | 04/01/18 12:29 | Accident Photo [Linked Accident Report Documents] | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 8 | 04/01/18 12:29 | Accident Photo [Linked Accident Report Documents] | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 9 | 04/01/18 12:29 | Accident Photo [Linked Accident Report Documents] | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 10 | 04/01/18 12:29 | Accident Photo [Linked Accident Report Documents] | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 11 | 04/01/18 13:57 | Accident Photo [Linked Accident Report Documents] | 1 | Load JPG | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail | Print |
| 1 | 19/03/19 19:24 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 2 | 19/03/19 19:24 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 3 | 19/03/19 19:24 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 4 | 19/03/19 19:24 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 5 | 19/03/19 19:24 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 6 | 19/03/19 19:24 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 7 | 19/03/19 19:24 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 8 | 19/03/19 19:24 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 9 | 19/03/19 19:24 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 10 | 19/03/19 19:24 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 11 | 19/03/19 19:24 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 12 | 19/03/19 19:24 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 13 | 19/03/19 19:24 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 14 | 19/03/19 19:24 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 15 | 19/03/19 19:24 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 16 | 19/03/19 19:24 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 17 | 19/03/19 19:24 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 18 | 19/03/19 19:24 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |

| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|--|--|-------------------------------------|
| No | Finalized On | Jin Auto Services Pte Ltd (Defu) | Thumbnail | Print |
| 19 | 19/03/19 19:24 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 20 | 19/03/19 19:24 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 21 | 19/03/19 19:24 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 22 | 19/03/19 19:25 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 23 | 19/03/19 19:25 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 24 | 19/03/19 19:25 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 25 | 19/03/19 19:25 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 26 | 19/03/19 19:25 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 27 | 19/03/19 19:25 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 28 | 19/03/19 19:25 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 29 | 19/03/19 19:25 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 30 | 19/03/19 19:25 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 31 | 19/03/19 19:25 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 32 | 19/03/19 19:25 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 33 | 19/03/19 19:25 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 34 | 19/03/19 19:25 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 35 | 19/03/19 19:25 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 36 | 19/03/19 19:25 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 37 | 19/03/19 19:25 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 38 | 19/03/19 19:25 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 39 | 19/03/19 19:25 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 40 | 19/03/19 19:25 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 41 | 19/03/19 19:25 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 42 | 19/03/19 19:25 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 43 | 19/03/19 19:25 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 44 | 19/03/19 19:25 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 45 | 19/03/19 19:25 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 46 | 19/03/19 19:25 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 47 | 19/03/19 19:25 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 48 | 19/03/19 19:25 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 49 | 19/03/19 19:25 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 50 | 19/03/19 19:25 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 51 | 19/03/19 19:25 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 52 | 19/03/19 19:25 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 53 | 19/03/19 19:25 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 54 | 19/03/19 19:25 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 55 | 19/03/19 19:25 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail | Print |
| 1 | 08/01/18 13:30 | OI GIA REPORT |  Load PDF | |
| No | Finalized On | Jin Auto Services Pte Ltd (Defu) | Thumbnail | Print |
| 1 | 04/01/18 13:57 | Accident Sketch Plan [Linked Accident Report Documents] |  Load JPG | <input checked="" type="checkbox"/> |
| 2 | 04/01/18 13:57 | Accident Sketch Plan [Linked Accident Report Documents] |  Load JPG | <input checked="" type="checkbox"/> |

Linked Accident Report Documents

View

| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|--------------|----------------------------------|------------|-------------------------------------|
| No | Finalized On | Jin Auto Services Pte Ltd (Defu) | Thumbnail | Print |

| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|----------------------------------|--|-------------------------------------|
| No | Finalized On | Jin Auto Services Pte Ltd (Defu) | Thumbnail | Print |
| 1 | 04/01/18 14:05 | Accident Statement |  Load HTM | <input checked="" type="checkbox"/> |
| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | Jin Auto Services Pte Ltd (Defu) | Thumbnail | Print |
| 1 | 04/01/18 12:28 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 2 | 04/01/18 12:29 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 3 | 04/01/18 12:29 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 4 | 04/01/18 12:29 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 5 | 04/01/18 12:29 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 6 | 04/01/18 12:29 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 7 | 04/01/18 12:29 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 8 | 04/01/18 12:29 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 9 | 04/01/18 12:29 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 10 | 04/01/18 12:29 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 11 | 04/01/18 13:57 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | Jin Auto Services Pte Ltd (Defu) | Thumbnail | Print |
| 1 | 04/01/18 13:57 | Accident Sketch Plan |  Load JPG | <input checked="" type="checkbox"/> |
| 2 | 04/01/18 13:57 | Accident Sketch Plan |  Load JPG | <input checked="" type="checkbox"/> |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> | | | |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | | | |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18000442/AQD3E2

Date: 21/03/2019

REFERENCE

| | | | |
|-----------------------|---|----------------------|------------------|
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No: | DMCVSN1536431702 |
| Claimant Vehicle No : | XD793P | Insured Vehicle No : | YN8088A |
| Date of Loss: | 03/01/2018 | Nature of Claim: | TP |
| | | Claim No: | SNM18D00093C02 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-------------------------------------|-------------|--------------|
| Reg No: | XD793P | Engine No: | 6D24383636 |
| Make & Model: | MITSUBISHI FP517DR2RDEB, 12.9 D (M) | Chassis No: | FP517DA06177 |
| Reg. Date: | 04/09/2006 (Man. Year: 2006) | Odometer: | 536444 km |
| Colour: | Yellow | | |
| Engine Capacity: | 11945 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size: | 295/80 R22.5 | Rear Tyre Size: | 295/80 R22.5 |
| Front Left Side: | Bridgestone 6 mm | Rear Left Side: | Bridgestone 6 mm |
| Front Right Side: | Bridgestone 6 mm | Rear Right Side: | Bridgestone 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

| | | | |
|-----------------------------|------------|---------------|---|
| Date of Assignment: | 08/01/2018 | | |
| Date Inspected: | 09/01/2018 | Inspected At: | SE Automobile System (HQ) 1 Kaki Bukit Avenue 6, #02-34/36 Singapore 417883 |
| Estimated Period of Repair: | 8.0 days | | |

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 -\$6,000.00

REPAIR DETAILS

| | | |
|----------------------|--|--|
| Reference | | |
| Part Source: | (Last Synchronised: 21 Mar 2019) | |
| Parts: | N/A | MITSUBISHI FP517DR2RDEB 12.9 D (M) (Model not available in database) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for XD793P) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

| |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >