

ASS. REP. BY:

REF: CS /ASM 18000 243 / Title Special Information

57-014 (LAW: 520)

ASSIGNMENT (Office)

Smart client

From (Person):

Tauhikh

Yvonne Ang

10

ASM

Date/Time 08/01/2018 4:27 pm

Estimated Cost

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SGR 4113

Insured:

at Workshop m/s

Com Fort Delano

Tel-

6867 6919

of

45 Pandan Road

Policy No:

Claim No:

SBM 006NA

Sum Insured:

Excess:

Nil

Make of Veh:

D.O.A. 03012018

(Client's Record)

(CA) / REV / REP. / REV 24 HRS

04.01.2018

H.O.D. Endorsement:

Date/Time:

08012018 5:04 pm

Person Contacted.

Mr Wong

Vehicle IN OUT

Date/Time

Action/Instruction	Date	Time	Location	Remarks
1. Arrived at the site.	10/10/2023	08:00	Site 1	Initial assessment.
2. Conducted initial assessment.	10/10/2023	08:15	Site 1	No significant findings.
3. Collected samples.	10/10/2023	08:30	Site 1	3 samples collected.
4. Analyzed samples.	10/10/2023	09:00	Lab	Results pending.
5. Departed the site.	10/10/2023	09:30	Site 1	End of shift.

✓

Estimate

SHR 1113 - x

10/1/2017 - Report via ~~monline~~ AGM

Taufik

ASM

Date 09/01/2018

SGR4111J

2009

Aug

Estimate No.

① FMS THREE CO RES EVA FORM

To: Insured Name

SGR 4111J

At: Insured's Address

Comfort Delgro

On:

45 Pandan Road

Insured

Policy No.

Claim No.

Sum Insured

Excess

NIL

Driver's Report

Make of car

Policy Condition

Remarks: The vehicle had commenced its repair at the time of inspection.

Est. or Market Value

\$20K.

DAC Accident Report

Consistent? Yes or No

BA - PP Seen

Consistent? Yes or No

Est. Repairs

days

Res.

Yes or No

Est. Sum

At

Site

Yes or No

① REV. REP. 24 HRS

Date Person Contacted

Thayer

Date Time Action/Inspection

30/1/18

Thayer

33486

6 days

removal to Thayer

(Red: 165:37%)

One Time Fee Pass

☐

Prelim. Report

☒

Final Report

1/2 Typist

Date Time Fee Payment

Days Of Report

6

Resume, No. of Tolls

1

Date Fee

200

Add Fee

☐ Pre-Inspection
☐ On-Site Inspection
☐ Laboratory Fee
☐ Other Fee

Pre-Inspection

On-Site Inspection

Laboratory Fee

Other Fee

Request to

OD

3486

Signature of Insured

200

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Fédération Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/ASM18000443/T1tb

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 08-01-2018



Code : ASM

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SGR 4111J
Policy No.	Coverage (\$)	0.00
Claim No. S8M006NA	Excess (\$)	0.00
Assign From SMART CLAIM (YVONNE ANG)	Assign Date	08/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 03/01/2018	Inspection Date 09/01/2018
Survey held at COMFORTDELGRO ENGINEERING PTE LTD 45 PANDAN ROAD SINGAPORE 609286	

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: S8M006NA

Date: 09th January 2018

Our Ref: CS/ASM18000443/T1tb

The Motor Claims Department
AXA Insurance Singapore Pte L td

Attn: Yvonne Ang

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SGO 4111J .


We thank you for the instruction on 08/01/2018 .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 09/01/2018 (5.15pm) at the premises of M/s COMFORTDELGRO and have the following to report:-

Workshop Estimate Amount	: S\$ <u>5,111.00</u> .
Revised Estimate Amount	: S\$ <u>2,806.00</u> .
"Check" Items Amount	: S\$ <u>1,295.00</u> .
Total	: S\$ <u>4,101.00</u> .
Market Value	: S\$ <u>20,000.00</u> .
LTA Reimbursement Value	: S\$ <u>9,521.00</u> .
Nett Value	: S\$ <u>10,479.00</u> .

Description of Damage:

The vehicle sustained damages at the front portion.



Comments/ Present Status:

Damages consistent.

Repair cost economical.

Estimated normal period for repairs: 6 working days.

We have authorised the repairs.

Yours faithfully

Taufikh
Automobile Assessor



Service Request Details

Claim

S8M006NA

Reference

None 

Loss Date

January 3, 2018

Request Date

January 8, 2018

Due Date

January 15, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Incident Only

Services

Accelerated survey and authorize

Actions

Next Step

Agree to perform service

[Cancel Work](#)

[Accept Work](#)

Vehicle Information

Incident Vehicle Registration #

SGR4111J

Make

KIA

Service Address

205 Braddell Road, , , 579701

Primary Contact/Insured

JAYAKUMAR RETHINASAMY

BLK 25 MARSILING DRIVE, #12-213, 730025, Singapore, Singapore

90627263

jayakumar7962@gmail.com

Claim Handler

Default Owner

Additional Instructions

EXCESS NIL ESTIMATE \$5468.77 VEHICLE AT COMFORT DELGRO

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	04/01/2018 11:21
Date Of Accident	03/01/2018 20:10
Exact Location Of Accident	JURONG TOWN HALL ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SGR4111J
Insured/Policyholder	
Name Of Registered Owner	JAYAKUMAR S/O RETHINASAMY
NRIC No	S1622707B
Email Address	JAYAKUMAR7962@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90627263
Alternative Phone No	OTHERS-90627263
Vehicle Particulars	
Manufacturer	KIA
Model	MAGENTIS-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P1648932
Cover Note Number	
Driver	
Name of Driver	JAYAKUMAR S/O RETHINASAMY
NRIC No	S1622707B
Date Of Birth	21/02/1963
Occupation	INDOOR
Date Of Driving Pass	10/07/1985
Driving Experience	32 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90627263
Fax Number	
Contact Number	OTHERS-90627263
EEmail Address	JAYAKUMAR7962@GMAIL.COM

Address	BLK 25 MARSILING DRIVE 12-213
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER ATTACHED SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD6648B
Vehicle Make/Model/Colour	I40
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	CHOO HIAN HENG
NRIC/Passport Number	S1297610J
Contact Number	96239707
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. This form must be **correctly** filled out and submitted to the police station as soon as possible.
2. This form must be **completed by the Policyholder and/or the Authorised Driver**.
3. All information provided must be **truthful and accurate as possible**. Any willful misrepresentation is with default of material facts may constitute an offence to **repudiate policy liability**.
4. The insured and/or the insured's company is not to admission of policy liability on the part of the insurer's representatives.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Road Accidents Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of the report will form a fee accessible available upon application by interested parties.
7. By the signing of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available to the police.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:




- (a) My insurer, my work shop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or provided by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims; (ii) investigating the accident and/or my claims; (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me; (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be based outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be stored and disclosed (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud; regulators, law enforcement and government agencies as reasonably required for the purposes stated; or (ii) for complying with requirements under any regulatory laws or court orders.

Policyholder Signature
Date & Time

Insurer's Signature
If driver is not the policyholder
Date & Time



Reporting Centre Representative Signature
Name
NRIC/ID No.

Accident Sketch Plan



Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I engaged my left hand pedal to drive to the left lane, having checked my left mirror and shoulder suddenly I saw my front vehicle SW 6648-8 taxi brake light became very bright and stop, I could not stop my brake pedal on time.

Officer's Name: [Signature] Date of Incident: 19/10/2018
 Time of Incident: 19:10 hrs

DECLARATION

We declare the foregoing particulars are true in every respect.

Driver's Signature: [Signature]
 Date & Time: 19/10

Witness Signature: [Signature]
 (If not used, please delete this box)
 Date & Time:

Reporting Officer's Signature: [Signature]
 Name: [Name]
 NR: [NR]

Accident Sketch Plan Pg. 1

AXA INSURANCE PTE LTD
8 Shenton Way, #24-01
AXA Tower, Singapore 068811
Customer Service Centre #B1-01
Tel:(65)63387288 Fax:(65)63382522
Website:www.axa.com.sg
GST Registration Number: 199903512M
customer.service@axa.com.sg



Private Cars COMP
POLICY SCHEDULE
RENEWAL
Duplicate

POLICY INFORMATION		Policy No. : VPA/P1648932	
Source	: (03) 01826 CITIBANK SINGAPORE LTD		
Insured	: RETHINASAMY JAYAKUMAR		
Address	: BLK 25 MARSILING DRIVE #12-213 SINGAPORE 730025		
Business/Profession	: TRADE - TRANSPORTATION Carrying on or engaged in the business or profession last declared and no other for the purpose of this insurance.		
Period of Insurance	: From 07/08/2017 To 06/08/2018 (Both Dates Inclusive)		
Any subsequent period for which the Insured shall pay and the Company shall agree to accept a renewal premium.			
PREMIUM			
Premium After 50.00%	: SGD 887.20		
NCD			
Safe Driver Disc	: SGD 88.72		
10.00%			
NCD Protector	: SGD 63.88		
GST 7.00%	: SGD 60.36		
Annual Premium	: SGD 922.72		
Total Payable	: SGD 922.72		
RISK DETAILS THE MOTOR VEHICLE			
Type Of Cover	: Comprehensive		
Regn No.	: SGR4111J		
Type Of Use	: Private Car		
Make/Model	: KIA MAGENTIS 2.0		
Year of Manufacture	: 2009	Seating Capacity (excl. Driver)	: 04
Body Type	: SALOON	Engine C.C.	: 1998
Engine No.	: G4KD9H054095	Chassis No.	: KNAME227395376088
Insured's Estimated Market Value	: Market Value At The Time Of Loss (including Accessories and Spare Parts)		
Limitations as to Use	: As specified in Certificate of Insurance		
Hire Purchase	: MALAYAN BANKING BERHAD		
<u>Extra Coverage(Premium Breakdown)</u>		<u>Limits (SGD)</u>	<u>Premium (SGD)</u>
NCD Protector			63.88
Basic Own Damage Excess		: SGD 400.00	
<u>Named Drivers</u>			
1 RETHINASAMY JAYAKUMAR			



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: S8M006NA

Our Ref: CS/ASM18000443/T1tb

Date: 09/01/2018

The Motor Claims Department
M/s AXA Insurance Singapore Pte Ltd

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO SGR 4111J


We thank you for the instruction on 08/01/2018

Please be informed that we had conducted the inspection of the abovementioned vehicle on 09/01/2018 @ 1715HRS at the premises of M/s COMFORTDELGRO ENGINEERING PTE LTD and have the following to report: -

Workshop Estimate Amount	: S\$ <u>5,111.00</u>
Revised Estimate Amount	: S\$ <u>1,236.00</u>
"Check" Items Amount	: S\$ <u>1,295.00</u>
Market Value	: S\$ <u>20,000.00</u>
LTA Reimbursement Value	: S\$ <u>9,521.00</u>
Nett Value	: S\$ <u>10,479.00</u>

Description of Damage:

The vehicle sustained damages at the front portion.



Comments/ Present Status:
Damages Consistent

Yours Faithfully,
Taufikh
Automotive Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 2707B

Vehicle Details

Vehicle No.: SGR4111J

Vehicle to be Exported: Yes

Intended De-registration Date: 10 Jan 2018

Vehicle Make: KIA

Vehicle Model: MAGENTIS 2.0L A/T ABS D/AIRBAG 2WD 4DR

Primary Colour: Brown

Manufacturing Year: 2009

Engine No.: G4KD9H054095

Chassis No.: KNAGE227395376088

Maximum Power Output: 120.7 kW (161 bhp)

Open Market Value: \$17,510.00

Original Registration Date: 07 Aug 2009

First Registration Date: 07 Aug 2009

Transfer Count: 0

Actual ARF Paid: \$17,311.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 06 Aug 2019

PARF Rebate Amount: \$9,521.00

Intended COE Rebate Details

COE Expiry Date: 06 Aug 2019

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

QP Paid: \$0.00

COE Rebate Amount: \$0.00

Total Rebate Amount: \$9,521.00

The information contained herein is correct as at 10 Jan 2018

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)
 45 Pandan Road
 Singapore 609286
 Tel: 6338 8778 Email: denisteo@cdge.com.sg

INSURER: AXA Insurance Pte Ltd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	VPA/P1648932	Date of Loss:	03/01/2018
Vehicle Reg. No.:	SGR4111J	Driveable?	
Driver Age/Info:	54 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	JAYAKUMAR S/O RETHINASAMY	Contact No:	+6590627263
Driver:	JAYAKUMAR S/O RETHINASAMY		
Make/Model:	KIA MAGENTIS, 2.0 (A)	Vehicle Reg. Date:	07/08/2009
Vehicle Colour:	METALLIC BROWN		
Engine No:	G4KD9H054095	Chassis No:	KNAGE227395376088
Odometer:	0 KM		

Paint Type:
 Total Loss? NO
 Est. Duration of Repair (day) 10

Description of Accident/Loss PLEASE REFER ATTACHED SKETCH PLAN.

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (PANDAN)

Taught 97495749
EX: NIL.
Authorised 9/1/18 @ 1715
6 days

Resurvey before paint
sur @ LKK auto

COST OF CLAIMS

Parts	Amount
Miscellaneous Items	2,561.00
Labour	120.00
Paintwork Labour	2,430.00
Towing	0.00
	0.00

Gross Total (S\$)	5,111.00
+ GST 7.00% (S\$)	357.77
Nett Amount (S\$)	5,468.77

This claim is handled by: THEAGARAJAN A/L MUNIANDIY

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Jan 2018)
Parts: 143 KIA MAGENTIS 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SGR4111J/08/01/2018 11:28
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET	0.00	0.00	✓*280.00 F <i>bt</i>
2	1		*BONNET INSULATION	0.00	0.00	*100.00 F <i>Xnn</i>
3	10		*BONNET INSUALTION CLIPS	0.00	0.00	*10.00 F <i>Xnn</i>
4	1		*BONNET LOCK	0.00	0.00	*30.00 F <i>Ly</i>
5	1		*HEADLAMP LH	0.00	0.00	✓*290.00 F <i>as</i>
6	1		*HEADLAMP RH	0.00	0.00	✓*290.00 F <i>as</i>
7	1		*FRONT BUMPER	0.00	0.00	✓*170.00 F <i>as</i>
8	10		*FRONT BUMPER CLIPS	0.00	0.00	✓*15.00 F <i>as</i>
9	1		*RETAINER LHF	0.00	0.00	✓*6.00 F <i>as</i>
10	1		*HEADLAMP LOWER BEAM LH	0.00	0.00	✓*18.00 F <i>as</i>
11	1		*FRONT REINFORCEMENT	0.00	0.00	*110.00 F <i>Xnn</i>
12	1		*FRONT GRILLE	0.00	0.00	✓*150.00 F <i>as</i>
13	1		*GRILLE BADGE	0.00	0.00	✓*12.00 F <i>as</i>
14	1		*FRONT SPONGE	0.00	0.00	✓*85.00 F <i>as</i>
15	1		*FRONT PANEL	0.00	0.00	✓*230.00 F <i>dis</i>
16	1		*FOG LAMP LH	0.00	0.00	*60.00 F <i>Xnn</i>
17	1		*FOG LAMP COVER LH	0.00	0.00	*75.00 F <i>Xnn</i>
18	1		*A/C CONDENSER	0.00	0.00	✓*320.00 F <i>as</i>
19	1		*RADIATOR	0.00	0.00	*330.00 F <i>Xnn</i>

F=Franchise part.

Total Parts (S\$) **2,561.00**

ComfortDelGro Engineering Pte Ltd/SGR4111J/08/01/2018 11:28. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	A/C GAS	40.00 <i>241</i>
2	1	COOLANT	80.00 <i>241</i>
Sub Total (S\$)			120.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REMOVE / REFIT AND REPAIR DAMAGED PARTS	New	950.00 <i>700</i>
2	TO PUTTY/ RE SPRAY PAINT :BONNET, FRT BUMPER , FENDER LH, FENDER RH, DOOR LHF, WHEEL HOUSE LH	New	1,200.00 <i>600</i>
3	TO CHECK WIRING, REALIGN & FOCUS HEADLAMP	New	100.00 <i>30</i>
4	TO REMOVE & REPLACE A/C CONDENSER/ RADIATOR AND TOP UP GAS	New	180.00 <i>120</i>
Gross Labour Cost (S\$)			2,430.00

ComfortDelGro Engineering Pte Ltd/SGR4111J/08/01/2018 11:28. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199606048W)
 45 Pandan Road
 Singapore 609286
 Tel: 6338 8778 Email: denisteo@cdge.com.sg

INSURER: AXA Insurance Pte Ltd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	VPA/P1648932	Date of Loss:	03/01/2018
Vehicle Reg. No.:	SGR4111J	Driveable?	
Driver Age/Info:	54 / MALE	Party At Fault:	UNKNOWN
TP Injury	NO	Third Party	YES
Involved?		Involved?	
Insured/Claimant:	JAYAKUMAR S/O RETHINASAMY	Contact No:	+6590627263
Driver:	JAYAKUMAR S/O RETHINASAMY		
Make/Model:	KIA MAGENTIS, 2.0 (A)	Vehicle Reg. Date:	07/08/2009
Vehicle Colour:	METALLIC BROWN		
Engine No:	G4KD9H054095	Chassis No:	KNAGE227395376088
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of	10		
Repair (day)			
Description of	PLEASE REFER ATTACHED SKETCH PLAN.		
Accident/Loss			
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (PANDAN)		

Tanah 97495749
EX: NIL.
Authorised 9/1/18 @ 1715
6 days
Resumy before paint
sur @ KK and on

COST OF CLAIMS	Amount
Parts	2,561.00
Miscellaneous Items	120.00
Labour	2,430.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	5,111.00
+ GST 7.00% (S\$)	357.77
Nett Amount (S\$)	5,468.77

This claim is handled by: THEAGARAJAN A/L MUNIANDIY

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Jan 2018)
Parts: 143 KIA MAGENTIS 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SGR4111J/08/01/2018 11:28
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET	0.00	0.00	*280.00 F <i>bt</i>
2	1		*BONNET INSULATION	0.00	0.00	*100.00 F ?
3	10		*BONNET INSUALTION CLIPS	0.00	0.00	*10.00 F ?
4	1		*BONNET LOCK	0.00	0.00	*30.00 F <i>ky</i>
5	1		*HEADLAMP LH	0.00	0.00	*290.00 F <i>as</i>
6	1		*HEADLAMP RH	0.00	0.00	*290.00 F ? <i>✓</i>
7	1		*FRONT BUMPER	0.00	0.00	*170.00 F <i>as</i>
8	10		*FRONT BUMPER CLIPS	0.00	0.00	*15.00 F <i>as</i>
9	1		*RETAINER LHF	0.00	0.00	*6.00 F <i>as</i>
10	1		*HEADLAMP LOWER BEAM LH	0.00	0.00	*18.00 F <i>as</i>
11	1		*FRONT REINFORCEMENT	0.00	0.00	*110.00 F ?
12	1		*FRONT GRILLE	0.00	0.00	*150.00 F <i>as</i>
13	1		*GRILLE BADGE	0.00	0.00	*12.00 F <i>as</i>
14	1		*FRONT SPONGE	0.00	0.00	*65.00 F <i>as</i>
15	1		*FRONT PANEL	0.00	0.00	*230.00 F <i>dis</i>
16	1		*FOG LAMP LH	0.00	0.00	*60.00 F ?
17	1		*FOG LAMP COVER LH	0.00	0.00	*75.00 F ?
18	1		*A/C CONDENSER	0.00	0.00	*320.00 F ? <i>✓</i>
19	1		*RADIATOR	0.00	0.00	*330.00 F ?

F=Franchise part.

Total Parts (S\$) **2,561.00**

ComfortDelGro Engineering Pte Ltd/SGR4111J/08/01/2018 11:28. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	A/C GAS	40.00 <i>24</i>
2	1	COOLANT	80.00 <i>24</i>
Sub Total (S\$)			120.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REMOVE / REFIT AND REPAIR DAMAGED PARTS	New	950.00 <i>700</i>
2	TO PUTTY/ RE SPRAY PAINT :BONNET, FRT BUMPER , FENDER LH, FENDER RH, DOOR LHF, WHEEL HOUSE LH	New	1,200.00 <i>600</i>
3	TO CHECK WIRING, REALIGN & FOCUS HEADLAMP	New	100.00 <i>30</i>
4	TO REMOVE & REPLACE A/C CONDENSER/ RADIATOR AND TOP UP GAS	New	180.00 <i>120</i>
Gross Labour Cost (S\$)			2,430.00

ComfortDelGro Engineering Pte Ltd/SGR4111J/08/01/2018 11:28. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



45 Pandan Road S 609268
Tel: 68676919 Fax:62626950

SGR4111J

Vehicle No. : **SGR4111J**

DOA @ 03.01.2018

0% Discount / Plus : \$ _____

Discount / Plus : \$ -

D. Labour : \$ 1,450.00

E. Lump Sum (less 20 %) : \$ _____

: \$ _____

Total Amount : : \$ **3,486.00**

Remarks : Please confirm & revert by fax. Thanks

Confirmed By / Date : _____

COMFORTDELGRO ENGINEERING PTE LTD

45 Pandan Road S 609268

Tel: 68676919 Fax:62626950 ,68676903

Appendix A

Spare PartsVehicle No. : **SGR4111J**Submit By : **THEAGA**Make & Model : **KIA MAGENTIS 2.0**Year Manufacture : **2009**Chassis No. : **KNAGE227395376088**Engine No. : **KNAGE227395376088****Supplementary****Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	AIR GUARD LH <i>Parts</i>	1	\$20.00		<i>del</i> ✓ (A)
2	NUMBER PLATE & LTA SEAL <i>Sn</i>	1	\$50.00		<i>del</i> ✓ (A)
3		1			
4		1			
5		1			
6		1			
7		1			
8		1			
9		1			
10		1			
11		1			
12		1			
13		1			
14		1			
15		1			
16		1			
17		1			
18		1			
19		1			
20		1			
21		1			
22		1			
23		1			
24		1			
25		1			
26		1			



友興汽車零件私人有限公司 YEW HENG AUTO PARTS PTE LTD

BLK 3017 UBI ROAD 1 #04-129 SINGAPORE 408708
TEL: 6743 9858 A/C: 6392 0830 FAX: 6749 0858
Email: yewheng@yewhengauto.sg
Co. Reg. No.: 201130046W GST Reg. No.: 201130046W

TAX INVOICE

M/S : COMFORTDELGRO ENGINEERING PTE LTD

NO 45 PANDAN ROAD SINGAPORE 609286
TEL: 68676905 FAX: 68676903 ATT: MR HENG

NO: YLI1200448
PAGE: 1
DATE: 11/01/2018
A/C CODE: LYCDE002
TERMS: 60 DAYS
P/O NO: 4500784297

Part No	Description	Location	Qty	Unit Price	Amount
				<u>SIN</u>	<u>SIN</u>
1 A92101-2G540	LAMP ASSY-HEAD,LH	2122	1	290.00	290.00 ✓
2 A92102-2G540	LAMP ASSY-HEAD,RH	2122	1	290.00	290.00 ✓
3 A97606-3L180	CONDENSER ASSY-COOLER	214	1	320.00	320.00 ✓
4 A29136-2G300	AIR GUARD LH	YDS	1	20.00	20.00 ✓
TOTAL QUANTITY:			4	TOTAL	SIN 920.00
				ADD GST @ 7%	64.40
				GRAND TOTAL	<u>SIN 984.40</u>

VEH:SGR4111J

6001002086

COMFORTDELGRO ENGINEERING PTE LTD	
Items issued to external business with no warranty and defects. Exceptions to be stated here.	
Issued by:	Received by: 11/01/18
Name: <u>Way</u>	Name: <u>A.20 PM</u>
Sign/Date: <u>Way</u>	Sign/Date: <u>A.20 PM</u>
SCM, CPD	Crash Repair

SALESMAN: KXM

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE



友興汽車零件私人有限公司 YEW HENG AUTO PARTS PTE LTD

BLK 3017 UBI ROAD 1 #04-129 SINGAPORE 408708

TEL: 6743 9858 A/C: 6392 0830 FAX: 6749 0858

Email: yewheng@yewhengauto.sg

Co. Reg. No.: 201130046W GST Reg. No.: 201130046W

TAX INVOICE

M/S: COMFORTDELGRO ENGINEERING PTE LTD

NO 45 PANDAN ROAD SINGAPORE 609286

TEL: 68676905 FAX: 68676903 ATT: MR HENG

NO: YLI1200406
PAGE: 1
DATE: 10/01/2018
A/C CODE: LYCDE002
TERMS: 60 DAYS
P/O NO: 4500784241

Part No	Description	Location	Qty	Unit Price	Amount	
				<u>SIN</u>	<u>SIN</u>	
1	A66400-2G500	PANEL ASSY-HOOD	K1-44	1	280.00	280.00 ✓
2	A86511-2G510	COVER-FR BUMPER	A2P	1	170.00	170.00 ✓
3	A86590-28000R	RETAINER ASSY-BUMPER	1YY	10	1.50	15.00 ✓
	COVER MTG					
4	A86513-2G500	BRKT-FR BUMPER SIDE	1P-2B13	1	6.00	6.00 ✓
	SUPT,LH					
5	A86551-2G500	BRACKET - FR BUMPER UPR	YDS	1	18.00	18.00 ✓
	SIDE MTG					
6	A86350-2G600	GRILLE ASSY-RADIATOR	YDS	1	150.00	150.00 ✓
7	A86320-3E500	EMBLEM-KIA	1P-2B29	1	12.00	12.00 ✓
8	A86520-2G500	ABSORBER-FR BUMPER	YDS	1	65.00	65.00 ✓
	ENERGY					
9	A64101-2G500	PANEL COMPL-RADIATOR	YDS	1	230.00	230.00 ✓
	SUPPORT					

TOTAL QUANTITY:

18 TOTAL SIN 946.00

ADD GST @ 7% 66.22

GRAND TOTAL SIN 1,012.22

5001002054

VEH: SGR4111J

COMFORTDELGRO ENGINEERING PTE LTD	
Items issued to external business without discrepancies and defects. Exceptions to be stated above.	
Issued by:	Received by:
Name _____	Name _____
Sign/Date _____	Sign/Date _____
SCM, CPD _____	Crash Repair _____

Print / KXM / 10/01/2018 3:02:56 PM

SALESMAN: KXM

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE