



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2008 HONDA CRV 2.4 (SJT3451M)

Date of Loss

18 December 2017

Time of Loss

18.30

Loss Description

SJT3451M (INSD) C/W SLT491T (TP)

Comment

Workshop Details

Total Rebate Amount

19175

Nett Loss Amount

\$20,825.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

26/03/2018



Days of work completion *

77



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SJT3451M

Registration State

SINGAPORE

Mileage

137572

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2008

ASSESSMENT INFO...

2008

Purchase Date

dd/mm/yyyy



Registration Date *

02/10/2009



Age of Vehicle

8

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

PORTER WOLFF KARENA SARA EYRE

CATEGORY Make

POLICY INFORMAT... HONDA

ASSESSMENT INFO... HONDA

CATEGORY Model

POLICY INFORMAT... CRV 2.4

ASSESSMENT INFO... HONDA CRV 2.4L AT

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... JHLRE48508C213899

POST SURVEY INF...

CATEGORY Date of Birth

FNOL INFORMATI... 8 February 1958

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 60

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO... JHLRE48508C213899

CATEGORY Engine No

POLICY INFORMAT... K24Z12764641

ASSESSMENT INFO... K24Z12764641

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 2354

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 40000

FNOL INFORMATI... 0

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY Address

FNOL INFORMATI... Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Personal Correspondence

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Male

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

G5812699W

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

10/01/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

400

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

225/60R18

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

225/60R18

Front left side

YOKOHAMA6mm

Front right side

YOKOHAMA6mm

Rear left side

YOKOHAMA6mm

Rear right side

YOKOHAMA6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes No

Assessment Details

General & Workshop Details				Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary	Parts			
Add		Approve		Deny										
	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
		1	1			DISKALUMINIUM 18 X 7.5			Serviceable	0	0	0	0	0
		2	14			CLIPBUMPER			Necessary	1.3				18.2
		3	1			PANELR.FR.FENDER.			Buckled	369.39				369.39
		4	1			FENDERR.FR INNER (*CHECK)				0				0
		5	1			PROTECTORR.FR.W/ARCH			Damaged	44.91				44.91
		6	1			FACEFR.BUMPER			Cut	370.63				370.63
		7	1			FACEFR.BUMPER LOWER			Repair	0	0	0	0	0
		8	1			GARNISHR.FR.SIDE			Damaged	12.87				12.87
		9	1			SPACERR.FR.BUMPER SIDE			Necessary	8.06				8.06
		10	1			SPACERL.FR.BUMPER SIDE			Necessary	8.06				8.06
		11	1			BEAMR.FR.BUMPER UPPER (*CHECK)				0				0
		12	1			UNIT HEAD LIGHTR (*CHECK)				0				0
		13	1			SUNDRIES			Necessary	10				10
Labour														

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT
 	1		INSPECT FR LIGHTING MECHANISMS & FOCUS	80	0	0	Reviewing	
 	2		REMOVE & RENEW REVERSE SENSORS - 2 PCS (N)	80	0	0	Reviewing	
 	3		REMOVE & RENEW FR R FENDER	0	0	0	Deny	
 	4		REMOVE & RENEW FR BUMPER	0	0	0	Deny	
 	5		SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (6P)	1050	0	0	Reviewing	
 	6		CUT OFF & RENEW BULKHEAD FR R WHEELHOUSE	900	0	0	Reviewing	

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Add

Approve

Deny

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		1	WHEEL ALIGNMENT X4	Deny	0	NOT NECESSARY	
☐		2	(REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$708.23 NETT)	Reviewing			

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount \$2,552.12

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$2,110.00	\$2,110.00
Spare Parts	\$842.12	\$842.12
Excess	-\$400.00	-\$400.00

Submit for Review