

ASS. REC. BY:

REF:

CS / III 18000448 / Urban

Special Instruction:

Surveyor

Marius

ASSIGNMENT (Office)

From (Person):

Gabriel Wee

of

III

Date/Time

08/01/2018 1:22pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGU 7288Y

Insured:

SHB 6242Z

at Workshop m/s

Automobile Hub

Tel:

9786 11483

of

Blk 1 Kaki Bukit Ave 6 #02-11

Policy No:

mcom0016

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

06/01/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

09/01/2018

H.O.D. Endorsement:

Date/Time:

08/01/2018 4:28pm

Person Contacted:

Ah Siong

Vehicle IN/OUT

| Date/Time | Action/Instruction (✓) Estimate | |
|-----------|------------------------------------------|-----------------|
| | SGU 7288Y - NA / INC 18000365 / h4 | DLA: 06/01/2018 |
| | SHB 6242Z - RES / AVI 16014335 / Hlye3g2 | DLA: 29/07/2016 |
| | | |
| | | |
| | | |
| | | |

Surrey mercu

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 564 72884at Workshop m/s Autowheel and

of _____

Insured: SHB 62422

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 830k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLump Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS 23/5/2012

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 564 72884 Yr Regn: 5 07

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAMake: Toyota corolla Altis 1598Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 104881 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR0532EC107139505

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 125/70 R14

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or KapsenFront 6 mm Rear 6 mmR/Bal. 6 mm L/Bal. 6 mmD.O.A. 6/1/18 D.O.I. 9/1/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Lt O/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 27A 22132 Altis 786815/1/18 1/545350 confirmed with AH Xiong (Red 17, 7610)

RECEIVED 16 JAN 2018

Date/Time File Pass to? ☐ : Preli. Report1) ☐ : Final Report

Date/Time File Return to?

2) 16/1- typistReport Format: merimenLump Sum / I.B.I. (\$) 5350 pDays Of Repair: 5Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

3 - RS - SI

Phone:

Other:

TOTAL

450

10

460

Survey Department Check List (Case Handler)

Reference No. : CS | TL 18000 448 | UVB
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

| | | Y-Date | N-Date | Y-Date | N-Date |
|---|---------------------------------------|--------|--------|--------|--------|
| C | Reference No. | ✓ | | | |
| C | Customer Code | | | | |
| N | Assign From | | | | |
| C | Assign Date | ✓ | | | |
| C | Veh No (Inspected) | ✓ | | | |
| C | Veh No (Insured) | ✓ | | | |
| C | D.O.A | ✓ | | | |
| C | Policy No | | | | |
| C | Claim No | | | | |
| C | Insurance Authorisation (CA /REV/REP) | | | | |
| C | Report Type | ✓ | | | |
| C | Weekend Charges | | | | |
| N | Survey held at/Repairer | ✓ | | | |
| C | Excess | | | | |

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

| | | | | | |
|---|------------------------|---|--|--|--|
| C | Vehicle No | ✓ | | | |
| C | Regn Month/Year | ✓ | | | |
| N | Vehicle Type | ✓ | | | |
| N | Make & Model | ✓ | | | |
| C | Engine Capacity. (C.C) | ✓ | | | |
| N | Colour | ✓ | | | |
| C | Odometer. (Sp.Reading) | ✓ | | | |
| C | Chassis No | ✓ | | | |
| N | General Condition | ✓ | | | |
| N | Steering | ✓ | | | |
| N | Brake | ✓ | | | |
| N | Modification (Modi) | ✓ | | | |
| C | Tyre Size | ✓ | | | |
| N | Tyre Make | ✓ | | | |
| C | Tyre Balance | ✓ | | | |
| C | Date of Inspection | ✓ | | | |
| N | Survey held | ✓ | | | |
| N | Des.of Damages | ✓ | | | |

(2) System - (Views/Merimen)

| | | | | | |
|---|--------------------------------------|---|--|--|--|
| C | Damaged Vehicle Photographs Uploaded | ✓ | | | |
|---|--------------------------------------|---|--|--|--|

(3) Workshop Estimate/Assignment Form

| | | | | | |
|---|-----------------------------------------------|---|--|--|--|
| N | ALL Parts condition | ✓ | | | |
| C | Market Value for OD cases | | | | |
| C | Estimate Repair Cost for PRI (RSI, TMI, MSIG) | | | | |
| C | Days of repair | ✓ | | | |
| C | Finalised Amount | ✓ | | | |
| C | Re-inspection Cases to Finalize within 5 Days | | | | |

(4) System - (Views/Merimen)

| | | | | | |
|---|-------------------------|---|--|--|--|
| C | Resurvey photo Uploaded | ✓ | | | |
|---|-------------------------|---|--|--|--|

Check By: Veron | 16/1/18
 Case Handler Date

*C: Critical *N: Non-Critical



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|----------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------|--------------------------|-------------------------------------------------------------------------------------|
| INDIA INTERNATIONAL INSURANCE PL | | Ref : CS/III18000448/Uvb | |
| 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711 | | Date : 08-01-2018 |  |
| | | Code : III2 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | SHB 6242Z | Veh. Inspected | SGU 7288Y |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | | Excess (\$) | 0.00 |
| Assign From | GABRIEL WEE | Assign Date | 08/01/2018 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. | |
| Chassis No. | | Colour | |
| Odometer | - | Steering | |
| Brakes | | Modification | |
| General | | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |
| 4. Description of Damages | | | |
| | | | |
| 5. General Information | | | |
| Accident Date | 06/01/2018 | Inspection Date | 09/01/2018 |
| Survey held at | AUTOMOBILE HUB ENTERPRISE 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883 | | |
| 5a. Remarks | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |

Catherine Chong (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, 8 January, 2018 1:22 PM
To: Sim Teo Koon; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: Sherini Pillai
Subject: RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. SGU7288Y (Accident involving SGU7288Y and SHB6242Z on 06.01.2018)
Attachments: shb6242z_20180108101630.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SGU7288Y and let us have your report urgently.

This claim will be handled by Ms Sherini.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Sim Teo Koon [mailto:tk_sim@juseq.com.sg]
Sent: 08 January, 2018 12:10 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. SGU7288Y (Accident involving SGU7288Y and SHB6242Z on 06.01.2018)

Dear Sir,

We refer to your email.

Our client is agreeable to appoint **LKK Auto Consultants Pte Ltd** as the single joint expert:

Please be informed that our client's motor vehicle is available for inspection at the under-stated workshop: -

Automobile Hub Enterprise

AutoBay @ Kaki Bukit #02-11,

Singapore

Person In-Charge: Ah Siong Tel: 9786 4483; Fax: 6758 3325

Regards,

Sim Teo Koon

JusEquity Law Corporation

171 Chin Swee Road #02-06, CES Centre

Singapore 169877

Tel: 6506 6488 / 6536 9339

Fax: 6536 5368

E-mail: tk_sim@juseq.com.sg

This message (and all its attachments) is intended only for the use of the individual or entity to whom it is addressed and is privileged and confidential. If you are not the intended recipient, please notify us immediately by return electronic mail, delete this message and you should not disseminate, distribute or copy any information contained herein.

From: Motor Claim - III [<mailto:motorclaim@iii.com.sg>]

Sent: Monday, January 8, 2018 10:26 AM

To: JUSEQ <juseq@singnet.com.sg>

Subject: PRE-REPAIR INSPECTION FOR VEHICLE NO. SGU7288Y (Accident involving SGU7288Y and SHB6242Z on 06.01.2018)

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.
Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.
Registration No. 198703792-K

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 6198R

Vehicle Details

Vehicle No.: SGU7288Y

Vehicle to be Exported: Yes

Intended De-registration Date: 10 Jan 2018

Vehicle Make: TOYOTA

Vehicle Model: COROLLA ALTIS 1.6
AUTO

Primary Colour: Blue

Manufacturing Year: 2006

Engine No.: 3ZZ4626446

Chassis No.: MR053ZEC107139505

Maximum Power Output: 81.0 kW (108 bhp)

Open Market Value: \$15,355.00

Original Registration Date: 24 May 2007

First Registration Date: 24 May 2007

Transfer Count: 2

Actual ARF Paid: \$16,891.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 23 May 2022

COE Category: A - Car (1600cc & below)

COE Period(Years): 5

PQP Paid: \$25,333.00

COE Rebate Amount: \$22,132.00

Total Rebate Amount: \$22,132.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

sgCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Articles

Forum

Tools & Tips



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Year Coe Renewal Toyota Estima 2.4A



\$6800 Downpayment Monthly
From \$6800 Onwards. Lowest
3.68%PA@GV Cars Financing
GV Credit Pte Ltd Stand



VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND

HOTLINE: 6741 9997

view our cars

Browse by Category

« Back (1 2 3 4) Next »

Sort by Date Posted

20 results/page

73 vehicles

toyota corolla

Advanced Search Submit

| | Make | Model | Price | Depreciation | Reg Date | Eng Cap | Mileage | Veh Type | Status |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------|--------------------------------|----------|--------------|------------------|----------|------------|----------|-----------|
| Search Selection | toyota corolla | | Any | Any | > 10 year(s) old | Any | Any | Any | Available |
|  | Toyota Corolla | Altis 1.6A (COE till 09/2022) | \$35,800 | \$7,660 /yr | 12-Sep-2007 | 1,598 cc | 158,000 km | Sedan | Available |
| One Year Warranty! With Official Warranty Certificate For Peace Of Mind, Our Company Renew Coe Cars For Sale Base On Car Conditions Not On Ownership, Fully Refurbished, New Paintwork, Accident Free, W... | | | | | | | | | |
| Carway | | | | | | | | | |
| Posted: 09-Jan-2018 Tags: 2007 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota | | | | | | | | | |
|  | Toyota Corolla | Altis 1.6A (COE till 02/2021) | \$22,588 | \$7,290 /yr | 15-Feb-2006 | 1,598 cc | 105,000 km | Sedan | Available |
| New Arrival! Low Mileage Done At 9,600km Yearly, Classic Grey On 2 Tone Interior, Well Maintained, Mint Condition, Easy In House Loan Available, Trade In Welcome, Call Now. | | | | | | | | | |
| Posted: 09-Jan-2018 Tags: 2006 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota | | | | | | | | | |
|  | Toyota Corolla | Altis 1.6A (COE till 06/2022) | \$39,800 | \$8,960 /yr | 20-Jun-2007 | 1,598 cc | 103,000 km | Sedan | Available |
| 100% Accident Free, New 5 Year COE, Low Mileage, Original Paint, Smooth And Quiet Engine, Tip Top Condition And Clean Interior, Flexible In House Loan Available Up To 90%, Please Call For Viewing. | | | | | | | | | |
| Posted: 08-Jan-2018 Tags: 2007 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota | | | | | | | | | |
|  | Toyota Corolla | 1.5M (COE till 04/2019) | \$10,900 | \$8,380 /yr | 23-May-2001 | 1,497 cc | - | Sedan | Available |
| 100% Accident Free, Low Depreciation Per Day Only \$20 Plus, Toyota Corolla The Most Reliable Car In The Market, Very Rate In The Market The Only 1 Unit For Sale, Please Call For Viewing By Appointment... | | | | | | | | | |
| Posted: 06-Jan-2018 Tags: 2001 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota | | | | | | | | | |
| <div> <div>Car Buying</div> <div>Car Ownership</div> </div> <div> <div>Car Selling</div> <div>On The Move</div> </div> <div> <div>Car Aftermarket</div> <div>Lifestyle</div> </div> <div> <div>Buying a pre-owned car, but Unsure of its Condition?</div> <div>Get, STA Car Evaluation</div> </div> | | | | | | | | | |
|  | Toyota Corolla | Altis 1.6A (COE till 02/2021) | \$23,800 | \$7,680 /yr | 15-Feb-2006 | 1,598 cc | 147,000 km | Sedan | Available |
| "One Year Warranty!" With Official Warranty Certificate For A Peace Of Mind, Fully Refurbished, New Paintwork, Accident Free, Wear And Tear Replaced, \$485 Low Monthly Instalment, 10% Down Payment, Ba... | | | | | | | | | |
| Carway | | | | | | | | | |
| Posted: 08-Jan-2018 Tags: 2006 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota | | | | | | | | | |
|  | Toyota Corolla | Axio 1.5A X (COE till 03/2022) | \$31,800 | \$7,680 /yr | 02-Mar-2007 | 1,496 cc | 120,354 km | Sedan | Available |
| "One Year Warranty!" With Official Warranty Certificate For Peace Of Mind, Our Company Renew Coe Cars For Sale Base On Car Conditions Not On Ownership, Fully Refurbished, New Paintwork, Accident Free,... | | | | | | | | | |
| Carway | | | | | | | | | |
| Posted: 08-Jan-2018 Tags: 2007 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota | | | | | | | | | |
|  | Toyota Corolla | Altis 1.6A (New 5-yr COE) | \$33,800 | \$6,760 /yr | 03-Dec-2007 | 1,598 cc | 145,000 km | Sedan | Available |
| \$0 Down Payment Available! Monthly \$703! Not A Leasing/Rental Scheme! No Gimmicks! We Only Put Up The Good Condition Units For Sale! High Trade In For Your Car! Call Us For A Viewing Appointment. | | | | | | | | | |
| Posted: 08-Jan-2018 Tags: 2007 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota | | | | | | | | | |

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|-------------------------------------------------|
| Date Of Report | 06/01/2018 14:50 |
| Date Of Accident | 06/01/2018 09:45 |
| Exact Location Of Accident | POTONG PASIR AVE 2 BESIDE SRI SIVA DURGA TEMPLE |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|------------------------------------------------------------------------------|----------------------------------------|
| Vehicle Registration Number | SGU7288Y |
| Insured/Policyholder | |
| Name Of Registered Owner | SG VEHICLE RENTAL PRIVATE LIMITED |
| Co Reg No | 201136198R |
| Email Address | NOEMAIL |
| Mobile Phone No | |
| Alternative Phone No | OFFICE-92729299 |
| Vehicle Particulars | |
| Manufacturer | TOYOTA |
| Model | COROLLA ALTIS |
| Exact Purpose for which vehicle was being used at time of accident | COMMERCIAL |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE HIRE |
| Insurance Company | |
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | 5096484753 |
| Cover Note Number | - |
| Driver | |
| Name of Driver | LIM CHYE SENG |
| NRIC No | S6923748G |
| Date Of Birth | 12/07/1969 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 28/11/1991 |
| Driving Experience | 26 YEARS AND 1 MONTH |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-91506176 |
| Fax Number | |
| Contact Number | |
| Email Address | NOEMAIL |

Address BLK 454 FAJAR RD #05-570
 Postcode 670454
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD ON COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : UNKNOWN
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING ALONG POTONG PASIR AVE 2, WHILE APPROACHING A ENTRANCE BESIDE THE SRI SIVA DURGA TEMPLE, SUDDENLY A TAXI FROM THE OPPOSITE DIRECTION WITHOUT STOPPING AND CHECKING THE ONCOMING TRAFFIC, MAKE A RIGHT TURN INTO THE ENTRANCE, AS THE RESULT, HIT ONTO MY VEH RIGHT FRONT PORTION.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: WITH DRIVER
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHB6242Z
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category TAXI
 Name of Driver CHNG HONG BOON
 NRIC/Passport Number S0293877D
 Contact Number
 Address
 Postcode
 Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

DETAILS OF INJURED PERSON 1

Name

LIM CHYE SENG

Approximate Age

Injuries Sustain

NECK AND BACK

Injured person in which vehicle?

SGU7288Y

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

1. Personal information collected from you will be used for the following purposes:
2. The Firm will use your personal information to provide you with the services and products that you have requested.
3. Information that you provide to the Firm will be used to contact you in the future with information about our products and services, including new products and services that we may offer.
4. The issue and administration of the Firm's insurance policies is not a permitted purpose for the use of the personal information of the insured.
5. Our Firm does not intend to share the personal information that you provide to us with any third party.
6. The report will be made available to members of the Firm's Executive Management and to the Board of Directors of the General Insurance Association of Singapore (GIAS) for analysis and the purpose of the report will be to assist GIAS in its role, available upon application by interested parties.
7. By the lodging of this report, the insured hereby consents to the use of the personal information and details of the report being made available to GIAS.
8. **Consent under the Personal Data Protection Act (PDPA)**

(a) My Insurer(s) will use the information gathered to make a determination of my claim ("claim") or claim authorized in contract, may disclose and/or use my personal data/personal information and other personal information provided by me, including but not limited to the following: (i) "Personal Information" and (ii) "Disclosure and Transfer with Personal Information" to all Insurer(s) who have insured vehicles and/or to any Insurer(s) who have insured vehicles owned or leased by me, which may be collected, transferred, used, disclosed, stored, retained, lawfully transferred, the delivery, distribution, sale or lease and other use of such information may be used for all the purposes for the purposes of:

- (i) processing, handling and/or dealing with my claim, including the processing of the claim and any necessary investigation relating to the claim;
- (ii) investigating the reasons for my claim;
- (iii) carrying out and/or dealing with my Insurer(s)'s responsibilities as an Insurer(s);
- (iv) administering my claim, including the mailing of correspondence, notices, records or letters to me, which may involve disclosure of certain personal data about me to third parties (including the Insurer(s) as well as on the administrative or clerical staff possibly hired);
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").

(b) all Insurer(s) who have insured vehicles and/or leased vehicles may, from time to time, may/are permitted to collect, use, disclose and/or transfer my Personal Information for one or more of the above Purposes, and

(c) my Personal Information may be provided to one or more Insurer(s) or to third party service providers or agents (including their lawyers/law firms), which may be used outside of Mississippi for one or more of the above Purposes.

(d) my Personal Information will also be collected and used to compile data/statistics for the purpose of fraud detection, investigation and management in present and all future claims.

(e) the information so collected under (c) above may be shared / disclosed:


- (i) to all Insurer(s) and/or any other third parties that assist in investigating, administering, handling or managing fraud, regulatory, law enforcement and government agencies as reasonably necessary for the purposes stated, or
- (ii) for complying with requirements under any applicable laws or court orders.



Deliver's Signature:
 At _____
 Date: 8/7/11

Signature Center Personnel's Signature
Name _____
Title/Position _____

Sketch Map



A = SGU 7288 Y

B = SHB 6242 Z

Sri Siva
Durga Temple

Ratang Road, Ave 2

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please Refer to statement

DECLARATION

I/We declare the vehicle and driver are true in every respect.



Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Policyholder's Signature
Date & Time:

AUTOMOBILE HUB ENTERPRISE

51 Defu lane 9, Singapore 539291

H/P: 9786 4483

Email: autohub325@gmail.com

FAX: 6758 3325

Not Allocated
1/5 253501
9/1/18
Zhephro After Rep-
517.

Vehicle No: SGU 7288Y

Model: TOYOTA ALTIS

| Qty | List Price | | Price |
|-----|----------------------------------------------|-----------|------------------|
| 1 | Front bonnet | 1 | 1429.50 α |
| 1 | Front bonnet seal | 11 | 62.20 α |
| 1 | Front bonnet lock | 11 | 91.50 α |
| 1 | Front bonnet lock cable | 11 | 89.60 α |
| 2 | Front bonnet hinges L/R @ 67.20 | 11 | 134.40 α |
| 1 | Front bumper | 11 | 881.85 |
| 1 | Front bumper undercover | 70.1 | 401.60 |
| 1 | Front bumper fog lamp - RH | 11 | 380.90 |
| 1 | Front bumper sponge | 11 | 89.70 α |
| 1 | Front bumper reinforcement | 11 | 354.70 α |
| 2 | Front bumper side retainers - L/R @ 81.50 | 31 | 163.00 |
| 10 | Front bumper clips @ 4.50 | 11 | 45.00 |
| 2 | Front fenders - L/R @ 675 | 0/500/800 | 1350.00 α |
| 2 | Front fender inner shields - L/R @ 179.50 | 0/5 1000 | 359.00 α |
| 30 | Front fender inner shield clips @ 4.50 | 11 | 135.00 |
| 2 | Front fender wheel housings - L/R @ 501 | 11 | 1002.00 α |
| 1 | Front grille assy | 11 | 408.10 α |
| 1 | Front grille logo | 11 | 58.50 α |
| 2 | Front headlamps - L/R @ 525.50 | 11 | 1051.00 α |
| 2 | Front headlamps side garnishes - L/R @ 58.60 | 11 | 117.20 α |
| 1 | Front shock absorber - RH | 11 | 390.70 α |
| 1 | Front lower arm | 11 | 627.50 α |
| 1 | Front knuckle arm | 11 | 526.60 α |
| 1 | Front wheel bearing | 11 | 140.60 α |
| 1 | Front support panel assy | 11 | 973.70 α |
| 1 | Front chassis frame member - RH | 11 | 1053.50 α |
| 1 | Washer tank | 11 | 57.90 α |
| 1 | Washer tank motor | 11 | 245.60 α |
| 1 | Air cleaner intake | 11 | 98.10 α |
| 1 | Air cleaner box assy | 11 | 779.10 α |
| 1 | Air con condenser | 11 | 1507.40 α |
| 1 | Air con discharge pipe | 11 | 501.60 α |
| 1 | Air con suction pipe | 11 | 489.60 α |
| 1 | Air con liquid pipe | 11 | 260.20 α |
| 1 | Radiator assy | 11 | 1345.50 α |
| 1 | Radiator top frame bracket | 11 | 126.30 α |
| 2 | Radiator top mounts @ 12.60 | 11 | 25.20 α |
| 1 | Radiator top hose | 11 | 48.60 α |
| 1 | Radiator lower hose | 11 | 52.50 α |
| 1 | Radiator fan cowling | 11 | 220.80 α |
| 1 | Radiator fan blade | 11 | 150.00 α |
| 1 | Radiator fan motor | 11 | 548.90 α |

187465
62229
4667.17

Vehicle No: SGU 7288Y

Model: TOYOTA ALTIS

| | | | | |
|---|------------------------------------|----|---------|---|
| 2 | Wiper panel garnish - L/R @ 525.30 | 17 | 1050.60 | X |
| 6 | Wiper panel garnish clips @ 4.50 | 17 | 27.00 | X |
| 1 | Engine mounting - RH | 17 | 390.40 | X |
| 1 | Engine mounting - LH | 17 | 230.90 | X |
| 1 | Engine mounting - CTR | 17 | 97.40 | X |
| 1 | Engine mounting - Rear | 17 | 230.90 | X |
| 1 | Engine mounting beam | 17 | 280.50 | X |
| 1 | ABS pump | 17 | 480.00 | X |

Less 25%

2787.70

Total: 22 561.35
(5640.35)

Subtotal: \$16 921.00

Special Nett items:

| | | | | |
|-------|--------------------|----|--------|---|
| 1 set | Front number plate | 17 | 60.00 | X |
| 1 | Front tyre | 17 | 280.00 | X |

Subtotal \$340.00

Labour charges:

| | | |
|------------------------------------------------------------|------------|----------|
| Towing charges | 150.00 | 50 |
| To remove F/undercarriage | 17 | 350.00 X |
| To check wheel alignment | 17 | 120.00 X |
| To remove, refix A/C condenser and refill A/C gas | 180.00 | 100 |
| To remove, refix engine parts | 17 | 300.00 X |
| To respray undercoating | 180.00 | 60 |
| To check front electrical wiring | 100.00 | 20 |
| To respray painting and etc | 2000.00 | 1000 |
| Panel beating, cut, weld, remove and replacing above parts | 2500.00 | 800 |
| Total labour: | \$5 880.00 | |

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ ~~23 141.00~~

22391.76

6697.17
5357.73

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Sign:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III18000448/UVBN2

Date: 17/01/2018

REFERENCE

| | | | |
|-----------------------|---------------------------------------|----------------------|----------|
| Handling Insurer: | India International Insurance Pte Ltd | Policy No: | |
| Claimant Vehicle No : | SGU7288Y | Insured Vehicle No : | SHB6242Z |
| Date of Loss: | 06/01/2018 | Nature of Claim: | TP |
| | | Claim No: | N/A |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-------------------------------|-------------|-------------------|
| Reg No: | SGU7288Y | Engine No: | 3ZZ4626446 |
| Make & Model: | TOYOTA COROLLA ALTIS, 1.6 (A) | Chassis No: | MR053ZEC107139505 |
| Reg. Date: | 24/05/2007 (Man. Year: 2006) | Odometer: | 104881 km |
| Colour: | Grey | | |
| Engine Capacity: | 1598 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (\$\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size: | 185/70R14 | Rear Tyre Size: | 185/70R14 |
| Front Left Side: | KAPSEN 6 mm | Rear Left Side: | KAPSEN 6 mm |
| Front Right Side: | KAPSEN 6 mm | Rear Right Side: | KAPSEN 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------------------|------------------|-----------------|------------------|--------------|
| Parts | 16,511.76 | 4,667.17 | 11,844.59 | 71.73 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 5,880.00 | 2,030.00 | 3,850.00 | 65.48 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (\$\$) | 22,391.76 | 6,697.17 | 15,694.59 | 70.09 |
| Approved Total (Overridden) (\$\$) | | 5,350.00 | | |
| (\$\$) | 22,391.76 | 5,350.00 | 17,041.76 | 76.11 |
| + GST 7.00/7.00% (\$\$) | 1,567.42 | 374.50 | 1,192.92 | 76.11 |
| Nett Amount (\$\$) | 23,959.18 | 5,724.50 | 18,234.68 | 76.11 |

INSPECTION

| | | |
|---------------------|--------------------------|--------------------------------------------------------------------------------------------------------|
| Date of Assignment: | 08/01/2018 | |
| Date Inspected: | 09/01/2018 Inspected At: | Automobile Hub Enterprise 1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @ KAKI BUKIT Singapore 417883 |

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | |
|-----------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Reference | |
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 17 Jan 2018) |
| Parts: 143 | TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SGU7288Y) |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| Further Info: Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. Particulars | Condition | Repairer's | Amount |
|-----|-----|-----------------------------------------------|--------------------|-------------|--------------|
| 1 | 1 | *FRONT BONNET | Repair | 1,429.50 FL | *- FL |
| 2 | 1 | *FRONT BONNET SEAL | Not Necessary | 62.20 FL | *- FL |
| 3 | 1 | *FRONT BONNET LOCK | Not Necessary | 91.50 FL | *- FL |
| 4 | 1 | *FRONT BONNET LOCK CABLE | Not Necessary | 89.60 FL | *- FL |
| 5 | 2 | *FRONT BONNET HINGES L/R | Not Necessary | 134.40 FL | *- FL |
| 6 | 1 | *FRONT BUMPER | Dented | 881.85 FL | *481.10 FL |
| 7 | 1 | *FRONT BUMPER UNDERCOVER | Torn | 401.60 FL | *248.10 FL |
| 8 | 1 | *FRONT BUMPER FOG LAMP RH | Cracked | 380.90 FL | *295.50 FL |
| 9 | 1 | *FRONT BUMPER SPONGE | No such part | 89.70 FL | *- FL |
| 10 | 1 | *FRONT BUMPER REINFORCEMENT | Dented | 354.70 FL | *354.70 FL |
| 11 | 2 | *FRONT BUMPER SIDE RETAINERS-L/R | Bent | 163.00 FL | *132.20 FL |
| 12 | 10 | *FRONT BUMPER CLIPS | Necessary | 45.00 FL | *45.00 FL |
| 13 | 1 | *FRONT FENDERS-L/R | O/s Dented/Buckled | 1,350.00 FL | *675.00 FL |
| 14 | 1 | *FRONT FENDERS INNER SHIELDS-L/R | O/s Torn | 359.00 FL | *179.50 FL |
| 15 | 1 | *FRONT FENDERS INNER SHIELD CLIPS (30 Pcs) | Necessary | 135.00 FL | *40.00 FL |
| 16 | 2 | *FRONT FENDER WHEEL HOUSINGS-L/R | Repair | 1,002.00 FL | *- FL |
| 17 | 1 | *FRONT GRILLE ASSY | Cracked | 408.10 FL | *285.20 FL |
| 18 | 1 | *FRONT GRILLE LOGO | Necessary | 58.50 FL | *58.50 FL |
| 19 | 2 | *FRONT HEADLAMPS-L/R | Cracked | 1,051.00 FL | *1,051.00 FL |
| 20 | 2 | *FRONT HEADLAMPS SIDE GARNISHS-L/R | Not Necessary | 117.20 FL | *- FL |
| 21 | 1 | *FRONT SHOCK ABSORBER-RH | Not Necessary | 390.70 FL | *- FL |
| 22 | 1 | *FROTN LOWER ARM | Not Necessary | 627.50 FL | *- FL |
| 23 | 1 | *FRONT KNUCKLE ARM | Not Necessary | 526.60 FL | *- FL |
| 24 | 1 | *FRONT WHEEL BEARING | Not Necessary | 140.60 FL | *- FL |
| 25 | 1 | *FRONT SUPPORT PANEL ASSY | Dented/Twisted | 973.70 FL | *973.70 FL |
| 26 | 1 | *FRONT CHASSIS FRAME MEMBER-RH | Repair | 1,053.50 FL | *- FL |
| 27 | 1 | *WASHER TANK | Deformed | 57.90 FL | *57.90 FL |
| 28 | 1 | *WASHER TANK MOTOR | Not Necessary | 245.60 FL | *- FL |
| 29 | 1 | *AIR CLEANER INTAKE | Not Necessary | 98.10 FL | *- FL |
| 30 | 1 | *AIR CLEANER BOX ASSY | Not Necessary | 779.10 FL | *- FL |
| 31 | 1 | *AIR CON CONDENSER | Not Necessary | 1,507.40 FL | *- FL |
| 32 | 1 | *AIR CON DISCHARGE PIPE | Not Necessary | 501.60 FL | *- FL |
| 33 | 1 | *AIR CON SUCTION PIPE | Not Necessary | 489.60 FL | *- FL |
| 34 | 1 | *AIR CON LIQUID PIPE | Not Necessary | 260.20 FL | *- FL |
| 35 | 1 | *RADIATOR ASSY | Bent/Cracked | 1,345.50 FL | *1,345.50 FL |
| 36 | 1 | *RADIATOR TOP FRAME BRACKET | Not Necessary | 126.30 FL | *- FL |
| 37 | 2 | *RADIATOR TOP MOUNTS | Not Necessary | 25.20 FL | *- FL |
| 38 | 1 | *RADIATOR TOP HOSE | Not Necessary | 48.60 FL | *- FL |
| 39 | 1 | *RADIATOR LOWER HOSE | Not Necessary | 52.50 FL | *- FL |
| 40 | 1 | *RADIATOR FAN COWLING | Not Necessary | 220.80 FL | *- FL |
| 41 | 1 | *RADIATOR FAN BLADE | Not Necessary | 150.00 FL | *- FL |
| 42 | 1 | *RADIATOR FAN MOTOR | Not Necessary | 548.90 FL | *- FL |
| 43 | 2 | *WIPER PANEL GARNISH-L/R | Not Necessary | 1,050.60 FL | *- FL |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|----------------------------|---------------|------------|--------|
| 44 | 6 | | *WIPER PANEL GARNISH CLIPS | Not Necessary | 27.00 FL | *-FL |
| 45 | 1 | | *ENGINE MOUNTING-RH | Not Necessary | 390.40 FL | *-FL |
| 46 | 1 | | *ENGINE MOUNTING-LH | Not Necessary | 230.90 FL | *-FL |
| 47 | 1 | | *ENGINE MOUNTING-CTR | Not Necessary | 97.40 FL | *-FL |
| 48 | 1 | | *ENGINE MOUNTING-REAR | Not Necessary | 230.90 FL | *-FL |
| 49 | 1 | | *ENGINE MOUNTING BEAM | Not Necessary | 280.50 FL | *-FL |
| 50 | 1 | | *ABS PUMP | Not Necessary | 480.00 FL | *-FL |
| 51 | 1 | | *SET FRONT NUMBER PLATE | Not Necessary | 60.00 FS | *-FS |
| 52 | 1 | | *FRONT TYRE | Not Necessary | 280.00 FS | *-FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|-----------------------------------------------------|-----------|----------|
| Sub Total (\$\$) | 21,902.35 | 6,222.90 |
| - List Item Discount on L Items 25.00/25.00% (\$\$) | 5,390.59 | 1,555.73 |

| | | |
|--------------------|-----------|----------|
| Total Parts (\$\$) | 16,511.76 | 4,667.17 |
|--------------------|-----------|----------|

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------|---------------------------------------------------------|----------|------------|----------|
| Labour Items | | | | |
| 1 | TOWING CHARGES | New | 150.00 | 50.00 |
| 2 | TO REMOVE F/UNDERCARRIAGE | New | 350.00 | - |
| 3 | TO CHECK WHEEL ALIGNMENT | New | 120.00 | - |
| 4 | TO REMOVE,REFIX A/C CONDENSER AND REFILL A/C GAS | New | 180.00 | 100.00 |
| 5 | TO REMOVE,REFIX ENGINE PARTS | New | 300.00 | - |
| 6 | TO RESPRAY UNDERCOATING | New | 180.00 | 60.00 |
| 7 | TO CHECK FRONT ELECTRICAL WIRING | New | 100.00 | 20.00 |
| 8 | TO RESPRAY PAINTING AND ETC | New | 2,000.00 | 1,000.00 |
| 9 | PANEL BEATING,CUT,WELD,REMOVE AND REPLACING ABOVE PARTS | New | 2,500.00 | 800.00 |
| Gross Labour Cost (\$\$) | | | 5,880.00 | 2,030.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >