

3/20/2018

Claim Portal

Menu

3/20/2018

Claim Portal

Menu

3/20/2018

Claim Portal

Menu

3/20/2018

Claim Portal

Menu

Reviewing



29

TO TRANSFER OF FENDER FITTINGS,
ATTACHMENTS AND PERFORM WATER
SEEPAGE TEST.

0

0

0

Reviewing



30

TO TRANSFER OF DOOR FITTINGS,
ATTACHMENTS AND PERFORM WATER
SEEPAGE TEST.

120



25

TO DROP DIESEL TANK, PIPES, HOSES TO
FACILITATE BODYWORK REPAIR, FINAL
CHECKING AND TESTING.

60

0

0

Reviewing



26

TO VACUUM, REPLACE, REFIX AND RECHARGE
AIR CONDENSER.

100

0



21

LABOUR CHARGE TO MOUNT AND DISMOUNT
VEHICLE ON JIG BENCH, TO FACILITATE
REPAIR.

0

0

0

Reviewing



22

TO LIFT-UP ENGINE WITH GEAR BOX AND
REFIT. (*CHECK \$440.00)

0

0

0



17

TO TRANSFER OF REAR WINDSCREEN
FITTINGS, ATTACHMENTS AND PERFORM
WATER SEEPAGE TEST.

120

0

0

Reviewing



18

TO REINSTALL REAR BUMPER PARKING
SENSOR.

60

0

0

Reviewing



13

TO SUPPLY AND RE-DO REAR LUGGAGE
FLOOR PANEL INSULATION PADDING. }

0

0

0

Reviewing



14

TO TRANSFER OF BOOTLID FITTINGS,
ATTACHMENTS AND PERFORM WATER
SEEPAGE TEST.

0

0

0

Reviewing

-

9

TO CHECK ELECTRICAL LIGHTING
CONCERNED.

40

0

0

Reviewing



10

TO PULL AND JACK OUT CHASSIS FRAME AND
CORRECT IT TO SYMMETRICAL POSITION WITH
THE AID OF HYDRAULIC PNEUMATIC JACK.

250

0

0

Reviewing



5

TO RUST-PROOFING OF THE AFFECTED
AREAS.

150

0

0

Reviewing



6

TO REMOVE AND REFIT INTERIOR FITTINGS,
TRIMINGS, GARNISH, FITTINGS AND OTHER, TO
ENABLE REPAIR.

120

0

0

Reviewing



PANEL BEATING, KNOCKING AND
STRAIGHTENING THE NECESSARY PORTION,
REMOVE AND RENEWAL OF PARTS, ADJUST
AND REALIGN THE SAME.

2600

0

0

Reviewing



2

TOWING FESS.

50

0

0

Reviewing



Serviceable

0

10

0

Reviewing



206

1

DOOR WAIST SEAL OUTER FRT RH

Serviceable

0

10

Serviceable

0

10

0

Reviewing



203

1

DOOR WEATHERSTRIP FRT RH

Serviceable

0

10

0

10

0

Reviewing



200

1

DOOR CASING LIGHT

Serviceable

0

10

0

Reviewing



Reviewing



197

1

DOOR MOULDING FRT RH

Serviceable

0

10

0

Reviewing





194

1

DOOR REGULATOR GUIDE FRT RH

Serviceable

0

10

0

Reviewing



195

1