


Accident Sketch Plan Pg. 2

SKETCH PLAN

PIE (Changi Airport) before Kallang Exit



A : SLQ 5063 D

B : GBG 8184 P

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As per attached statement.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 08/01/2018  
11.00am

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



On 6/1/2018 @ about 12:00hrs, I  
Lee Cheon Hsien, PIN G8231584K  
was driving company motor van,  
GBG 8184P along PIE towards the  
direction of Changi Airport. I was  
driving on the extreme left lane of  
3-lanes express-way, somewhere before  
Kallang exit near 1/P 67A, this motor  
car SLQ 5063D, slow down and  
stop as traffic ahead of him stop.  
when I saw that I jam my brake  
but could not stop in time and  
hit onto the rear of the said  
motor car. The front portion of my motor  
van was damaged.

Lee  
G8231584K

Chp. No.

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo

