

22/03/2001

ASS. REC. BY:

REF: CS/CTI18000477/Kqd302

Special Instruction:

SIGNED BY:

Manmen

Kenneth

ASSIGNMENT (Office)

From (Person):

Chong Boun Sen

of

CTI

Date/Time:

5/01/2018 @ 3.32pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKD 6593P

Insured:

CB 7431 Y

at Workshop m/s

Soon Seng Company

Tel:

9625 0518

of Blk 18 Sin Ming Ind. Est. & Co. A #01-33

Policy No:

DMB1SN1534721700

Claim No:

SNM18D00096C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

04/01/2018

CA / REV / REP. / REV 24 HRS

'wp'

08/01/2017

B1K160 SM #04-05

H.O.D. Endorsement:

Date/Time:

4.42pm @ 05/01/2018

Person Contacted:

Mr. Chai

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction
	(✓) Enrol
	SKD 6593P - NA/CTI18000477/24
	CB 7431 Y - NA/CTI18000477/24
1/2	1/1 Lp & 4800 encl & cal form (Red 89325, 66%)

CT1

Date 08/01/2017

SKD 6593P

12 11

Estimated Cost

CD TR WS TR RES CD RES BVA MW MW

The insured vehicle is

SKD 6593P

The insured company

Soon Beng Company

BIK160 Sin Ming Ind. #04-05

Insured

Policy No

Claims No

Sum Insured

Excess


Claims Record

Mr Chai @ 9625 0518

Make of car

Policy Condition

Remarks: The veh had commenced its repair at the time of inspection



Est. of Market Value

CAG Accident Report Consistent? Yes or No

GAG AP Report Consistent? Yes or No

Est. Repairs 05 days Yes Yes or No

LTM Sum 20 Yes No Yes or No

CAG REV REP 24 HRS 'wpi

Date Person Contacted Vehicle No OUT

Date Time Action Instruction

9/11 PM 1455 to Car Home

RECEIVED 11/01/2017

Days To Repair of



Pre Report

01/2 hours



Final Report

Days To Repair of

Days Of Repair

Resurver No of This

Days To Repair

220

Add Fee



Days To Repair



Days To Repair



Days To Repair



Days To Repair



Days To Repair



Days To Repair

Amount Paid

Total Sum

MER-TP

4800

Total Sum Paid

220

Make of car

Type of car

Make

Volkswagen

Jetta

1390

Model

M. City

Color of car

Est. Repairs

101441

Type of car

Engine

Cyls

WVW 777167CM058354

Gear Type

Steering Type

Brake Type

Wheels

Type Size

R

R

BS DON EXNOVA BY FS LIA MS CHTSU PP SUM

TOYOTA YOKO

Front

Rear

LBS

CAG

Survey report

Des of Damages Fr Rear OS MS LC Potholes

The LC Chassis frame Body Structure affected due to car




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18000477/Kqd3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 09-01-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	CB 7431Y	Veh. Inspected	SKD 6593P	
Policy No.	DMB1SN1534721700	Coverage (\$)	0.00	
Claim No.	SNM18D00096C02	Excess (\$)	0.00	
Assign From	MERIMEN (CHING BOON SEN)	Assign Date	09/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	Steering			
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	04/01/2018	Inspection Date	08/01/2018	
Survey held at	SOON SENG COMPANY BLK 18 #01-33 SIN MING ROAD SINGAPORE 575756			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

SKD 6593P

Policy Type: OD / TF / TF RES / TL / EVA

Typist

Admin (

[illegible]

- | | |
|---|---------------------------------------|
| C | Reference No. |
| C | Customer Code |
| N | Assign From |
| C | Assign Date |
| C | Veh No (Inspected) |
| C | Veh No (Insured) |
| C | D.O.A |
| C | Policy No |
| C | Claim No |
| C | Insurance Authorisation (CA /REV/REP) |
| C | Report Type |
| C | Weekend Charges |
| N | Survey held at/Repairer |
| C | Excess |

Surveyor I

[illegible]

- | | |
|---|------------------------|
| C | Vehicle No |
| C | Regn Month/Year |
| N | Vehicle Type |
| N | Make & Model |
| C | Engine Capacity. (C.C) |
| N | Colour |
| C | Odometer. (Sp.Reading) |
| C | Chassis No |
| N | General Condition |
| N | Steering |
| N | Brake |
| N | Modification (Modi) |
| C | Tyre Size |
| N | Tyre Make |
| C | Tyre Balance |
| C | Date of Inspection |
| N | Survey held |
| N | Des.of Damages |

<input checked="" type="checkbox"/>			
-------------------------------------	--	--	--

- ### C Damaged Vehicle Photographs Uploaded

[illegible]

- | | |
|---|---|
| N | ALL Parts condition |
| C | Market Value for OD cases |
| C | Estimate Repair Cost for PRI (RSI, TMI, MSIG) |
| C | Days of repair |
| C | Finalised Amount |
| C | Re-inspection Cases to Finalize within 5 Days |

--	--	--

- C Resurvey photo Uploaded

Check By:

Date _____

21/05/2014

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Jan 2018		05 Jan 2018 15:32 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	M/S YANG BUS TRANSPORT SERVICES		
Main Claimant:	AW HOCK KENG, ID: S0377486D		
Vehicle Reg. No.:	SKD6593P	Date of Loss:	04/01/2018 13:00 - :59
Claim Type:	TP / SNM18D00096C02	Policy/Cover Note No.:	DMB1SN1534721700
Vehicle Reg. No. (Insured):	CB7431Y	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Soon Seng Company (HQ) Blk 18 Sin Ming Industrial Estate Sector A, #01-33, 575676 Sin Ming - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 16/01/2018]		
Adj Asg. Remarks:	PLEASE SURVEY THIRD PARTY, CHECK CONSISTENCY OF THE DAMAGES ON WITHOUT PREJUDICE BASIS. OUR INSURED HAD NOT FILED SAS REPORT.		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Soon Seng Company (SG)

YOUR REF: CB7431Y
OUR REF: SKD6593P

BY HAND

11 JANUARY 2018

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD, #16-00 SPRINGLEAF TOWER
SINGAPORE 079909

ATTN: (CUSTOMER SERVICE/CLAIMS DEPT.)

Dear Sirs,

RE: DATE OF ACCIDENT : 4 JANUARY 2018
VEHICLE MAKE : TOYOTA VIOS
VEHICLE NO : SKD6593P
YOUR INSURED VEHICLE NO (T/P) : CB7431Y

We refer to the above matter wherein we act for **AW HOCK KENG**

We are informed that the above third party vehicle was insured with you at the material time when the accident occurred. The accident was caused by the negligence of your insured, his servant and/or

Our client is now making a third party claim against your insured for the sum of **SGD 5,640.00** and we enclose herewith the following documents to substantiate the claim -

1. Original Invoice No: 118 To CHINA TIAPING INSURANCE (S) PTE LTD
2. Copy of Singapore Accident Statement
3. A Copy of Authorisation to Act
4. A Copy of Discharge Voucher

SOON SENG COMPANY (SG)
180 Sin Ming Drive
#04-05 AutoCity
Singapore 575722
Tel: 6453 6088

The Claims are as follows:-

1. Car Rental (Pre-survey 2Day X \$120)	SGD \$	240.00
2. Cost of Repair	SGD \$	4,800.00
3. Car Rental (Repair 5 Days X \$120)	SGD \$	600.00
	SGD	
TOTAL CLAIM: SGD		<u>\$ 5,640.00</u>

Kindly forward the Letter of Offer and Discharge Voucher to **SOON SENG COMPANY (SG) PTE LTD.**

Please acknowledge receipt and let us have your reply within **Fourteen (14) days**, failing which we have our client's instructions to litigate this matter. Your kind co-operation in this matter is most

Yours faithfully,

James Chew

for **SOON SENG COMPANY (SG) PTE LTD**

160 SIN MING DRIVE #04-05 SINGAPORE 575722
T: +65 92960289 EMAIL: jameschew88@outlook.com

Soon Seng Company (SG)

160 Sin Ming Drive, #04-05

Sin Ming Autocity

Singapore (575722)

Invoice No: 118

Date: 11 January 2018

Terms: 30 Days

Bill to:

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD, #16-00 SPRINGLEAF TOWER
SINGAPORE 079909

ATTN: (CUSTOMER SERVICE/CLAIMS DEPT.)

S/NO	DESCRIPTION	AMOUNT SGD\$
	VEHICLE NO: SKD6593P MODEL: VW JETTA JOB NO: 118	
	THIRD PARTY CLAIM: LUMP SUM REPAIR TOTAL REPAIR COST	\$ 4,800.00
	DOLLARS: FOUR THOUSAND EIGHT HUNDRED ONLY	
TOTAL DUE:		\$ 4,800.00

For payment, please make payable to :
SOON SENG COMPANY (SG) PTE LTD


for SOON SENG COMPANY (SG) PTE LTD

SOON SENG COMPANY (SG)
160 Sin Ming Drive
#04-05 AutoCity
Singapore 575722
Tel: 6453 6088

WORKSHOP DISCHARGE VOUCHER


WITHOUT PREJUDICE to:
(a) Insurers' Subrogated Claim and/or
(b) Any Personal Injury Claims
Note: This Notice supersedes any
inconsistencies found in this
Discharge Voucher

Claims No:

I hereby acknowledge that my vehicle SKD 6593P has been
repaired to my satisfaction and the repairer's workshop and staff of
SOON SENG COMPANY (SG) shall not be liable in any way whatsoever
after the completion of the repairs with respect to the following
accident that occurred on 4/1/18 at 81K 13A Upper Boon Keng Carpark.

Dated 11 Day of January 2018.

Signature of Witness:




Name: James

NRIC: S8823053A

Signature of Claimant:

(*Company's stamp if applicable)



Name: Aw Hock Leng

NRIC: S0377486D

AUTHORISATION TO ACT


I/We Aw Hock Keng (the third party claimant) of _____


(address), owner of SKD6593P (vehicle no.) hereby
authorize San Sang Company (SG) Pte Ltd ("the workshop") to act for me with respect
to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no.
_____ that was damaged pursuant to the accident which occurred on 4/1/18 (date)
along BK 13A Upper Boon Keng Carpark (location) involving
vehicle no/s CB 7431 Y ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they
deem fit and the workshop is further authorized to receive payment further to settlement of my
claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a
without prejudice and without admission of liability basis insofar as the driver/owner/insurers
of the other vehicle/s is concerned.

Dated this 4 (day) of January (month) 2018 (year)


Signed by "the third party claimant"
(with company stamp if applicable)


Signed by "the workshop"
(with company stamp)

WITHOUT PREJUDICE to:
(a) Insurers' Subrogated Claim and/or
(b) Any Personal Injury Claims
[Note: This Notice supersedes any
inconsistencies found in this
Discharge Voucher]

VEHICLE AGREEMENT

AGREEMENT NO: 126

Owner Particular's

Name:

NRIC:

Address:

Vehicle Number: SJB 7371DMake & Model: Mitsubishi Lancer Ex

Date Out:

5/1/2018



Time Out:

9.35 amDaily \$120 @ 7 days = \$840/- ✓

Hirer/Authorised Driver is responsible for the first \$1,500 excess for collision/damage to the owner of the vehicle SJB 7371D (including windscreen) and also first \$1500 excess for collision/damage to third party's vehicle for each and every accident/damage.

Hirer/Authorised Driver Signature

Hirer/Authorised Driver's Particulars

Name: AW Hock KengNRIC: S0577486DAddress: 67 Compassvale Bow #07-32
S(544992)Pass Date: 1/2/1967Date of Birth: 26/4/19443/4 tank.

I/We agreed to the terms and conditions in this agreement and that all information given are true & correct in all respect. My/Our driving licence(s) is/are current and not disqualified from driving. You may charge all amount due on the rental to my/our credit card.

***IMPORTANT**

1. ONLY PERSONS ABOVE 25 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THIS VEHICLE.

2. VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT FROM THE OWNER.

3. IN THE EVENT OF AN ACCIDENT, THE HIRER/AUTHORISED DRIVER:

(i) shall report all accidents involving the said vehicle to the Owner immediately;

(ii) shall take immediate steps to complete and sign Form MAR 1 (Motor Accident Report Form) and do all other acts required in compliance with the 'Non-injury Motor Accident Report Scheme';

RETURN OF VEHICLE – THE HIRER/AUTHORISED DRIVER IS REQUIRED TO SIGN IN THE COLUMN 'SIGNATURE OF HIRER/AUTHORISED DRIVER' FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL BE DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO THE OWNER AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE RETURN AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	REMARKS	SIGNATURE OF HIRER/AUTHORISED DRIVER
<u>10 January '18</u> <u>7 14 pm</u>			



MOBILE CAR FIX

Mobile Car Fix Pte Ltd (SG)
70 Redhill Close
#1-890
Singapore, 150070
Singapore

Invoice

BILL TO
AW HOCK KENG VW JETTA SKD6593P

Invoice Number: 126

Invoice Date: January 11, 2018

Payment Due: January 11, 2018

Amount Due (SGD): \$840.00


Items	Quantity	Price	Amount
7 Days Car Rental 5 January 2018 (935am) to 10 January 2018 (715pm)	7	\$120.00	\$840.00

Total: \$840.00

Amount Due (SGD): \$840.00

Notes

Cash payment required upon return of vehicle.



Business Registration Number: 201426776H

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/01/2018 14:23
Date Of Accident	04/01/2018 13:35
Exact Location Of Accident	BLK 13A UPPER BOON KENG
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKD6593P
Insured/Policyholder	
Name Of Registered Owner	AW HOCK KENG
NRIC No	S0377486D
Email Address	WILSONAW2001@YAHOO.COM
Mobile Phone No	(LOCAL) +65-91001870
Alternative Phone No	OFFICE-91001870
Vehicle Particulars	
Manufacturer	VOLKSWAGEN
Model	JETTA
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5085735463-01
Cover Note Number	
Driver	
Name of Driver	AW HOCK KENG
NRIC No	S0377486D
Date Of Birth	26/04/1944
Occupation	INDOOR
Date Of Driving Pass	07/02/1967
Driving Experience	50 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91001870
Fax Number	
Contact Number	OFFICE-91001870
E Mail Address	WILSONAW2001@YAHOO.COM

Address	67 COMPASSVALE BOW #07-32 THE QUARTZ
Postcode	544992
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : ZHOU SHANG LI
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER STATEMENT (ATTENDED BY: JAMES NG)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Details of Witness 1

Name	ZHOU SHANG LI
Phone Number	91837281
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	CB7431Y
Vehicle Make/Model/Colour	NISSAN / WHITE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	SHAHBIN BIN ABDUL KADIR
NRIC/Passport Number	S1469293B
Contact Number	
Address	

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




 Policyholder's Signature
 Date & Time: 04 JAN 2018

Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 04 JAN 2018

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

NG WING KIN JAMES
S7927881E

SKETCH PLAN

Refer
attachment


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

There are two way lane leading to the car park at 13A Brook Keng Road. I was my car was on way out to the right with my sign on. The other car came from right which is a opposite (suppose) behind of the road.

I was on the right lane about to turn to the right side. The nissan ck 74319 drove on the wrong lane, came from behind and crashed into my right side of the car causing damage to the passenger side of the door.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time: 04 JAN 2016

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

NG WING KIN JAMES
S7927881E

Figure 1

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Jan 2018		05 Jan 2018 15:32 Edit Adj Rpt	\$4,800.00 Edit Estimates	\$4,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by Insurer]

Insured:	M/S YANG BUS TRANSPORT SERVICES, Co. Reg. No.: -		
Main Claimant:	AW HOCK KENG, ID: S0377486D		
Vehicle Reg. No.:	SKD6593P	Date of Loss:	04/01/2018 13:00 - :59
Claim Type:	TP / SNM18D00096C02	Policy/Cover Note No.:	DMB1SN1534721700
Vehicle Reg. No. (Insured):	CB7431Y	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Soon Seng Company (HQ) Blk 18 Sin Ming Industrial Estate Sector A, #01-33, 575676 Sin Ming - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 16/01/2018]		
Adj Asg. Remarks:	PLEASE SURVEY THIRD PARTY, CHECK CONSISTENCY OF THE DAMAGES ON WITHOUT PREJUDICE BASIS. OUR INSURED HAD NOT FILED SAS REPORT.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)
























There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKD6593P (SNM18D00096C02)**
[CB7431Y]
TP
AW HOCK KENG
Jan 4 2018 1:00PM
[M/S YANG BUS TRANSPORT SERVICES]
Soon Seng Company

Upload Documents Upload Photos Compose New Letter			View View In Browser		
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	01/02/18 17:29	General View	 Load JPG	<input checked="" type="checkbox"/>	
2	01/02/18 17:29	General View	 Load JPG	<input checked="" type="checkbox"/>	
3	01/02/18 17:29	General View	 Load JPG	<input checked="" type="checkbox"/>	
4	01/02/18 17:29	General View	 Load JPG	<input checked="" type="checkbox"/>	
5	01/02/18 17:29	General View	 Load JPG	<input checked="" type="checkbox"/>	
6	01/02/18 17:29	General View	 Load JPG	<input checked="" type="checkbox"/>	
7	01/02/18 17:29	General View	 Load JPG	<input checked="" type="checkbox"/>	
8	01/02/18 17:29	General View	 Load JPG	<input checked="" type="checkbox"/>	
9	01/02/18 17:29	General View	 Load JPG	<input checked="" type="checkbox"/>	
10	01/02/18 17:29	General View	 Load JPG	<input checked="" type="checkbox"/>	
11	01/02/18 17:29	General View	 Load JPG	<input checked="" type="checkbox"/>	
12	01/02/18 17:29	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>	
13	01/02/18 17:29	General View	 Load JPG	<input checked="" type="checkbox"/>	
14	01/02/18 17:29	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>	
15	01/02/18 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
16	01/02/18 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
17	01/02/18 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
18	01/02/18 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
19	01/02/18 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
20	01/02/18 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
21	01/02/18 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
22	01/02/18 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
Documentation			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	05/01/18 15:33	THIRD PARTY SKD6593P -FROM SOON SENG CO -ESTIMATE	 Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^

v

Show Remarks To:

☐ Handling Insurer

Note:

Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT18000477/KQD3E2

Date: 08/02/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SN1534721700

Claimant Vehicle No: SKD6593P Insured Vehicle No: CB7431Y

Date of Loss: 04/01/2018 Nature of Claim: TP Claim No: SNM18D00096C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKD6593P**

Make & Model: VOLKSWAGEN JETTA, 1.6 (A) Engine No: CAX947639

Reg. Date: 23/12/2011 (Man. Year: 2011) Chassis No: WWWZZZ16ZCM058354

Colour: Metallic Grey Odometer: 101441 km

Engine Capacity: 1390 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55Z R16 Rear Tyre Size: 205/55Z R16

Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm

Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,145.00	4,870.00	4,275.00	46.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,980.00	1,160.00	3,820.00	76.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,125.00	6,030.00	8,095.00	57.31
Approved Total (Overridden) (\$\$)		4,800.00		
Nett Amount (\$\$)	14,125.00	4,800.00	9,325.00	66.02

INSPECTION

Date of Assignment: 05/01/2018

Date Inspected: 08/01/2018 Inspected At: Soon Seng Company (HQ)
Blk 18 Sin Ming Industrial Estate Sector A,
#01-33
Singapore 575676

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 08 Feb 2018)
Parts: 143 **VOLKSWAGEN JETTA 1.6 (A)** (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKD6593P)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*RH FRONT DOOR	Bent	1,765.00 F	*1,480.00 F
2	1	*RH REAR DOOR	Buckled	1,611.00 F	*1,350.00 F
3	1	*RH FRONT DOOR LOCK MOTOR ASSY	Dented	869.00 F	*500.00 F
4	1	*RH FRONT DOOR LATCH	Repair	69.00 F	*- F
5	1	*RH FRONT DOOR POWER WINDOW MOTOR	Jammed	811.00 F	*530.00 F
6	1	*RH FRONT DOOR WINDOW RUBBER	Serviceable	350.00 F	*- F
7	1	*RH FRONT & REAR DOOR RUBBER MOULDING (2 pcs)	Distorted / Cut-1pc only	360.00 F	*180.00 F
8	1	*RH FRONT DOOR JACK	Repair	131.00 F	*- F
9	1	*RH FRONT DOOR HINGE	Repair	98.00 F	*- F
10	20	*RH FRONT DOOR RIVETS	Necessary	120.00 F	*120.00 F
11	1	*RH FRONT DOOR HANDLE	Dented	311.00 F	*130.00 F
12	1	*RH FRONT DOOR LOCK	Repair	198.00 F	*- F
13	1	*RH LOWER ROCKER PANEL	Repair	1,212.00 F	*- F
14	1	*RH SIDE MIRROR MOTOR ASSY	MTG Distorted / Dented	965.00 F	*580.00 F
15	1	*RH SIDE MIRROR TOP COVER	Serviceable	211.00 F	*- F
16	1	*RH SIDE MIRROR GLASS	Serviceable	64.00 F	*- F

F=Franchise part.

Total Parts (S\$) **9,145.00** **4,870.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING AND SYSTEM FUNCTION	New	480.00	20.00
2	RUST PROOFING ON AFFECTED AREAS	New	700.00	60.00
3	LABOR TO REMOVE AND REFIT 2 RH DOORS, SIDE MIRROR & MOTOR, DOOR INTERIOR PARTS OF LOCK MOTOR ASSY, POWER WINDOW MOTOR, DRIVER WINDOW	New	2,000.00	500.00
4	TO RESPRAY DAMAGED AND REFITTED PARTS (2 DOORS, SIDE MIRROR AND LOWER ROCKER PANEL)	New	1,800.00	580.00
Gross Labour Cost (\$\$)			4,980.00	1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >