

12/03/2017

ASS. REC. BY:

REF:

CS/MSG18000-487/Wrdz^{er} Special Instruction:

Wilson

ASSIGNMENT (Office)

From (Person):

Lionel Tan

of

MSIG

Date/Time:

09/01/18 @ 10:05am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SIG 5424 Y

Insured:

SGM 9571 H

at Workshop m/s

Reliable Carz

Tel:

8166 9797

of

8 Kaki Bkt Ave 4 #05-50

Policy No:

A28837281QMX

Claim No:

543859

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/12/2017

CA / REV / REP. / REV 24 HRS

'wup'

10/01/2018

H.O.D. Endorsement:

Date/Time: 11:25am @ 09/01/18

Person Contacted:

jason lee

Vehicle: IN OUT

Date/Time

Action/Instruction (✓) Estimate

SIG 5-124 Y - NA / INC18000398/24

D.O.A. = 30/12/2017

SGM 9571 Y - NA / INC18000398/14

D.O.A. = 30/12/2017

Sent preli thru merimen

Confirm \$600, 2 days

Red of 3857.69, 87%.

STAMP

MSL

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD/TP/WS/TP RES/OD RES/EVA/INV/INV
 To inspect Vehicle No 53G 5424Y
 at Workshop m/s Reliable Car
 of 8 Koker Buley Ave 4 #35
 Insured _____
 Policy No _____
 Claims No _____
 Sum Insured _____ Excess _____
 (Client's Record) _____
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lump Sum: \$ 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No 53G 5424Y Reg 4/7/2008
 Type: Al. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make Toyota Vios cc 1497
 Colour Silver Insured / Std / NI / NA
 Sp. Reading 184541 Race: Insured / Std / NI / NA
 Eng No _____
 C No MR053H493058T0243
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / SIRIM / STD A/Rim or
 Tyre Size R.F. 185/50 R15
P.R. 185/60 R15
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Bridgestone (F) / (R)
 Front: _____ Rear: _____
 R/Bal. 3 mm R/Bal. 3 mm
 L/Bal. 3 mm L/Bal. 3 mm
 D.O.A. _____ DOA 10/1/2018
 Survey held at: As Above
 Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or
Right Rear
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

10/1/2018 Repair Estimate Given

RECEIVED 7 FEB 20

Date Time File Pass to

☐ : Prel. Report
☒ : Final Report

Days Of Repair: 2

Resurvey No. of Trip: 2

Survey Fee

Transcriber

U/C - FS - S

Amount

Charge

Add Fee:

☐ Site Insp. \$
☐ Interview \$
☐ Techn. Insp. \$
☐ Weighing \$

Report Format

Lump Sum / t.B.I. :

TP
600

200

10

210

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case No.	Date Recd	Assigned To	Date Assigned	Assigned By	Assigned To	Assigned To	Assigned To
Main	09 Jan 2018		09 Jan 2018 10:05	Assign			
							New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	POON EE LE DEBBIE, ID: S8117264A, Tel: +6598327834, Email: DEBBIEPOON1981@GMAIL.COM								
Main Claimant:	RENT A RIDE LEASING PTE. LTD., Co. Reg. No.: 201530139G								
Vehicle Reg. No.:	SJG5424Y	Date of Loss:	30/12/2017 18:00 - :59						
Claim Type:	TP / 543859	Policy/Cover Note No.:	A28837284QMX (Comprehensive) Coverage: 20/11/2017 - 19/11/2018						
Vehicle Reg. No. (Insured):	SGM9571H	Policy No. (Claimant):							
		Excess:	S\$300.00						
Repairer:	Reliable Carz Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #05-50, 415875 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 10/01/2018]								
Driver/Custodian (Insured):	POON EE LE DEBBIE (36 / Female), NRIC: S8117264A, Tel: +6598327834								
Adj Asg. Remarks:	Please contact Ms Jason Lee @ 8166 9797 to arrange for survey.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail 									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Date	Priority	Type	Task Group	Subject	Author	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18000487/Wrd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 09-01-2018	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGM 9571H	Veh. Inspected	SJG 5424Y	
Policy No.	A28837284QMX	Coverage (\$)	0.00	
Claim No.	543859	Excess (\$)	0.00	
Assign From	MERIMEN (LIONEL TAN)	Assign Date	09/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	Steering			
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	30/12/2017	Inspection Date		
Survey held at	RELIABLE CARZ PTE LTD 8 KAKI BUKIT AVE 4 #05-50 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan Tian Pei

Date: 01 Feb 2018

Preliminary Advice

Insured Vehicle No	: SGM9571H	Accident Date	: 30/12/2017
TP Vehicle No	: SJG5424Y	Assignment Date	: 09/01/2018
Make	: TOYOTA VIOS	Est. Duration of Repair	: 2.00
Date of Inspection	: 10/01/2018		
Inspection At	: RELIABLE CARZ PTE LTD (HQ) 8 KAKI BUKIT AVE 4, #05-50 SINGAPORE 415875		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,457.69
Revised Amount	:S\$	791.48
Check Items (Estimated)	:S\$	0.00
Total	:S\$	791.48

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


ACCIDENT STATEMENT

Date Of Report 08/01/2018 13:16
 Date Of Accident 30/12/2017 18:00
 Exact Location Of Accident PONGGOL EAST TWDS KPE / TPE
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJG5424Y
 Insured/Policyholder RENT A RIDE LEASING PTE. LTD.
 Name Of Registered Owner 201530139G
 Co Reg No NOEMAIL
 Email Address (LOCAL) +65-96611153
 Mobile Phone No OFFICE-96611153
 Alternative Phone No
 Vehicle Particulars TOYOTA
 Manufacturer VIOS E AUTO
 Model
 Exact Purpose for which vehicle was being used at time of accident WORK
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE HIRE
 Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Name of Insurance Company THIRD PARTY
 Type Of Coverage NO
 Fleet Policy 5096814724
 Policy Number
 Cover Note Number
 Driver OSMAN BIN OMAR
 Name of Driver S1835859Z
 NRIC No 07/03/1967
 Date Of Birth OUTDOOR
 Occupation 23/05/1987
 Date Of Driving Pass 30 YEARS AND 7 MONTHS
 Driving Experience MALE
 Gender (LOCAL) +65-96611153
 Mobile Number
 Fax Number
 Contact Number OTHERS-96611153
 EMail Address NOEMAIL

SKETCH PLAN



A - SJG 5424Y
B - SGM 9571H

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Vehicle A was driving along ~~KPE / TPE~~ Ponggol East toward KPE / TPE. Vehicle A slow down because in front vehicle stop and suddenly Vehicle B hit on Vehicle A rear portion.

DECLARATION

I/We declare that the above particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Enquire Transfer Fee

Vehicle Details

Vehicle No. :	SJG5424Y
Vehicle Type :	Z10 - Private Hire (Chauffeur) Motor Car
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	TOYOTA
Vehicle Model :	VIOS E AUTO
Chassis No. :	MR053HY9305070243
Propellant :	Petrol
Engine No. :	1NZX774648
Engine Capacity :	1497 cc
Maximum Power Output :	80.0 kW (107 bhp)
Maximum Laden Weight :	1505 kg
Unladen Weight :	1095 kg
Year Of Manufacture :	2008
Original Registration Date :	04 Jul 2008
Lifespan Expiry Date :	-
COE Category :	A - Car (1600cc & below)
Quota Premium :	\$15,701.00
COE Expiry Date :	03 Jul 2018
Road Tax Expiry Date :	03 Jul 2018
PARF Eligibility Expiry Date :	03 Jul 2018
Inspection Due Date :	03 Jul 2019

RELIABLE CARZ PTE LTD

8 Kaki Bukit Avenue 4 #05-50 Premier @ Kaki Bukit Singapore 415875
Contact No.: +65 8166 9797

Vehicle No.: SJG 5424Y

Model: TOYOTA VIOS

QTY DESCRIPTION

AMOUNT (S\$)

List Items:

1	Rear bumper ✓ DE	389.07 ✓
2	Rear bumper bracket @ S\$28.91 2. X NN	57.82 X
2	Rear bumper retainer @ S\$82.90 ✓ RHS Retainer. NEC	165.80 #82.90
1	Rear bumper lamp RH X NOT Such Part	80.43 X
1	Rear bumper lamp LH X NOT NOT Such Part	80.43 X
10	Rear bumper clip @ S\$5.00 ✓ NEC	50.00 ✓
1	Rear end panel X NN	513.51 X
1	Rear end panel top garnish X NN	189.49 X
1	Taillamp RH X NN	265.90 X
1	Taillamp LH X NN	265.90 X
1	Rear bootlid X NN	450.30 X
1	Rear bootlid lock X NN	87.00 X
1	Bootlid emblem "LOGO" X NN	44.87 X
1	Bootlid emblem "E" X NN	30.24 X
1	Bootlid emblem "VIOS" X NN	38.85 X
		2709.61 521.90
		Less 20 % (541.92)
		Subtotal 2167.69

Special Nett Items:

1	Reverse sensor X NN	350.00 X
		Subtotal 350.00

Labour Charges:

To remove and replace above parts
To spray painting on affected area
To transfer bootlid mechanism
To remove and refix reverse sensor system

850.00 200
850.00 200
120.00 X
120.00 X
Subtotal 1940.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL S\$

4457.69

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Without Prejudice
Parts Subject To
W.B.M, LKK
hump Survey Repair
Repair Day 1 - 2 Days
Resurvey Disassemble / After Part.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Jan 2018		09 Jan 2018 10:05 Edit Adj Rpt	S\$600.00 Edit Estimates	S\$600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:		POON EE LE DEBBIE, ID: S8117264A, Tel: +6598327834, Email: DEBBIEPOON1981@GMAIL.COM							
Main Claimant:		RENT A RIDE LEASING PTE. LTD., Co. Reg. No.: 201530139G							
Vehicle Reg. No.:		SJG5424Y	Date of Loss:	30/12/2017 18:00 - :59					
Claim Type:		TP / 543859	Policy/Cover Note No.:	A28837284QMX (Comprehensive) Coverage: 20/11/2017 - 19/11/2018					
Vehicle Reg. No. (Insured):		SGM9571H	Policy No. (Claimant):						
		Excess:	S\$300.00						
Repairer:		Reliable Carz Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #05-50, 415875 Kaki Bukit - Tel:							
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Final Rpt due 08/02/2018]							
Driver/Custodian (Insured):		POON EE LE DEBBIE (36 / Female), NRIC: S8117264A, Tel: +6598327834							
Adj Asg. Remarks:		Please contact Ms Jason Lee @ 8166 9797 to arrange for survey.							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJG5424Y (543859)**
[SGM9571H]
TP
RENT A RIDE LEASING PTE. LTD.
Dec 30 2017 6:00PM
[POON EE LE DEBBIE]
Reliable Carz Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser		
Assessment Reports			1 per page	☒	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	09/01/18 09:32	Accident Statement From: SC - Reg. No: SGM9571H, Claimant: POON EE LE DEBBIE	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/02/18 14:07	Adjuster Immediate Advice	1	Load HTM	
Photos/Images			3 per page	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/02/18 12:40	General View	1	Load JPG	☒
2	07/02/18 12:40	General View	1	Load JPG	☒
3	07/02/18 12:40	General View	1	Load JPG	☒
4	07/02/18 12:40	General View	1	Load JPG	☒
5	07/02/18 12:40	General View	1	Load JPG	☒
6	07/02/18 12:40	General View	1	Load JPG	☒
7	07/02/18 12:40	General View	1	Load JPG	☒
8	07/02/18 12:40	General View	1	Load JPG	☒
9	07/02/18 12:40	General View	1	Load JPG	☒
10	07/02/18 12:40	General View	1	Load JPG	☒
11	07/02/18 12:40	General View	1	Load JPG	☒
12	07/02/18 12:40	General View	1	Load JPG	☒
13	07/02/18 12:40	General View	1	Load JPG	☒
14	07/02/18 12:40	General View	1	Load JPG	☒
15	07/02/18 12:40	General View	1	Load JPG	☒
16	07/02/18 12:40	General View	1	Load JPG	☒
17	07/02/18 12:40	General View	1	Load JPG	☒
18	07/02/18 12:40	General View	1	Load JPG	☒
19	07/02/18 12:40	General View	1	Load JPG	☒
20	07/02/18 12:40	General View	1	Load JPG	☒
21	07/02/18 12:40	General View	1	Load JPG	☒
22	07/02/18 12:40	General View	1	Load JPG	☒
23	07/02/18 12:40	General View	1	Load JPG	☒
24	07/02/18 12:40	General View	1	Load JPG	☒
25	07/02/18 12:40	General View	1	Load JPG	☒
26	07/02/18 12:40	General View	1	Load JPG	☒
27	07/02/18 12:40	General View	1	Load JPG	☒
28	07/02/18 12:40	General View	1	Load JPG	☒
29	07/02/18 12:40	General View	1	Load JPG	☒
30	07/02/18 12:40	General View	1	Load JPG	☒

					☒
31	07/02/18 12:40	General View	1	Load JPG	☒
32	07/02/18 12:40	General View	1	Load JPG	☒
33	07/02/18 12:40	General View	1	Load JPG	☒
34	07/02/18 12:40	General View	1	Load JPG	☒
35	07/02/18 12:40	General View	1	Load JPG	☒
36	07/02/18 12:40	General View	1	Load JPG	☒
37	07/02/18 12:40	General View	1	Load JPG	☒
38	07/02/18 12:40	General View	1	Load JPG	☒
39	07/02/18 12:40	General View	1	Load JPG	☒
40	07/02/18 12:40	General View	1	Load JPG	☒
41	07/02/18 12:40	General View	1	Load JPG	☒
42	07/02/18 12:40	General View	1	Load JPG	☒
43	07/02/18 12:40	General View	1	Load JPG	☒
44	07/02/18 12:40	General View	1	Load JPG	☒
45	07/02/18 12:40	Dismantled Parts	1	Load JPG	☒
46	07/02/18 12:40	Dismantled Parts	1	Load JPG	☒
47	07/02/18 12:40	Dismantled Parts	1	Load JPG	☒
48	07/02/18 12:40	Dismantled Parts	1	Load JPG	☒
49	07/02/18 12:40	Reinspection Photo	1	Load JPG	☒
50	07/02/18 12:40	Reinspection Photo	1	Load JPG	☒
51	07/02/18 12:40	Reinspection Photo	1	Load JPG	☒
52	07/02/18 12:40	Reinspection Photo	1	Load JPG	☒
53	07/02/18 12:40	Reinspection Photo	1	Load JPG	☒
54	07/02/18 12:40	Reinspection Photo	1	Load JPG	☒
55	07/02/18 12:40	Reinspection Photo	1	Load JPG	☒
56	07/02/18 12:40	Reinspection Photo	1	Load JPG	☒
57	07/02/18 12:40	Reinspection Photo	1	Load JPG	☒
58	07/02/18 12:40	Reinspection Photo	1	Load JPG	☒
59	07/02/18 12:40	Reinspection Photo	1	Load JPG	☒
Documentation					1 per page ☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	09/01/18 09:32	TPD SJG5424Y GIA REPORT	1	Load PDF	
2	09/01/18 09:34	Pre-Repair Survey	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18000487/WRD3E2

Date: 09/02/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28837284QMX

Claimant Vehicle No : SJG5424Y

Insured Vehicle No : SGM9571H

Date of Loss: 30/12/2017

Nature of Claim: TP

Claim No: 543859

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJG5424Y**

Make & Model: TOYOTA VIOS, 1.5 (A)

Engine No: 1NZX774648

Reg. Date: 04/07/2008 (Man. Year: 2008)

Chassis No: MR053HY9305070243

Colour: Silver

Odometer: 184541 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/50 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Bridgestone 3 mm

Rear Left Side: Bridgestone 3 mm

Front Right Side: Bridgestone 3 mm

Rear Right Side: Bridgestone 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,517.69	391.48	2,126.21	84.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,940.00	400.00	1,540.00	79.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,457.69	791.48	3,666.21	82.24
Approved Total (Overridden) (S\$)		600.00		
Nett Amount (S\$)	4,457.69	600.00	3,857.69	86.54

INSPECTION

Date of Assignment: 09/01/2018

Date Inspected: 10/01/2018 Inspected At:

Reliable Carz Pte Ltd (HQ)
8 Kaki Bukit Ave 4, #05-50
Singapore 415875

Estimated Period of Repair: 2.0 days

Adjuster: Teo Cheng Ming Wilson

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Feb 2018)
Parts: 143 TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJG5424Y)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	389.07 FL	*389.07 FL
2	2		*REAR BUMPER BRACKET	Not Necessary	57.82 FL	*- FL
3	1		*REAR BUMPER RETAINER	O/S Necessary	165.80 FL	*82.90 FL
4	1		*REAR BUMPER LAMP RH	No such part	80.43 FL	*- FL
5	1		*REAR BUMPER LAMP LH	No such part	80.43 FL	*- FL
6	10		*REAR BUMPER CLIP	Necessary	50.00 FL	*50.00 FL
7	1		*REAR END PANEL	Not Necessary	513.51 FL	*- FL
8	1		*REAR END PANEL TOP GARNISH	Not Necessary	189.49 FL	*- FL
9	1		*TAILLAMP RH	Not Necessary	265.90 FL	*- FL
10	1		*TAILLAMP LH	Not Necessary	265.90 FL	*- FL
11	1		*REAR BOOTLID	Not Necessary	450.30 FL	*- FL
12	1		*REAR BOOTLID LOCK	Not Necessary	87.00 FL	*- FL
13	1		*BOOTLID EMBLEM LOGO	Not Necessary	44.87 FL	*- FL
14	1		*BOOTLID EMBLEM E	Not Necessary	30.24 FL	*- FL
15	1		*BOOTLID EMBLEM VIOS	Not Necessary	38.85 FL	*- FL
16	1		*REVERSE SENSOR	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,059.61	521.97
- List Item Discount on L Items 20.00/25.00% (S\$)	541.92	130.49
Total Parts (S\$)	2,517.69	391.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REPLACE ABOVE PARTS	New	850.00	200.00
2	TO SPRAY PAINTING ON AFFECTED AREA	New	850.00	200.00
3	TO TRANSFER BOOTLID MECHANISM	New	120.00	0.00
4	TO REMOVE AND REFIX REVERSE SENSOR SYSTEM	New	120.00	0.00
Gross Labour Cost (\$\$)			1,940.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >