

ASS. REC. BY:

REF: CS3/MSG 18000490/Wd3/2

Range

Special Instruction:

Surveyor:

Munim

ASSIGNMENT (Office)

From (Person): Catherine Thin of MNC Date/Time: 08/01/2018 @ 4:25pm

Estimated Cost:

Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJS 4650D

Insured:

SLF 7666J

at Workshop m/s

Hiap Lek Automobile

Tel:

9660 1347

of

31K14 #01-19 before B

Policy No:

80437079QMY

Claim No:

543555

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 30/12/2017

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

9:15am @ 04/01/18

Person Contacted:

Han Wei

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SJS 4650D-X
	SLF 7666J-X
	Dismantle Part: 15012018

PRS
W. Wilson

REF:

MSLH

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SJS 4650 D

at Workshop No:

Hip Lek

of:

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Vehicle:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Ball or Market Value:

JDAC Accident Report:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

days:

Res:

Yes or No

Lump Sum:

by:

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time:

Action / Instruction:

Range

\$2500

— \$3000

5 Days Repairing

RECEIVED 08 APR 2018.

Date / Time / File / Pass:

06042018

Date / Time / File / Return:

Report Format:

PRS.

Lump Sum / I.B.I.

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp. \$

☐

Inter. Ev. \$

☐

Techn. Insp. \$

☐

Free-End \$

Survey Fee:

Transaction:

1-4-18 \$

1-4-18 \$

1-4-18 \$

1-4-18 \$

120

50

10

180

Var No:

SJS 4650 D

Reg:

19/8/2009

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer:

Make:

Hyundai

cc 1591

Colour:

Silver

Insured / Std / NI / NA

Sp. Reading:

153382

Insured / Std / NI / NA

Eng No:

C.No:

KMHDC 81 DMAU 054900

Gen. Con: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt:

Steering: ☐ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt:

Brake: ☐ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt:

Mod: ☒ N / ☐ S / ☐ R / ☐ STD A / ☐ Rim:

Tyre Size:

F: 195/60R15

R: 195/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

Rear:

R.Bal:

4

mm

R.Bal:

4

mm

L.Bal:

4

mm

L.Bal:

4

mm

D.O.A:

30/2/17

D.O.A:

12/1/18

Survey held at:

At Above

Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

Right Rear

The U/C / Chassis frame / Body Structure affected due to collision

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Jan 2018		08 Jan 2018 16:25 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LIU YI, ID: S7980358H, Tel: +6591817860		
Main Claimant:	NG SWEE SIONG WILSON, ID: S7107923F		
Vehicle Reg. No.:	SJS4650D	Date of Loss:	30/12/2017 16:00 - :59
Claim Type:	TP / 543555	Policy/Cover Note No.:	80437079QMY (Comprehensive) Coverage: 17/08/2017 - 16/08/2018
Vehicle Reg. No. (Insured):	SLF7666J	Policy No. (Claimant):	
		Excess:	S\$600.00
Repairer:	Hiap Lek Automobile Trading () Bldg 14 #01-19 Sector B, Sin Ming Industrial Est, 575658 Sin Ming - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 09/01/2018]		
Driver/Custodian (Insured):	LIU YI (38 / Male), NRIC: S7980358H, Tel: +6591817860		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

MSME18000911 / SME Motor Pte Ltd - Kaki Bukit
ENTRY DATE & TIME: 02/01/2018 17:52
SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/01/2018 17:52
Date Of Accident	30/12/2017 17:45
Exact Location Of Accident	MALAYSIA CHECKPOINT TWDS SINGAPORE
Country/State of Loss	MALAYSIA/JOHOR DARUL TAKZIM

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJS4650D
Insured/Policyholder	
Name Of Registered Owner	NG SWEE SIONG WILSON
NRIC No	S7107923F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96692728
Alternative Phone No	OFFICE-96692728
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	I30
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D17MTPV01001315
Cover Note Number	
Driver	
Name of Driver	NG SWEE SIONG WILSON
NRIC No	S7107923F
Date Of Birth	06/03/1971
Occupation	INDOOR
Date Of Driving Pass	07/06/1996
Driving Experience	21 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96692728
Fax Number	
Contact Number	OFFICE-96692728
EMail Address	NOEMAIL

Address 61 UPPER SERANGOON VIEW #11-17
 Postcode 534015
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 4
 Passenger 1 NAME: : LEONG WYNN-NA ROWEENA
 GENDER: : FEMALE
 Passenger 2 NAME: : NG YEE TENG RAENEICE
 GENDER: : FEMALE
 Passenger 3 NAME: : NG JINN KHAI WILSHERE
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON THE ABOVE DATE AND TIME, I WAS DRIVING ALONG MALAYSIA TOWARDS SINGAPORE ON THE 2 LANES OF 4 LANES ROAD. SOMEWHERE BEFORE THE CHECKPOINT, VEHICLES AHEAD OF ME SLOWED DOWN AND STOPPED DUE TO HEAVY TRAFFIC FLOW. AS SUCH, I APPLIED BRAKE TO SLOW DOWN AND STOPPED. VEHICLE B (SLF7666J) THAT WAS TRAVELLING ON THE RIGHT LANE (ON MY RIGHT) SUDDENLY FILTERED TO THE LEFT WITHOUT ANY SIGNAL THUS ENCROACHING INTO MY PATH. AS A RESULT, THE LEFT PORTION OF VEHICLE B (SLF7666J) COLLIDED ONTO THE RIGHT PORTION OF MY VEHICLE.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLF7666J
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

ND(

Sketch Plan #2 Pg. 1

SKETCH PLAN

Malaysia Check Point Toward Singapore.



A-SJS 4650-1)

B-SLF 7666 J

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the above date and time, I was driving along Malaysia toward Singapore on the 2 lanes of a 4 lanes road. Somewhere before the check point, vehicle ahead of me slowed down and stopped due to heavy traffic flow.

As such, I applied brake to slowed down and stopped. Vehicle B (SLF 7666 J) that was travelling on the right lane (On my Right), suddenly filtered to the left, without any signal thus encroaching into my path. As a result, The left portion of vehicle B (SLF 7666 J) collided onto the right portion of my vehicle.

A-SJS 4650 1)

B-SLF 7666 J

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	SJS4650D
Vehicle Type :	P11 - Passenger Station Wagon/Jeep/Land Rover
Vehicle Attachment 1 :	With Sun Roof
Vehicle Scheme :	Normal
Vehicle Make :	HYUNDAI
Vehicle Model :	FD I30 CW 1.6 A
Chassis No. :	KMHDC81DMAU054966
Propellant :	Petrol
Engine No. :	G4FC9U701591
Engine Capacity :	1591 cc
Maximum Power Output :	89.7 kW (120 bhp)
Maximum Laden Weight :	1780 kg
Unladen Weight :	1360 kg
Year Of Manufacture :	2009
Original Registration Date :	19 Aug 2009
Lifespan Expiry Date :	-
COE Category :	A - Car (1600cc & below)
Quota Premium :	\$15,291.00
COE Expiry Date :	18 Aug 2019
Road Tax Expiry Date :	18 Feb 2018
PARF Eligibility Expiry Date :	18 Aug 2019
Inspection Due Date :	18 Aug 2018

Intended Transfer Date : 16 Jan 2018

CO2 Emission : -

CO Emission : -

HC Emission : -

NOx Emission : -

PM Emission : -

The current road tax expiry is 18 Feb 2018. You may renew the road tax from 19 Nov 2017 with all pre-requisite(s) fulfilled. If the road tax is renewed after 18 Feb 2018, late renewal fee(s) will be imposed. Please use [Enquire Road Tax Payable](#) to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 19 Feb 2018 to 18 Aug 2018)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	369.00	-	369.00
Total Amount Payable :			394.00

Amount Payable (From 19 Feb 2018 to 18 Feb 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	738.00	-	738.00
Total Amount Payable :			763.00

You may print this page for reference.

OK

Print

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Jan 2018		08 Jan 2018 16:25 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: LIU YI , ID: S7980358H, Tel: +6591817860									
Main Claimant: NG SWEE SIONG WILSON , ID: S7107923F									
Vehicle Reg. No.: SJS4650D		Date of Loss: 30/12/2017 16:00 - :59 [100 Months and 11 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 543555		Policy/Cover Note No.: 80437079QMY (Comprehensive) Coverage: 17/08/2017 - 16/08/2018							
Vehicle Reg. No. (Insured): SLF7666J		Policy No. (Claimant):							
		Excess: \$600.00							
Repairer: Hiap Lek Automobile Trading () Blk 14 #01-19 Sector B, Sin Ming Industrial Est, 575658 Sin Ming - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Imm.Advice due 09/01/2018]									
Driver/Custodian (Insured): LIU YI (38 / Male) , NRIC: S7980358H, Tel: +6591817860									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents























*SJS4650D (543555)
[SLF7666J]
TP
NG SWEE SIONG WILSON
Dec 30 2017 4:00PM
[LIU YI]
Hiap Lek Automobile Trading

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	08/01/18 16:20	Accident Statement From: SC - Reg. No: SLF7666J, Claimant: LIU YI	Load HTM	<input type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/04/18 18:46	General View	Load JPG	<input checked="" type="checkbox"/>
2	05/04/18 18:46	General View	Load JPG	<input checked="" type="checkbox"/>
3	05/04/18 18:46	General View	Load JPG	<input checked="" type="checkbox"/>
4	05/04/18 18:46	General View	Load JPG	<input checked="" type="checkbox"/>
5	05/04/18 18:46	General View	Load JPG	<input checked="" type="checkbox"/>
6	05/04/18 18:46	General View	Load JPG	<input checked="" type="checkbox"/>
7	05/04/18 18:46	General View	Load JPG	<input checked="" type="checkbox"/>
8	05/04/18 18:46	General View	Load JPG	<input checked="" type="checkbox"/>
9	05/04/18 18:46	General View	Load JPG	<input checked="" type="checkbox"/>
10	05/04/18 18:46	General View	Load JPG	<input checked="" type="checkbox"/>
11	05/04/18 18:46	General View	Load JPG	<input checked="" type="checkbox"/>
12	05/04/18 18:46	General View	Load JPG	<input checked="" type="checkbox"/>
13	05/04/18 18:46	General View	Load JPG	<input checked="" type="checkbox"/>
14	05/04/18 18:46	General View	Load JPG	<input checked="" type="checkbox"/>
15	05/04/18 18:46	General View	Load JPG	<input checked="" type="checkbox"/>
16	05/04/18 18:46	General View	Load JPG	<input checked="" type="checkbox"/>
17	05/04/18 18:46	General View	Load JPG	<input checked="" type="checkbox"/>
18	05/04/18 18:46	General View	Load JPG	<input checked="" type="checkbox"/>
19	05/04/18 18:46	General View	Load JPG	<input checked="" type="checkbox"/>
20	05/04/18 18:46	General View	Load JPG	<input checked="" type="checkbox"/>
21	05/04/18 18:46	General View	Load JPG	<input checked="" type="checkbox"/>
22	05/04/18 18:46	General View	Load JPG	<input checked="" type="checkbox"/>
23	05/04/18 18:46	General View	Load JPG	<input checked="" type="checkbox"/>
24	05/04/18 18:46	General View	Load JPG	<input checked="" type="checkbox"/>
25	05/04/18 18:46	General View	Load JPG	<input checked="" type="checkbox"/>
26	05/04/18 18:46	General View	Load JPG	<input checked="" type="checkbox"/>
27	05/04/18 18:46	General View	Load JPG	<input checked="" type="checkbox"/>
28	05/04/18 18:46	General View	Load JPG	<input checked="" type="checkbox"/>
29	05/04/18 18:46	General View	Load JPG	<input checked="" type="checkbox"/>
30	05/04/18 18:46	General View	Load JPG	<input checked="" type="checkbox"/>
31	05/04/18 18:46	General View	Load JPG	<input checked="" type="checkbox"/>
32	05/04/18 18:46	General View	Load JPG	<input checked="" type="checkbox"/>
33	05/04/18 18:46	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	08/01/18 16:19	TPD SJS4650D GIA REPORT	 Load PDF	
2	08/01/18 16:19	Pre-Repair Survey	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18000490/WD3E2

Date: 09/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 80437079QMY

Claimant Vehicle No : SJS4650D

Insured Vehicle No : SLF7666J

Date of Loss: 30/12/2017

Nature of Claim: TP

Claim No: 543555

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJS4650D

Make & Model: HYUNDAI I30, 1.6 FD CW (A)

Engine No: G4FC9U701591

Reg. Date: 19/08/2009 (Man. Year: 2009)

Chassis No: KMHDC81DMAU054966

Colour: Silver

Odometer: 153382 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 08/01/2018

Date Inspected: 12/01/2018 Inspected At:

Hiap Lek Automobile Trading
Blk 14 #01-19 Sector B, Sin Ming Industrial
Est
Singapore 575658

Estimated Period of Repair: 0.0 days

Adjuster: Teo Cheng Ming Wilson

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500.00 - \$3,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 09 Apr 2018)

Parts: 143 HYUNDAI I30 1.6 FD CW (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJS4650D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >