Estimated Cost			II (Office) ISIG Bill to:	Date/Time: 08 01	2018 @ 4.28 pm
To Inspect Vel at Workshop n	TEPRESTOD RESTEV Sicle No: FBK 64 He Xin Kaki Bkt Rd 4	56 Y Motor		Insured: S12 89	66 <i>E</i> 25
	70149108MP	11 01 13	Claim No: Excess:	545038	
Make of Veh. (Client's Record CA / REV Date/Time: ¶		WP) Person Contacted: _	Screne	D.O.A. 30/12 H.O.D. Endorseme Vehicle OUT	51 5 0
Date/Time	Action/Instruction () FBK 6456 V -				

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Authred	Status		
Main	08 Jan 2018		08 Jan 2018 16:28 Assign				New Assigna Cancel Case		
	Main	Re	ference	Cla	im Details	Docume	nts	Show All	
CLAIM S	UBFOLDER DET	TAILS				[Created by	y insurer]		
Insured:		WU LI YUN,	ID: S2744312E						
Main Clai	imant:	MUHD AZWA	NDY BIN ARJUNA	H, ID: S900	06037F				
Vehicle F	Reg. No.:	FBK6456Y		D	ate of Loss:	30/12/2017	17:00 - :59		
Claim Type:		TP			olicy/Cover Note No		27014910SMP (Comprehensive) Coverage: 30/11/2017 - 29/11/201		
Vehicle Reg. No. (Insured):		S3Z8966E			olicy No. (Claimant)):			
(anounce	,.				ccess:	\$\$1,000.00			
Repairer		Tel:			4 #01-75 SYNERGY				
Handling	Insurer:	2545]) - Tel: +65 6827 78			a Shi Yi - 659	
Adjuster	:	LKK Auto Cor	sultants Pte Ltd	(HQ) - Tel: 6	256-3561 [Imm.	Advice due 09/	01/2018]		
ASSOCI	ATED MAIL REC	CEIVED				View A	II Compo	se Case Mail	
There are	no mail for this	case.							
Е								770	
ALL ASS	OCIATED TASE						ate New Task	Complete	
Due Da		Type Task (Group Subjec	t Handler	Assigned By	Completed On	Created	On Done	
No results	S								

RIAZ

REG/CS/PAY/FA 0 B JAN 2018

ADVOCATES AND SOLICITORS

ACRA NUMBER : 200911678H

GST REGISTRATION NUMBER : 200911678H

8/01/2018

Our Ref: FBK 6456Y (V) HE XIN

Your Ref: SJZ 8966E

TO:

MSIG Insurance (Singapore) Pte Ltd

16 Raffles Quay

#24-01 Hong Leong Building

Singapore 048581

Attn: Motor Claims Department

RIAZ QAYYUM (LLB HONSI NUS

TAN KOK SIANG ILLE HONSI LON

IASSOCIATEI

ABOUL HALIM BIN ROSALAN (LLB HONS) UTAS

BY FAX ONLY (6225-7402)

NOTICE OF ACCIDENT

Dear Sir

We are instructed by our client to notify you of a road traffic accident on 30 December 2017 at about 1710 hours along Pasir Ris Dr 6 involving our client's vehicle registration number FBK 6456Y and vehicle registration number SJZ 8966E driven by you or your authorized driver at the material time. A copy of Singapore accident statement / traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client/ we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client /we shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Name of workshop

HE XIN MOTOR

Address

25 Kaki Bukit Road 4

#01-75 Synergy @ KB

Singapore 417800

Telephone no.

9060 3128 (Ah Keong)

9487 7625 (Serene)

Please let us hear from you by the stipulated time.

Yours faithfully

Riaz

encs

cc 1. Client

FOR SURVEYOR

Please initial here after completion of prerepair inspection. Thank you.

Appointed surveyor (Name & signature)

Date & time of inspection

133 NEW BRIDGE ROAD #09-09 CHINATOWN POINT SINGAPORE 059413
TEL: 65340110 FAX: 65340220 EMAIL: RIAZ@JUSTICE.COM.SG
(PLEASE NOTE THAT OUR FAX IS NOT FOR SERVICE OF COURT DOCUMENTS)

WWW.INJURYCLAIMS.SG



IdVA318001756 / VAC - Kaki Bukit ENTRY DATE & TIME: 04/01/2018 09:38 SUBMITTED BY: SITI FADHLON BTE ABDUL KADER

Your NCD will be affected due to late reporting Actual e-Filling Submission Date & Time: 04/01/2018 09:48

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GiA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

ACCIDIENT	CAL STATE OF THE S
04/01/2018	09:38

ACCIDENT STATEMENT

Date Of Report 30/12/2017 17:10 Date Of Accident

PASIR RIS DRIVE 6 Exact Location Of Accident

SINGAPORE Country/State of Loss

DETAILS OF OWN VEHICLE

FBK6456Y Vehicle Registration Number

Insured/Policyholder

MUHD AZWANDY BIN ARJUNAH Name Of Registered Owner

S9006037F NRIC No NOEMAIL Email Address

(LOCAL) +65-90088421 Mobile Phone No

OTHERS 0008942 Memative Phone No

Vehicle Particulars

Manufacturer AGASH AGA

CBR600RR Model

Exact Purpose for which vehicle was being used at PRIVATE USE

time of accident Are you claiming under your own insurance policy

NO for repair to your vehicle?

THIRD PARTY If No. Please state action to be taken

MOTORCYCLE Vehicle Category

Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD Name of Insurance Company

THIRD PARTY FIRE AND/OR THEFT Type Of Coverage

NO Fleet Policy

5076198256-02 Policy Number

Cover Note Number

Driver

MUHD AZWANDY BIN ARJUNAH Name of Driver

S9006037F NRIC No 27/02/1990 Date Of Birth INDOOR Occupation 03/08/2011 Date Of Driving Pass

6 YEARS AND 4 MONTHS Driving Experience

MALE Gender

(LOCAL) +65-90088421 Mobile Number

Fax Number

OTHERS-90088421 Contact Number

NOFMAIL EMail Address

Address

BLK 105 #04-205 LORONG 1 TOA PAYOH

Postcode

310105

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLIDED INTO PARKED VEHICLE

Weather Conditions

CLEAR

Road Surface

DRY.

Other Information

was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

0

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

PASIR RIS NEIGHBOURHOOD POLICE CENTRE

Police Station Address

ROAD: 1 PASIR RIS DRIVE 4, POSTCODE: 519457, COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: 1800-5852999 - FAX NO: 65855261

Was notice of intended Prosecution given?

If Yes, against whom?

NO

Circumstances of Accident

AS PER POLICE REPORT No.T/20171230/2121

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SJZ8966E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

0 4 JAN 2010


Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder) Date & Time: IDAC KAKI BUKIT (VAC)

23 KAKI BUKIT AVE 4

Reporting SHITT BY SIGNATURE
Name: Tel: 67416697

NRIC/FIN NGIXX: 67492305

Email: vackb@singnet.com.sg



Accident Sketch Plan Pg. 1





T/20171230/2121

1 of 3 Report No. T/20171230/2121

Police Station Of Origin: Pasir Ris N.P.C 1 Pasir Ris Drive 4 #01-01 SINGAPORE 519457

Tel No: 1800-5852999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 30/12/2017 19:14		lade:	Vide Report No.: G/20171230/0178	Station Diary No.: 101		
Informa	nt's Partice	ulars				
Name of Informant: MUHAMMAD AZWANDY BIN ARJUNAH			Address: APT BLK 105 LORONG 1 TOA PAYOH #04-205 SINGAPOR 310105			
ID Type / ID No.: NRIC NO / S9006037F		37F	Contact No.: Home/Office:	Mobile: 90088421		
National SINGAP	ity: ORE CITIZ	EN	Email:			
Sex: Male	Age: 27	Date of Birth: 27/02/1990	Type of Informant: Vehicle Owner			
Race: Malay			Language: English	Institution / School Name:		
	Occupation: LOGISTICS OFFICER		Driving Licence Information: Class:	Date of Expiry:		

General Infor	mation of the Accider	it		
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 30/12/2017 17:10	Type of Location: Car Park
Location: Along Road 1 PASIR RIS D BLK 417 PAS				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way			477	Traffic Volume: Light
Type of Collis Moving Vehic	sion: de Against - Parked Ve	hicle		Anyone conveyed by ambulance: No

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenge
FBK6456Y	Motorcycle	HONDA	CBR600RR	Orange	Slightly Damaged	0
SJ Z89 66E	Car					0

Details of V	ehicle Insurance			100000000000000000000000000000000000000
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBK6456Y	NTUC Income Insurance Co-Operative Limited	5076198256-02	03/12/2017	02/12/2018





Police Station Of Origin: Pasir Ris N.P.C 1 Pasir Ris Drive 4 #01-01 SINGAPORE 519457 Tel No: 1800-5852999

2 or 3 Report No. T/20171230/2121

CONTINUATION OF REPORT

,

Details of Perso	n involved	2/16/16/19		NO ME	97.SE.10	
Any Pedestrian II	nvolved: No					The Tally In the Indian
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA			
Vehicle Owner					THE STATE OF	
Name	MUHAMMAD AZWANDY BIN ARJUNAH		ID No		S9006037F	
Related Vehicle	FBK6456Y (Motorcycle)			Conta	ct No.	90088421
Hospital/Clinic	NIL			Class Drivin Licend Expiry	g	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Dis		NIL	
No. of Days gran	ted Medical Leave	NIL	Degree o			

Brief Details

Today, 30/12/2017 at about 1710hours, I parked an secured my motorcycle bearing the registration number, FBK6456Y, at the open spaced carpark near to Blk 417 Pasir Ris Drive 6, in between car parking lots 373 and 373, near a grass patch. Everything was normal and intact.

At about 1720hours, I came back to my motorcycle and discovered it had fallen on the right side on the motorcycle, onto the grass patch. While I was picking my motorcycle, a person came up to me and he informed me that his mother witnessed, a BMW rose gold in color, modelled 740i, bearing the registration number, SJZ8966E had collided onto my vehicle and drove off without leaving a note. I then called Traffic Police for assistance.

A Traffic Police officer came down and gave me incident number G/20171230/0178.

I did not take down the particulars of the person who came down but I did leave a note on their vehicle to contact me. I also did noticed that there was a vehicle which parked directly opposite my vehicle but I am not sure if the car had an in-vehicle camera installed. No is injured.

The damages to my vehicle side faring, leg brake was slanted, engine oil was leaking from the engine. However, my motorcycle is still working.





T/20171230/2121

3 of 3 Report No. T/20171230/2121

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Re G / Sgt 2 MUHAMMAD ALIF BIN AZALI	port:	Signature Of Informant:	and any
Signature Of Interpreter: Not applicable	D	Date/Time: 30/12/2017 19:14	*
Officer In Charge Of Case: TP / HRT /		Classification Of Case:	•
Sr Staff Sgt LIM WOON TIONG Contact No.: 65476418	(B) SI	NGAPORE DLICE FORCE	
Authentication Stamp NP168		(X)	

...CLAIM SUBFOLDER...(Pending for Survey Report)

	Notified	Est Submitted	Adj Assigned	Adj Rpt	Ad1	Submitted	Ins Auth'ed	Stat	tus	
Case	08 Jan 2018	Est Submitted	08 Jan 2018 16:28 Edit Adj Rpt	S\$0.00 Edit Estimates	5\$0			Pending for Surve Report Cancel Case		Survey
	Main	R	eference	Claim I	etails		Document	ts	1_	Show All
CLAIM S	UBFOLDER D	ETAILS				[Created	by insurer]			
Insured:	WU LI YU	IN, ID: S274431	2E							
Main Claimant:	MUHD AZ	MUHD AZWANDY BIN ARJUNAH, ID: S9006037F								
Vehicle Re	FBK645	6Y		Date	of Loss:	30/12/2017 17:00 - :59 [24 Months and 29 Days From LTA Reg Date (Man Y			Man Yr)]	
Claim Typ	e: TP / 545	Policy/Cover 27014910SMP (Comprehensive) TP / 545038 Policy/Cover 27014910SMP (Comprehensive) Coverage: 30/11/2017 - 29/11/2018					3			
Vehicle Ro No. (Insured)	SJZ8966	E		Polic (Clair	No. nant):					
(msureu)				Exce	is:	S\$1,000.0	0			
Repairer:	He Xin M	otor (HQ) BLK 25	KAKI BUKIT ROAD	4 #01-75 SYNER	SY@KB S	SINGAPORE	417800, 417800	Kaki Buk	it - Tel:	
Handling Insurer:	MSIG In	surance (Singap	ore) Pte. Ltd. (HQ) - Tel: +65 6827	7888	[Handled by	Catherine Thia	Shi Yi -	6594 254	
Adjuster:	09/01/2		e Ltd (HQ) - Tel: 6	256-3561 [Han	iled by 1	reo Cheng I	Ming Wilson]	[Imm.	Advice	iue
ASSOCI	ATED MAIL R	ECEIVED						/iew All	Compos	e Case Ma
There are	no mail for thi	s case.								
ALL ASS	SOCIATED TA	sks⊟				View All	Search Tasks	Create N	ew Task	Comple
Due Da		y Type Tas	k Group Subje	ct Handler	Assig	ned By	Completed Or	ı C	reated Or	Don

Claim Documents

*FBK6456Y (545038)
[SJZ8966E]
TP
MUHD AZWANDY BIN ARJUNAH
Dec 30 2017 5:00PM
[WU LI YUN]
He Xin Motor

Pho	tos/Images		3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbna	il Print
1	06/04/18 17:11	Odometer Reading	1 Load JPG	V
2	06/04/18 17:11	General View	1 Load JPG	▼
3	06/04/18 17:11	General View	1 Load JPG	V
4	06/04/18 17:11	General View	■ Load JPG	V
5	06/04/18 17:11	General View	1 Load JPG	V
6	06/04/18 17:11	General View	Load JPG	V
7	06/04/18 17:11	General View	1 Load JPG	~
8	06/04/18 17:11	General View	1 Load JPG	<u>V</u>
9	06/04/18 17:11	General View	1 Load JPG	
10	06/04/18 17:11	General View	1 Load JPG	Y
11	06/04/18 17:11	General View	6 Load JPG	V
12	06/04/18 17:11	General View	■ Load JPG	∀
13	06/04/18 17:11	General View	1 Load JPG	V
14	06/04/18 17:11	General View	1 Load JPG	· 🗸
15	06/04/18 17:11	General View	1 Load JPG	
16	06/04/18 17:11	General View	Load JPG	
17	06/04/18 17:11	General View	■ Load JPG	
18	06/04/18 17:11	General View	■ Load JPG	· 🗹
19	06/04/18 17:11	General View	■ Load JPG	
20	06/04/18 17:11	General View	1 Load JPG	V
21	06/04/18 17:11	General View	1 Load JPC	· 🗸
22	06/04/18 17:11	General View	1 Load JPC	V
23	06/04/18 17:11	General View	1 Load JPC	· 🗸
24	06/04/18 17:11	General View	■ Load JPC	3 V
25	06/04/18 17:11	General View	€ Load JPC	V
26	06/04/18 17:11	General View	■ Load 3PC	3 🗸
27	06/04/18 17:11	General View	€ Load 3PC	y
28	06/04/18 17:11	General View	Load JPC	3 2
29	06/04/18 17:11	General View	■ Load JPC	3 🗸
30	06/04/18 17:11	General View	1 Load JPC	3 V
31	06/04/18 17:11	General View	■ Load JPC	3 V
32	06/04/18 17:11	General View	1 Load JPC	3 4
33	06/04/18 17:11	General View	■ Load JPC	G 🗸
34	06/04/18 17:11	General View	1 Load JPG	G 🔽
35	06/04/18 17:11	General View	1 Load JPG	G 🔽
36	06/04/18 17:11	General View	■ Load JPC	G 🗸
37	06/04/18 17:11	General View	1 Load JPC	G 🔽

Pho	otos/Images		3 per page 🗸	V
No.	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnai	-
38	06/04/18 17:11	General View	1 Load JPG	V
39	06/04/18 17:11	General View	♠ Load JPG	V
10	06/04/18 17:11	General View	Load JPG	V
1	06/04/18 17:11	General View	♠ Load JPG	~
12	06/04/18 17:11	General View	1 Load JPG	V
13	06/04/18 17:11	General View	1 Load JPG	V
14	06/04/18 17:11	General View	■ Load JPG	V
45	06/04/18 17:11	General View	1 Load JPG	V
16	06/04/18 17:11	General View	● Load JPG	V
17	06/04/18 17:20	Dismantled Parts	1 Load JPG	V
18	06/04/18 17:20	Dismantled Parts	■ Load JPG	~
49	06/04/18 17:20	Dismantled Parts	■ Load JPG	printer
50	06/04/18 17:20	Dismantled Parts	Load JPG	~
51	06/04/18 17:20	Dismantled Parts	■ Load JPG	-
52	06/04/18 17:20	Dismantled Parts	■ Load JPG	- Contract
53	06/04/18 17:20	Dismantled Parts	Load 3PG	-
54	06/04/18 17:20	Dismantled Parts	■ Load JPG	-
55	06/04/18 17:20	Dismantled Parts	1 Load JPG	-
56	06/04/18 17:20	Dismantled Parts	Load JPG	-
57	06/04/18 17:20	Dismantled Parts	1 Load JPG	
58	06/04/18 17:20	Dismantled Parts	1 Load JPG	-
		Dismantled Parts	1 Load JPG	1
59	06/04/18 17:20	Dismantled Parts	■ Load JPG	-
60	06/04/18 17:20		1 Load JPG	prints
61	06/04/18 17:20	Dismantled Parts		-
62	06/04/18 17:20	Dismantled Parts	1 Load JPG	-
63	06/04/18 17:20	Dismantled Parts	Load JPG Load JPG	
64	06/04/18 17:20	Dismantled Parts		-
65	06/04/18 17:20	Dismantled Parts	Load JPG Load JPG Load JPG	-
66	06/04/18 17:20	Dismantled Parts		_
67	06/04/18 17:20	Dismantled Parts	1 Load JPG	_
68	06/04/18 17:20	Dismantled Parts	1 Load JPG	-
69	06/04/18 17:20	Dismantled Parts	1 Load JPG	-
70	06/04/18 17:20	Dismantled Parts	1 Load JPG	
71	06/04/18 17:20	Dismantled Parts	1 Load JPG	-
72	06/04/18 17:20	Dismantled Parts	1 Load JPG	-
73	06/04/18 17:20	Dismantled Parts	1 Load JPG	-
74	06/04/18 17:20	Dismantled Parts	1 Load JPG	-
75	06/04/18 17:20	Dismantled Parts	1 Load JPG	
76	06/04/18 17:20	Dismantled Parts	■ Load JPG	-
77	06/04/18 17:20	Dismantled Parts	1 Load JPG	-
78	06/04/18 17:20	Dismantled Parts	1 Load JPG	
79	06/04/18 17:20	Dismantled Parts	1 Load JPG	-
80	06/04/18 17:20	Dismantled Parts	1 Load JPG	
81	06/04/18 17:20	Dismantled Parts	1 Load JPG	-
82	06/04/18 17:20	Dismantled Parts	1 Load JPG	4
83	06/04/18 17:20	Dismantled Parts	1 Load JPG	_
84	06/04/18 17:20	Dismantled Parts	1 Load JPG	V
85	06/04/18 17:20	Dismantled Parts	■ Load JPG	V
86	06/04/18 17:20	Dismantled Parts	1 Load JPG	~
87	06/04/18 17:20	Dismantled Parts	■ Load JPG	4

Photos/Images			3 per p	3 per page 💟	
/ I I I I I I I I I I I I I I I I I I I			Thumbnail		
No 88	Relabel/Reorder 06/04/18 17:20	Dismantled Parts	0	Load JPG	~
		Dismantled Parts	O	Load JPG	~
89	06/04/18 17:20	Dismantled Parts	0	Load JPG	V
90	06/04/18 17:20		0	Load JPG	V
91	06/04/18 17:20	Dismantled Parts	0	Load JPG	V
92	06/04/18 17:20	Dismantled Parts	0	Load JPG	-
93	06/04/18 17:20	Dismantled Parts			
94	06/04/18 17:20	Dismantled Parts	0	Load JPG	
95	06/04/18 17:20	Dismantled Parts	0	Load JPG	
96	06/04/18 17:20	Dismantled Parts	0	Load JPG	-
97	06/04/18 17:20	Dismantled Parts	0	Load JPG	-
98	06/04/18 17:20	Dismantled Parts	0	Load JPG	-
99	06/04/18 17:20	Dismantled Parts	0	Load JPG	-
100	06/04/18 17:20	Dismantled Parts	0	Load JPG	400
101	06/04/18 17:20	Dismantled Parts	0	_	7.17
102	06/04/18 17:20	Dismantled Parts	0	Load JPC	
103		Dismantled Parts	0	Load JPC	V
Des	cumentation		1 per	page 🕒	
	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbna	il Prin
No 1	08/01/18 15:47	PRI	0		-
2	08/01/18 16:28	EMAIL to TP reject their list of SJE	0	Load PD	F.

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/MSG18000495/R1D3

Date:

15/05/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

27014910SMP

Claimant Vehicle

FBK6456Y

Insured Vehicle No:

SJZ8966E

No: Date of Loss:

30/12/2017

Nature of Claim:

TP

Claim No: 545038

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

FBK6456Y

Make & Model:

HONDA CBR600RR, 599cc 01/12/2015 (Man. Year: 2015) Engine No: Chassis No: Odometer:

PC40E2409503

31124 km

JH2PC40C2DK601421

Reg. Date: Colour:

Multi-colour

Engine Capacity: Market Value/New Car Price: N/A

599 cc

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Footbrake (Serviceable): Pre-accident Condition:

Yes

Diff %

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size:

120/70Z R17

Rear Tyre Size:

180/55Z R17 Metzeler 4 mm

Front Left Side:

Metzeler 4 mm

Rear Left Side:

Front Right Side: The above values represent the remaining tyre treads depth

0 mm

Rear Right Side:

0 mm

Difference Adjuster's Repairer's COST OF CLAIMS 0.00 0.00 0.00 Parts 0.00 0.00

Nett Amount (S\$)	0.00	0.00	0.00
Towing	0.00	0.00	
Paintwork Labour		0.00	0.00
Paintwork Labour	0.00	0.00	0.00
Labour	0.00	0.00	0.00
Miscellaneous Items			0.00
t di II It aman	0.00	0.00	0.00

INSPECTION

Date of Assignment:

08/01/2018

Date Inspected:

09/01/2018 Inspected At:

He Xin Motor (HQ)

BLK 25 KAKI BUKIT ROAD 4 #01-75 SYNERGY@KB SINGAPORE 417800

Singapore 417800

Estimated Period of Repair:

0.0 days

Teo Cheng Ming Wilson Adjuster:

Manager:

Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,500.00 -\$5,500.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 15 May 2018)

Parts: N/A HONDA CBR600RR 599cc (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBK6456Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >