

ASS. REC. BY:

REF: CS/GAI18000499/T1vd3<sup>n2</sup>

Special Instruction:

Surveyor: Tan Kah

ASSIGNMENT (Office)

From (Person): Kelyvna

of GAI.

Date/Time: 6.35pm @ 08/01/2018

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLF 2509M

Insured:

FBL 5089A

at Workshop m/s

Cycle &amp; Camry

Tel:

6568 4501

of

209 Pandan Gardens

Policy No:

Claim No:

CLMOMVM000000151

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/12/2017

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time: 9.10am @ 09/01/2018

Person Contacted:

Mr. Tay

Vehicle ☒ IN ☒ OUT

Date/Time

Action/Instruction ( ☒ ) Estimate

SLF 2509M - X

FBL 5089A - X

11/1/18 Email preli revised to Kelyvna

16/5/18 Final fig \$ 5972 (Red 3585, 3512) confirmed by email

Est. Repairs:

days

Res.: Yes or No

D.O.A.

D.O.I.

9/1/18 @ 1730

Lum Sum:

%

3 Val: Yes or No

Survey held at

C&amp;C Pandan Gdn. 18

CA / REV / REP. / 24 HRS 'wp'

Vehicle IN/OUT

Date:

Person Contacted

Jai Ye.

The UIC / Chassis frame / Body Structure affected due to collision

Date/Time

Action/Instruction

RECEIVED 17 MAY 2018

Date/Time File Pass to:

☐ : Preli. Report  
☐ : Final Report

Days Of Repair:

9

Resurvey No. of Trip:

1

Date/Time File Return to:

Survey Fee

Transportation

100-100

Amount

Line

16/5- typist

Add Fee:

Sta Insc 18

1800 6

Tech 18 6

1800 6

Report Format:

TP

Lum Sum / LB 18

P/P \$ 5972 1/2