

Surveyor

Wilson

ASSIGNMENT (Office)

From (Person):

Clara Li

of

FWD

Date/Time:

08/01/2018 @ 5:59pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGZ2647B

Insured:

SLH 623T

at Workshop m/s

EM Solution

Tel:

64560226

of

160 Sin Ming Drive # 03-15/19

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

07/01/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:01am @ 09/01/18

Person Contacted:

Nicole

Vehicle IN/OUT

Date/Time	Action/Instruction	
	(4) Estimate	
	SGZ 2647B - CS/AXA08024770/U621	D.O.A: 28/08/2018
	SLH 623T - X	
	After repair: 12/1/2018	
	Dismantle: 9/1/2018	

Surveyor PRS
Wilson

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD/TP/WS/TP RES/OD RES/EVA/INV/MV
To inspect Vehicle No. SGZ 2647 B
at Workshop mis _____
of _____
Insured _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

4	
N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction -

Range -> \$2000 - \$2400

3 Days

6/4/2018

RECEIVED 12 APR 2018

Veh No SGZ 2647 B Yr Regn 24/10/2007
Type M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make Honda Accord cc 1998
Colour white AC Insured / Std / NI / NA
Sp. Reading 414639 T Radio: Insured / Std / NI / NA
Eng No _____
C/No CL7-3303280
Gen. Cond Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size F: 225/45 ZR17
R: 225/45 ZR17
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Michellin
Front _____ Rear _____
R/Bal 3 mm R/Bal 2 mm
L/Bal 3 mm L/Bal 2 mm
D.O.A. _____ DOI 9/1/2018
Survey held at As Above
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Right Front Side
The U/C / Chassis frame / Body Structure affected due to collision

Date/Time File Pass to:

☐ : Preli. Report

Days Of Repair: 3

1

☐ : Final Report

Resurvey No. of Trip:

Date/Time File Return to:

Survey Fee

Transportation

2

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Insp (\$

☐ Weekend (\$

1 - S - RS - S

Phone

Smart

Report Format: PRE-

Lump Sum / I.B.I: (\$

TOTAL

Catherine Chong (LKK Auto)

From: clara.li@fwd.com
Sent: Monday, 8 January, 2018 5:59 PM
To: assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com
Cc: motorclaims.sg@fwd.com
Subject: FW: OUR REF.: E21-MISC.18 (SGZ 2647B @ 07/01/2018) // FWD REF.: SLH 623T
Importance: High

Hi LKK team,

Please refer to the email below and liaise with TP repairer for PRS.

Please create the case in Merimen.

Thank you.

Kind Regards

Clara Li
Senior Executive, Claims

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722
E clara.li@fwd.com
W fwd.com.sg



	Endowment Plan Get the biggest guaranteed return for a 3 year plan available online. Limited time offer!		2.02% p.a. fwd.com.sg save now
--	--	--	---

From: Sally Chong [mailto:sallychong@visionlawllc.com]
Sent: Monday, 8 January, 2018 5:52 PM
To: Clara Li Zirong - SGUser
Cc: Motor Claims SG - SG Common; EM Solution Pte Ltd; 'Judy Soh'
Subject: RE: OUR REF.: E21-MISC.18 (SGZ 2647B @ 07/01/2018) // FWD REF.: SLH 623T
Importance: High

VERY URGENT

Dear Clara,

NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

CLAIMANT: ALFIE SIM KAI LENG

ACCIDENT INVOLVING SGZ 2647B & SLH 623T ON 7 JAN 2018 AT RAFFLES CITY CARPARK AT ABOUT 11:50 HRS

We refer to your email of even date below.

TAKE NOTICE that we object to your surveyor stated in your said List, for appointment as the Single Joint Expert.

Pursuant to Pre-Action Protocol for NIMA cases, we now propose for appointment as Single Joint Expert the following List of Motor Surveyors for your consideration:-

<u>Name of Surveyor</u>	<u>Company Name</u>
Dennis Yap	Pal's Appraiser Pte Ltd
Michael Yap	Mc-coy Appraiser Pte Ltd
Andy Yap	LCW Appraiser Pte Ltd
B J Loi	Par Automotive Consultancy
Sebastian Lim	Constant Appraiser Services
Lee Yew Hok	Constant Appraiser Services
Alan Cheong	CL Appraiser Pte Ltd
Jason Lek	JP Knights
Tay Beng Hee	Autoprobe Consultants
Samuel Phun	Autoprobe Consultants

Please be informed that the said vehicle can be inspected at:-

Venue : **E M SOLUTION PTE LTD**
160, Sin Ming Drive, #03-18/19, Sin Ming Autocity,
Singapore 575722
Contact : Mr. Bernard (Tel.: 6456-0226 / 9101-8302)

If you fail to conduct the pre-repair inspection within the next 2 working days, the said workshop will commence repairs thereafter without further reference to you.

Thank you.

Sally Chong

(Secretary)

VISION LAW LLC
133 NEW BRIDGE ROAD,
#18-01/02, CHINATOWN POINT,
SINGAPORE 059413
TEL.: 6534-2811 (ext 115)
FAX : 6535-6802

From: clara.li@fwd.com [<mailto:clara.li@fwd.com>]

Sent: Monday, 8 January, 2018 5:00 PM

To: sallychong@visionlawllc.com

Cc: motorclaims.sg@fwd.com

Subject: RE: OUR REF.: E21-MISC.18 (SGZ 2647B @ 07/01/2018) // FWD REF.: SLH 623T

WITHOUT PREJUDICE

Dear Sally,

We refer to your letter dated 08 January 2018 of the PRI Notice of your client's vehicle SGZ2647B.

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. Appraisals Associates Pte Ltd
5. VICOM Ltd

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

Kind Regards

Clara Li

Senior Executive, Claims

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722

E clara.li@fwd.com

W fwd.com.sg





Endowment Plan

Get the biggest guaranteed return for a 3 year plan available online.

Limited time offer!



2.02% p.a.

fwd.com.sg

save now

From: Sally Chong [<mailto:sallychong@visionlawllc.com>]

Sent: Monday, 8 January, 2018 4:31 PM

To: Clara Li Zirong - SGUser

Subject: FW: OUR REF.: E21-MISC.18 (SGZ 2647B @ 07/01/2018) // FWD REF.: SLH 623T

From: Sally Chong [<mailto:sallychong@visionlawllc.com>]

Sent: Monday, 8 January, 2018 4:27 PM

To: 'contact.sg@fwd.com'

Cc: EM Solution Pte Ltd (emautosolution@singnet.com.sg); 'Judy Soh'

Subject: OUR REF.: E21-MISC.18 (SGZ 2647B @ 07/01/2018) // FWD REF.: SLH 623T

URGENT

Dear Sir,

NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

CLAIMANT: ALFIE SIM KAI LENG

ACCIDENT INVOLVING SGZ 2647B & SLH 623T ON 7 JAN 2018 AT RAFFLES CITY CARPARK AT ABOUT 11:50 HRS

We are instructed by ALFIE SIM KAI LENG to notify you of a road traffic accident on 7 JAN 2018 at about AT RAFFLES CITY CARPARK AT ABOUT 11:50 HRS involving our client's vehicle registration number SGZ 2647B and vehicle registration number SLH 623T driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Thank you.

Sally Chong

(Secretary)

VISION LAW LLC

133 NEW BRIDGE ROAD,

#18-01/02, CHINATOWN POINT,

SINGAPORE 059413

TEL.: 6534-2811 (ext 115)

FAX : 6535-6802

C.c. VEHICLE OWNER OF SLH 623T

LEE WEIKANG

114, Punggol Walk,

#07-32,

Singapore 828767

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email

by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email

by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any

person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email

transmission or any illegal or unauthorised usage or tampering of its email system.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/01/2018 18:00
Date Of Accident	07/01/2018 11:50
Exact Location Of Accident	RAFFLES CITY CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGZ2647B
Insured/Policyholder	
Name Of Registered Owner	SIM KAI LENG ALFIE
NRIC No	S7517002E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90681251
Alternative Phone No	OTHERS-90681251

Vehicle Particulars

Manufacturer	HONDA
Model	ACCORD
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 29039181 QMX
Cover Note Number	

Driver

Name of Driver	SIM KAI LENG ALFIE
NRIC No	S7517002E
Date Of Birth	05/06/1975
Occupation	OUTDOOR
Date Of Driving Pass	04/01/2001
Driving Experience	17 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90681251
Fax Number	
Contact Number	OTHERS-90681251
Email Address	NOEMAIL

Address	BLK 203B PUNGGOL FIELD #09-328
Postcode	822203
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : LIN YU TING GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLH623T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIM CHEOW HUI
NRIC/Passport Number	S8412559H
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 7/1/2018 at about 11.50 AM I was driving my vehicle - SGZ 2647 B at Raffles City Carpark. While I was leaving the carpark going down the ramp of the carpark, a vehicle - SLH 623 T from the right side of the carpark never stop her vehicle at the stop line and collided onto the right side of my vehicle. I was at the right way of traffic and it was the driver of SLH 623 T never stop her vehicle and drove out and collided onto my vehicle - SGZ 2647 B. She wanted to have a private settlement but at last she couldn't afford for the repair-cost and advised me to lodge a Third Party Claim against her insurance.

I have proof of evidence from her Text messages sent to me for our negotiation for private settlement.

Name of Passenger: LIN YU TING
I/C NO: G6690882P
Relationship: WIFE

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Constable Personnel's Signature
Name:
NRIC/FIN No.:

Accident Photo



Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	SGZ2647B
Vehicle Type :	P10 - Passenger Motor Car
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	HONDA
Vehicle Model :	ACCORD 2.0 A
Chassis No. :	CL73303280
Propellant :	Petrol
Engine No. :	K20A6053816
Engine Capacity :	1998 cc
Maximum Power Output :	114.0 kW (152 bhp)
Maximum Laden Weight :	1645 kg
Unladen Weight :	1370 kg
Year Of Manufacture :	2007
Original Registration Date :	24 Oct 2007
Lifespan Expiry Date :	-
COE Category :	E - Open Category
PQP Paid :	\$25,226.00
COE Expiry Date :	23 Oct 2022
Road Tax Expiry Date :	23 Apr 2018
Inspection Due Date :	23 Oct 2018
Intended Transfer Date :	10 Jan 2018
CO2 Emission :	-

CO Emission : -

HC Emission : -

NOx Emission : -

PM Emission : -

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use [Enquire Road Tax Payable](#) for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

You may print this page for reference.

OK

Print

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Apr 2018 Edit Reg		08 Jan 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Lee Weikang, ID: S8220844E		
Main Claimant:	SIM KAI LENG ALFIE, ID: S7517002E		
Vehicle Reg. No.:	SGZ2647B	Date of Loss:	07/01/2018 00:00 - :59 [122 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1201800000601	Policy/Cover Note No.:	PNPV2017-00007999 (Comprehensive)
Vehicle Reg. No. (Insured):	SLH623T	Policy No. (Claimant):	
		Excess:	
Repairer:	Em Solution Pte Ltd (160 Sin Ming) (HQ) 160 Sin Ming Drive, #03-19 Sin Ming Autocity, 575722 Sin Ming - Tel:		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Final Rpt due 23/04/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGZ2647B (1201800000601)**
[SLH623T]

TP

SIM KAI LENG ALFIE




































Jan 7 2018 12:00AM







[Lee Weikang]

Em Solution Pte Ltd (160 Sin Ming)

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/04/18 13:40	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
2	12/04/18 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
3	12/04/18 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
4	12/04/18 13:40	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
5	12/04/18 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
6	12/04/18 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
7	12/04/18 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
8	12/04/18 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
9	12/04/18 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
10	12/04/18 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
11	12/04/18 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
12	12/04/18 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
13	12/04/18 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
14	12/04/18 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
15	12/04/18 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
16	12/04/18 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
17	12/04/18 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
18	12/04/18 13:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
19	12/04/18 13:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
20	12/04/18 13:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
21	12/04/18 13:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
22	12/04/18 13:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
23	12/04/18 13:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
24	12/04/18 13:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
25	12/04/18 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
26	12/04/18 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
27	12/04/18 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
28	12/04/18 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
29	12/04/18 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
30	12/04/18 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
31	12/04/18 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
32	12/04/18 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
33	12/04/18 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
34	12/04/18 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
35	12/04/18 13:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	12/04/18 13:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
37	12/04/18 13:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
38	12/04/18 13:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
39	12/04/18 13:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
40	12/04/18 13:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	12/04/18 17:03	OI GIA Report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD18000501/WD3S2
Date: 16/04/2018

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2017-00007999
Claimant Vehicle No : SGZ2647B **Insured Vehicle No :** SLH623T
 Date of Loss: 07/01/2018 Nature of Claim: TP Claim No: 1201800000601

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGZ2647B**
 Make & Model: HONDA ACCORD, 1.6 (M) Engine No: K20A6053816
 Reg. Date: 24/10/2007 (Man. Year: 2007) Chassis No: CL73303280
 Colour: White Odometer: 414639 km
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45ZR17 Rear Tyre Size: 225/45ZR17
 Front Left Side: Michelin 3 mm Rear Left Side: Michelin 2 mm
 Front Right Side: Michelin 3 mm Rear Right Side: Michelin 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 08/01/2018
 Date Inspected: 09/01/2018 Inspected At: Em Solution Pte Ltd (160 Sin Ming) (HQ)
 160 Sin Ming Drive, #03-19 Sin Ming Autocity
 Singapore 575722
 Estimated Period of Repair: 3.0 days

Adjuster: Teo Cheng Ming Wilson**Manager:** Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$2,400.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Apr 2018)
Parts:	143	HONDA ACCORD 1.6 (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGZ2647B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >