

INSURANCE

INS. CASE OWNER:

JACLYN

CC 4/AIG1800

05/11/18, R1/18/18

LKK:

IDAC:

Surveyor:

RAGUL

DOI:

ASSIGNMENT

9/1/18

Date/Time:

9/1/18

Registered in Merimen:

9/1/18

Pre-assign / CCU / FTE:



Insured Vehicle No.:

SFZ 5833M

Claim No.:

515874595354

Name of Insured:

YEO HEE KWANG

Policy No.:

200424866

Insured Tel No.:

HP:

97731735

Make / Model:

MERCEDES

Excess Sec II :SS

D.O.A.:

04/01/18

Place of Accident:

LOAN LHM FARM NORTH 6

Is driver the owner? (YES/NO)

(YES/NO)

Nature of Accident:

If NO, Driver Name / Age:

EUBENE YEO (M 20Y)

OI GIA REPORT YES/NO : TP GIA REPORT: YES/NO

Driver Tel No.:

98207999

(V/L: YES/NO)

Insured Liability: %

Final ? Yes / No

PBE 277K



INSRS:

WSP:

Tel:

Liability:

RMKS:

sg 98



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time	STAGE	DATE / PIC
11/1/18	PBE 277K - X	97731735 - X
01-02-18	PIR - OI VIDEO UPLOADED IN MERIMEN. OUR LIABILITY IS DOWN, ASK OI TO PRODUCE FRONT VIEW OF CCTV WHICH WILL REVEAL ACTUAL FACT BEFORE COLLISION. (SEE COMMENT ON TP'S SKETCH PLAN)	Notification ltr (if non-pickup): Call OI: 9/1/18 After call ltr to OI: 06/08/18 - 06/08/18
06/08/18	PIR IN. OI CHARGED FOR INCONSPICUOUS EXCHNG. SPOKE TO OI. COMMENTED ACCIDENT DETAILS & COMPLETED TO TP. INFORMED HIM OF TP CLAIM & LIABILITY BASED ON PIR. AGREED TO SETTLING & SURETY NOW MADE. SEND LETTER TO OI. SURETY LIABILITY CLAIM. TP LOD IN BY SURETY. SEND 1ST OFFER TO TP. TP ACCEPTED SETTLED 12 SEP 2018. QM BOCS IN OCTOBER.	Documentation Check List: Handler Typist Notification ltr (if non-pickup) [] [] After call ltr to OI [] [] Authorisation To Act [] [] Release Voucher [] [] Final Repair Bill [] [] Car Rental Invoice [] [] Towing Invoice [] [] LTA / GIA : [] [] Medical Bill [] [] PIR - AGAINST OI [] [] Mandate/Reject Instruction: [] [] LOD [] [] Payment Breakdown Form: [] [] Post-Repair Photos: [] [] Others: [] []

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by:

FINAL SETTLEMENT Date/Time: 10/09/18 Confirm with: LORNA HIL Email [] Call []

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. :
 Repair Cost: S\$ 1,500.00
 Loss of Rental (LOR): S\$ - (days)
 Loss of Use (LOU): S\$ 90.00 (S\$ 30 x 3 days)
 Loss of Income (LOI): S\$ - (S x days)
 LOR only [] LOU only [] LOR + LOU [] LOR + LOI [] (Tick only one)
 CIA/LTA Search: S\$ -
 Medical: S\$ -
 Disbursement: S\$ - (e.g. Tow/Independent)
 Legal Cost: S\$ -
 Total: S\$ 1,590.00 Global Sum S\$: -
 1) Claim status: Normal/Reject/Private Settle
 2) Report Format:
 3) Survey fee: 4800.00

FINAL PAYMENT Date/Time: Confirm with: Email [] Call []

Payee 1: S\$ 1,590.00 Name 1: EG 98 MOTOR PTE LTD
 Payee 2: (Strike if N.A.) S\$ - Name 2: -
 Payee 3: (Strike if N.A.) S\$ - Name 3: -

SUNIT PRS

Dasu

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: FBE 2177K
 at Workshop m/s SG 98 Motor
 of B/K 4001, Amic Fuel Park
 Insured _____
 Policy No _____
 Claims No _____
 Sum Insured: _____ Excess _____
 (Client's Record) _____
 Make of Ven _____

Veh No: FBE 2177K yr Regn _____
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Honda cc _____
 Colour: Dark Grey AC Insured / Std / NI / NA _____
 Sp. Reading: 56808 T. Radio: Insured / Std / NI / NA _____
 Eng No _____
 C/No _____
 Gen Cond: Good / Fair / Poor / Burnt _____
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Mod: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 3.00-18 (S)
 R: 100/30-17 (S)
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or City Dune (F)
 Front: Dunlop (R) Rear: _____
 R/Bal: 3 mm R/Bal: 3 mm
 L/Bal: _____ mm L/Bal: _____ mm
 D.O.A: 4/1/2018 DOI: 9/1/18
 Survey held at: At Above
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
(O/S)

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.
 Bal. or Market Value: _____
 JDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

<u>X</u>	<u>X</u>
N/S	O/S

The U/C / Chassis frame / Body Structure affected due to collision

9/1/18: Quotation workshop will send to H&K
40 \$1,500.00
CRMO: \$ 2,382.70 (61%)

Case Time File Pass to: : Preli. Report
 : Final Report

Days Of Repair: _____
 Resurvey No. of Trip: _____

Add Fee: Site Insp \$
 Interview \$
 Tech Insp \$
 Weekend \$

Survey Fee
 Transporter

Report Format:
 Lump Sum / I.B.I: \$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/AIG18000523/R1yb3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 09-01-2018	
Code : AIG			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKZ 5833M	Veh. Inspected	FBE 2177K
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	09/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	04/01/2018	Inspection Date	09/01/2018
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Reflex Ramon

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4868 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 12 January 2018

To : LKK

By Fax: 6256-4315

Attn : Rasul

Tel : 90010068

lot ref: 2020/344

VEHICLE NO : F8E 2177K

ACCIDENT DATE: 4 January 2018

Tiger GL 200RM | 197 / M11 MC22135 / 2010 24

	<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1	Front Mudguard	1	130.00 <i>scr</i>
2	Handle Bar	1	110.00 <i>X</i>
3	Clutch Lever	1	25 65.00 <i>scr</i>
4	Cone Bearing	1	75.00 <i>scr</i>
5	Mirror LH	1	65.00 <i>scr</i>
6	Visor	1	78.00 <i>scr</i>
7	Head Lamp Assy	1	280 320.00 <i>scr</i>
8	Head Lamp Cover	1	180.00 <i>scr</i>
9	RH Head Lamp Guard	1	40.00 <i>mis</i>
10	LH Head Lamp Guard	1	40.00 <i>scr</i>
11	Rear Footrest LH	1	52.00 <i>cut</i>
12	Footrest Rubber LH	1	35.00 <i>cut</i>
13	Fork Tube	1 set	380.00 <i>PT</i>
14	Fuel Tank	1	760.00 <i>X</i>
15	Front Signal LH	1	60.00 <i>X</i>
16	Fork Oil Seal	1	50 150.00 <i>scr</i>
17	Fork Under Bracket	1	150.00 <i>PT</i>
18	Rear Tail Cover LH	1	130.00 <i>X</i>
19	Welding Handle Bar Stopover	1	75.00 <i>X</i>
20	Tank Side Guard LH	1	120.00 <i>X</i>
21	Front Rim	1	340.00 <i>repair</i>
22	Head Lamp Stay	1	150.00 <i>X</i>
	Sub-Total		3,403.00 <i>1580</i>
	Less 10%		340.30 <i>10%</i>
	Sub-Total		3,062.70 <i>1422</i>

(1)

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 669622

Tel: 6452 4898 Fax: 6452 4888

Email: sg_motor_enterprise@yahoo.com.sg

Date: 12 January 2018

To : LKK

By Fax: 6256-4315

Attn : Rasul

Tel : 90010068

VEHICLE NO : FBE 2177K

Tiger GL 200RM

ACCIDENT DATE: 4 January 2018

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1 Front Mudguard	1	130.00
2 Handle Bar	1	110.00
3 Clutch Lever	1	65.00
4 Cone Bearing	1	75.00
5 Mirror LH	1	65.00
6 Visor	1	78.00
7 Head Lamp Assy	1	320.00
8 Head Lamp Cover	1	180.00
9 RH Head Lamp Guard	1	40.00
10 LH Head Lamp Guard	1	40.00
11 Rear Footrest LH	1	52.00
12 Footrest Rubber LH	1	35.00
13 Fork Tube	1 set	380.00
14 Fuel Tank	1	760.00
15 Front Signal LH	1	60.00
16 Fork Oil Seal	1	75.00
17 Fork Under Bracket	1	150.00
18 Rear Tail Cover LH	1	130.00
19 Welding Handle Bar Stopover	1	75.00
20 Tank Side Guard LH	1	120.00
21 Front Rim	1	340.00
22 Head Lamp Stay	1	150.00
	Sub-Total	3,403.00
	Less 10%	340.30
	Sub-Total	3,062.70

(1)

VEHICLE NO : FBE 2177K

Tiger GL 200RM

Nett items

1 Towing fee	40.00
2 Remove & replace fork assy & top up fork oil	130.00
3 Remove & replace necessary parts, align & etc	350.00
4 Putty & re-spray parts to touch up	300.00
Sub-Total	820.00
Nett Total	3,882.70

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion

Thank you



SG 98 MOTOR PTE LTD

LG

(2)

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3340H
Vehicle Details	
Vehicle No.:	FBE2177K
Vehicle to be Exported:	Yes
Intended Deregistration Date:	10 Sep 2018
Vehicle Make:	HONDA
Vehicle Model:	TIGER GL200R M
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	MC22E1051743
Chassis No.:	MH1MC22139K051854
Maximum Power Output:	-
Open Market Value:	\$3,430.00
Original Registration Date:	07 Jan 2010
First Registration Date:	07 Jan 2010
Transfer Count:	3
Actual ARF Paid:	\$515.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	06 Jan 2020
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$851.00
COE Rebate Amount:	\$185.00
Total Rebate Amount:	\$185.00

The information contained herein is correct as at 10 Sep 2018

OK

Vic (LKKAuto)

From: Sg Motor <sgmotor2000@yahoo.com.sg>
Sent: Tuesday, 11 September, 2018 1:16 PM
To: Vic (LKKAuto)
Cc: Sg Motor; Admin A
Subject: Re: RE: Your Insured: SKZ 5833M (Our ref: FBE 2177K) LKK REF
CC4/AIG18000523/R1hb3
Attachments: FBE 2177K (Release Voucher).pdf

Dear Vic

Attached is the signed Release Voucher and Letter of Authorization for your action.

Thank You

Regards
Linda

SG 98 Motor Pte Ltd

Blk 4001 #01-21
Ang Mo Kio Industrial Park 1
Singapore 569622
Tel: 64524898 Fax: 64526898

On Monday, 10 September 2018, 2:44:22 PM GMT+8, Vic (LKKAuto) <vicalpeh@lkkauto.com> wrote:

Your Ref: FBE 2177K
PREJUDICE

WITHOUT

Our Ref: CC4/AIG18000523/R1hb3

Dear Leena,

We refer to your below email.

On a without prejudice basis and purely for an amicable settlement without admission of liability to our Insured's part, we offer a global sum of **\$1,590.00 (all in)** to settle your client's claim.

If agreeable, kindly chop and sign the attached DV then forward back a copy to us to together with the **Authorization Letter signed by the owner** for payment processing.

The above amount is to be made payable to **SG 98 MOTOR PTE LTD.**

Thank you.

"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

 *Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Sg Motor [mailto:sgmotor2000@yahoo.com.sg]
Sent: Monday, 10 September, 2018 11:38 AM
To: Vic (LKKAuto)
Cc: Sg Motor
Subject: Your Insured: SKZ 5833M (Our ref: FBE 2177K)

Refer to the above claim, we would like to do a direct
settlement for the property damage to our client's bike FBE 2177K

- 1) Invoice for Cost of Repairs
- 2) GIA Report

3) Police Report

4) TP Result

We seek your assistance to expedite this claim as we wish
to close the file.

Thank You

Regards

Leena

SG 98 Motor Pte Ltd

Blk 4001 #01-21

Ang Mo Kio Industrial Park 1

Singapore 569622

Tel: 64524898 Fax: 64526898



SINGAPORE
POLICE FORCE

TRAF 1464
1011A AVENUE
SINGAPORE 139947
TEL 310 2011 0000
FAX 310 2011 0000
www.police.gov.sg

Our Ref : TP/IP/12675/2018
Date : 19 JUNE 2016

MOHAMED IMRAN BIN MOHAMED KHAMDAN
BLK 574 CHOA CHU KANG STREET 62
#13-306
SINGAPORE 660574

Dear Sir/Madam

ROAD TRAFFIC ACCIDENT INVOLVING FBE 2177 K AND BKZ 5833 M ALONG CHOA CHU
KANG NORTH 6 ON 04/01/2016 AT ABOUT 9:30PM

I refer to the above report.

Please be informed that we have completed our investigation with regard to the driver of
BKZ 5833 M had committed an offence under Section 41(b) of the
Road Traffic Act Chapter 276A (S.41(b)) and issued a notice to you to the said offence.

Yours faithfully

HEAD INVESTIGATION
TRAFFIC POLICE
SINGAPORE POLICE FORCE

This is a computer-generated document. No signature required.

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

DATE: 7 September 2018

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
SINGAPORE 079120

LETTER OF DEMAND

Your Insured: SKZ 5833M
Date of Accident: 4-Jan-18

Location: Choa Chu Kang North 6 / Choa Chu Kang Drive

FINAL REPAIR COSTS

VEHICLE NO. FBE 2177K Tiger GL200 RM)

Cost of Repair for Vehicle No.:	FBE 2177K (lump sum)	\$1,500.00
Loss of Use:	3 days x \$35	\$105.00
	Total:	\$1,605.00

SINGAPORE DOLLARS: ONE THOUSAND SIX HUNDRED FIVE ONLY

Notes:

1. All cheque payment should be "Crossed" and made payable to **SG 98 MOTOR PTE LTD**
2. All cheque should have our "Invoice No" written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



SG 98 Motor Pte Ltd

LG



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

06 AUGUST 2018

YEO HEE KWANG
45 LOWLAND ROAD
SINGAPORE 547445

Dear Sir/Madam,

OUR REF : CC4/AIG18000523/R1mb3
YOUR REF : SKZ 5833M
ACCIDENT INVOLVING SKZ 5833M AND FBE 2177K ALONG CHUA CHU KANG
NORTH 6 ON 04.01.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of FBE 2177K against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided to the Third-Party vehicle FBE 2177K. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 10 days from the date of this letter **if not provided at AIG's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Vic Alpeh
Case Handler
DID: 6841 2096
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORIZATION TO ACT

I, Mohamed Imran Bin Mohamed ^{Khandan} ("the third party claimant")
of Blk 574 Choa Chu Kang St 52 #13-306 ⁽⁶⁸⁰⁵⁷⁴⁾ (address),
owner of FBE 2177K (vehicle no.) hereby authorize
SG 98 Motor Pte Ltd


("the workshop") to act for me with respect to my claim for
repair costs and/or rental and/or loss of use ("claim") for my
vehicle no. FBE 2177K that was damaged pursuant to the
accident which occurred on 4/1/2018 (date) along Choa Chu
Kang North 6 (location)
involving vehicle no/s SK2 5833M
("the accident").

I further authorize the workshop to settle my above mentioned
claim in a manner that they deem fit and the workshop is further
authorized to receive payment further to settlement of my claim
with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach
on my behalf is on a without prejudice and without admission of
liability basis insofar as the driver/owner/insurers of the
other vehicle/s is concerned.

Dated this 6 day of January (month) 20 18 (year)

[Signature]
Signed by "the third party claimant"


Signed by "the workshop"

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **SG 98 MOTOR PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$1,590.00** (Global Sum – all in) for vehicle no. **FBE 2177K** that was damaged pursuant to the accident which occurred on **04/01/2018** (date) along **CHUA CHU KANG NORTH 6** (location) involving vehicle no/s **04/01/2018**. This is pursuant to the inspection conducted on **09/01/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **MOHAMED IMRAN BIN MOHAMED KHAMDAN** ("the third-party claimant") of vehicle no. **FBE 2177K** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **FBE 2177K** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 10th (day) of Sept (month) **2018** (year)



MBK

Signed by appointed surveyor



Signed by "the workshop" (with chop)

Provided always that this discharge of my claim for damages resulting from the accident to my vehicle shall not apply to, or release or preclude me from making a claim for general and special damages for any personal injuries sustained in the same accident.

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

DATE: 7 September 2018

Invoice No: SG98-PD-18-064

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
SINGAPORE 079120

PD - Direct Settlement

Your Insured: SKZ 5833M
Date of Accident: 4-Jan-18

Location: Choa Chu Kang North 6 / Choa Chu Kang Drive

FINAL REPAIR COSTS

VEHICLE NO. FBE 2177K Tiger GL200 RM)

Cost of Repair for Vehicle No.: FBE 2177K (lump sum) \$1,500.00

Total: \$1,500.00

SINGAPORE DOLLARS: ONE THOUSAND FIVE HUNDRED ONLY

Notes:

1. All cheque payment should be "Crossed" and made payable to SG 98 MOTOR PTE LTD
2. All cheque should have our "Invoice No" written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



SG 98 Motor Pte Ltd

.LG

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Jan 2018 Edit Reg		09 Jan 2018 00:00 Edit Adj Rpt	S\$1,500.00 Edit Estimates	S\$1,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Yeo Hee Kwang , ID: S1176878D								
Main Claimant:	MOHAMED IMRAN BIN MOHAMED KHAMDAN , ID: S8913340H								
Vehicle Reg. No.:	FBE2177K	Date of Loss:	04/01/2018 00:00 - :59 [95 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 5158155953SG	Policy/Cover Note No.:	2100424886 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKZ5833M	Policy No. (Claimant):	MSD/VMS/17-373627-CA						
Repairer:	Sg 98 Motor Pte Ltd (HQ) BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21, 569622 Ang Mo Kio - Tel: 64524898								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M] Jaclyn-M.Kesaval@aig.com								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 18/01/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (10/01/2018): Request for TP GIA report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBE2177K (5158155953SG)
[SKZ5833M]**

TP

MOHAMED IMRAN BIN MOHAMED KAMDAN






Jan 4 2018 12:00AM

[Yeo Hee Kwang]

Sg 98 Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View <input type="button" value="View in Browser"/>		
Video															1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail	Print				
1	19/01/18 15:27	Video - Accident											Load MP4				
Letters/Correspondences															1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print				
1	(Draft)	Third Party Express Settlement - Payment Breakdown											Edit				
Assessment Reports															1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail	Print				
1	10/01/18 10:38	Accident Statement <small>From: SC - Reg. No: SKZ5833M, Claimant: YEO HEE KWANG</small>											Load HTM				
Photos/Images															3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print				
1	10/09/18 13:06	General View											Load JPG <input checked="" type="checkbox"/>				
2	10/09/18 13:06	General View											Load JPG <input checked="" type="checkbox"/>				
3	10/09/18 13:06	General View											Load JPG <input checked="" type="checkbox"/>				
4	10/09/18 13:06	General View											Load JPG <input checked="" type="checkbox"/>				
5	10/09/18 13:06	General View											Load JPG <input checked="" type="checkbox"/>				
6	10/09/18 13:06	General View											Load JPG <input checked="" type="checkbox"/>				
7	10/09/18 13:06	General View											Load JPG <input checked="" type="checkbox"/>				
8	10/09/18 13:06	General View											Load JPG <input checked="" type="checkbox"/>				
9	10/09/18 13:06	General View											Load JPG <input checked="" type="checkbox"/>				
10	10/09/18 13:06	General View											Load JPG <input checked="" type="checkbox"/>				
11	10/09/18 13:06	General View											Load JPG <input checked="" type="checkbox"/>				
12	10/09/18 13:06	General View											Load JPG <input checked="" type="checkbox"/>				
13	10/09/18 13:06	General View											Load JPG <input checked="" type="checkbox"/>				
14	10/09/18 13:06	General View											Load JPG <input checked="" type="checkbox"/>				
15	10/09/18 13:06	General View											Load JPG <input checked="" type="checkbox"/>				
16	10/09/18 13:06	General View											Load JPG <input checked="" type="checkbox"/>				
17	10/09/18 13:06	General View											Load JPG <input checked="" type="checkbox"/>				
18	10/09/18 13:06	General View											Load JPG <input checked="" type="checkbox"/>				
19	10/09/18 13:06	General View											Load JPG <input checked="" type="checkbox"/>				
20	10/09/18 13:06	General View											Load JPG <input checked="" type="checkbox"/>				
21	10/09/18 13:06	General View											Load JPG <input checked="" type="checkbox"/>				
22	10/09/18 13:06	General View											Load JPG <input checked="" type="checkbox"/>				
23	10/09/18 13:06	General View											Load JPG <input checked="" type="checkbox"/>				
24	10/09/18 13:06	General View											Load JPG <input checked="" type="checkbox"/>				
25	10/09/18 13:06	General View											Load JPG <input checked="" type="checkbox"/>				
26	10/09/18 13:06	General View											Load JPG <input checked="" type="checkbox"/>				
27	10/09/18 13:06	General View											Load JPG <input checked="" type="checkbox"/>				

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
				<input checked="" type="checkbox"/>
28	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
29	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
30	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
31	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
32	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
33	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
34	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
35	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
36	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
37	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
38	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
39	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
40	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
41	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
42	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
43	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
44	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
45	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
46	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
47	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
48	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
49	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
50	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
51	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
52	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
53	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
54	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
55	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
56	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
57	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
58	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
59	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
60	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
61	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
62	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
63	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
64	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
65	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
66	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
67	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
68	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
69	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
70	10/09/18 13:06	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/01/18 15:18	EMAIL FROM AIG DD 08012018	Load PDF	
2	09/01/18 15:18	WKSP NOTICE	Load PDF	
3	10/01/18 18:23	TP GIA REPORT	Load PDF	
4	06/08/18 12:01	PIR - AGAINST OI	Load PDF	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
5	06/08/18 13:47	LETTER TO OI	 Load PDF	
6	10/09/18 14:38	TP ESTIMATE - MARKED	 Load PDF	
7	24/09/18 08:15	WORKSHOP INVOICE	 Load PDF	
8	24/09/18 08:15	AUTHORISATION TO ACT FORM	 Load PDF	
9	24/09/18 08:15	Release Voucher	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SKZ5833M (Insd veh)	Model:	HONDA TIGER 197CC GL 200R
	FBE2177K (TP veh)		
Date of Accident:	04/01/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No		
Repair Estimate	:\$			3,907.00	
Final Repair Cost	:\$			1,500.00	
Loss of Use	:\$			90.00	3.00 days at \$30.00 per day
Rental (if any)	:\$			0.00	days
LTA / GIA Search Fee	:\$			0.00	
Others:	:\$			0.00	
	:\$				
Final Settlement Sum	:\$			1,590.00	

Is Third Party Workshop GIA Registered? YES NO (Kindly indicate below)

A) For **Non GIA Registered Workshop:** Agreed Liability ____ 100 ____ (%)

B) For **GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	SG 98 Motor Pte Ltd	:\$	1,590.00
2)		:\$	

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

24 Sep
2018

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18000523/R1HB3Q2
Date: 24/09/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100424886
Claimant Vehicle No : FBE2177K	Insured Vehicle No :	SKZ5833M
Date of Loss: 04/01/2018	Nature of Claim:	TP Claim No: 5158155953SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBE2177K	Engine No:	MC22E1051743
Make & Model:	HONDA TIGER, 197cc GL 200R	Chassis No:	MH1MC22139K051854
Reg. Date:	07/01/2010 (Man. Year: 2009)	Odometer:	56808 km
Colour:	Dark Grey		
Engine Capacity:	197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	3.00-18	Rear Tyre Size:	100/30-17
Front Left Side:	CITY DEMON 3 mm	Rear Left Side:	Dunlop 3 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,087.00	1,422.00	1,665.00	53.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	820.00	470.00	350.00	42.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,907.00	1,892.00	2,015.00	51.57
Approved Total (Overridden) (S\$)		1,500.00		
Nett Amount (S\$)	3,907.00	1,500.00	2,407.00	61.61
+ Loss of Use (3.0 x S\$30.00/day) (S\$)		90.00		
Nett Liability (S\$)		1,590.00		

INSPECTION

Date of Assignment:	09/01/2018	
Date Inspected:	09/01/2018 Inspected At:	Sg 98 Motor Pte Ltd (HQ) BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 Singapore 569622
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT MUDGUARD	Scratched	130.00 FL	*130.00 FL
2	1		*HANDLE BAR	Serviceable	110.00 FL	*- FL
3	1		*CLUTCH LEVER	Scratched	65.00 FL	*25.00 FL
4	1		*CNE BEARING	Necessary	75.00 FL	*75.00 FL
5	1		*MIRROR LH	Scratched	65.00 FL	*65.00 FL
6	1		*VISOR	Cracked	78.00 FL	*78.00 FL
7	1		*HEAD LAMP ASSY	Scratched	320.00 FL	*280.00 FL
8	1		*HEAD LAMP COVER	Scratched	180.00 FL	*180.00 FL
9	1		*RH HEAD LAMP GUARD	Missing	40.00 FL	*40.00 FL
10	1		*LH HEAD LAMP GUARD	Scratched	40.00 FL	*40.00 FL
11	1		*REAR FOOTREST LH	Cut	52.00 FL	*52.00 FL
12	1		*FOOTREST RUBBER LH	Cut	35.00 FL	*35.00 FL
13	1		*SET FORK TUBE	Bent	380.00 FL	*380.00 FL
14	1		*FUEL TANK	Serviceable	760.00 FL	*- FL
15	1		*FRONT SIGNAL LH	Serviceable	60.00 FL	*- FL
16	1		*FORK OIL SEAL	Necessary	75.00 FL	*50.00 FL
17	1		*FORK UNDER BRACKET	Bent	150.00 FL	*150.00 FL
18	1		*REAR TAIL COVER LH	Serviceable	130.00 FL	*- FL
19	1		*WELDING HANDLE BAR STOPOVER	Serviceable	75.00 FL	*- FL
20	1		*TANK SIDE GUARD LH	Serviceable	120.00 FL	*- FL
21	1		*FRONT RIM	Repair	340.00 FL	*- FL
22	1		*HEAD LAMP STAY	Serviceable	150.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	3,430.00	1,580.00
- List Item Discount on L Items 10.00/10.00% (S\$)	343.00	158.00
Total Parts (S\$)	3,087.00	1,422.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING FEE	New	40.00	40.00
2	REMOVE & REPLACE FORK ASSY & TOP UP FORK OIL	New	130.00	80.00
3	REMOVE & REPLACE NECESSARY PARTS,ALIGN & ETC	New	350.00	200.00
4	PUTTY RESPRAY PARTS TO TOUCH UP	New	300.00	150.00
Gross Labour Cost (\$\$)			820.00	470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >