

## Enquire PARF/COE Rebate for Registered Vehicle

## Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 3570M

## Vehicle Details

Vehicle No.: PC5571E

Vehicle to be Exported: No

Intended De-registration  
Date: 08 Jan 2018

Vehicle Make: TOYOTA

Vehicle Model: HIACE COMMUTER GL  
3.0 AUTO

Primary Colour: White

Manufacturing Year: 2015

Engine No.: 1KD2517098

Chassis No.: KDH2230024120

Maximum Power Output: -

Open Market Value: \$38,364.00

Original Registration Date: 04 Jan 2017

First Registration Date: 04 Jan 2017

Transfer Count: 0

Actual ARF Paid: \$1,919.00

## Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry  
Date: -

PARF Rebate Amount: \$0.00

## Intended COE Rebate Details

COE Expiry Date: 03 Jan 2027

COE Category: C - Goods Vehicle &amp; Bus

COE Period(Years): 10

PQP Paid: \$40,673.00

COE Rebate Amount: \$36,551.00

**Total Rebate Amount: \$36,551.00**

The information contained herein is correct as at 08 Jan 2018

OK



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG18000527/Uka3

11<sup>th</sup> January 2018

**GEORGE ISAAC TAN KIANG MENG**

90 TANGLIN HALT 07-324

SINGAPORE 141090

Dear Sirs,

**ACCIDENT INVOLVING SGV 4424K AND PC 5571E ON 05.01.2018 ALONG/  
AT BUKIT TIMAH ROAD TOWARDS NEWTON CIRCUS**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, AIG Asia Pacific Insurance Pte Ltd (AIG) to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Kindly proceed to lodge your GIA report within five (05) working days of receipt of this letter, giving the version of the accident amongst other things related to the accident. The GIA report can be lodged at any of AIG reporting centres. You may refer to your Certificate of Insurance for the list of the reporting centres.

If you have any information to add or any amendments to make, please contact the undersigned within five days from the date of this letter.

Please note that the standing of your insurance policy such as NCD, premium & etc would be affected.

Yours faithfully,

Zaini

Claims

Tel : 6841 2132

Fax: 6741 4108

Email : [Zaini@lkkauto.com](mailto:Zaini@lkkauto.com)

c.c. *Claims Manager*  
*AIG Asia Pacific Insurance Pte Ltd*  
*(Motor Claims Dept)*

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3570M
Vehicle Details	
Vehicle No.:	PC5571E
Vehicle to be Exported:	No
Intended De-registration Date:	10 Jan 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE COMMUTER GL 3.0 AUTO
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	1KD2517098
Chassis No.:	KDH2230024120
Maximum Power Output:	-
Open Market Value:	\$38,364.00
Original Registration Date:	04 Jan 2017
First Registration Date:	04 Jan 2017
Transfer Count:	0
Actual ARF Paid:	\$1,919.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	03 Jan 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$40,673.00
COE Rebate Amount:	\$36,529.00
<b>Total Rebate Amount:</b>	<b>\$36,529.00</b>

The information contained herein is correct as at 10 Jan 2018

OK



# KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-50 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379R

Date : 22.01.2018

AIK Asia Pacific Insurance Pte Ltd

Chartis Building

78 Shenton Way #07-16

Singapore 079120

Attn: Motor Claim Department

## **ACCIDENT INVOLVING VEHICLE: PC5571E AND SGV4424K ON 05/01/2018**

We are the authorized repair workshop for the owner of motor vehicle no: **PC5571E**, which was involved in the captioned accident with your insured vehicle no: **SGV4424K**. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

1) Cost of Repair (inclusive of GST)	\$ 1,828.76
2) Loss Of Use (3days x \$300)	\$ 900.00
3) GIA Search Fee	\$ 2.00
	<u>\$ 2,730.76</u>

We enclosed herewith the following documents to support the claims:

- |                                    |                                  |
|------------------------------------|----------------------------------|
| a) Final Repair Invoice            | b) Vehicle Registration Log Card |
| c) GIA Report                      | d) I/C & Driving Licence         |
| e) Insurance Certificate           | f) GIA Search Result             |
| g) Letter of Authorisation, etc... |                                  |

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

**Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.**

Thank you.

Yours faithfully,

Jason Tang (jason@fastechauto.com.sg)  
For Kim Chwee Auto Pte Ltd





Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

27 AUGUST 2019

**GEORGE ISAAC TAN KIAN MENG  
BLOCK 90 TANGLIN HALT ROAD  
#07-324  
SINGAPORE 141090**

Dear Sir/Madam,

**OUR REF : CC6/AIG18000527/Uha3  
YOUR REF : SGV 4424K**

**ACCIDENT INVOLVING SGV 4424K AND PC 5571E ALONG NEWTON CIRCUS ON  
05.01.2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of PC 5571E against your motor insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Please be informed that your No Claim Discount (NCD – if any) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6841 2096 or email us at [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com).

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Vjc Alpeh  
*Case Handler*  
DID: 6841 2096  
FAX: 6741 4108  
Email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)

DATE : 22 Jan 2018

TO : AICA Asia Pacific Insurance Pte Ltd

RE : ACCIDENT INVOLVING VEHICLE NO. PL5571E & SGV4424K

ALONG Bukit Timah Rd twds Newton Circus  
ON 5/01/2018

I/We, AirKing Transport construction & Engineering P/L  
of (NRIC No./ROC No.) 199503570M

of 61A Sing Avenue S217906

owner of vehicle no. PL5571E in consideration of M/s KIM CHWEE AUTO PTE LTD repairing my/our vehicle PL5571E at my/our instruction and hereby authorise M/s KIM CHWEE AUTO PTE LTD to demand claim settle receive whatever amount settled/payable by the Insurance Company and/or third party or to commence legal proceedings, if necessary, under my name, for the cost of repairs, car rental and/or loss of use, etc. and to their appointing solicitor to act for me/us in respect of the said accident/claim and all claimed and/or settled shall belong to them absolutely.

I/We further agree and undertake to indemnify them against the abovementioned claim cost which may arisen therewith.

Signature of Owner :





Name of Owner :

\_\_\_\_\_

**RELEASE VOUCHER**  
**(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)**

"We/I, Kim Chwee Auto Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. LKK AUTO CONSULTANTS PTE LTD ("name of surveyor") with respect to the amount claimed for SG\$ 2,280.00 <sup>GLOBAL SUM-ALIN</sup> (repair costs), SG\$ — (loss of use/rental) SG\$ — (search fees) for vehicle no. PL5571E that was damaged pursuant to the accident which occurred on 5/1/2018 (date) along BUKIT TIMAH ROAD > NEWTON CIRCUS (location) involving vehicle no/s SG V4424K.

This is pursuant to the inspection conducted on 09/01/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Alf King Transport Construction & Engineering Pte Ltd ("third party claimant") of vehicle no. PL5571E to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to PL5571E (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 09 day of 10 (month) 20 18 (year)



CKS

Signed by AIG appointed surveyor



Chopped & Signed by "the workshop"

## TAX INVOICE

### KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-50 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379R

AIG Asia Pacific Insurance Pte Ltd

Chartis Building

78 Shenton Way #07-16

Singapore 079120

Attn: Motor Claim Department

Tax Invoice : 20071

Date: 22.01.2018

Vehicle No: PC5571E

Make/Model: TOYOTA HIACE

Chassis/Eng# :

Accident Date: 05.01.2018

Claim No : 0118-20071

:

---

	Amount
To proceed on parts by parts repair inclusive of knocking ,spray painting labour charges and etc.	S\$ 1,709.12

E. & O. E.

Total : S\$ 1,709.12

GST @ 7% : S\$ 119.64

*Amount Due* : **S\$ 1,828.76**

  
for KIM CHWEE AUTO PTE LTD

All Invoices are subjected to GST



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

**Third Party Insurer Enquiry**

Our Ref No: GR-18-003144

Date of Request: 06/01/2018

Your Ref No: Online Purchase

Kim Chwee Auto Pte Ltd  
1 Kaki Bukit Avenue 6 #01-48  
AutoBay@Kaki Bukit  
Singapore 417883

Dear Sir/Madam,

Enquiry Date 06/01/2018  
Enquiry By Tang Kok Wee, Allan  
TP Vehicle No. SGV4424K  
Accident Date 05/01/2018

**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SGV4424K	AIG Asia Pacific Insurance Pte. Ltd.	22/12/2017-21/12/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-18-003144

Date of Request: 06/01/2018

Your Ref No: Online Purchase

Kim Chwee Auto Pte Ltd  
1 Kaki Bukit Avenue 6 #01-48  
AutoBay@Kaki Bukit  
Singapore 417883

Dear Sir/Madam,

Enquiry Date 06/01/2018  
Enquiry By Tang Kok Wee, Allan  
TP Vehicle No. SGV4424K  
Accident Date 05/01/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Jan 2018 <a href="#">Edit Reg</a>		09 Jan 2018: 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$1,709.12</b> <a href="#">Edit Estimates</a>	<b>S\$1,709.12</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

<b>CLAIM SUBFOLDER DETAILS</b>		[Created by adjuster]							
Insured:	GEORGE ISAAC TAN KIANG MENG, ID: 57404875G								
Main Claimant:	AIRKING TRANSPORT CONSTRUCTION & ENGINEERING PTE. LTD., Co. Reg. No.: 199503570M								
Vehicle Reg. No.:	PC5571E	Date of Loss: 05/01/2018 16:00 - :59 [12 Months and 1 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / 9214733100SG	Policy/Cover Note No.: 2100494644-01 (Comprehensive)							
Vehicle Reg. No. (Insured):	SGV4424K	Policy No. (Claimant): DA311218/1							
		Excess:							
Repairer:	Kim Chwee Auto Pte Ltd (HQ) 1 Kaki Bukit Avenue 6 #01-48, AutoBay@Kaki Bukit, 417883 Eunos - Tel: 67465405/67417244								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 18/01/2018]								
<b>ASSOCIATED MAIL RECEIVED</b>									
		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
<ul style="list-style-type: none"> <li>AIG_SG (10/01/2018): No OI GIA report</li> <li>AIG_SG (10/01/2018): Request for TP GIA report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b>									
		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*PC5571E (9214733100SG)

[SGV4424K]

TP


















AIRKING TRANSPORT CONSTRUCTION & ENGINEERING PTE. LTD.

Jan 5 2018 4:05PM

[GEORGE ISAAC TAN KIANG MENG]

Kim Chwee Auto Pte Ltd

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>   <a href="#">Upload Video</a>   <a href="#">Upload Audio</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Letters/Correspondences</b>			1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	{Draft}	Third Party Express Settlement – Payment Breakdown		Edit
<b>Assessment Reports</b>			1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	26/01/18 14:32	<b>Accident Statement</b> <small>From: SC - Reg. No: SGV4424K, Claimant: GEORGE ISAAC TAN KIANG MENG</small>		Load HTM
<b>Photos/Images</b>			3 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/01/18 17:55	Odometer Reading		Load JPG <input checked="" type="checkbox"/>
2	09/01/18 17:55	General View		Load JPG <input checked="" type="checkbox"/>
3	09/01/18 17:55	Chassis Number		Load JPG <input checked="" type="checkbox"/>
4	09/01/18 17:55	General View		Load JPG <input checked="" type="checkbox"/>
5	09/01/18 17:55	General View		Load JPG <input checked="" type="checkbox"/>
6	09/01/18 17:55	General View		Load JPG <input checked="" type="checkbox"/>
7	09/01/18 17:55	General View		Load JPG <input checked="" type="checkbox"/>
8	09/01/18 17:55	General View		Load JPG <input checked="" type="checkbox"/>
9	09/01/18 17:55	General View		Load JPG <input checked="" type="checkbox"/>
10	09/01/18 17:55	General View		Load JPG <input checked="" type="checkbox"/>
11	09/01/18 17:55	General View		Load JPG <input checked="" type="checkbox"/>
12	09/01/18 17:55	General View		Load JPG <input checked="" type="checkbox"/>
13	09/01/18 17:55	General View		Load JPG <input checked="" type="checkbox"/>
14	09/01/18 17:55	General View		Load JPG <input checked="" type="checkbox"/>
15	09/01/18 17:55	General View		Load JPG <input checked="" type="checkbox"/>
16	09/01/18 17:55	General View		Load JPG <input checked="" type="checkbox"/>
17	09/01/18 17:55	General View		Load JPG <input checked="" type="checkbox"/>
18	09/01/18 17:55	General View		Load JPG <input checked="" type="checkbox"/>
19	09/01/18 17:55	General View		Load JPG <input checked="" type="checkbox"/>
20	09/01/18 17:55	General View		Load JPG <input checked="" type="checkbox"/>
21	09/01/18 17:55	General View		Load JPG <input checked="" type="checkbox"/>
22	09/01/18 17:55	General View		Load JPG <input checked="" type="checkbox"/>
23	09/01/18 17:55	General View		Load JPG <input checked="" type="checkbox"/>
24	09/01/18 17:55	General View		Load JPG <input checked="" type="checkbox"/>
25	09/01/18 17:55	General View		Load JPG <input checked="" type="checkbox"/>
26	09/01/18 17:55	General View		Load JPG <input checked="" type="checkbox"/>
27	09/01/18 17:55	General View		Load JPG <input checked="" type="checkbox"/>
28	09/01/18 17:55	General View		Load JPG <input checked="" type="checkbox"/>
29	09/01/18 17:55	General View		Load JPG <input checked="" type="checkbox"/>
30	09/01/18 17:55	General View		Load JPG <input checked="" type="checkbox"/>
31	09/01/18 17:55	General View		Load JPG <input checked="" type="checkbox"/>
32	09/01/18 17:55	General View		Load JPG <input checked="" type="checkbox"/>
33	09/01/18 17:55	General View		Load JPG <input checked="" type="checkbox"/>
34	09/01/18 17:55	General View		Load JPG <input checked="" type="checkbox"/>
35	09/01/18 17:55	General View		Load JPG <input checked="" type="checkbox"/>
36	09/01/18 17:55	General View		Load JPG <input checked="" type="checkbox"/>

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
					<input checked="" type="checkbox"/>
37	09/01/18 17:55	General View		Load JPG	<input checked="" type="checkbox"/>
38	31/01/18 10:47	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
39	31/01/18 10:47	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
40	31/01/18 10:47	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
41	31/01/18 10:47	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
42	31/01/18 10:47	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
43	31/01/18 10:47	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
44	31/01/18 10:47	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/01/18 08:26	Non reporting letter		Load PDF	
2	11/01/18 08:58	TP GIA REPORT + ACCIDENT SCENE PHOTO		Load PDF	
3	26/01/18 10:06	TP ESTIMATE - MARKED		Load PDF	
4	27/08/19 13:47	LETTER TO OI		Load PDF	
5	16/10/19 11:51	WORKSHOP INVOICE		Load PDF	
6	16/10/19 11:51	AUTHORISATION TO ACT FORM		Load PDF	
7	16/10/19 11:51	Release Voucher		Load PDF	
8	16/10/19 11:51	GIA SEARCH		Load PDF	
9	16/10/19 11:51	LOD		Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

Vehicle No:	SGV4424K (Insd veh)	Model:	TOYOTA HIACE 3.0
	PC5571E (TP veh)		COMMUTER GL (A)
Date of Accident:	05/01/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> [ X ] Yes	<input type="checkbox"/> [ ] No
Repair Estimate	:	\$	6,456.27
Final Repair Cost	:	\$	2,280.00
Loss of Use	:	\$	3.00 days at \$150.00 per day
Rental (if any)	:	\$	days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	2,280.00

**Is Third Party Workshop GIA Registered?** ☐ [ ] YES ☒ [ X ] NO (Kindly indicate below)

**A) For Non GIA Registered Workshop:** Agreed Liability \_\_\_\_\_ 100 \_\_\_\_\_ (%)

**B) For GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Kim Chwee Auto Pte Ltd	:	\$ 2,280.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

16 Oct  
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18000527/UHA3Q2

Date: 16/10/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100494644-01

## Claimant

Vehicle No : PC5571E

Insured Vehicle No : SGV4424K

Date of Loss: 05/01/2018

Nature of Claim: TP

Claim No: 9214733100SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: PC5571E

Make &amp; Model: TOYOTA HIACE, 3.0 COMMUTER GL (A)

Engine No: 1KD2517098

Reg. Date: 04/01/2017 (Man. Year: 2015)

Chassis No: KDH2230024120

Colour: White

Odometer: 64458 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195/80 R15

Rear Tyre Size: 195/80 R15

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,533.90	889.12	3,644.78	80.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	820.00	680.00	45.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,033.90</b>	<b>1,709.12</b>	<b>4,324.78</b>	<b>71.67</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>422.37</b>	<b>119.64</b>	<b>302.73</b>	<b>71.67</b>
<b>Nett Amount (S\$)</b>	<b>6,456.27</b>	<b>1,828.76</b>	<b>4,627.51</b>	<b>71.67</b>
<b>+ Loss of Use (3.0 x S\$150.00/day) (S\$)</b>		<b>450.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		<b>2.00</b>		
<b>Nett Liability (S\$)</b>		<b>2,280.76</b>		
<b>Global Sum Settlement (S\$)</b>		<b>2,280.00</b>		

## INSPECTION

Date of Assignment: 09/01/2018

Date Inspected: 09/01/2018 Inspected At:

Kim Chwee Auto Pte Ltd (HQ)  
1 Kaki Bukit Avenue 6 #01-48,  
AutoBay@Kaki Bukit  
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: VIC ALPEH

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	2,150.70 F	*- FL
2	1		*TAILGATE REAR LOGO	Necessary	45.90 F	*45.90 FL
3	1		*TAILGATE HIACE EMBLEM	Necessary	60.30 F	*60.30 FL
4	1		*TAILGATE WEATHERSTRIP	Not Necessary	395.10 F	*- FL
5	1		*REAR BUMPER	Dented / Deformed	599.30 F	*599.30 FL
6	2		*REAR BUMPER SIDE HOLDERS	Necessary	230.00 F	*230.00 FL
7	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
8	4		*REAR BUMPER LOWER BRACKETS	Bent	180.00 F	*180.00 FL
9	1		*REAR END PANEL	Repair	499.50 F	*- FL
10	1		*TAILLAMP O/S	Not Necessary	303.10 F	*- FL
11	1		*REAR 70KM/HR STICKER	Necessary	20.00 F	*20.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,533.90</b>	<b>1,185.50</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b>	<b>0.00</b>	<b>296.38</b>
<b>Total Parts (\$\$)</b>	<b>4,533.90</b>	<b>889.12</b>

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	50.00	0.00
3	LABOUR FOR PANEL BEATING AND REPLACING PARTS	New	800.00	400.00
4	TO PUTTY AND SPRAY PAINTING	New	600.00	400.00
Gross Labour Cost (S\$)			1,500.00	820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >