

30/01/17


REF:

ASSIGNMENT

From _____ Date _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect vehicle No. _____
at Workshop no. _____
of _____
Insured _____
Policy No. _____
Claims No. _____
Sum Insured _____ Excess _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value: _____
IDAO Accident Report: _____ Consistent? : Yes or No
GIA / PR. Seen: _____ Consistent? : Yes or No
Est. Repairs: 2 days Res: Yes or No
Lum. Sum: 20 % S. Val: Yes or No

OA / REV / REP. / 24 HRS
Date: _____ Person Contacted _____ Vehicle: IN / OUT

Van No. BHC 3347U Regn 2011 Jon
Type: M.Car / M.Cycle / Bus / Van / Lorry ☒ Prime Mover
Truck / Trailer or _____
Make: Hyundai Sonata Yr: 1991
Colour: Blue A.O. Insured / Std / Nil / NA
Sp. Reading: 163898 T. Radio Insured / Std / Nil / NA
Eng. No: D4EAB935835
C.No: KMHET41VMBA 805567
Gen. Cond: ☒ Good / Fair / Poor / Burnt
Steering: ☒ In Order / Jammed / Leaked / Burnt or
Brake: ☒ In Order / Jammed / Leaked / Burnt or
Mod: Nil / S.Rim / STD A/Rim or
Tyre Size F: 015/60 R16
R: —
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Maxxis
Front Rear
R.Bal. S mm R.Bal. S mm
L.Bal. S mm L.Bal. S mm
D.O.A. 05/01/2018 D.O.I. 08/01/2018
Survey held at: CDGB Logon
Des. of Damages: Frt / Rear / O/S / N/S / U/O / Roof top or
H/S Front
The U/O / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction
Chine Taping & W 793R

Date/Time File Passed: ☐ : Prelim. Report
☐ : Final Report
Date/Time File Returned: _____
Report Format: _____
Lump Sum / B/L: \$ _____
Days Of Repair: _____
Resurvey No. of Trips: _____
Survey Fee: _____
Add Fee: ☐ Site Insp. \$ _____
☐ Night \$ _____
☐ Tech. Fee \$ _____
☐ Repairs \$ _____
Total: _____

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO305104429

MER COMFORT TRANSPORTATION PTE LTD 7010045 MER NO 383 SIN MING DRIVE SS Singapore SINGAPORE 575717 65508755 (R) (O) (P)	REGN NO:	SHC3347U	MILEAGE
	MAKE:	HYUNDAI	FUEL E.....1/2.....F
	MODEL	SONATA	DATE/TIME IN 06.01.2018 08:15
	YR OF MANU	29.01.2011	TARGET DATE
	CHASSIS CODE	KMHET41VMBA805567	COMPLETION DATE/TIME:

CHINA

UNT CARD NO.

JOB DESCRIPTION

cident Date: 05.01.2018
TURE: 3P 05.01.2018

NO	LABOR CODE	DESCRIPTION
----	------------	-------------

LED & PASSED OUT BY: _____

SERVICE ADVISOR	CUSTOMER'S SIGNATURE
-----------------	----------------------

edgement Slip

Exit Pass

io.: SHC3347U LKE/KALVIN

Vehicle No.: SHC3347U

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard