

SMRT Accident Vehicle Repair Estimates

Ca/A

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHD6071P
Ref. No : TAX/01/18/2031
Reg. Date : 01/11/2017
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS4
Name of Driver : LIM SOO KHOON
Type of Accident : SIDE SWIPE
Date / Time of Accident : 07/01/2018 10:56:00 AM
Accident Reported Date / Time : 08/01/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024093967
Special Instruction to ARC, if any :
SLJ6076Y / *Fus/Repair by paint*
Prepared Date : 08/01/2018 10:04:12 AM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU503573344

Mileage


: 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,183.00	0.00
Total Spray Painting Charges	: 1,494.00	0.00
Total Material Charges	: 3,274.42	3,274.42
Other Charges	: 700.00	0.00
TOTAL	: 6,651.42	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 7.00	0.00 7 days / part by part
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 08/01/2018 11:55:12 AM	01/01/1900 12:00:00 AM


10/01/18 1420

Prepared / Adjusted Date :

Remarks :

Prepared Date : 08/01/2018 11:20:49 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 1/8/2018 11:55:14 AM

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	1,183.00	0.00 800
Total Labour	1,183.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR LH	378.00	0.00 200
TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00 100
TO RESPRAY REAR DOOR LH	378.00	0.00 200
TO RESPRAY REAR FENDER LH	378.00	0.00 200
RESPRAY WHEEL CAP	180.00	0.00 X
Total Spray Painting & Panel Beating	1,494.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 60
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 60
TO TRANSFER DOOR MECHANISM	240.00	0.00 60
TO REMOVE / REFIT SEAT	120.00	0.00 80
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 40
Total Other Costs	700.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
6700247162			PANEL SUB-ASSY, FRONT DOOR LH	1	1,249.60	25.00	937.20	Replace	Replace PA <i>Repair</i>	No
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace <i>new</i>	No
7586047900			MOULDING ASSY, BODY ROCKER PANEL, LH	1	576.00	25.00	432.00	Replace	Replace <i>new</i>	No
6700447210			PANEL SUB-ASSY, REAR DOOR, LH	1	1,243.90	25.00	932.92	Replace	Replace <i>PA</i>	No
			PIXEL STICKER	1	60.00	0.00	60.00	Replace	Replace <i>new</i>	No
6160247160			PANEL SUB-ASSY, FENDER REAR LH	1	824.80	25.00	618.60	Replace	Replace <i>TURN</i>	No
6563847060			LINER, REAR FENDER, LH	1	135.80	25.00	101.85	Replace	Replace <i>?</i>	No
4260247180			CAP SUB-ASSY, WHEEL	1	175.80	25.00	131.85	Replace	Replace <i>new</i>	No
TOTAL MATERIALS								3,274.43	3,274.42	
TOTAL MATERIALS(Discounted)								3,274.42	3,274.42	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									