

Surveyor:
Meimien

REF: CS3 / MS618000552 / T1rd352

Special Instruction:

From (Person): Katherine Wong of MSH Date/Time: 02042018
Estimated Cost: Bill to:

US: \$4000.00

Third Parties:

Claimant:

Surveyor: AEON Auto

Workshop: Miracle Works

OD/TP Re-inspection / (Evaluation)

To Inspect Vehicle No: SAV 1757U Insured: SKH 5903P
at Workshop m/s Miracle Works Tel: 6385 5262.
of 48 Tuh Guan Rd East #04-126
Policy No: 272420935MP Claim No: 544992
Sum Insured: Excess:
Make of Veh: D.O.A. 08012018
(Client's Record)

Do Not Touch

Date/Time: Person Contacted: Vehicle IN / OUT
Date/Time: Confirmed with Final Fig days (Red \$ / %; Original 7 days)
Date/Time: 4/5/18 Submit Final Fig 4/5 82550, 5 days (Red \$ 1450 / 36 %; Original days)

Date/Time	Action/Instruction
	SAV 1757U - x
	SKH 5903P - x
	MV: 824,000, LTA: \$20,686.00, NV: \$3,314.00
	Submit PRs + Paper survey

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add
Transport
Photos
Others
Total

Date:

1) Date/Time 4/5/18 File Pass to typer

3) Date/Time File Pass to

5) Date/Time File Pass to

2) Date/Time File Return to

4) Date/Time File Return to

6) Date/Time File Return to

ASS. REC. BY

REF: CS3|MSG18000592|T1d3

12/21/2011

Date/Time: 09/01/2018 @ 4:56pm

Menemen Taufikh
Kathe

ASSIGNMENT (Office)

Meinungen Katharine Wong

MSIG

2015

Estimated Cost

Estimated Cost _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS
 SCV 1757U

1999, 2000, 2001, 2002, 2003, 2004, 2005, 2006, 2007, 2008, 2009, 2010, 2011, 2012, 2013, 2014, 2015, 2016, 2017, 2018, 2019, 2020, 2021, 2022, 2023, 2024, 2025, 2026, 2027, 2028, 2029, 2030, 2031, 2032, 2033, 2034, 2035, 2036, 2037, 2038, 2039, 2040, 2041, 2042, 2043, 2044, 2045, 2046, 2047, 2048, 2049, 2050, 2051, 2052, 2053, 2054, 2055, 2056, 2057, 2058, 2059, 2060, 2061, 2062, 2063, 2064, 2065, 2066, 2067, 2068, 2069, 2070, 2071, 2072, 2073, 2074, 2075, 2076, 2077, 2078, 2079, 2080, 2081, 2082, 2083, 2084, 2085, 2086, 2087, 2088, 2089, 2090, 2091, 2092, 2093, 2094, 2095, 2096, 2097, 2098, 2099, 2100, 2101, 2102, 2103, 2104, 2105, 2106, 2107, 2108, 2109, 2110, 2111, 2112, 2113, 2114, 2115, 2116, 2117, 2118, 2119, 2120, 2121, 2122, 2123, 2124, 2125, 2126, 2127, 2128, 2129, 2130, 2131, 2132, 2133, 2134, 2135, 2136, 2137, 2138, 2139, 2140, 2141, 2142, 2143, 2144, 2145, 2146, 2147, 2148, 2149, 2150, 2151, 2152, 2153, 2154, 2155, 2156, 2157, 2158, 2159, 2160, 2161, 2162, 2163, 2164, 2165, 2166, 2167, 2168, 2169, 2170, 2171, 2172, 2173, 2174, 2175, 2176, 2177, 2178, 2179, 2180, 2181, 2182, 2183, 2184, 2185, 2186, 2187, 2188, 2189, 2190, 2191, 2192, 2193, 2194, 2195, 2196, 2197, 2198, 2199, 2200, 2201, 2202, 2203, 2204, 2205, 2206, 2207, 2208, 2209, 2210, 2211, 2212, 2213, 2214, 2215, 2216, 2217, 2218, 2219, 2220, 2221, 2222, 2223, 2224, 2225, 2226, 2227, 2228, 2229, 2230, 2231, 2232, 2233, 2234, 2235, 2236, 2237, 2238, 2239, 2240, 2241, 2242, 2243, 2244, 2245, 2246, 2247, 2248, 2249, 2250, 2251, 2252, 2253, 2254, 2255, 2256, 2257, 2258, 2259, 2260, 2261, 2262, 2263, 2264, 2265, 2266, 2267, 2268, 2269, 2270, 2271, 2272, 2273, 2274, 2275, 2276, 2277, 2278, 2279, 2280, 2281, 2282, 2283, 2284, 2285, 2286, 2287, 2288, 2289, 2290, 2291, 2292, 2293, 2294, 2295, 2296, 2297, 2298, 2299, 2300, 2301, 2302, 2303, 2304, 2305, 2306, 2307, 2308, 2309, 2310, 2311, 2312, 2313, 2314, 2315, 2316, 2317, 2318, 2319, 2320, 2321, 2322, 2323, 2324, 2325, 2326, 2327, 2328, 2329, 2330, 2331, 2332, 2333, 2334, 2335, 2336, 2337, 2338, 2339, 2340, 2341, 2342, 2343, 2344, 2345, 2346, 2347, 2348, 2349, 2350, 2351, 2352, 2353, 2354, 2355, 2356, 2357, 2358, 2359, 2360, 2361, 2362, 2363, 2364, 2365, 2366, 2367, 2368, 2369, 2370, 2371, 2372, 2373, 2374, 2375, 2376, 2377, 2378, 2379, 2380, 2381, 2382, 2383, 2384, 2385, 2386, 2387, 2388, 2389, 2390, 2391, 2392, 2393, 2394, 2395, 2396, 2397, 2398, 2399, 2400, 2401, 2402, 2403, 2404, 2405, 2406, 2407, 2408, 2409, 2410, 2411, 2412, 2413, 2414, 2415, 2416, 2417, 2418, 2419, 2420, 2421, 2422, 2423, 2424, 2425, 2426, 2427, 2428, 2429, 2430, 2431, 2432, 2433, 2434, 2435, 2436, 2437, 2438, 2439, 2440, 2441, 2442, 2443, 2444, 2445, 2446, 2447, 2448, 2449, 2450, 2451, 2452, 2453, 2454, 2455, 2456, 2457, 2458, 2459, 2460, 2461, 2462, 2463, 2464, 2465, 2466, 2467, 2468, 2469, 2470, 2471, 2472, 2473, 2474, 2475, 2476, 2477, 2478, 2479, 2480, 2481, 2482, 2483, 2484, 2485, 2486, 2487, 2488, 2489, 2490, 2491, 2492, 2493, 2494, 2495, 2496, 2497, 2498, 2499, 2500, 2501, 2502, 2503, 2504, 2505, 2506, 2507, 2508, 2509, 2510, 2511, 2512, 2513, 2514, 2515, 2516, 2517, 2518, 2519, 2520, 2521, 2522, 2523, 2524, 2525, 2526, 2527, 2528, 2529, 2530, 2531, 2532, 2533, 2534, 2535, 2536, 2537, 2538, 2539, 2540, 2541, 2542, 2543, 2544, 2545, 2546, 2547, 2548, 2549, 2550, 2551, 2552, 2553, 2554, 2555, 2556, 2557, 2558, 2559, 2560, 2561, 2562, 2563, 2564, 2565, 2566, 2567, 2568, 2569, 2570, 2571, 2572, 2573, 2574, 2575, 2576, 2577, 2578, 2579, 2580, 2581, 2582, 2583, 2584, 2585, 2586, 2587, 2588, 2589, 2590, 2591, 2592, 2593, 2594, 2595, 2596, 2597, 2598, 2599, 2600, 2601, 2602, 2603, 2604, 2605, 2606, 2607, 2608, 2609, 2610, 2611, 2612, 2613, 2614, 2615, 2616, 2617, 2618, 2619, 2620, 2621, 2622, 2623, 2624, 2625, 2626, 2627, 2628, 2629, 2630, 2631, 2632, 2633, 2634, 2635, 2636, 2637, 2638, 2639, 2640, 2641, 2642, 2643, 2644, 2645, 2646, 2647, 2648, 2649, 2650, 2651, 2652, 2653, 2654, 2655, 2656, 2657, 2658, 2659, 2660, 2661, 2662, 2663, 2664, 2665, 2666, 2667, 2668, 2669, 2670, 2671, 2672, 2673, 2674, 2675, 2676, 2677, 2678, 2679, 2680, 26

SKH 5903P

To Inspect Vehicle No:

SGV 17574

100

SRH 59051
6385 5262

in Workshop 11's

Miracle Works

48, Toh Guan Rd East # 04-126

Claim No:

544992

Policy No.

27242093SMF

Forest

08/01/2018

Make of Veh
(Motor Record)

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

Nicole

1707

Date/Time: 10:01am @ 10/01/18

Person Contacted

Nicole

Date/Time:

X

SGV 17574 - X

91KH 5903P-X

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Jan 2018		09 Jan 2018 16:56 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	XIAO FANGMIN, ID: S2678810B		
Main Claimant:	RENT MY CAR PTE LTD, Co. Reg. No.: 201535871N		
Vehicle Reg. No.:	SGV1757U	Date of Loss:	08/01/2018 11:00 - :59
Claim Type:	TP / 544992	Policy/Cover Note No.:	27242093SMP Coverage: 23/12/2017 - 22/12/2018
Vehicle Reg. No. (Insured):	SKH5903P	Policy No. (Claimant):	
		Excess:	
Repairer:	Miracle Works Pte Ltd (HQ) 48 TOH GUAN ROAD EAST #04-126 ENTERPRISE HUB, 608586 Jurong West - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 10/01/2018]		

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									




883 North Bridge Road
#19-05 Southbank
Singapore 108785
T: 6292 5836
F: 6292 5838
(UEN No. 201333127N)
(GST Reg No. 201333127N)

Our Ref : CY.SGV1757U.18.MW(HW).wp(Lh)

Your Ref : Your insured vehicle SKH 5903P

09 January 2018



XIAO FANGMIN
c/o Motor Claims Department
MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way #21-01
SGX Centre 2
Singapore 068807

By Fax : 68277809 / 6643 1349


Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES SGV 1757U & SKH 5903P ON 08.01.2018 @ 11:45HRS ALONG BUKIT BATOK CENTRAL

We are instructed by M/S RENT MY CAR to notify you of a road traffic accident on 08.01.2018 @ 11:45hrs along Bukit Batok Central involving our client's customer's vehicle registration number SGV 1757U and vehicle registration number SKH 5903P driven by you at the material time. A copy of the Singapore accident statement report is enclosed.

As the result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully,


C. Yogarajah LLC
Enc

Cc: M/s/ Miracle Works Pte Ltd
48 Toh Guan Road East
#04 - 126 Enterprise Hub
Singapore 608586
Nicole (82045858 / 96472568 / 6385 5262)
Fax no : 6515 5434

Confidentiality & Privilege: This message is intended for the recipient to whom it is addressed. It may contain confidential or privileged information. If you are not the intended recipient, please notify the sender immediately by replying to this message and then delete it from your system. Do not read, copy, use or circulate this communication. **Disclaimer:** Mail/Fax/Internet communications are not secure. While every reasonable effort has been made to ensure that this communication has been securely transmitted and not been tampered with, C. Yogarajah LLC cannot be responsible for alterations made to the contents of this message without its express consent. If you wish to receive a hard copy of this communication for comparison or should you require any other form of confirmation of the contents of this message, please contact the sender. Opinions, conclusions and other information in this message that do not relate to the official business of the firm shall be understood as neither given nor endorsed by C. Yogarajah LLC Advocates & Solicitors. Thank you

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/01/2018 13:47
Date Of Accident	08/01/2018 11:45
Exact Location Of Accident	OPEN CARPARK BESIDES BUKIT BATOK CENTRAL @BLK 120
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGV1757U
Insured/Policyholder	
Name Of Registered Owner	RENT MY CAR PTE LTD
Co Reg No	201535871N
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91885017
Alternative Phone No	OFFICE-91885017

Vehicle Particulars

Manufacturer	HONDA
Model	JAZZ-1.4 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5074695065-02
Cover Note Number	

Driver

Name of Driver	MAS AHMAD FAHMI BIN MASMOHAMED
NRIC No	S9413985F
Date Of Birth	26/04/1994
Occupation	OUTDOOR
Date Of Driving Pass	20/09/2015
Driving Experience	2 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91885017
Fax Number	
Contact Number	OFFICE-91885017
Email Address	NOEMAIL

Address	450 BUKIT PANJANG RING ROAD #03-587
Postcode	S670450
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : - GENDER: : MALE
Passenger 2	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT BATOK NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 21 BUKIT BATOK EAST AVE 4 , POSTCODE: 659840 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-6659999 - FAX NO: 66655793
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACHED POLICE REPORT. ATTENDED BY : SUSAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKH5903P
Vehicle Make/Model/Colour	BMW
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	FENG YANYAN

NRIC/Passport Number

S2678811J

Contact Number

97480836

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time


Driver's Signature
(If driver is not the policyholder)
Date & Time:

9 JAN 2018

IDAC BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 659545
Tel: 6560 3312 Fax: 6569 0722
Email: vacbb@singnet.com.sg

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please Refer to Police Report

Report No: 7/20180108/2035

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time: _____



Driver's Signature
(If driver is not the policyholder)
Date & Time

9 JAN 2018

IDAC BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 659545
Tel: 6560 3312 Fax: 6569 0722
Email: vacbbb@singnet.com.sg

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____



SINGAPORE
POLICE FORCE



T/20180108/2035

Police Station Of Origin:
Bukit Batok NPP
103 Bukit Batok Central #01-00 SINGAPORE
650103
Tel No: 1800-5639999

1 of 3

Report No. T/20180108/2035

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 08/01/2018 12:38	Vide Report No.:	Station Diary No.: 14
--	------------------	--------------------------

Informant's Particulars

Name of Informant: MAS AHMAD FAHMI BIN MASMOHAMED			Address: APT BLK 450 BUKIT PANJANG RING ROAD #03-587 SINGAPORE 670450	
ID Type / ID No.: NRIC NO / S9413985F			Contact No.: Home/Office: Mobile: 91885017	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 23	Date of Birth: 26/04/1994	Type of Informant: Driver	
Race: Boyanese			Language: English	Institution / School Name:
Occupation: ICA OFFICER			Driving Licence Information: Class: 3,4 Date of Expiry:	

General Information of the Accident

Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 08/01/2018 11:45	Type of Location: Car Park
Location: Along Road 1 BUKIT BATOK CENTRAL				
OPEN SPACE CARPARK BESIDE BUKIT BATOK CC				
Weather: Clear		Road Surface: Wet		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: No Traffic
Type of Collision: Moving Vehicle Against - Others				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGV1757U	Car	HONDA	JAZZ	Blue	Slightly Damaged	2
SKH5903P	Car	BMW		Black	Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	



SINGAPORE
POLICE FORCE



T/20180108/2035

Police Station Of Origin:
Bukit Batok NPP
103 Bukit Batok Central #01-00 SINGAPORE
650103
Tel No: 1800-5639999

2 of 3

Report No. T/20180108/2035

CONTINUATION OF REPORT

Driver			
Name	MAS AHMAD FAHMI BIN MASMOHAMED	ID No.	S9413985F
Related Vehicle	SGV1757U (Car)	Contact No.	91885017
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	FENG YANYAN	ID No.	S2678811J
Related Vehicle	SKH5903P (Car)	Contact No.	97480836
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 08.01.2018 at about 1145hrs, I drove a rental car, a Blue Honda Jazz bearing plate number SGV1757U, into an open space carpark in between Blk 120 Bukit Batok Central and Bukit Batok CC. I came to a stop as there was one Black BMW bearing plate number SKH5903P which had came to stop. Subsequently, without any hazard light or indicators, the car made a reversed and it's rear right bumper hit onto my car's front right bumper which caused a dent. The driver informed me that she wanted to make a reverse into an empty lot. I already reported this accident to my car rental company and they informed to lodge an accident report.



SINGAPORE
POLICE FORCE



T/20180108/2035

3 of 3

Police Station Of Origin:
Bukit Batok NPP
103 Bukit Batok Central #01-00 SINGAPORE
650103
Tel No: 1800-5639999

Report No. T/20180108/2035

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Sgt 2 MOHAMMAD FIRDAUS BIN JAFFAR

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIA /

Staff Sgt TANG SIEW PING

Contact No.: 65476430

Authentication Stamp

Signature Of Informant:

Date/Time:

08/01/2018 12:38

Classification Of Case:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5871N
Vehicle Details	
Vehicle No.:	SGV1757U
Vehicle to be Exported:	No
Intended De-registration Date:	04 May 2018
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.4A
Primary Colour:	Blue
Manufacturing Year:	2007
Engine No.:	L13A54001802
Chassis No.:	JHMGD18507S222457
Maximum Power Output:	60.0 kW (80 bhp)
Open Market Value:	\$13,841.00
Original Registration Date:	06 Jun 2007
First Registration Date:	06 Jun 2007
Transfer Count:	2
Actual ARF Paid:	\$15,226.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	05 Jun 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$25,313.00
COE Rebate Amount:	\$20,686.00
Total Rebate Amount:	\$20,686.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 04 May 2018

OK

Depreciation = 6050.00/yr MV
= 504/mth

~~22K~~ 22.5K
24K.

20,686.00 +
504
21,190.00

Jan

4.5.18

MV

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years COE Renewal Toyota Altis 1.6A.



\$2800 Down Payment Monthly
From \$588 Onwards. Lowest
3.68% P.A. @ GV Cars Financing.
GV Credit Pte Ltd StarAd

Lake View
Credit Pte Ltd

view our c

- > Low prices guaranteed
- > Specialist in Japanese c
- > Easy loan approval
- > All terms are negotiable

Browse by Category

Sort by Date Posted

20 results/

Advanced Search

6 vehicles


Honda Jazz

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Stat
Search Selection	Honda Jazz		Any	Any	> 10 year(s) old	Any	Any	Any	Av
	Honda Jazz	Honda Jazz 1.3A (COE till 02/2021)	\$18,300	\$6,520 /yr	22-Feb-2006	1,339 cc	117,342 km	Hatchback	Av
Best Buy, High Paper Rebate, Low Mileage, Accident Free, Mechanically Well Maintained, Tip Top Driving Condition, Excellent Engine, Gearbox And Bodywork, Must View, Condition Assure, No Low Baller, Ke...									
Posted: 04-May-2018 Tags: 2006 Honda Jazz, Honda Jazz, Honda, Jazz, Used Honda									
	Honda Jazz	Honda Jazz 1.3A (COE till 05/2022)	\$26,800	\$6,590 /yr	29-May-2007	1,339 cc	157,000 km	Hatchback	Av
From \$3000 Drive Away! Bank In House Loan Available, Selling Near Export Value! "One Year In House Warranty!" With Official Warranty Certificate. Peace Of Mind, Fully Refurbished, Wear And Tear Replace...									
Carway Posted: 02-May-2018 Tags: 2007 Honda Jazz, Honda Jazz, Honda, Jazz, Used Honda									
	Honda Jazz	Honda Jazz 1.3A (COE till 06/2021)	\$19,000	\$6,010 /yr	11-Jul-2006	1,339 cc	145,480 km	Hatchback	Av
Direct Owner Sale, Prefer Dealing With Non Agents. Transact At LTA. Please Sms If No Replies.									
Posted: 22-Apr-2018 Tags: 2006 Honda Jazz, Honda Jazz, Honda, Jazz, Used Honda									
	Honda Jazz	Honda Jazz 1.3A (COE till 10/2020)	\$17,800	\$7,210 /yr	22-Oct-2005	1,339 cc	-	Hatchback	Av
Standard Honda Jazz - Works Well, Extremely Low Fuel Consumption.									
Posted: 21-Apr-2018 Tags: 2005 Honda Jazz, Honda Jazz, Honda, Jazz, Used Honda									
Car Buying			Car Selling			Car Ownership			
Car Aftermarket			On The Move			Lifestyle			
	Honda Jazz	Honda Jazz 1.3A (COE till 05/2022)	\$27,000	\$6,680 /yr	19-May-2007	1,339 cc	90,743 km	Hatchback	Av
Lady Owner, Clean And Neat Interior, Very Well-Maintain, Lowest Mileage In Market, Supreme Condition, Servicing Just Done, No Repairs Needed, Trade In Welcome, Viewing Straightly By Appointment Only, ...									
Posted: 11-Apr-2018 Tags: 2007 Honda Jazz, Honda Jazz, Honda, Jazz, Used Honda									
	Honda Jazz	Honda Jazz 1.3A (COE till 05/2022)	\$24,500	\$6,050 /yr	22-May-2007	1,339 cc	174,877 km	Hatchback	Av
Pink Jazz Is Up For Sale. Compact Car For Small Families. Great Performance. Hurry, Call Me Now.									
sd: 23-Mar-2018 Tags: 2007 Honda Jazz, Honda Jazz, Honda, Jazz, Used Honda									



Our Ref : CY.9711.18.MW(HW).wp(Lh)

Your Ref : 544992 ✓



21 March 2018

BY HAND

Motor Claims Department
MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way #21-01
SGX Centre 2
Singapore 068807

Dear Sirs

ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES SGV 1757U & SKH 5903P ON 08.01.2018 @ 11:45HRS ALONG BUKIT BATOK CENTRAL

We are instructed by **M/s Rent My Car Pte Ltd** to claim damages and losses against you in connection with the above-captioned road traffic accident which our client's vehicle **SGV 1757U** was damaged by vehicle **SKH 5903P** by your insured at the material time.

We are instructed that the said accident was caused by your insured's negligent driving and/or management of the vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

1) Repair Costs	\$ 4,000.00
2) Loss of Use	\$ 1,350.00
3) Survey Fee	\$ 450.00
4) LTA fee	\$ 7.49
5) Accident report fee	\$ 29.00
6) Costs & Incidental	\$ 800.00
7) GST on costs & Incidentals	\$ 56.00
	<u>\$ 6,692.49</u>

A copy each of the following supporting documents is enclosed:-

- 1) Accident report on our client's vehicle
- 2) Survey Report on SGV 1757U with coloured photographs
- 3) Final repair bill
- 4) LTA search on SKH 5903P

AKR, pu ak. d. CoP

done
22/3/18

We had on **09 January 2018** notified your company of the above accident and a pre-repair inspection was carried out by your appointed surveyor.

Please let us know within the next seven (7) days upon receipt of this letter whether you intend to re-inspect our client's vehicle failing which the said vehicle will no longer be available for the same.


(CY.9711.18.MW(HW).wp(Lh))

Page 2

Please note that you should send to us an acknowledgment of receipt of this letter within fourteen(14) days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against your insured without further notice to you.

Please note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

Yours faithfully



C. YOGARAJAH LLC
Enc

Cc XIAO FANGMIN
39 Mount Sinai Rise
#25 - 02
Singapore 276957
(Documents were enclosed to your insurers)



MIRACLE
BODYWORKZ

MIRACLE WORKZ PTE LTD

CO.REF: 201119510W
NO 48 TOH GUAN ROAD EAST
#04-126 ENTERPRISE HUB
SINGAPORE 608586
DIRECT LINE: 96472568
TEL: 64683096
FAX: 65155434

Attn: Motor Claims Department
MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Final Bill: MW-225-1757
Date: 09/03/2018
Vehicle No: SGV1757U
Make & Model: Honda Jazz 1.4 A
Accident Date: 08/01/2018
Third Party Vehicle: SKH5903P

S/N	DESCRIPTION	AMOUNT
1	REPAIR COST (LUMPSUM)	\$4,000.00

GRAND TOTAL \$4,000.00

Kindly make payment to : MIRACLE WORKZ PTE LTD



MIRACLE WORKZ PTE LTD



INVOICE

TO : RENT MY CAR PTE LTD
C/O MIRACLE WORKZ PTE LTD
48 TOH GUAN ROAD EAST, #04-126
ENTERPRISE HUB,
SINGAPORE 608586

Invoice No.: 118/MW462
Date: 30 JANUARY 2018

PARTICULARS

Vehicle Registration No.: SGV 1757 U
Date of Loss: 08 JANUARY 2018
Date of Assessment: 09 JANUARY 2018

SERVICES

FEES

1. Assessment with report Photographs - Including
films, developing, storage and Transport. \$450.00

TOTAL \$450.00

SINGAPORE DOLLARS FOUR HUNDRED FIFTY ONLY

We would appreciate your cheque crossed and made payable to:
"AEON AUTO CONSULTANTS LLP" with our invoice no. written on the back of
the cheque.

AEON AUTO CONSULTANTS LLP



AEON AUTO CONSULTANTS LLP

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874
Telephone +65 97687958 Facsimile +65 68264112 Email amas@aeonac.com
Reg. No. LL0701273L (registered with limited liability)

Enquire Vehicle & Owner Information (Vehicle No. SKH5903P As At 08 Jan 2018 / 11:45:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: CY.SGV1757U.18.HW.WP

Current Owner Details

Owner ID Type: Singapore NRIC
Owner ID: S2678810B
Owner Name: XIAO FANGMIN
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 39
Registered Street Name: MOUNT SINAI RISE
Registered Unit No.: # 25 - 02
Registered Building Name: -
Registered Postal Code: 276957

Current Vehicle Details

Vehicle No.: SKH5903P
Make Description/Model: B.M.W. / 528I 2.0L AT D/AB 2WD 4DR GAS/D NAV
Insurance Company Name: MSIG INSURANCE (SINGAPORE) PTE LTD

Thank you



Phee Lay San has successfully logged out.

Your last login date and time was 09 Jan 2018, 12:25:55.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

<u>S/No.</u>	<u>Asset Type</u>	<u>Asset ID</u>	<u>Asset Owner ID</u>	<u>Transaction Type</u>	<u>Transaction Amount(\$\$)</u>	<u>Log Date/Time</u>
1	Vehicle	SKH5903P	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	09 Jan 2018 / 12:26:30

AUTOMOBILE ASSESSMENT REPORT

TO: RENT MY CAR PTE LTD
C/O: MIRACLE WORKZ PTE LTD
48 TOH GUAN ROAD EAST, #04-126
ENTERPRISE HUB,
SINGAPORE 608586

Our Reference: 118/MW462
Date: 30 JANUARY 2018

ASSESSMENT OF VEHICLE NO. SGV 1757 U DATE OF LOSS: 08/12/2017

We have carried out a physical assessment of SGV1757U at **MIRACLE WORKZ PTE LTD**, 48 Toh Guan Road East, #04-126 Enterprise Hub, Singapore 608586, according to your instruction on 09 JANUARY 2018 and are pleased to submit our report herewith.

1. VEHICLE PARTICULARS

Registration No.:	SGV 1757 U
Make & Model:	HONDA JAZZ 1.4 A
Year of Registration:	2007
Engine Capacity:	1339
Chassis No.:	JHMGD18507S222457
Engine No.:	L13A54001802
Colour:	BLUE
Mileage (km):	233020

2. VEHICLE CONDITION

Body Paint:	GOOD
Steering:	SERVICEABLE
Foot Brake:	SERVICEABLE
Parking Brake:	SERVICEABLE
Modification:	NIL

3. TYRE PARTICULARS & CONDITION

Front

RH Make/Size/Thread:	HAIDA	195/50 R15 - 70%
LH Make/Size/Thread:	HAIDA	195/50 R15 - 70%

Rear

RH Make/Size/Thread:	KAPSEN	195/50 R15 - 70%
LH Make/Size/Thread:	KAPSEN	195/50 R15 - 70%


4. DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the FRONT portion.

5. REMARKS

Market Value: Na
Salvage Value: Na
Repair Limit: Na

Estimated Amount: \$ 5,837.04
Adjusted Amount: \$ 4,485.84 (Lump Sum of \$4,000.00)
Estimated Repair Days: 7 days



Pursuant to your instruction, we have **NOT AUTHORISED** repair.

The assessment was conducted on a "**Without Prejudice**" basis.

If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by Aeon Auto Consultants LLP for any reliance on this report by any third party.

ASSESSMENT REPORT FOR VEHICLE NO. SGV 1757 U

PARTS (LIST ITEMS)

Qty	Description	Condition	Workshop's Estimate	Our Assessment
1	FRONT BONNET	Repair	464.70	-
1	FRONT GRILLE	Cracked	121.60	nm X 121.60
1	FRONT GRILLE 'LOGO' EMBLEM	Necessary	22.90	nm X 22.90
1	FRONT RH HEADLAMP	Cracked	486.20	486.20
2	FRONT RH HEADLAMP CLIPS	Necessary	13.00	13.00
1	FRONT RH HEADLAMP LOWER BRACKET	Bent	26.70	26.70
1	FRONT BUMPER	Cracked	523.50	523.50
2	FRONT BUMPER AIR GRILLE L/R	Cracked	26.00	26.00
1	FRONT BUMPER LOWER CENTER GRILLE	Cracked	95.60	95.60
1	FRONT BUMPER REINFORCEMENT	Bent	158.40	158.40
2	FRONT BUMPER SIDE RETAINER L/R	Bent	22.00	22.00
1	FRONT BUMPER TOW HOOK COVER	Necessary	15.80	X nm 15.80
1	FRONT SUPPORT PANEL	Repair	374.00	-
1	WASHER TANK	Cracked	60.80	60.80
1	WASHER TANK CAP	Cut	9.00	9.00
1	WASHER TANK HOSE	Cut	11.00	11.00
1	WASHER TANK MOTOR	Faulty	62.60	nm X 62.60
1	WASHER TANK NECK	Cracked	21.90	21.90
1	FRONT RH FENDER	Bent	375.60	375.60
1	FRONT RH FENDER INNER PANEL	Repair	300.30	-
1	FRONT RH FENDER INNER SHIELD	Cracked	83.70	83.70
1	FRONT RH FENDER INNER SHIELD 'VERTICAL'	Cracked	17.00	17.00
3	FRONT RH FENDER INNER SHIELD 'VERTICAL' CLIPS	Necessary	19.50	19.50
3	FRONT RH FENDER QUATER GLASS INNER GARNISH CLIPS	Necessary	19.50	19.50

Less 20% discount

Parts Total:

3,331.30	2,192.30	1969.40
666.26	438.46	
2,665.04	1,753.84	1575.52

ASSESSMENT REPORT FOR VEHICLE NO. SGV 1757 U

SPECIAL NETT ITEMS

1	FRONT RH HEADLAMP 'BULB'	Cracked	40.00	40.00
1	FRONT RH HEADLAMP 'PARKING' BULB	Cracked	10.00	10.00
1	FRONT RH HEADLAMP 'SIGNAL' BULB	Cracked	12.00	12.00
1	FRONT RH FENDER INNER SHIELD CLIPS - SET	Necessary	30.00	30.00
1	FRONT RH FENDER QUATER GLASS SEALANT	Necessary	80.00	80.00
1	FRONT BUMPER CLIPS - SET	Faulty	30.00	30.00
1	ENGINE UNDER COVER CLIPS - SET	Necessary	30.00	30.00
Special Nett Total :			232.00	232.00

LABOUR

S/N	Description	Workshop's Estimate	Our Assessment
1	To remove, reinstall electrical wiring harness, check lighting and resetting.	120.00	100.00
2	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,300.00	1,100.00
3	To provide labour, workmanship to change the above damaged bodyparts, repair and re-construct consistent to the accident.	1,400.00	1,200.00
4	To apply anti-rust chemical on repaired and replaced panel.	120.00	100.00
Labour Total :		2,940.00	2,500.00
TOTAL (PARTS & LABOUR) \$		5,837.04	4,485.84

The workshop has agreed to undertake the repair on a Lump Sum basis. The final adjusted Lump Sum contract amount is **\$4,000.00** (SINGAPORE DOLLARS FOUR THOUSAND ONLY)



Amas Ong
Automobile Assessor

3195.52
4512550
5 days

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Jan 2018		09 Jan 2018 16:56 Edit Adj Rpt	S\$2,550.00 Edit Estimates	S\$2,550.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	XIAO FANGMIN, ID: S26788108		
Main Claimant:	RENT MY CAR PTE LTD, Co. Reg. No.: 201535871N		
Vehicle Reg. No.:	SGV1757U	Date of Loss:	08/01/2018 11:00 - :59 [127 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 544992	Policy/Cover Note No.:	27242093SMP Coverage: 23/12/2017 - 22/12/2018
Vehicle Reg. No. (Insured):	SKH5903P	Policy No. (Claimant):	
		Excess:	
Repairer:	Miracle Works Pte Ltd (HQ) 48 TOH GUAN ROAD EAST #04-126 ENTERPRISE HUB, 608586 Jurong West - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Imm.Advice due 10/01/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGV1757U (544992)
[SKH5903P]**

TP

RENT MY CAR PTE LTD

Jan 8 2018 11:00AM

[XIAO FANGMIN]

Miracle Works Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Assessment Reports

1 per page ☒

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/02/18 16:19	Accident Statement From: SC - Reg. No: SKH5903P, Claimant: XIAO FANGMIN	Load HTM	<input checked="" type="checkbox"/>

Photos/Images

3 per page ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/04/18 15:23	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
2	02/04/18 15:23	General View	Load JPG	<input checked="" type="checkbox"/>
3	02/04/18 15:23	General View	Load JPG	<input checked="" type="checkbox"/>
4	02/04/18 15:23	General View	Load JPG	<input checked="" type="checkbox"/>
5	02/04/18 15:23	General View	Load JPG	<input checked="" type="checkbox"/>
6	02/04/18 15:23	General View	Load JPG	<input checked="" type="checkbox"/>
7	02/04/18 15:23	General View	Load JPG	<input checked="" type="checkbox"/>
8	02/04/18 15:23	General View	Load JPG	<input checked="" type="checkbox"/>
9	02/04/18 15:23	General View	Load JPG	<input checked="" type="checkbox"/>
10	02/04/18 15:23	General View	Load JPG	<input checked="" type="checkbox"/>
11	02/04/18 15:23	General View	Load JPG	<input checked="" type="checkbox"/>
12	02/04/18 15:23	General View	Load JPG	<input checked="" type="checkbox"/>
13	02/04/18 15:23	General View	Load JPG	<input checked="" type="checkbox"/>
14	02/04/18 15:23	General View	Load JPG	<input checked="" type="checkbox"/>
15	02/04/18 15:23	General View	Load JPG	<input checked="" type="checkbox"/>
16	02/04/18 15:23	General View	Load JPG	<input checked="" type="checkbox"/>
17	02/04/18 15:23	General View	Load JPG	<input checked="" type="checkbox"/>
18	02/04/18 15:23	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
19	02/04/18 15:23	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
20	02/04/18 15:23	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
21	02/04/18 15:23	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
22	02/04/18 15:23	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
23	02/04/18 15:23	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
24	02/04/18 15:23	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
25	02/04/18 15:23	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
26	02/04/18 15:23	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
27	02/04/18 15:23	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
28	02/04/18 15:23	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
29	02/04/18 15:23	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
30	02/04/18 15:23	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
31	02/04/18 15:23	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
32	02/04/18 15:23	Photographs of Damaged Parts	Load JPG	✓
33	02/04/18 15:23	Photographs of Damaged Parts	Load JPG	✓
34	02/04/18 15:23	Photographs of Damaged Parts	Load JPG	✓
35	02/04/18 15:23	Photo After Spray	Load JPG	✓
36	02/04/18 15:23	Photo After Spray	Load JPG	✓
37	02/04/18 15:23	Photo After Spray	Load JPG	✓
38	02/04/18 15:23	Photo After Spray	Load JPG	✓
39	02/04/18 15:23	Photo After Spray	Load JPG	✓
40	02/04/18 15:23	Photo After Spray	Load JPG	✓
41	02/04/18 15:23	Photo After Spray	Load JPG	✓
42	02/04/18 15:23	Photo After Spray	Load JPG	✓
43	02/04/18 15:23	Photo After Spray	Load JPG	✓
44	02/04/18 15:23	Photo After Spray	Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	09/01/18 16:24	TP request for PRI	Load PDF	
2	09/01/18 16:53	TP REJECT SJE - assign LKK	Load PDF	
3	24/03/18 11:51	LOD - Repair bill -survey bill - LTA Search	Load PDF	
4	24/03/18 11:51	Survey report	Load PDF	
5	24/03/18 11:51	Survey Photo	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18000592/T1RD3S2
Date: 07/05/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 27242093SMP
Claimant Vehicle No : SGV1757U **Insured Vehicle No :** SKH5903P
Date of Loss: 08/01/2018 **Nature of Claim:** TP **Claim No:** 544992

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGV1757U**
 Make & Model: HONDA JAZZ, 1.4 (A) Engine No: L13A54001802
 Reg. Date: 06/06/2007 (Man. Year: 2007) Chassis No: JHMGD18507S222457
 Colour: Blue Odometer: 233023 km
 Engine Capacity: 1339 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/50R15 Rear Tyre Size: 195/50R15
 Front Left Side: KAPSEN 6 mm Rear Left Side: KAPSEN 6 mm
 Front Right Side: KAPSEN 6 mm Rear Right Side: KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,897.04	1,725.52	1,171.52	40.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,940.00	1,470.00	1,470.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,837.04	3,195.52	2,641.52	45.25
Approved Total (Overridden) (S\$)		2,550.00		
Nett Amount (S\$)	5,837.04	2,550.00	3,287.04	56.31

INSPECTION

Date of Assignment: 09/01/2018
 Date Inspected: 10/01/2018 Inspected At: Miracle Works Pte Ltd (HQ)
 48 TOH GUAN ROAD EAST #04-126 ENTERPRISE HUB
 Singapore 608586
 Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 May 2018)
Parts:	144	HONDA JAZZ 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGV1757U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	464.70 FL	*- FL
2	1		*FRONT GRILLE	Not Necessary	121.60 FL	*- FL
3	1		*FRONT GRILLE LOGO EMBLEM	Not Necessary	22.90 FL	*- FL
4	1		*FRONT RH HEADLAMP	Cracked	486.20 FL	*486.20 FL
5	2		*FRONT RH HEADLAMP CLIPS	Necessary	13.00 FL	*13.00 FL
6	1		*FRONT RH HEADLAMP LOWER BRACKET	Bent	26.70 FL	*26.70 FL
7	1		*FRONT BUMPER	Cracked	523.50 FL	*523.50 FL
8	2		*FRONT BUMPER AIR GRILLE L/R	Cracked	26.00 FL	*26.00 FL
9	1		*FRONT BUMPER LOWER CENTER GRILLE	Cracked	95.60 FL	*95.60 FL
10	1		*FRONT BUMPER REINFORCEMENT	Bent	158.40 FL	*158.40 FL
11	2		*FRONT BUMPER SIDE RETAINER L/R	Bent	22.00 FL	*22.00 FL
12	1		*FRONT BUMPER TOW HOOK COVER	Not Necessary	15.80 FL	*- FL
13	1		*FRONT SUPPORT PANEL	Repair	374.00 FL	*- FL
14	1		*WASHER TANK	Cracked	60.80 FL	*60.80 FL
15	1		*WASHER TANK CAP	Cut	9.00 FL	*9.00 FL
16	1		*WASHER TANK HOSE	Cut	11.00 FL	*11.00 FL
17	1		*WASHER TANK MOTOR	Not Necessary	62.60 FL	*- FL
18	1		*WASHER TANK NECK	Cracked	21.90 FL	*21.90 FL
19	1		*FRONT RH FENDER	Bent	375.60 FL	*375.60 FL
20	1		*FRONT RH FENDER INNER PANEL	Repair	300.30 FL	*- FL
21	1		*FRONT RH FENDER INNER SHIELD	Cracked	83.70 FL	*83.70 FL
22	1		*FRONT RH FENDER INNER SHIELD VERTICAL	Cracked	17.00 FL	*17.00 FL
23	1		*FRONT RH FENDER INNER SHIELD VERTICAL CLIPS	Necessary	19.50 FL	*19.50 FL
24	1		*FRONT RH FENDER QUARTER GLASS INNER GARNISH CLIPS	Necessary	19.50 FL	*19.50 FL
25	1		*FRONT RH HEADLAMP BULB	Not Necessary	40.00 FS	*- FS
26	1		*FRONT RH HEADLAMP PARKING BULB	Not Necessary	10.00 FS	*- FS
27	1		*FRONT RH HEADLAMP SIGNAL BULB	Not Necessary	12.00 FS	*- FS
28	1		*SET FRONT RH FENDER INNER SHIELD CLIPS	Necessary	30.00 FS	*30.00 FS
29	1		*FRONT RH FENDER QUARTER GLASS SEALANT	Necessary	80.00 FS	*60.00 FS
30	1		*SET FRONT BUMPER CLIPS	Faulty	30.00 FS	*30.00 FS
31	1		*SET ENGINE UNDER COVER CLIPS	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,563.30	2,119.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	666.26	393.88
Total Parts (\$\$)	2,897.04	1,725.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTNG.	New	120.00	30.00
2	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.	New	1,300.00	700.00
3	TO PROVIDE LABOUR, WORKAMNSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR AND RE-CONSTRUCT CONSISTENT TO THE ACCIDENT.	New	1,400.00	700.00
4	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.	New	120.00	40.00
Gross Labour Cost (\$\$)			2,940.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >