

FORM

ASS. REQ. BY:

REF:

CS3/MSG18000648/Gber

large

Special Instructions

ASSIGNMENT (Office)

Murimen

Person:

Monica chung

of

MSG

Date/Time:

11/01/18 @ 10:49am

Estimated Cost:

Bill to:

OD TP WS7 IP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBC 9012S

Insured:

SDN 1678S

at Workshop no:

Precise Auto

Tel:

6745 7367

at No. 1 kaki 8kt Ave 6 #02-34/36 Autobay

Policy No:

B27709425SMP

Claim No:

545 035

Sum Insured:

Excess:

Make of Veh:

Client's Record:

12/01/2018

DATE 09/01/2018

CA / REV / REP. / REV 24 HRS

'wup'

RECEIVED

Date/Time: 11:31am @ 11/01/18

Person Declared

Anne

STATUS IN OUT

Date/Time

Action/Remarks

X

REMARK

GBC 9012S-

SDN 1678S - CS3/AIG120004386/Res197

D.O.A : 1/03/2012

Dismantle Part : 15/01/2018

26/03/18 6:27pm Email to Monica Chung thru murimen

PKS Xmd.

MS19

12/01/2018

GBC 9012 S

24 Jan 2014

BS: 100%

12-13 V/S TRPES COPEES BVA 100%

12-13 V/S TRPES COPEES BVA 100%

12-13 V/S TRPES COPEES BVA 100%

12-13 V/S TRPES COPEES BVA 100%

12-13 V/S TRPES COPEES BVA 100%

12-13 V/S TRPES COPEES BVA 100%

12-13 V/S TRPES COPEES BVA 100%

12-13 V/S TRPES COPEES BVA 100%

12-13 V/S TRPES COPEES BVA 100%

12-13 V/S TRPES COPEES BVA 100%

12-13 V/S TRPES COPEES BVA 100%

12-13 V/S TRPES COPEES BVA 100%

12-13 V/S TRPES COPEES BVA 100%

12-13 V/S TRPES COPEES BVA 100%

12-13 V/S TRPES COPEES BVA 100%

12-13 V/S TRPES COPEES BVA 100%

12-13 V/S TRPES COPEES BVA 100%

12-13 V/S TRPES COPEES BVA 100%

12-13 V/S TRPES COPEES BVA 100%

12-13 V/S TRPES COPEES BVA 100%

12-13 V/S TRPES COPEES BVA 100%

12-13 V/S TRPES COPEES BVA 100%

Nissan NV200 1461

silver

96128

VSKYBAM2040071840

VSKYBAM2040071840

VSKYBAM2040071840

VSKYBAM2040071840

VSKYBAM2040071840

175/70 R14

175/70 R14

175/70 R14

Road stone

Road stone

Road stone

Road stone

Road stone

Road stone

Road stone

Road stone

Road stone

Road stone

Road stone

Road stone

Road stone

Road stone

Road stone

Road stone

Road stone

Road stone

Road stone

Road stone

Road stone

Road stone

Road stone

Road stone

Road stone

Road stone

Road stone

Road stone

Estimated repair range \$4,000 - \$5,300

26/3/2018

26/3/2018

26/3/2018

26/3/2018

26/3/2018



26/3/2018

26/3/2018

26/3/2018

26/3/2018

26/3/2018

26/3/2018

26/3/2018

26/3/2018

26/3/2018

26/3/2018

26/3/2018

26/3/2018

PKS




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|---|--|--------------------------|------------|---|
| MSIG INSURANCE (SINGAPORE) PTE LTD | | Ref : CS3/MSG18000648/Gb | | |
| 16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581 | | Date : 11-01-2018 | |  |
| | | Code : MSG | | |
| 1. Policy Particulars :- (THIRD PARTY CLAIM) | | | | |
| Insured Veh. | SDN 1678S | Veh. Inspected | GBC 9012S | |
| Policy No. | B27709425SMP | Coverage (\$) | 0.00 | |
| Claim No. | 545035 | Excess (\$) | 0.00 | |
| Assign From | MERIMEN (MONICA CHUNG) | Assign Date | 11/01/2018 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | | c.c | 0 | |
| Engine No. | HIDDEN | Year of Reg. | | |
| Chassis No. | | Colour | | |
| Odometer | - | Steering | | |
| Brakes | | Modification | | |
| General | | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | | | mm | |
| L/H Front Tyre | | | mm | |
| R/H Rear Tyre | | | mm | |
| L/H Rear Tyre | | | mm | |
| 4. Description of Damages | | | | |
| | | | | |
| 5. General Information | | | | |
| Accident Date | 09/01/2018 | Inspection Date | 12/01/2018 | |
| Survey held at | PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|-------------|---------------|--|---------|---------------|------------|--|
| Main | 09 Jan 2018 | | 11 Jan 2018 10:49 Assign | | | | New Assignment Cancel Case |

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

| | | | |
|-----------------------------|---|------------------------|---|
| Insured: | FOO KWEE YEW, ID: S7216857G, Tel: +6598756657, Email: NOEMAIL | | |
| Main Claimant: | SINGAPORE RADIO & INDUSTRY PTE LTD, Co. Reg. No.: 197702852M | | |
| Vehicle Reg. No.: | GBC9012S | Date of Loss: | 09/01/2018 08:00 - :59 |
| Claim Type: | TP / 545035 | Policy/Cover Note No.: | B27709425SMP (Comprehensive) Coverage: 16/05/2017 - 15/05/2018 |
| Vehicle Reg. No. (Insured): | SDN1678S | Policy No. (Claimant): | |
| | | Excess: | S\$1,250.00 |
| Repairer: | Precise Auto Service (HQ) No 1 Kaki Bukit Ave 6, #02-34/36, 417883 Kaki Bukit - Tel: 67457367 | | |
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552] | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/01/2018] | | |
| Driver/Custodian (Insured): | FOO KWEE YEW (45 / Male), NRIC: S7216857G, Tel: +6598756657 | | |
| Adj Asg. Remarks: | PRI SURVEY | | |

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

CHIA S ARUL LLC
ADVOCATES & SOLICITORS
UEN201330709H

ARULCHELVAN S

REG/CS/PAY/FA
09 JAN 2018

Our ref: GBC 9012 S (iz)

Your ref: SDN 1678 S

9 January 2018

MSIG Insurance (Singapore) Pte Ltd
Singapore

By Fax Only: 6225 7402

Dear Sirs,

**NOTICE TO INSURANCE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2
WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL
FOR NIMA CASE
ACCIDENT ON INVOLVING MOTOR VEHICLES GBC 9012 S AND SDN 1678 S
ALONG TRAFFIC JUNCTION ALONG YIO CHU KANG AND THOMSON HILL DRIVE
ON 9 JANUARY 2018**

We act for Singapore Radio and Industry Pte Ltd, the owner of motor vehicle GBC 9012 S who has appointed us to act on his behalf to claim against your insured's vehicle no. SDN 1678 S in regards to the road traffic accident on 9 January 2018.

Please be informed that the said motor vehicle can be inspected at:-

**Precise Auto Service
1 Kaki Bukit Avenue 6. #02-36
Autobay @ Kaki Bukit
Singapore 417883**

Kindly contact Ms Yan Hong at 6745 7367 to make the necessary arrangements.

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,

MR ARULCHELVAN S

Cc Precise Auto Service
Singapore

By Fax Only: 6841 3390

MSME18004478 / SME Motor Pte Ltd - Kaki Bukit
ENTRY DATE & TIME: 09/01/2018 17:51
SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 09/01/2018 17:51
Date Of Accident 09/01/2018 08:50
Exact Location Of Accident TRAFFIC JUNCTION ALONG YIO CHU KANG RD & THOMSON H
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBC9012S

Insured/Policyholder

Name Of Registered Owner SINGAPORE RADIO & INDUSTRY PTE LTD
Co Reg No 197702852M
Email Address NOEMAIL
Mobile Phone No
Alternative Phone No OFFICE-65523318

Vehicle Particulars

Manufacturer NISSAN
Model NV200
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company QBE INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 8-V0009493-MVA-R003
Cover Note Number

Driver

Name of Driver SEET CHYE GUAN
NRIC No S0236156F
Date Of Birth 22/12/1950
Occupation INDOOR
Date Of Driving Pass 18/10/1976
Driving Experience 41 YEARS AND 2 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-97889320
Fax Number
Contact Number
Email Address NOEMAIL

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

SINGAPORE RADIO & INDUSTRY PTE LTD

SEBET CHYE GUO

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

| | |
|----------------|---------|
| Owner ID Type: | Company |
| Owner ID: | 2852M |

Vehicle Details

| | |
|--------------------------------|---|
| Vehicle No.: | GBC9012S |
| Vehicle to be Exported: | No |
| Intended De-registration Date: | 15 Jan 2018 |
| Vehicle Make: | NISSAN |
| Vehicle Model: | NV200 1.5L MT ABS AIRBAG 2WD 6DR EURO 5 |
| Primary Colour: | Silver |
| Manufacturing Year: | 2013 |
| Engine No.: | K9KC400D052388 |
| Chassis No.: | VSKYBAM20U0071840 |
| Maximum Power Output: | - |
| Open Market Value: | \$19,232.00 |
| Original Registration Date: | 24 Jan 2014 |
| First Registration Date: | 24 Jan 2014 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$962.00 |

Intended PARF Rebate Details

| | |
|-------------------------------|--------|
| PARF Eligibility: | No |
| PARF Eligibility Expiry Date: | - |
| PARF Rebate Amount: | \$0.00 |

Intended COE Rebate Details

| | |
|----------------------|-------------------------|
| COE Expiry Date: | 23 Jan 2024 |
| COE Category: | C - Goods Vehicle & Bus |
| COE Period(Years): | 10 |
| QP Paid: | \$48,001.00 |
| COE Rebate Amount: | \$28,903.00 |
| Total Rebate Amount: | \$28,903.00 |

The information contained herein is correct as at 15 Jan 2018

OK

View Sent Message

This mail is associated with :

***GBC9012S (545035)**
[SDN1678S]

TP
SINGAPORE RADIO & INDUSTRY PTE LTD
Jan 9 2018 8:00AM
[FOO KWEE YEW]
Precise Auto Service

| | | | | |
|--------|-----------------|---------------|----------------|---------|
| Resend | View Recipients | Print Message | Delete Message | Forward |
|--------|-----------------|---------------|----------------|---------|

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 26/03/2018 18:27 PM.
To MSIG_CPZ
Subject Pre-repair Inspection

Dear Monica,

Refer to your assignment on 11.01.2018 at 1049AM.

Please be informed that we have inspected the vehicle GBC 9012S on 12.01.2018 at 5PM.

At the time of inspection the repairer did not present their estimation to the damaged vehicle.

We will submit our report accordingly.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--|--|--|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 09 Jan 2018 | | 11 Jan 2018 10:49 Edit Adj Rpt | S\$0.00 Edit Estimates | S\$0.00 View Rpt | | Pending for Survey Report Cancel Case |

| | | | | |
|-------------|------------------|----------------------|------------------|-----------------|
| Main | Reference | Claim Details | Documents | Show All |
|-------------|------------------|----------------------|------------------|-----------------|

































| CLAIM SUBFOLDER DETAILS | | [Created by Insurer] | | | |
|-----------------------------|---|------------------------|---|--|--|
| Insured: | FOO KWEE YEW, ID: S7216857G, Tel: +6598756657, Email: NOEMAIL | | | | |
| Main Claimant: | SINGAPORE RADIO & INDUSTRY PTE LTD, Co. Reg. No.: 197702852M | | | | |
| Vehicle Reg. No.: | GBC9012S | Date of Loss: | 09/01/2018 08:00 - :59 | | |
| Claim Type: | TP / 545035 | Policy/Cover Note No.: | B27709425SMP (Comprehensive) Coverage: 16/05/2017 - 15/05/2018 | | |
| Vehicle Reg. No. (Insured): | SDN1678S | Policy No. (Claimant): | | | |
| | | Excess: | S\$1,250.00 | | |
| Repairer: | Precise Auto Service (HQ) No 1 Kaki Bukit Ave 6, #02-34/36, 417883 Kaki Bukit - Tel: 67457367 | | | | |
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552] | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 12/01/2018] | | | | |
| Driver/Custodian (Insured): | FOO KWEE YEW (45 / Male), NRIC: S7216857G, Tel: +6598756657 | | | | |
| Adj Asg. Remarks: | PRI SURVEY | | | | |

| ASSOCIATED MAIL RECEIVED | | View All | Compose Case Mail |
|--|--|--------------------------|-----------------------------------|
| <ul style="list-style-type: none"> MSIG_SG (11/01/2018): Alert - Adj Mandate Approved (S\$4334.00) - GBC9012S - Claim Handler: Monica Chun... | | | |

| ALL ASSOCIATED TASKS | | View All | Search Tasks | Create New Task | Complete | | | | |
|----------------------|----------|--------------------------|------------------------------|---------------------------------|--------------------------|-------------|--------------|------------|-------|
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

***GBC9012S (545035)**
[SDN1678S]
TP
SINGAPORE RADIO & INDUSTRY PTE LTD
Jan 9 2018 8:00AM
[FOO KWEE YEW]
Precise Auto Service

| Upload Documents | | Upload Photos | Compose New Letter | View View in Browser <input type="button" value="v"/> | |
|----------------------------------|-----------------|--|---|--|-------------------------------------|
| Assessment Reports | | | | 1 per page <input type="button" value="v"/> | <input checked="" type="checkbox"/> |
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | | Thumbnail | Print |
| 1 | 11/01/18 10:48 | Accident Statement From:OD - Reg. No: SDN1678S, Claimant: FOO KWEE YEW |  | Load HTM | <input type="checkbox"/> |
| Photos/Images | | | | 3 per page <input type="button" value="v"/> | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail | Print |
| 1 | 26/03/18 18:25 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 2 | 26/03/18 18:25 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 3 | 26/03/18 18:25 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 4 | 26/03/18 18:25 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 5 | 26/03/18 18:25 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 6 | 26/03/18 18:25 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 7 | 26/03/18 18:25 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 8 | 26/03/18 18:25 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 9 | 26/03/18 18:25 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 10 | 26/03/18 18:25 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 11 | 26/03/18 18:25 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 12 | 26/03/18 18:25 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 13 | 26/03/18 18:25 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 14 | 26/03/18 18:25 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 15 | 26/03/18 18:25 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 16 | 26/03/18 18:25 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 17 | 26/03/18 18:25 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 18 | 26/03/18 18:25 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 19 | 26/03/18 18:25 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 20 | 26/03/18 18:25 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 21 | 26/03/18 18:25 | Chassis Number |  | Load JPG | <input checked="" type="checkbox"/> |
| 22 | 26/03/18 18:25 | Odometer Reading |  | Load JPG | <input checked="" type="checkbox"/> |
| 23 | 26/03/18 18:25 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 24 | 26/03/18 18:25 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 25 | 26/03/18 18:25 | General View |  | Load JPG | <input checked="" type="checkbox"/> |
| 26 | 26/03/18 18:26 | Photographs of Damaged Parts |  | Load JPG | <input checked="" type="checkbox"/> |
| 27 | 26/03/18 18:26 | Photographs of Damaged Parts |  | Load JPG | <input checked="" type="checkbox"/> |
| 28 | 26/03/18 18:26 | Photographs of Damaged Parts |  | Load JPG | <input checked="" type="checkbox"/> |
| 29 | 26/03/18 18:26 | Photographs of Damaged Parts |  | Load JPG | <input checked="" type="checkbox"/> |
| 30 | 26/03/18 18:26 | Photographs of Damaged Parts |  | Load JPG | <input checked="" type="checkbox"/> |
| 31 | 26/03/18 18:26 | Photographs of Damaged Parts |  | Load JPG | <input checked="" type="checkbox"/> |

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRdoc&fuseaction=dsp_doc... 28/3/2018

| | | | | | |
|----------------------|----------------|--|---|------------|-------------------------------------|
| 82 | 26/03/18 18:26 | Photographs of Damaged Parts | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 83 | 26/03/18 18:26 | Photographs of Damaged Parts | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 84 | 26/03/18 18:26 | Photographs of Damaged Parts | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 85 | 26/03/18 18:26 | Photographs of Damaged Parts | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 86 | 26/03/18 18:26 | Photographs of Damaged Parts | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 87 | 26/03/18 18:26 | Photographs of Damaged Parts | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 88 | 26/03/18 18:26 | Photographs of Damaged Parts | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 89 | 26/03/18 18:26 | Photographs of Damaged Parts | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 90 | 26/03/18 18:26 | Photographs of Damaged Parts | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 91 | 26/03/18 18:26 | Photographs of Damaged Parts | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 92 | 26/03/18 18:26 | Photographs of Damaged Parts | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 93 | 26/03/18 18:26 | Photographs of Damaged Parts | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 94 | 26/03/18 18:26 | Photographs of Damaged Parts | 1 | Load JPG | <input checked="" type="checkbox"/> |
| Documentation | | | | | |
| | | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | | Thumbnail | Print |
| 1 | 11/01/18 10:42 | TP GIA REPORT | 1 | Load PDF | |
| 2 | 11/01/18 10:43 | PRI FROM CHIA S ARUL | 1 | Load PDF | |
| 3 | 11/01/18 10:47 | WE REJECT TP SURVEYORS & APPOINT LKK TO BE THE SJE | 1 | Load PDF | |

Documents Checklist

| DOCUMENTS CHECKLIST | | Reset | Save | Print |
|--|--|-------|------|-------|
| There are no document checklists configured. | | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> | | | | |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | | | | |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18000648/GB

Date: 28/03/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: B27709425SMP
 Claimant Vehicle No: GBC9012S Insured Vehicle No: SDN1678S
 Date of Loss: 09/01/2018 Nature of Claim: TP Claim No: 545035

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBC9012S**
 Make & Model: NISSAN NV200, 1.5 (A) Engine No: K9KC400D052388
 Reg. Date: 24/01/2014 (Man. Year: 2013) Chassis No: VSKYBAM20U0071840
 Colour: Silver Odometer: 96128 km
 Engine Capacity: 1461 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 175/70 R14 Rear Tyre Size: 175/70 R14
 Front Left Side: Roadstone 6 mm Rear Left Side: Roadstone 6 mm
 Front Right Side: Roadstone 6 mm Rear Right Side: Roadstone 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---------------------------|-------------|-------------|-------------|--------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (\$\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

Date of Assignment: 11/01/2018
 Date Inspected: 12/01/2018 Inspected At: Precise Auto Service (HQ)
 No 1 Kaki Bukit Ave 6, #02-34/36
 Singapore 417883
 Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,800.00 -\$5,300.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 28 Mar 2018)

Parts: N/A NISSAN NV200 1.5 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBC9012S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

| |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >