

ASS. REC. BY:

REF: CS / ASM18000669 / Krbaz

Special Instruction:

HUNDY

Smart claim
From (Person):

Kenneth

Yvonne

ASSIGNMENT (Office)

Killy Teo Ang

of ASM

Date/Time: 11-01-2018 1003am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLJ 1844E

Insured:

at Workshop m/s

Midur Image

Tel:

9299 2683

of

No. 19 Tad Puyuh 8 Loring

Policy No:

Claim No:

S8M006ND

Sum Insured:

Excess:

\$600.00

Make of Veh:

D.O.A. 0301. 2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time:

11-01-2018 1030am

Person Contacted:

Sayed

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLJ 1844E - X

12/1/18

Sent preli through smart claim

Confirm \$2675.52 @ 4 days

Red: \$1392.96, 34%

ASS. REC. BY:

REF:

AXA/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OO/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA REV / REP. / 24 HRS

Date:

Person Contacted

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

12/1 PM 11:15 to 12:00

RECEIVED 20 AUG 2010

Date/Time, File Pass to?

1) Input

Date/Time, File Return to?

2)



: Prell. Report



: Final Report

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format:

OD

Lump Sum / I.B.I. (\$

2675.52

150
150



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/ASM18000669/Krb

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 11-01-2018



Code : ASM

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SLJ 1844E
Policy No.	Coverage (\$)	0.00
Claim No. S8M006ND	Excess (\$)	600.00
Assign From SMART CLAIM (KITTY TEO)	Assign Date	11/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 03/01/2018	Inspection Date 11/01/2018
Survey held at MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 SINGAPORE 319255	

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--



Service Request Details

Claim

S8M006ND

Reference

None 

Loss Date

January 3, 2018

Request Date

January 11, 2018

Due Date

January 18, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Incident Only

Services

Accelerated survey and authorize

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLJ1844E

Make

SUBARU

Service Address

19 Lorong 8 Toa Payoh, . . 319255

Primary Contact/Insured

KAH WEE EMILY TAN
BLK 237 #10-406, HOUGANG STREET 21, 530237, Singapore, Singapore

emilytkw@gmail.com

Claim Handler

Default Owner

Additional Instructions
EXCESS \$600

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

New Message

TYPE	
SENT	1/11/18 10:05 AM
FROM	Kitty TEO
SUBJECT	SLJ1844E - URGENT SURVEY
BODY	Hi Please survey car today. Thanks.



Your Ref: S8M006ND

Date: 12 January 2018

Our Ref: CS/ASM1S000669/Krb

The Motor Claims Department
AXA INSURANCE PTE LTD

Dear Sir/Madam,


PRELIMINARY ADVICE OF VEHICLE NO. SLJ 1844E

We thank you for the instruction on 11/01/2017

Please be informed that we had conducted the inspection of the abovementioned vehicle 11/01/2017 at the premises of m/s: MOTOR IMAGE ENTERPRISES PTE LTD and have the following to report:-

Repairer's Estimate (Gross)	: S\$ <u>4,068.48</u>
Revised Estimate Amount	: S\$ <u>2,675.52</u>
"Check" Items (Estimated)	: S\$ <u>599.04</u>
Total Repair (Estimated)	: S\$ <u>3,274.56</u>
Pre-Accident Value	: S\$ <u>96,000.00</u>
COE/PARF value	: S\$ <u>62,767.00</u>
Nett Value	: S\$ <u>33,233.00</u>

Description of Damage:
The vehicle sustained damages
at the n/s body.



Comments:
We have authorize repair.

Yours faithfully
KENNETH
Automotive Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0038F
Vehicle Details	
Vehicle No.:	SLJ1844E
Vehicle to be Exported:	No
Intended De-registration Date:	12 Jan 2018
Vehicle Make:	SUBARU
Vehicle Model:	FORESTER 2.0i-L CVT AWD SR
Primary Colour:	Brown
Manufacturing Year:	2016
Engine No.:	FB20Y491280
Chassis No.:	JF1S1J5KC5GG081076
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$16,896.00
Original Registration Date:	30 Nov 2016
First Registration Date:	30 Nov 2016
Transfer Count:	0
Actual ARF Paid:	\$16,896.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Nov 2026
PARF Rebate Amount:	\$12,672.00
Intended COE Rebate Details	
COE Expiry Date:	29 Nov 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,410.00
COE Rebate Amount:	\$50,095.00
Total Rebate Amount:	\$62,767.00

The information contained herein is correct as at 12 Jan 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/01/2018 12:07
Date Of Accident	03/01/2018 12:30
Exact Location Of Accident	SKYVUE CONDO BISHAN ST 15
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLJ1844E
Insured/Policyholder	
Name Of Registered Owner	TAN KAH WEE EMILY
NRIC No	S7230038F
Email Address	EMILYTKW@GMAIL.COM
Mobile Phone No	(LOCAL) +65-93680355
Alternative Phone No	HOME-66129794

Vehicle Particulars

Manufacturer	SUBARU
Model	FORESTER 2.0I-L CVT AWD SR

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA140390/1
Cover Note Number	

Driver

Name of Driver	TAN KAH WEE EMILY
NRIC No	S7230038F
Date Of Birth	28/08/1972
Occupation	INDOOR
Date Of Driving Pass	13/09/1995
Driving Experience	22 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-93680355
Fax Number	
Contact Number	HOME-66129794
Email Address	EMILYTKW@GMAIL.COM

HUSBAND (98505059).
MR BOO.

contact person

Address	BLK 237 HOUGANG ST 21 #10-406
Postcode	530237
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

* HIT BY BARRIER * PLEASE REFER TO ATTACHED STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

SKETCH PLAN**IMPORTANT NOTICE**

1. It is ~~your~~ your responsibility to report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The filing and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. The vehicle recording may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By completion of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be based outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature

Date & Time: 4/1/2018

12:25 pm


Driver's Signature

(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature

Name:
NIC/TIN No.:

SKETCH PLAN



StarVue Condo Entrance

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Condo Gantry Barrier came down and hit the left side car doors.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature

Date & Time: 4/1/2018
12:25 pm

Driver's Signature

(if driver is not the policyholder)

Print Name

[Signature]

Reporting Centre Personnel's Signature

Name:

Print Name



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 2 Motor Cars and Motor Tractors the weight of which together does not exceed 2000 kilograms

PASS DATE: 12 Sep 1995

NP 425A





redefining / insurance

AXA Insurance Pte Ltd
 1800 300 4555 (Within Singapore)
 (65) 6550 4555 (International)
 (65) 6580 4740
 customer.care@axa.com.sg
 www.axa.com.sg

Certificate of Insurance

Document number
 03926

Motor Vehicle (Third Party Risk and Compensation) Act (Chapter 132); Motor Vehicle (Third Party Risk and Compensation) Rules, 1967; Road Transport Act, 1967 (Malaysia); Motor Vehicle (Third Party Risk) Rules, 1979 (Malaysia)

Policy details

Policyholder name	TAN SAN WEE EMERY	Certificate number	GA140399 / 1
Cover	Comprehensive	Chassis number	JF11JH-C500051076
Plan name	Flexi	Engine number	7520-491280
NCD applicable	10%		
Vehicle registration number	SU1844E		
Period of insurance	from 30/11/2017 to 28/11/2018 (both dates inclusive)		
Finance loan company	UNITED OVERSEAS BANK LIMITED		

Persons or classes of persons entitled to drive*

- (a) The Policyholder
- (b) Any Licensed Driver as stated in this Policy
 - 1. FOO SIEW HUI
- (c) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover - use for hire or reward, racing, stunting, driving, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade or when the Motor Car, whether stationary, in use or otherwise, is in or on a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, stunting or such similar purposes.

* Limitations referred to above by Section 8 of the Motor Vehicle (Third Party Risk and Compensation) Act (Chapter 132) and Section 93 of the Road Transport Act, 1967 (Malaysia) are not to be construed under these headings.

EXCESS Excess Own Damage Excess
 Windscreen Excess

RM 5000
 RM 5000

An additional excess is applicable as follows:

1. \$5500 for unnamed Authorized Driver
2. \$4500 for declared young and inexperienced Driver
3. \$45 000 for undetected young and inexperienced Driver. This additional excess is reduced to \$62 500 if you have chosen AXA Premium Workplaces.

Additional clauses & endorsements to your policy

Nil

We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicle (Third Party Risk and Compensation) Act (Chapter 132) and Part IV of the Road Transport Act, 1967 (Malaysia).

AXA Insurance Pte Ltd

Authorized signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third Party Risk and Compensation) Act (Cap. 132).

The Premium Security Clause requires the premium to be paid in full within a specific period, failing which there could be no liability under the policy without sufficient arrangements.

AXA Insurance Pte Ltd (199803512M)
 8 Shenton Way #24-01, AXA Tower
 Singapore 068811
 Customer Centre #21-01

1 of 3

Date:

04/01/18

To: Owner of Vehicle Number

SLJ1844E

The following has been advised to you via your workshop, their staff


EDGE

through

Please tick the applicable box if you had been advised on the content as seen below:

- ☒ You had been advised by the workshop that in the event that you wish to claim against your own policy, there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.
- ☒ You had been advised by the workshop on the liability and merits of the case accordingly.
- ☐ You had been advised by the workshop on the claims procedure for the type of claim that you will be making due to this accident.
- ☐ There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to import it from overseas.
- ☐ The estimated waiting time for the spare parts to arrive is _____
The estimated arrival time does not include the repair period.
- ☐ You will be driving the vehicle out despite being advised by the workshop mechanic personnel that the vehicle may not be road worthy.
- ☐ For vehicles below Three (3) years old, your insurance company will use only genuine or parts to repair your vehicle.
- For vehicles above Three (3) years old, your insurance company will be carrying out repair using any combination of genuine original parts and/or original equipment manufacturer (OEM) parts.
- ☐ You had been advised by the workshop of the Twelve (12) months warranty for Own repair on workmanship related to the accident.
- ☐ For vehicles below Five (5) years old, you had been advised by the workshop to check local distributor on your warranty status.
- ☐ Other _____

Signed and acknowledged by:



Emily Tan Kah Wee

Name and signature of policyholder/ authorised driver



Name and signature of workshop personnel including company stamp

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



MOTORIMAGE ENTERPRISES PTE. LTD.
19 LOMONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64738333
REFERENCE : IRS/IC/CHI/0576/2018
DATE : 04-JAN-2018

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 6338 7288
FAX : 6880 4838/6338 2522
MS LINA EXT: E24

OWNER'S NAME : EMILY TAN KAH WEE
ADDRESS : APT BLK 237 HOUGANG STREET 21
#10-406
S(530237)
TELEPHONE NO : 93680355

TYPE OF CLAIM : COMPREHENSIVE CLAIM
POLICY NO : GA140390/1
VEHICLE NO : SLJ1844E
MODEL CODE : S25DK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20Y491280
CHASSIS NO : JF1SJSKC5GG881076
MILEAGE : 1 KM
DATE IN : 04/01/2018
LIABILITY : 0.00
EXCESS CLAUSE : 600.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 03/01/2018

Print Date : 06/01/2018
Print Time : 15:46:46

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLJ1944E

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	00CLAIM	CONDUCT BODYWORK REPAIR (OWN DAMAGE CLAIM)		
2	22/001	CONDUCT OD CLAIM LOCATION:SKYVUE CONDO BISHAN BT 15 DATE:03/01/2018 TIME:1230H		
3	22/002	REPLACE/REPAIR LH FRTOOR,LH RR DOOR	1120.00	840 ✓
4	22/003	RESPRAY LH FRT DOOR,LH RR DOOR	840.00	✓
5	22/004	TRANSFER DOOR(PER SIDE)MECHANISM	400.00	280 ✓
6	22/005	SUNDRIES	100.00	20 ✓
TOTAL LABOUR CHARGES			2460.00	

MOTOKIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLJ1844E

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES				REMARKS
			NETT	LIST	S/NETT	S/LIST	
1	FRT FENDER LH	57120800309P	270.00	X			
2	PNL COMPL DR R LH	60409800119P	684.00	✓			
3	HANDLE DR OUT	61160FJ010V2	144.00	✓			
4	WSTR OUT DR F LH	(2) PDISLOC.1PC 61280SG030	100.80	7			
5	WSTR OUT DR R LH	62280SG030	100.80	7			
6	WSTR DR F LH	635118G011	144.00	7			
7	WSTR DR R LH	635138G011	144.00	7			
8	GLASSRUN DR R LH	635278G030	72.00	7			
9	GLASSRUN F DR LH	635278G110	72.00	7			
10	WSTR BODY SD FLG F	635718G001	122.40	7			
11	WSTR BODY SD FLG R	635728G001	72.00	7			
12	TAPE DR SASH F F LH	904228G010	5.40	✓			
13	TAPE DR SASH F M LH	904228G030	18.00	✓			
14	TAPE DR SASH F R LH	904228G050	18.00	✓			
15	TAPE DR SASH R F LH	DT 1PC 904228G070	18.00	7			
16	TAPE DR SASH R M LH	904228G090	10.80	7			
17	TAPE DR SASH R R LH	904228G110	14.40	7			
SUB TOTAL			2010.60	0.00	0.00	0.00	
LESS DISCOUNT (NETT-20 %)			402.12	0.00	0.00	0.00	
GRAND TOTAL			1608.48	0.00	0.00	0.00	
OVERALL TOTAL			1608.48				

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLJ1844E

TOTAL LABOUR CHARGES	2460.00
TOTAL SPARE PARTS CHARGES	1608.48
GRAND TOTAL	4068.48 *

* All charges do not include GST.

SURVEYOR'S PARTICULARS

NAME	:
SURVEYED DATE	:
AUTHORIZED DATE	:
EXCESS CLAUSE	: 600.00
LIABILITY	: 0.00
REMARKS	:

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

Authorised
Penny B4pam
Ex 860d

4da1

Liak Auto Consultants hence notify the Repairer of the following:

- To repair by following the work order
- To display damaged parts during recovery
- Parts should be replaced on a "No Fault" basis
- To provide a copy of the "No Fault" basis
- To provide a copy of the "No Fault" basis
- To provide a copy of the "No Fault" basis

By Repairer

Kr

MYTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

FINALIZED : ACCIDENT/BOOD REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0576/2018
DATE : 04-JAN-2018

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 6338 7288
FAX : 6880 4838/6338 2522
MS LINA EXT: 824

OWNER'S NAME : EMILY TAN KAH WEE
ADDRESS : APT BLK 237 HOUGANG STREET 21
#10-406
S(530237)
TELEPHONE NO : 93680355

TYPE OF CLAIM : COMPREHENSIVE CLAIM
POLICY NO : GA140390/1
VEHICLE NO : SLJ1844E
MODEL CODE : SJSUKJC
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20Y491280
CHASSIS NO : JF1SJS5RC5GG081076
MILEAGE : 1 KM
DATE IN : 04/01/2018
LIABILITY : 0.00
EXCESS CLAUSE : 600.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 03/01/2018

Print Date : 27/06/2018
Print Time : 20:21:12

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLJ1844E

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ODCLAIM	CONDUCT BODYWORK REPAIR (OWN DAMAGE CLAIM)		
2	ZZ/001	CONDUCT OD CLAIM LOCATION:SKYVUE CONDO BISHAN ST 15 DATE:03/01/2018 TIME:1230H		
3	ZZ/002	REPLACE/REFIX LH FRDOR,LH RR DOOR	1120.00	840.00
4	ZZ/003	RESFRAY LH FRD DOOR,LH RR DOOR	840.00	840.00
5	ZZ/004	TRANSFER DOOR(PER SIDE)MECHANISM	400.00	280.00
6	ZZ/005	SUNDRIES	100.00	20.00
TOTAL LABOUR CHARGES			2460.00	1980.00

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLJ1844E

S/NO PARTS DESCRIPTION		PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	FRT FENDER LH	57120SG0309P	270.00			X
2	PNL COMPL DR R LH	60409SG0119P	684.00			OK
3	HANDLE DR OUT	61160FJ010V2	144.00			OK
4	WSTR OUT DR F LH	(2) PDI@LOC.1PC 61280SG030	100.80			X
5	WSTR OUT DR R LH	62280SG030	100.80			X
6	WSTR DR F LH	63511SG011	144.00			X
7	WSTR DR R LH	63512SG011	144.00			X
8	GLASSRUN DR R LH	63527SG030	72.00			X
9	GLASSRUN F DR LH	63527SG110	72.00			X
10	WSTR BODY SD FLG F	63571SG001	122.40			X
11	WSTR BODY SD FLG R	63572SG001	72.00			X
12	TAPE DR SASH F F LH	90422SG010	5.40			OK
13	TAPE DR SASH F M LH	90422SG030	18.00			OK
14	TAPE DR SASH F R LH	90422SG050	18.00			OK
15	TAPE DR SASH R F LH	DT 1PC 90422SG070	18.00			X
16	TAPE DR SASH R M LH	90422SG090	10.80			X
17	TAPE DR SASH R R LH	90422SG110	14.40			X
SUB TOTAL			869.40	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			173.88	0.00	0.00	0.00
GRAND TOTAL			695.52	0.00	0.00	0.00
OVERALL TOTAL			695.52			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MYTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLJ1844E

NETT ITEM	869.40
LESS 20 %	-173.88
NETT AMOUNT	695.52

LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00

SPECIAL NETT AMOUNT	0.00
---------------------	------

S/LIST ITEM	0.00
LESS 30 %	0.00
S/LIST AMOUNT	0.00

TOTAL LABOUR CHARGES	1980.00
TOTAL SPARE PARTS CHARGES	695.52

TOTAL CHARGES	2675.52
LESS EXCESS	600.00

TOTAL	2075.52
ADD 7 % GST	145.29

GRAND TOTAL	2220.81
-------------	---------



Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 319255
T (65) 6417 0333 F (65) 6252 5655
W www.motorimage.net
Co Reg No: 198702032R

DISCHARGE VOUCHER

Name of Insured: EMILY TAN KAH WEE
Address of Insured: BLK 237 HOUGANG STREET 21 #10-406 S(530237)
Name of Repairs: MOTOR IMAGE ENTERPRISES PTE LTD / WORKSHOP
Address of Repairs: NO. 19 LORONG 8 TOA PAYOH SINGAPORE 319225
Place of Accident: SKYVUE CONDO BISHAN ST 15
Date of Accident: 03/01/2018 Vehicle No: SLJ1844E
Policy No: GA140390/1 Claim No: _____

I/We hereby declare that I/We have received from the aforesaid repairers my/our aforesaid Motor Vehicle in good running order and repaired to my/our entire satisfaction and in consideration of AXA INSURANCE PTE LTD settling the repair costs stated above with the said repairers, I/We hereby release and discharge the said insurers from all further obligations and liabilities under the aforesaid policy in respect on and accident involving my/our said motor vehicle on or about the abovementioned date and place.

I/We agree that by virtue of such payment, all my/our rights and remedies in respect of the damages to the said Motor Vehicle are subrogated to the said Insurers in accordance with the laws governing such matters.

I/We hereby grant the said insurers the authority to use my/our name to the extent necessary to effectively exercise all or any of such rights and remedies including the right to give discharge and receipts therefore.

I/We further agree to furnish the said Insurers with any assistance that they may reasonably require of me/us when exercising such rights and remedies whilst on their parts they agree to indemnify me/us against liability for costs charges and expenses arising in connection with any proceedings which they may take in my/our name in the exercise of such rights and remedies.

REPAIRERS:

Company's Chop & Signature

SAYEDINAH ALI

Name

17/01/2018

Date

INSURED:

S7230038F

IC No. & Signature/Company's Chop

EMILY TAN KAH WEE

Name

17/01/2018

Date

MotorImage



Motor Image Enterprises Pte Ltd
 19 Lorong 8 Toa Payoh Singapore 319255
 Service Centre Tel: (65) 6703 8101 / 102 Fax: (65) 6253 5535
 25 Leng Kee Road Singapore 159097
 Service Centre Tel: (65) 6703 8163 Fax : (65) 6479 1137
 Website: www.motorimage.net



TAX INVOICE

GST Reg No. M2-0076975-9
 Co. Reg No. 198702032R

Sales: INSURANCE CUSTOMER

Invoice No: L481375

**For cash sales, payment will be
 endorsed on this invoice and no
 separate receipt will be issued.**

DATE REC'D: 13-Jan-2018

SERVICE ADVISOR: SAYED

JOB No.: L474313

MILEAGE: 20712

ID:

NAME: AXA INSURANCE PTE LTD
ADDRESS: 8 SHENTON WAY
#27-01 AXA TOWER. S(068811)
TELEPHONE: 63387288
MODEL: FORESTER 2.0I-L AWD CVT
ENGINE No.: FB20Y491280
CHASSIS No.: JF1SJ5KCSGG081076
REGISTRATION No.: SLJ1844E

ITEMS CODE	DESCRIPTION OF REPAIRS	AMOUNT
1	ODCLAI CONDUCT BODYWORK REPAIR (OWN DAMAGE CLAIM)	
2	REMARK CONDUCT OD CLAIM LOCATION:SKYVUE CONDO BISHAN ST 15 DATE:03/01/2018 TIME:1230H	
3	REMARK REPLACE/REFIX LH FRTDOOR,LH RR DOOR	840.00
4	REMARK RESPRAY LH FRT DOOR,LH RR DOOR	840.00
5	REMARK TRANSFER DOOR(PER SIDE)MECHANISM	280.00
6	REMARK SUNDRIES	20.00
7	INS01 FOR ACCIDENT CAR OR REPAIR JOB QUOTATION, AN ADMINISTRATIVE CHARGE WILL BE IMPOSED IF VEHICLE	
8	INS02 IS WITHDRAW AND TOWED OUT FOR REPAIR. REFER TO STANDARD RATE CHART (REF. 0338).	
9	INS03 STORAGE CHARGES OF \$30/DAY WILL BE IMPOSED FROM THE DATE OF CONFIRMATION OF AUTHORISATION BY THE	
10	INS05 INSTRUCTIONS WILL BE TAKEN FROM THE OWNER ONLY. IF IT IS NOT POSSIBLE, AN AUTHORISATION LETTER FROM	
11	INS06 THE OWNER IS REQUIRED.	
12	INS07 CUSTOMER ARE INFORMED AND ACCEPT THAT NUMBER OF DAYS FOR LOSS OF USE IS BASE ON THE FOLLOWING:	
13	INS08 NO.OF DAYS FOR LOSS OF USE RECOMMENDED BY INS.CO. APPOINTED SURVEYOR NO FURTHER CLAIM CAN BE ALLOWED	
14	INS09 CUST ACK THAT CLAIMS NOT EXCEEDING \$3,000 & ABOVE WILL HAVE TO BE REFER TO FIDREC DIRECTLY.	
	TOTAL(LABOUR)	1,980.00
1	PNL COMPL DR R LH 60409SG0119P(Qty : 1 @ 684.00 each(Discount 20.00%))	547.20
2	HANDLE DR OUT 61160FJ010V2(Qty : 1 @ 144.00 each(Discount 20.00%))	115.20
3	TAPE DR SASH F F LH	4.32



Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 319255
Service Centre Tel (65) 64170100/101 Fax (65) 62535535
25 Leng Kee Road Singapore 159097
Service Centre Tel (65) 64764776 Fax (65) 64791137
Website: www.motorimage.net



TAX INVOICE

GST Reg No. M2-0076975-9
Co. Reg No. 198702032R

Sales: INSURANCE CUSTOMER

Invoice No: L481375

**For cash sales, payment will be
endorsed on this invoice and no
separate receipt will be issued.**

DATE REC'D: 13-Jan-2018

SERVICE ADVISOR: SAYED

JOB No.: L474313

MILEAGE: 20712

ID:

NAME: AXA INSURANCE PTE LTD
ADDRESS: 8 SHENTON WAY
#27-01 AXA TOWER, S(068811)
TELEPHONE: 63387288
MODEL: FORESTER 2.0I-L AWD CVT
ENGINE No.: FB20Y491280
CHASSIS No.: JF1SJ5KC5GG081076
REGISTRATION No.: SLJ1844E

ITEMS CODE	DESCRIPTION OF REPAIRS	AMOUNT
	90422SG010(Qty : 1 @ 5.40 each(Discount 20.00%))	
4	TAPE DR SASH F M LH	14.40
	90422SG030(Qty : 1 @ 18.00 each(Discount 20.00%))	
5	TAPE DR SASH F R LH	14.40
	90422SG050(Qty : 1 @ 18.00 each(Discount 20.00%))	
	TOTAL(SPARE PARTS)	695.52
	less INSURANCE EXCESS	600.00

Subtotal 2,075.52
GST(7%) 145.29
TOTAL \$2,220.81

DATE : 14-Aug-2018

CUSTOMER

MANAGER

The customer acknowledges and confirms by taking delivery of the vehicle and/or upon receipt of this invoice, either personally or by an agent that his/her complaints relating to the vehicle have been rectified to his/her satisfaction and that the Company's liability for defective work and/or materials will be limited to rectification works and/or replacement of parts without charge or at discounted charge, at the Company's option. The customer further acknowledges that any discrepancy in this invoice (with the exception of errors and omissions) must be brought to the Company's attention in writing within three(3) days from the date of this invoice falling which it will be deemed correct.

CUSTOMER

Not yet a DUO Member? Join us now at www.DUO.com.sg and start accumulating your points for your invoice today!



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CS/ASM18000669/Krbe2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN : KITTY TEO			Date : 09-10-2018	
			Code : ASM	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected		SLJ 1844E
Policy No.	GA140390/1	Coverage (\$)	0.00	
Claim No.	S8M006ND	Excess (\$)	600.00	
Assign From	KITTY TEO	Assign Date	11/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	SUBARU FORESTER (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JF1SJ5KC5GG081076	Colour	METALLIC GREY	
Odometer	20712	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/60 R17	YOKOHAMA	8 mm	
L/H Front Tyre	225/60 R17	YOKOHAMA	8 mm	
R/H Rear Tyre	225/60 R17	YOKOHAMA	8 mm	
L/H Rear Tyre	225/60 R17	YOKOHAMA	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/01/2018	Inspection Date	11/01/2018	
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 SINGAPORE 319255			
5a. Remarks				
A) THE MARKET VALUE IS S\$96,000.00 (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 1844E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRT FENDER LH (N)	TO REPAIR SEE LABOUR	270.00	-
1	PNL COMPL DR R LH (N)	BENT	684.00	684.00
1	HANDLE DR OUT (N)	DISTORTED	144.00	144.00
1	WSTR OUT DR F LH (N)	SERVICEABLE	100.80	-
1	WSTR OUT DR R LH (N)	SERVICEABLE	100.80	-
1	WSTR DR F LH (N)	SERVICEABLE	144.00	-
1	WSTR DR R LH (N)	SERVICEABLE	144.00	-
1	GLASSRUN DR R LH (N)	SERVICEABLE	72.00	-
1	GLASSRUN F DR LH (N)	SERVICEABLE	72.00	-
1	WSTR BODY SD FLG F (N)	SERVICEABLE	122.40	-
1	WSTR BODY SD FLG R (N)	SERVICEABLE	72.00	-
1	TAPE DR SASH F F LH (N)	NECESSARY	5.40	5.40
1	TAPE DR SASH F M LH (N)	NECESSARY	18.00	18.00
1	TAPE DR SASH R F LH (N)	NECESSARY	18.00	18.00
1	TAPE DR SASH R F LH (N)	NOT NECESSARY	18.00	-
1	TAPE DR SASH R M LH (N)	NOT NECESSARY	10.80	-
1	TAPE DR SASH R R LH (N)	NOT NECESSARY	14.40	-
	LESS 20% DISCOUNT		-402.12	-173.88
			1,608.48	695.52
	SPECIAL NETT ITEMS			
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
			100.00	20.00
	LABOUR			
	REPLACE / REFIX LH FRT DOOR, LH RR DOOR. INCLUSIVE OF THE REPAIR OF FRT FENDER LH.		1,120.00	840.00
	RESPRAY LH FRT DOOR, LH RR DOOR.		840.00	840.00
	TRANSFER DOOR (PER SIDE), MECHANISM.		400.00	280.00
			2,360.00	1,960.00
	GRAND TOTAL		4,068.48	2,675.52

Report Ref No. CS/ASM18000669/Krbe2



RECOMMENDED COST OF REPAIRS			2,675.52
LESS EXCESS			-600.00
NETT LIABILITY			2,075.52

Report Ref No. CS/ASM18000669/Krbe2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.