



Your Ref: MT/CA/TP/003/0958057-002

Date: 24<sup>th</sup> January 2018

Our Ref: CS3/AIG17016118/Svbs2-1

**M/s NTUC Income Insurance Co-Operative Ltd**

73 Bras Basah Road  
#05-01 NTUC Trade Union House  
Singapore 189556  
(The Motor Claims Department)

Attn: Marcus Xiao

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:**

**SJD 2125X**

**INSURED VEHICLE: SJM 594R**

**ACCIDENT DATE: 17/08/2017**

We thank you for your instruction on 08/01/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJD 2125X from M/s Automax Survey.
- b) Colour damaged vehicle photographs of SJD 2125X.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SJD 2125X
Make & Model	: Honda Fit 1.3G A
Year of Registration	: 2008
Chassis Number	: GE61019656
Engine Capacity	: 1339 cc

2. We recommend that the repairs of the entire damage require about 7 (Seven) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.