

ASS. REC. BY:

REF: CS/MSG18000702/ R/vd322

Instruction:

SURVEYOR

Merimen

Rasul

ASSIGNMENT (Office)

From (Person):

Elaine Ngu

of

MSG

Date/Time: 11/01/2018 @ 2.22pm

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBG 5935 J

Insured:

SIB 9080G

at Workshop m/s

Sg 98 Motor

Tel:

6452 4898

of BIK 4001, AMK Ind. Prk. 1, 569622

Policy No:

A28930560 QMY

Claim No:

545048

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 08/01/2018

CA / REV / REP. / REV 24 HRS

'wp'

12/01/2018

H.O.D. Endorsement:

Date/Time: 11/01/18 @ 2.22pm

Person Contacted:

Rose

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	FBG 5935 J-x
	SIB 9080G-x
17/1/18	Informed Elaine pending workshop est by merimen
26/1/18	LS \$ 2050 confirmed by email (Red 2287.70, SIB)
4/10/18	Send preli revised via merimen

PKS 11347

Resul.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No. FBG 5935J

at Workshop m/s SG Motor

of 4001, Amk

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No FBG 5935J Yr Regn 17/9/201

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make Yamaha F216 cc 153

Colour Black A/C Insured / Std / NI / NA

Sp. Reading 30474 T Radio Insured / Std / NI / NA

Eng/No _____

C/No ME121C3D8C20109T5

Gen Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size F: 90/80-17 m/c

R: 140/70-17 mil

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal 2 mm

L/Bal — mm

D.O.A. 8/1/2018

Survey held at: As Above

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

12/1/18 Workshop informed will send repair estimate to Rasul.

RECEIVED 04 OCT 2018

Date/Time File Pass to: _____

1. ☐ : Preli. Report

2. ☐ : Final Report

Date/Time File Return to: _____

4/10- typist

Report Format: merimen

Lump Sum / I.B.I: (\$) 2050/-

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$) ☐ Interview (\$) ☐ Tech. Insp (\$) ☐ Weekend (\$)

Survey Fee 200

Transportation 10

1. S - R - S

2. S - R - S

3. S - R - S

4. S - R - S

5. S - R - S

6. S - R - S

7. S - R - S

8. S - R - S

9. S - R - S

10. S - R - S

11. S - R - S

12. S - R - S

13. S - R - S

14. S - R - S

15. S - R - S

16. S - R - S

17. S - R - S

18. S - R - S

19. S - R - S

20. S - R - S

21. S - R - S

22. S - R - S

23. S - R - S

24. S - R - S

25. S - R - S

26. S - R - S

27. S - R - S

28. S - R - S

29. S - R - S

30. S - R - S

31. S - R - S

32. S - R - S

33. S - R - S

34. S - R - S

35. S - R - S

36. S - R - S

37. S - R - S

38. S - R - S

39. S - R - S

40. S - R - S

41. S - R - S

42. S - R - S

43. S - R - S

44. S - R - S

45. S - R - S

46. S - R - S

47. S - R - S

48. S - R - S

49. S - R - S

50. S - R - S

51. S - R - S

52. S - R - S

53. S - R - S

54. S - R - S

55. S - R - S

56. S - R - S

57. S - R - S

58. S - R - S

59. S - R - S

60. S - R - S

61. S - R - S

62. S - R - S

63. S - R - S

64. S - R - S

65. S - R - S

66. S - R - S

67. S - R - S

68. S - R - S

69. S - R - S

70. S - R - S

71. S - R - S

72. S - R - S

73. S - R - S

74. S - R - S

75. S - R - S

76. S - R - S

77. S - R - S

78. S - R - S

79. S - R - S

80. S - R - S

81. S - R - S

82. S - R - S

83. S - R - S

84. S - R - S

85. S - R - S

86. S - R - S

87. S - R - S

88. S - R - S

89. S - R - S

90. S - R - S

91. S - R - S

92. S - R - S

93. S - R - S

94. S - R - S

95. S - R - S

96. S - R - S

97. S - R - S

98. S - R - S

99. S - R - S

100. S - R - S

Survey Department Check List (Case Handler)

Reference No.: CS MSG 18000 702 Rvd3
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 4/10/18
Case Handler Date

*N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18000702/R1vd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 11-01-2018



Code : MSG

Policy Particulars :- THIRD PARTY CLAIM

1.	Insured Veh.	SLB 9080G	Veh. Inspected	FBG 5935J
	Policy No.	A28930560QMY	Coverage (\$)	0.00
	Claim No.	545048	Excess (\$)	0.00
	Assign From	MERIMEN (ELAINE NGU)	Assign Date	11/01/2018

Vehicle Particulars & Condition

2.	Make & Model	c.c	0
	Engine No.	HIDDEN	Year of Reg.
	Chassis No.		Colour
	Odometer	-	Steering
	Brakes		Modification
	General		

Conditions of Tyres

3.		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm

Description of Damages

4.

General Information

5.

Accident Date	08/01/2018	Inspection Date
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622	

Remarks

5a.

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Jan 2018		11 Jan 2018 14:22 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SIM TIONG BENG, ID: S1805418C		
Main Claimant:	NURUL SAFWANAH BINTE TUPAM, ID: S9043579E		
Vehicle Reg. No.:	FBG5935J	Date of Loss:	08/01/2018 17:00 - :59
Claim Type:	TP / 545048	Policy/Cover Note No.:	A28930560QMY (Comprehensive) Coverage: 26/04/2017 - 25/04/2018
Vehicle Reg. No. (Insured):	SLB9080G	Policy No. (Claimant):	
		Excess:	
Repairer:	Sg98 Motor (HQ) Blk 4001 AMK ind park 1, 569622 Ang Mo Kio - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/01/2018]		
Driver/Custodian (Insured):	SIM ANN CHEE (), NRIC: S9603627B, Tel: +6583337507		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date : 10 January 2018

MSIG
4 Shenton Way
#21-01 SGX Centre 2
SINGAPORE 068807

Attn : Motor Claim Dept
Fax : 6225-7402
Email: claims@sg.msiga-asia.com

Dear Sir/Mdm,

PRE-REPAIR INSPECTION

Accident between FBG 5935J and SLB 9080G accident on 08 January 2018 at 1745 HRS
Location: Clementi Road towards Woodlands Road

- 1) We hereby give you NOTICE that we are claiming against your insured motor Vehicle No : SLB 9080G damages to our client's Motor Vehicle No: FBG5935J
- 2) Plse provide a list of surveyors and their respective company name.
- 3) Kindly let us know if you wish to conduct a pre-repair inspection only after 11.30am at Blk 4001 Ang Mo Kio Industrial Park 1 #01-21 Singapore 569622.
(Tel : 6452 4898, HP : 9171 1655)
- 4) If we do not hear from you within the next two (2) working days, we shall advise our clients to proceed with their own inspection and repairs.

Hope you are able to assist us on the above matter soonest.

Yours faithfully



Rose
SG 98 Motor Pte Ltd
Tel : 6452 4898
:LG

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 04 Oct 2018

Preliminary Advice

Insured Vehicle No : SLB9080G

TP Vehicle No : FBG5935J

Accident Date : 08/01/2018

Make : YAMAHA FZ16

Assignment Date : 11/01/2018

Date of Inspection : 12/01/2018

Est. Duration of Repair : 4.00

Inspection At : SG98 MOTOR (HQ)
BLK 4001 AMK IND PARK 1
SINGAPORE 569622

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,337.70
Revised Amount	:S\$	2,050.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,050.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

View Sent Message

This mail is associated with :

***FBG5935J (545048)**
[SLB9080G]

TP
NURUL SAFWANAH BINTE TUPAM
Jan 8 2018 5:00PM
[SIM TIONG BENG]
Sg98 Motor

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 17/01/2018 10:29 AM.
To MSIG_ENSM
Subject TP SURVEY FBG 5935J

Dear Elaine,

Please be informed that we have inspected the vehicle FBG 5935J on 12/1/2018.

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/01/2018 09:59
Date Of Accident	08/01/2018 17:45
Exact Location Of Accident	CLEMENTI ROAD TOWARDS WOODLANDS ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBG5935J
Insured/Policyholder	
Name Of Registered Owner	NURUL SAFWANAH BINTE TUPARI
NRIC No	S9043579E
Email Address	NURULSAFWANAH5@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97527492
Alternative Phone No	OFFICE-97527492

Vehicle Particulars

Manufacturer	YAMAHA
Model	FZ16-153CC (M)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5073769851-02
Cover Note Number	

Driver

Name of Driver	NURUL SAFWANAH BINTE TUPARI
NRIC No	S9043579E
Date Of Birth	13/11/1990
Occupation	INDOOR
Date Of Driving Pass	07/09/2012
Driving Experience	5 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97527492
Fax Number	
Contact Number	OFFICE-97527492
Email Address	NURULSAFWANAH5@GMAIL.COM

Address	BLK 250 BUKIT BATOK EAST AVE 5 #06-152
Postcode	650250
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO MOTORCYCLIST
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	10 UBI AVENUE 3
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED REMARK ; TYPE OF ACCIDENT REFER SKETCH AND STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLB9080G
Vehicle Make/Model/Colour	TOYOTA ALTIS 1.6
Details Of Properties	LEFT SIDE PORTION
Vehicle Category	PRIVATE CAR
Name of Driver	NA
NRIC/Passport Number	
Contact Number	83337507
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	NURUL SAFWANAH BINTE TUPARI
Approximate Age	27
Injuries Sustain	BOTH LEGS,ANKLE,RIGHT ARM,RIB CAGE - SWOLLEN
Injured person in which vehicle?	FBG5935J
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	YES
Address	BLK 250 BUKIT BATOK EAST AVE 5 #06-152
Postcode	650250

Sketch Plan #2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with any instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: WILLIAM
NRIC/FIN No.:

Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT *Clementi Road.*

Refer to police Report no. T/20180109/2049.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
Policyholder's Signature
Date & Time:

[Signature]
Driver's Signature
(if driver is not the policyholder)
Date & Time:

[Signature]
Reporting Centra Personnel's Signature
Name: *TUL/PA20*
NRIC/FIN No.:



Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20180109/2049

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 09/01/2018 12:11		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: NURUL SAFWANAH BINTE TUPARI			Address: APT BLK 250 BT BATOK EAST AVE 5 #06-152 SINGAPORE 650250		
ID Type / ID No.: NRIC NO / S9043579E			Contact No.: Home/Office: Mobile: 97527492		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 27	Date of Birth: 13/11/1990	Type of Informant: Rider		
Race: Javanese			Language: English		Institution / School Name:
Occupation: SCHOOL PROGRAM EXGUTIVE			Driving Licence Information: Class: 2B,3A Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 08/01/2018 17:45	Type of Location: Straight Road
Location: Along Road 1 CLEMENTI ROAD TOWARDS WOODLANDS ROAD				
Weather: Raining		Road Surface: Wet	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBG5935J	Motorcycle	YAMAHA	FZ 16	Black		0
SLB9080G	Car	TOYOTA	TOYOTA COROLLA ALTIS 1.6L CVT	Black		2

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date



SINGAPORE POLICE FORCE



T/20180109/2049

2 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20180109/2049

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBG5935J	NTUC Income Insurance Co-Operative Limited	5073769851-02	18/09/2017	17/09/2018

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	NURUL SAFWANAH BINTE TUPARI	ID No.	S9043579E
Related Vehicle	FBG5935J (Motorcycle)	Contact No.	97527492
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3A Date of Expiry: NIL
Date Treatment	08/01/2018	Date Discharge	08/01/2018
No. of Days granted Medical Leave	05	Degree of Injury	NIL

Brief Details.

ON THE ABOVE MENTIONED DATE, TIME AND LOCATION,

I WAS MOVING OFF FROM THE TRAFFIC JUNCTION AND THERE WAS TWO U-TURN SERVICE ROAD. I WAS TRAVELLING ON THE SECOND LANE FROM THE RIGHT. WHEN APPROACHING THE SECOND U-TURN POINT, THE VEHICLE FROM THE OPPOSITE DIRECTION MADE A SUDDEN U-TURN, I BRAKE AND UPON KNOWING THAT I WAS UNABLE TO STOP IN TIME, I SWERVED TO THE RIGHT, SKIDDED AND COLLIDED ONTO THE SIDE PORTION OF THE VEHICLE.



**SINGAPORE
POLICE FORCE**



T/20180109/2049

3 of 3

Report No. T/20180109/2049





Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: TP / NICHOLAS YEO HAO QUAN	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 09/01/2018 12:11
Officer In Charge Of Case: TP / GIT / Staff Sgt YAN MINGSHENG DANIEL Contact No.: 65476252	Classification Of Case:  SINGAPORE POLICE FORCE 
Authentication Stamp NP168	Signature: 

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 12 January 2018

To : LKK

By Fax: 6256-4315

Attn : Rasul

Tel : 90010068

VEHICLE NO : FBG 5935J

Yamaha FZ16

ACCIDENT DATE: 8 January 2018

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1 Mirror	1 set	160.00 <i>Bro</i>
2 Handle Bar	1	125.00 <i>PA</i>
3 Throttle Grip	1	95.00 <i>cut</i>
4 Steering Cone Bearing	1 set	135.00 <i>nu</i>
5 Brake Lever	1	75.00 <i>scr</i>
6 Meter Array <i>Assy</i>	1	400 450.00 <i>scr</i>
7 Head Lamp	1	250 350.00 <i>scr</i>
8 Head Lamp Stay	1	155.00 <i>Xscr</i>
9 Head Lamp Guard RH	1	85.00 <i>Chr</i>
10 Head Lamp Top Cover	1	155.00 <i>scr</i>
11 Front Signal LH	1	85.00 <i>Xscr</i>
12 Front Fork Tube	1 set	480.00 <i>repair</i>
13 Front Mudguard	1	98 148.00 <i>scr</i>
14 Front Rim <i>dist</i>	1	L - 100 320.00 <i>repair</i> <i>Local (repair 100)</i>
15 Fork Under Bracket	1	195.00 <i>Xscr</i>
16 Tank Cover RH	1	120 180.00 <i>scr</i>
17 Footrest RH	1	95.00 <i>Bro</i>
18 Footrest Bracket	1	145.00 <i>Xscr</i>
19 Exhaust Guard Chrome	1	155.00 <i>scr</i>
20 Exhaust Guard Black	1	175.00 <i>scr</i>
21 Rear RHTail Cover	1	130 160.00 <i>Chr</i>
22 Rear Footrest RH	1	95.00 <i>Xscr</i>
23 Fork Oil Seal	1	60 135.00 <i>nu</i>
Sub-Total		4,153.00
Less 10%		415.30
Sub-Total		3,737.70

2313
10%
2081.70

1/2

Received
19/1/18

VEHICLE NO : FBG 5935J

Yamaha FZ16

Nett items

- 1 Towing fee
- 2 Remove & replace necessary parts, align & etc
- 3 Remove & replace fork tube, top up oil
- 4 Supply body decal set
- 5 To top up engine oil

40.00
~~280.00~~ 180
130.00 80
120.00 60
30.00 15
375
+
Local repair
100

Sub-Total

600.00

475

Nett Total

4,337.70

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion
Thank you

SG 98 MOTOR PTE LTD

LG

Repair
Hp 90000068
4 days
H/S
12/01/18 @ 1700hrs

2081.70
475.00
2556.70
20%
2045.36

Signature
24/9/18

4/3 - 2,050
4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2/2

Veron Chen (LKKAUTO)

From: Sg motor enterprise Giam <sg_motor_enterprise@yahoo.com.sg>
Sent: Friday, 28 September 2018 10:57 AM
To: Veron Chen (LKKAUTO)
Subject: Re: RE: RE: Please finalize bike FBG 5935J.-DOA: 8/1/2018
Attachments: 002.JPG; 006.JPG; 008.JPG; 004.JPG

Hi Veron,

attached the after repaired photo.
of FBG 5935J

thank you
rose

On Wednesday, 26 September 2018, 12:41:52 PM GMT+8, Veron Chen (LKKAUTO) <veronchen@lkkauto.com> wrote:

Dear Rose,

Kindly provides us after paint photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sg motor enterprise Giam <sg_motor_enterprise@yahoo.com.sg>
Sent: Wednesday, 26 September 2018 11:46 AM
To: Sg Motor <sgmotor2000@yahoo.com.sg>; Rasul (LKKAUTO) <Rasul@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: Re: RE: RE: Please finalize bike FBG 5935J.-DOA: 8/1/2018

Hi all,

ok acceptance pls proceed accordingly.

thank you

rose

On Monday, 24 September 2018, 10:31:24 AM GMT+8, Veron Chen (LKKAuto) <veronchen@lkkauto.com> wrote:

Dear Linda,

WITHOUT PREJUDICE

Offer Lump Sum \$2050/- @ 4 working days.

Kindly check and confirm, please forward us resurvey photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sg Motor <sgmotor2000@yahoo.com.sg>

Sent: Wednesday, 15 August 2018 5:13 PM

To: Rasul (LKKAUTO) <Rasul@lkkauto.com>

Cc: Sg Motor <sg_motor_enterprise@yahoo.com.sg>; SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>

Subject: Please finalize bike FBG 5935J.

Dear Rasul

Please finalize bike FBG 5935J.

Thank You

Regards

Linda

SG 98 Motor Pte Ltd

Blk 4001 #01-21

Ang Mo Kio Industrial Park 1

Singapore 569622

Tel: 64524898 Fax: 64526898

On Thursday, 3 May 2018, 10:51:05 AM GMT+8, Sg Motor <sgmotor2000@yahoo.com.sg> wrote:

Dear Rasul

Please finalize bike FBG 5935J.

Thank You

Regards

Linda

SG 98 Motor Pte Ltd

Blk 4001 #01-21

Ang Mo Kio Industrial Park 1

Singapore 569622
Tel: 64524898 Fax: 64526898

On Wednesday, 4 April 2018, 3:28:43 PM GMT+8, Sg Motor <sgmotor2000@yahoo.com.sg> wrote:

Dear Rasul

Please finalize bike FBG 5935J.

Thank You

Regards
Linda

SG 98 Motor Pte Ltd

Blk 4001 #01-21
Ang Mo Kio Industrial Park 1
Singapore 569622
Tel: 64524898 Fax: 64526898

On Wednesday, 14 March 2018, 5:37:23 PM GMT+8, Sg Motor <sgmotor2000@yahoo.com.sg> wrote:

Dear Rasul

Please finalize bike FBG 5935J.

Thank You

Regards
Linda

SG 98 Motor Pte Ltd

Blk 4001 #01-21
Ang Mo Kio Industrial Park 1
Singapore 569622
Tel: 64524898 Fax: 64526898

On Thursday, 22 February 2018, 3:21:04 PM GMT+8, Sg Motor <sgmotor2000@yahoo.com.sg> wrote:

Dear Rasul

Please finalize bike FBG 5935J.

Thank You

Regards
Linda

SG 98 Motor Pte Ltd

Blk 4001 #01-21
Ang Mo Kio Industrial Park 1
Singapore 569622
Tel: 64524898 Fax: 64526898

On Tuesday, 6 February 2018, 5:01:23 PM GMT+8, Sg Motor <sgmotor2000@yahoo.com.sg> wrote:

Dear Rasul

Please finalize bike FBG 5935J.

Thank You

Regards

Linda

SG 98 Motor Pte Ltd

Blk 4001 #01-21

Ang Mo Kio Industrial Park 1

Singapore 569622

Tel: 64524898 Fax: 64526898

On Monday, 15 January 2018, 10:46:06 AM GMT+8, Sg Motor <sgmotor2000@yahoo.com.sg> wrote:

Attached plse find the Estimate Cost of Repairs for bike FBG 5935J.

Thank You

Regards

Leena

SG 98 Motor Pte Ltd

Blk 4001 #01-21

Ang Mo Kio Industrial Park 1

Singapore 569622

Tel: 64524898 Fax: 64526898

...CLAIM SUBFOLDER...(Pending for Survey Report)



































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Jan 2018		11 Jan 2018 14:22 Edit Adj Rpt	S\$2,050.00 Edit Estimates	S\$2,050.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SIM TIONG BENG , ID: S1805418C								
Main Claimant:	NURUL SAFWANAH BINTE TUPAM , ID: S9043579E								
Vehicle Reg. No.:	FBG5935J	Date of Loss:	08/01/2018 17:00 - :59 [63 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 545048	Policy/Cover Note No.:	A28930560QMY (Comprehensive) Coverage: 26/04/2017 - 25/04/2018						
Vehicle Reg. No. (Insured):	SLB9080G	Policy No. (Claimant):							
		Excess:							
Repairer:	Sg98 Motor (HQ) Blk 4001 AMK ind park 1, 569622 Ang Mo Kio - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 10/02/2018]								
Driver/Custodian (Insured):	SIM ANN CHEE (), NRIC: S9603627B, Tel: +6583337507								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBG5935J (545048)**
[SLB9080G]

TP
NURUL SAFWANAH BINTE TUPAM
Jan 8 2018 5:00PM
[SIM TIONG BENG]
Sg98 Motor

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	11/01/18 09:56	MSIG Insurance (Singapore) Pte. Ltd. (HQ) Accident Statement <small>From: SC - Reg. No: SLB9080G, Claimant: SIM TIONG BENG</small>	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/10/18 15:49	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder		Thumbnail	Print
1	17/01/18 10:32	LKK Auto Consultants Pte Ltd (HQ) General View	 Load JPG	<input checked="" type="checkbox"/>
2	17/01/18 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
3	17/01/18 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
4	17/01/18 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
5	17/01/18 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
6	17/01/18 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
7	17/01/18 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
8	17/01/18 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
9	17/01/18 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
10	17/01/18 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
11	17/01/18 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
12	17/01/18 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
13	17/01/18 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
14	17/01/18 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
15	17/01/18 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
16	17/01/18 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
17	17/01/18 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
18	17/01/18 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
19	17/01/18 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
20	17/01/18 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
21	17/01/18 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
22	17/01/18 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
23	17/01/18 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
24	17/01/18 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
25	17/01/18 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
26	17/01/18 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
27	17/01/18 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
28	17/01/18 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
29	17/01/18 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
30	17/01/18 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
31	17/01/18 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
32	17/01/18 10:32	General View	 Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
33	17/01/18 10:32	General View	Load JPG	<input checked="" type="checkbox"/>
34	17/01/18 10:32	General View	Load JPG	<input checked="" type="checkbox"/>
35	17/01/18 10:32	General View	Load JPG	<input checked="" type="checkbox"/>
36	17/01/18 10:32	General View	Load JPG	<input checked="" type="checkbox"/>
37	17/01/18 10:32	General View	Load JPG	<input checked="" type="checkbox"/>
38	17/01/18 10:32	General View	Load JPG	<input checked="" type="checkbox"/>
39	17/01/18 10:32	General View	Load JPG	<input checked="" type="checkbox"/>
40	17/01/18 10:32	General View	Load JPG	<input checked="" type="checkbox"/>
41	17/01/18 10:32	General View	Load JPG	<input checked="" type="checkbox"/>
42	17/01/18 10:32	General View	Load JPG	<input checked="" type="checkbox"/>
43	17/01/18 10:32	General View	Load JPG	<input checked="" type="checkbox"/>
44	17/01/18 10:32	General View	Load JPG	<input checked="" type="checkbox"/>
45	17/01/18 10:32	General View	Load JPG	<input checked="" type="checkbox"/>
46	17/01/18 10:32	General View	Load JPG	<input checked="" type="checkbox"/>
47	17/01/18 10:32	General View	Load JPG	<input checked="" type="checkbox"/>
48	17/01/18 10:32	General View	Load JPG	<input checked="" type="checkbox"/>
49	17/01/18 10:32	General View	Load JPG	<input checked="" type="checkbox"/>
50	17/01/18 10:32	General View	Load JPG	<input checked="" type="checkbox"/>
51	17/01/18 10:32	General View	Load JPG	<input checked="" type="checkbox"/>
52	17/01/18 10:32	General View	Load JPG	<input checked="" type="checkbox"/>
53	17/01/18 10:32	General View	Load JPG	<input checked="" type="checkbox"/>
54	17/01/18 10:32	General View	Load JPG	<input checked="" type="checkbox"/>
55	17/01/18 10:32	General View	Load JPG	<input checked="" type="checkbox"/>
56	17/01/18 10:32	General View	Load JPG	<input checked="" type="checkbox"/>
57	17/01/18 10:32	General View	Load JPG	<input checked="" type="checkbox"/>
58	17/01/18 10:32	General View	Load JPG	<input checked="" type="checkbox"/>
59	17/01/18 10:32	General View	Load JPG	<input checked="" type="checkbox"/>
60	04/10/18 15:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
61	04/10/18 15:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
62	04/10/18 15:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
63	04/10/18 15:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	11/01/18 09:55	Request for PRI	Load PDF	
2	11/01/18 10:02	Email from Third Party	Load PDF	
3	11/01/18 14:22	Agree on SJE	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18000702/R1VD3E2

Date: 05/10/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28930560QMY

Claimant Vehicle No : FBG5935J

Insured Vehicle No : SLB9080G

Date of Loss: 08/01/2018

Nature of Claim: TP

Claim No: 545048

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBG5935J

Make & Model: YAMAHA FZ16, 153cc (M)

Engine No: 21CD010404

Reg. Date: 17/09/2012 (Man. Year: 2012)

Chassis No: ME121C0D8C2010395

Colour: Black

Odometer: 50474 km

Engine Capacity: 153 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 90/80-17

Rear Tyre Size: 140/70-17

Front Left Side: Pirelli 2 mm

Rear Left Side: Pirelli 2 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,737.70	2,181.70	1,556.00	41.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	600.00	375.00	225.00	37.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,337.70	2,556.70	1,781.00	41.06
Approved Total (Overridden) (S\$)		2,050.00		
Nett Amount (S\$)	4,337.70	2,050.00	2,287.70	52.74

INSPECTION

Date of Assignment: 11/01/2018

Date Inspected: 12/01/2018

Inspected At:

Sg98 Motor (HQ)
Blk 4001 AMK ind park 1
Singapore 569622

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 05 Oct 2018)	
Parts:	N/A	YAMAHA FZ16 153cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBG5935J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET MIRROR	Broken	160.00 FL	*160.00 FL
2	1		*HANDLE BAR	Bent	125.00 FL	*125.00 FL
3	1		*THROTTLE GRIP	Cut	95.00 FL	*95.00 FL
4	1		*SET STEERING CONE BEARING	Necessary	135.00 FL	*135.00 FL
5	1		*BRAKE LEVER	Scratched	75.00 FL	*75.00 FL
6	1		*METER ASSY	Scratched	450.00 FL	*400.00 FL
7	1		*HEAD LAMP	Scratched	350.00 FL	*250.00 FL
8	1		*HEAD LAMP STAY	Serviceable	155.00 FL	*- FL
9	1		*HEAD LAMP GUARD RH	Cracked	85.00 FL	*85.00 FL
10	1		*HEAD LAMP TOP COVER	Scratched	155.00 FL	*155.00 FL
11	1		*FRONT SIGNAL LH	Serviceable	85.00 FL	*- FL
12	1		*SET FRONT FORK TUBE	Repair	480.00 FL	*- FL
13	1		*FRONT MUDGUARD	Scratched	148.00 FL	*98.00 FL
14	1		*FRONT RIM (LOCAL REPAIR)	Distorted	288.00 FS	*100.00 FS
15	1		*FORK UNDER BRACKET	Serviceable	195.00 FL	*- FL
16	1		*TANK COVER RH	Scratched	180.00 FL	*120.00 FL
17	1		*FOOTREST RH	Broken	95.00 FL	*95.00 FL
18	1		*FOOTREST BRACKET	Serviceable	145.00 FL	*- FL
19	1		*EXHAUST GUARD CHROME	Scratched	155.00 FL	*155.00 FL
20	1		*EXHAUST GUARD BLACK	Scratched	175.00 FL	*175.00 FL
21	1		*REAR RH TAIL COVER	Cracked	160.00 FL	*130.00 FL
22	1		*REAR FOOTREST RH	Serviceable	95.00 FL	*- FL
23	1		*FORK OIL SEAL	Necessary	135.00 FL	*60.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,121.00	2,413.00
- List Item Discount on L Items 10.00/10.00% (S\$)	383.30	231.30
Total Parts (S\$)	3,737.70	2,181.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING FEE	New	40.00	40.00
2	REMOVE & REPLACE NECESSARY PARTS, ALIGN & ETC	New	280.00	180.00
3	REMOVE & REPLACE FORK TUBE, TOP UP OIL	New	130.00	80.00
4	SUPPLY BODY DECAL SET	New	120.00	60.00
5	TO TOP UP ENGINE OIL	New	30.00	15.00
Gross Labour Cost (\$\$)			600.00	375.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >