

ASS. REC. BY:

REF: CS/AIG/18000711/D 903 n2

Special Instruction:

Regency 12/1/18 Mr. Roldan  
11/14/18 Wilson folder

Supervisor: Meinman

MA

ASSIGNMENT (Office)

From (Person): Mariesa

of AIG

Date/Time: 11/01/18 @ 4:57pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLD 5762M

Insured: SLS 6777K

at Workshop m/s

E.M. Solution

Tel: 6456 0226

of

160 Sin Ming Drive #03-18/19

Policy No:

1700039496

Claim No:

877223679156

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 10/01/2018

After 10am @ 12/01/2018

CA / REV / REP. / REV 24 HRS

wp

H.O.D. Endorsement:

Date/Time:

5:30pm @ 11/01/18

Person Contacted:

SIM

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SLD 5762M-X</u> <u>12/1/18</u> <u>Wilson reserved</u>
	<u>SLS 6777K-X</u>
<u>12/8/18 @ 2:27pm</u>	<u>confirmed with Harvard w/ \$2150, 4 days by email.</u>
	<u>(Red \$5676.74, 73%)</u>

PPA (A702)

REF:

Mu.

# ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLD 5762 M.

at Workshop no: 16a, Simung Drive

at #103/18-14

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bar or Market Value

IDAC Accident Report

Consistent? Yes or No

GR PR Seen

Consistent? Yes or No

Est. Repairs: 4 days Res Yes or No

Lump Sum: % 3 Val Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction:

Veh No: SLD 5762 M

Yr Regn: Jun 16

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda

1998

Colour: Black

A/C Insured / Std / Nil / NA

Sp Reading: 30883

T Radio Insured / Std / Nil / NA

Eng No:

C/V: 3M6GJ102G0239684

Gen Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225 / 55 R15

R: 225 / 55 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R Bal: 4 mm

R Bal: 4 mm

L Bal: 4 mm

L Bal: 4 mm

D/O A: 10/1/2018

D/O: 12/1/2018

Survey held at: As Above

Des of Damages: Fr: Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

RECEIVED 20 AUG 2018

Date Time File Pass to:

☐: Preli. Report

☐: Final Report

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Site Insp: \$

Interview: \$

Tech Insp: \$

Weekend: \$

250  
20

270

Report Format:

MER-TP

Lump Sum / I.B.T. \$

2150

Add Fee:

☐ Site Insp: \$

☐ Interview: \$

☐ Tech Insp: \$

☐ Weekend: \$



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS/AIG18000711/M1qd3

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 11-01-2018



Code : AIG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLS 6777K	Veh. Inspected	SLD 5762M
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MARIESA	Assign Date	11/01/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

## 5. General Information

Accident Date	10/01/2018	Inspection Date	
Survey held at	EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

## Nivitha (LKK Auto)

---

**From:** Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>  
**Sent:** Thursday, 11 January 2018 4:57 PM  
**To:** assignments@lkkauto.com; admin-a@lkkauto.com  
**Cc:** Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Fan, Winnie-LW; Lim, Sheng Yang; Md Ishak, Mohd Imran; Chan, Yoke Shi; Supramaniam, Darshene  
**Subject:** aigencrypt - Pre repair inspection request - SLD5762M VS SLS6777K (OI) DOA: 10/1/2018  
**Attachments:** RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLS67... (68.8 KB)

Hi,

Please refer to the enclosed request from **VISION LAW LLC**

Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

*Kindly assist to assign Ma Chin Fook as Single Joint Expert as requested.*

Thank you.

Best Regards,

Mariesa Abu Kassim

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel +6 03 2719 6000 | Ext 1012202 | Fax +6 03 2685 5898

[NoorMariesa.AbuKassim@aig.com](mailto:NoorMariesa.AbuKassim@aig.com) | [www.aig.com](http://www.aig.com)

### IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**Nivitha (LKK Auto)**

---

**From:** Sally Chong <sallychong@visionlawllc.com>  
**Sent:** Thursday, 11 January 2018 4:39 PM  
**To:** Abu Kassim, Noor Mariesa  
**Cc:** EM Solution Pte Ltd; judysoh@visionlawllc.com  
**Subject:** RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLS6777K AND SLD5762M ON 10/1/2018

**Importance:** High

**Follow Up Flag:** Follow up  
**Flag Status:** Flagged

**VERY URGENT**

Dear Mr Mariesa,

**NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES**  
**CLAIMANT: TAN WEE PING**  
**ACCIDENT INVOLVING SLD 5762M & SLS 6777K ON 10 JAN 2018 ALONG BUKIT TIMAH ROAD NEAR FARRER RD AT ABOUT 18:25 HRS**

Thank you for your email of even date below.

Our client confirms the appointment of **MA CHIN FOOK (LKK AUTO CONSULTANTS PTE LTD)** as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at :

Venue : **E M SOLUTION PTE LTD**  
160, Sin Ming Drive, #03-18/19, Sin Ming Autocity,  
Singapore 575722  
Contact : Mr. Bernard (Tel.: 6456-0226 / 9101-8302)

If you fail to conduct the pre-repair survey within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Thank you.

*Sally Chong*

(Secretary)  
VISION LAW LLC  
133 NEW BRIDGE ROAD,  
#18-01/02, CHINATOWN POINT,  
SINGAPORE 059413  
TEL.: 6534-2811 (ext 115)  
FAX : 6535-6802

---

**From:** Abu Kassim, Noor Mariesa [mailto:NoorMariesa.AbuKassim@aig.com]  
**Sent:** Thursday, 11 January, 2018 2:03 PM  
**To:** Sally Chong

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Fan, Winnie-LW; Lim, Sheng Yang; Md Ishak, Mohd Imran; Chan, Yoke Shi; Supramaniam, Darshene

**Subject:** PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLS6777K AND SLD5762M ON 10/1/2018

Your Reference : SLD5762M  
Our Reference : SLS6777K

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

<b>Name of Surveyor</b>	<b>Company Name</b>
Lim Kok Chong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Ricky Teng	RT Appraisal Pte Ltd
Elson Teng	RT Appraisal Pte Ltd
Michael Cheong	RT Appraisal Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Henry Ng	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Steven Foong	LKK Auto Consultants Pte Ltd
Wei Jie	LKK Auto Consultants Pte Ltd
Ma Chin Fook	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.



Best Regards,

**Mariesa Abu Kassim**

**AIG**

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel +6 03 2719 6000 | Ext 1012202 | Fax +6 03 2685 5898

[NoorMariesa.AbuKassim@aig.com](mailto:NoorMariesa.AbuKassim@aig.com) | [www.aig.com](http://www.aig.com)

---

**From:** Sally Chong [<mailto:sallychong@visionlawllc.com>]

**Sent:** Thursday, January 11, 2018 12:59 PM

**To:** Chin, Lee-Ying; AIG SGP, Claims-Survey; Lim, Sheng Yang

**Cc:** EM Solution Pte Ltd; Leong, Kah Yin; Hassim, Mohd Fitri; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran;

[judysoh@visionlawllc.com](mailto:judysoh@visionlawllc.com)

**Subject:** OUR REF.: E21-MISC.18 (SLD 5762M @ 10.01.2018) AIG REF.: SLS 6777K

## VERY URGENT

Dear Sir,

**NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES**

**CLAIMANT: TAN WEE PING**

**ACCIDENT INVOLVING SLD 5762M & SLS 6777K ON 10 JAN 2018 ALONG BUKIT TIMAH ROAD NEAR FARRER RD AT ABOUT 18:25 HRS**

We are instructed by **TAN WEE PING** to notify you of a road traffic accident on **10 JAN 2018 ALONG BUKIT TIMAH ROAD NEAR FARRER RD AT ABOUT 18:25 HRS** involving our client's vehicle registration number **SLD 5762M** and vehicle registration number **SLS 6777K** driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Thank you.

*Sally Chong*

(Secretary)

VISION LAW LLC

133 NEW BRIDGE ROAD,

#18-01/02, CHINATOWN POINT,

SINGAPORE 059413

TEL.: 6534-2811 (ext 115)

FAX : 6535-6802

C.c.: **VEHICLE OWNER OF SLS 6777K**  
**SHANTI UMA DEVI D/O GNANAMANI**  
893C, Woodlands Drive 50,  
#047-89,

---

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

---

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

---

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

---

---

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

---

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

---



## Shiau Chan (LKKAuto)

---

**From:** EM Auto <emautosolution@singnet.com.sg>  
**Sent:** Friday, 17 August 2018 2:27 PM  
**To:** Shiau Chan (LKKAuto)  
**Subject:** RE: FINALISE OF SLD 5762M (DOA: 10/01/2018)

Hi Shiau Chan,

Ok, Agreed, Accept 😊

Thanks & regards,

*Bernard*

HP: 91018302

---

**From:** Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]  
**Sent:** Thursday, 16 August, 2018 4:36 PM  
**To:** emautosolution@singnet.com.sg  
**Subject:** FINALISE OF SLD 5762M (DOA: 10/01/2018)

Dear Bernard,

WITHOUT PREJUDICE

Offer Lump Sum \$2,150.00 and 4 repair days.

Kindly confirm.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	2326F
<b>Vehicle Details</b>	
Vehicle No.:	SLD5762M
Vehicle to be Exported:	No
Intended De-registration Date:	18 Jan 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA6 4-DOOR SEDAN 2.0L SP6EAT
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	PE20787145
Chassis No.:	JM6GJ1072G0239684
Maximum Power Output:	121.0 kW (162 bhp)
Open Market Value:	\$22,073.00
Original Registration Date:	22 Jun 2016
First Registration Date:	22 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$22,903.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Jun 2026
PARF Rebate Amount:	\$17,177.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	21 Jun 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,000.00
COE Rebate Amount:	\$47,180.00
<b>Total Rebate Amount:</b>	<b>\$64,357.00</b>

The information contained herein is correct as at 18 Jan 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	11/01/2018 13:56
Date Of Accident	10/01/2018 18:25
Exact Location Of Accident	BUKIT TIMAH RD NEAR FARRER RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD5762M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAN WEE PING
NRIC No	S8222326F
Email Address	ZITER@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97472646
Alternative Phone No	OTHERS-81232484

### Vehicle Particulars

Manufacturer	MAZDA
Model	6
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D17MTPV01008803
Cover Note Number	

### Driver

Name of Driver	TAN WEE PING
NRIC No	S8222326F
Date Of Birth	02/07/1982
Occupation	INDOOR
Date Of Driving Pass	18/06/2003
Driving Experience	14 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97472646
Fax Number	
Contact Number	OTHERS-81232484
Email Address	ZITER@GMAIL.COM

Address	6 GATEWAY DRIVE #07-21
Postcode	608535
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	DRIZZLE
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLS6777K
Vehicle Make/Model/Colour	VOLVO
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KAVIN KUMAR SUGUMARAN
NRIC/Passport Number	S9813306B
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Sketch Plan Pg. 1

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time

11/1/2018  
12.00pm

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Person's Signature  
Name:  
NRIC/FIN No.:


Mac C  
11/1/18

Sompo  
Vehicle: -  
SLD 5762 M

# Sketch Plan Pg. 2

## SKETCH PLAN

Date: 10/1/2018 Time: 6:25 PM Location: BUKIT TIMAH ROAD  
 My Vehicle A: SLD 5762 M Vehicle B: SLS 6777 K Vehicle C/Others: -



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 10/1/2018 at about 6:25 pm I was driving my vehicle - SLD 5762 M along Bukit Timah Road. It was raining and Traffic was heavy. There was vehicle in front stopped so I stopped behind, out of a sudden a vehicle - SLS 6777 K from behind bang onto my rear. My vehicle sustained damage on the rear portion and I submitting this incident for TPA claim against SLS 6777 K.

( ) Claim OD / TP at Ah Lim Motor ☒ Claim OD / TP at other workshop ( ) Reporting Only

Remarks: Please forward a copy of my efile accident report to

My workshop: EM solution PTE LTD  
 Email Address: emautosolution@singnet.com.sg  
 & Myself:  
 Email Address:

- zixter@gmail.com

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.


## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature: [Signature]  
 Date & Time: 11/1/18  
12:00 pm

Driver's Signature (if driver is not the policyholder):  
 Date & Time:

Witnessed by Reporting Centre Personnel: [Signature]  
11/1/18





# Policy Holder-Driver's Particulars Pg. 1



**SOMPO**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048523  
Tel: 6461 6505 | Fax: 6221 3082 | Website: www.sompo.com.sg  
Co. Reg. No. 198902490E | GST Reg. No. M200903196

## Certificate of Insurance

**MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 169)**  
**MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960**  
**ROAD TRANSPORT ACT, 1987 (MALAYSIA)**  
**MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)**

**Cert No./Policy No.** : D17MTPV01008903  
**Insured** : TAN WEE PING  
**Motor Car (Registration No.)** : SLD6752M  
**Cover** : Comprehensive - ExcelDrive PRESTIGE  
**Policy Commencement Date** : 22 JUNE 2017 00:00  
**Policy Expiry Date** : 21 JUNE 2018 23:59  
**Maximum Liability (Section I)** : Market value at time of loss  
**Excess\*** : \$600 - Section I  
(Waived up to \$1,000 if accident repair is done at ExcelDrive Workshops for the first claim per policy year)  
**Voluntary Excess\*** : N.A.  
**Windscreen Excess\*** : \$5100.00 - Waived if Repair at ExcelDrive Workshop  
**Loss of Use** : Per Policy Schedule  
\* Subject to GST wherever applicable

### Persons or Classes of Persons entitled to drive\*

1. The Insured.
2. Any other person who is driving on the Insured's order or with his permission.
3. In the event of the death of the insured,
  - a. any member of the insured's family, or a paid driver who has been driving the Motor Car during the life of the insured and permission to drive had not been withdrawn prior to the death of the insured; and
  - b. any other person who has been given permission to drive the Motor Car prior to the death and such permission had not been withdrawn by the Insured.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Car or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Car. And provided further that the Motor Car is registered under the Road Traffic Act (Chapter 276) and its registration under the Road Traffic Act (Chapter 276) has not been cancelled at the time of the accident, loss or damage.

### Limitations As To Use

Use only for social, domestic and pleasure purpose and for the Insured's business. The Policy does not cover use for hire or reward, racing, pace-making, speed testing, reliability trial, the carriage of goods other than samples in connection with any trade or business or use for any purposes in connection with the Motor Trade.

### ExcelDrive Workshops and Accident Reporting

It is a condition precedent to liability that the Insured shall call at the Company's Accident Reporting Center with the Motor Car within 24 hours of the accident or by the next working day thereof.

All accident repairs to the Motor Car must be carried out at ExcelDrive Workshops, otherwise the claim is not payable under the Policy. For ExcelDrive Prestige Plan, accident repairs to the Motor Car can be carried out at any workshop other than ExcelDrive Workshops.

For the list of Accident Reporting Centres and ExcelDrive Workshops, please visit our website at [www.sompo.com.sg](http://www.sompo.com.sg) or call our Emergency Hotline: (65) 6228 3323.

(We HEREBY CERTIFY that the policy to which this Certificate relates is issued in accordance with (1) the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 169) and Part IV of the Road Transport Act, 1987 (Malaysia); and (2) the Policy terms, conditions and exclusions of the Private Car Policy ref MTP 27.

Sompo Insurance Singapore Pte. Ltd.

*Stallup*  
HUTS

Authorised Signatory

Date/Time of Issue | 05 JUNE 2017 22:43

### IMPORTANT NOTICE

- a. Keep the Certificate in your Motor Car.
- b. Under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 169), it shall be unlawful for any person to use or cause to use or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.
- c. On the sale of the Motor Car or if for any reason the insurance is terminated during its currency, the Insured must surrender the Certificate of Insurance and the Policy to the Insurance company. If the Certificate of Insurance has been lost or destroyed, a statutory declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 169).
- d. This Policy will cease to be valid once the Motor Car has been sold to another person. The Policy is not transferable to the new owner of the Motor Car.

Intermediary Code & Name : IC01600 & CHIA WEE BOON ROY | CI Code: 22A JJAULSW44LL18CNA

# E M SOLUTION PTE LID

160, Sin Ming Drive, #03-18/19, Sin Ming Autocity, Singapore 575722

Tel: 64560226 Fax: 64584500

Registration No: 201016308K

02.05.2012

Tan Wee Ping

## REPAIR ESTIMATE FOR MAZDA 6 - SLD 5762 M

1 pc	rear bumper		1,216.50	BR ✓	1078.00
1 2 pcs	rear bumper reflectors	68.20 ✓	136.40	BR ✓	
2 pcs	rear bumper side retainers	49.30	98.60	NEC ✓	
1 pc	rear bumper reinforcement		465.30	RX	
2 pcs	taillamps	937.20	1,874.40	NN X	
1 pc	rear end panel		498.10	RX	
1 pc	rear end panel top garnish		245.30	NNX	
1 pc	boot lid		1,306.80	RX	
1 pc	boot inner lock		293.80	NNX	
2 pcs	boot reflectors	368.50	737.00	NNX	
1 pc	boot rubber		192.50	NNX	
1 pc	boot emblem		59.10	NEC ✓	
1 pc	boot "Mazda" badge		32.30	NEC ✓	
1 pc	boot "6" badge		26.30	NEC ✓	
1 pc	boot "Skyactiv Technology" badge		39.00	NEC ✓	
2 pcs	rear exhaust silencers	893.90	1,787.80	NN X	
4 pcs	rear exhaust mountings	31.20	124.80	NN X	
			<u>9,134.00</u>		1401.50
		Less 20%	<u>1,936.56</u>		280.30
			<u>7,746.24</u>		1121.20
1 set	reverse sensor		350.00	SN	200.00 DM
1 set	rear bumper clips		40.00	SN	NECV
1)	Check electrical wiring.		60.00		
2)	Renew rear exhaust silencer.		180.00	NN	
3)	Repair accident damages and renew above parts.		880.00	600.00	
4)	Spray paint on accident affected portions.		880.00	600.00	
5)	Rust proofing on accident affected portions.		60.00	✓	
6)	Renew reverse sensor.		80.00	60.00	
			<u>\$ 7,826.24</u>		2741.20

L/S 2150/2  
Repair days 4

  
15/8/18

## LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18000711/DQD3N2

Date: 21/08/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700059496  
 Claimant: SLD5762M Insured Vehicle No: SLS6777K  
 Vehicle No: SLD5762M Nature of Claim: TP Claim No: 8772236791SG  
 Date of Loss: 10/01/2018

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLD5762M Engine No: PE20787145  
 Make & Model: MAZDA 6, 2.0 V (A) Chassis No: JM6GJ1072G0239684  
 Reg. Date: 22/06/2016 (Man. Year: 2016) Odometer: 30883 km  
 Colour: Black  
 Engine Capacity: 1998 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17  
 Front Left Side: Toyo 4 mm Rear Left Side: Toyo 4 mm  
 Front Right Side: Toyo 4 mm Rear Right Side: Toyo 4 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,697.20	1,361.20	6,336.00	82.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,140.00	1,380.00	760.00	35.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,837.20	2,741.20	7,096.00	72.13
Approved Total (Overridden) (S\$)		2,150.00		
(S\$)	9,837.20	2,150.00	7,687.20	78.14
+ GST 7.00/7.00% (S\$)	688.60	150.50	538.10	78.14
Nett Amount (S\$)	10,525.80	2,300.50	8,225.30	78.14

## INSPECTION

Date of Assignment: 11/01/2018  
 Date Inspected: 12/01/2018 Inspected At: E M Solution Pte Ltd (HQ)  
 160 Sin Ming Drive., #03-18, Sin Ming  
 Autocity  
 Singapore 575722  
 Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	1,216.50 FL	*1,078.00 FL
2	1		*REAR BUMPER REFLECTORS	Broken (1 Pc Only)	136.40 FL	*68.20 FL
			(2 Pcs)			
3	2		*REAR BUMPER SIDE RETAINERS	Necessary	98.60 FL	*98.60 FL
4	1		*REAR BUMPER REINFORCEMENT	Repair	465.30 FL	*- FL
5	2		*TAILLAMPS	Not Necessary	1,874.40 FL	*- FL
6	1		*REAR END PANEL	Repair	498.10 FL	*- FL
7	1		*REAR END PANEL TOP GARNISH	Not Necessary	245.30 FL	*- FL
8	1		*BOOT LID	Repair	1,306.80 FL	*- FL
9	1		*BOOT INNER LOCK	Not Necessary	293.80 FL	*- FL
10	2		*BOOT REFLECTORS	Not Necessary	737.00 FL	*- FL
11	1		*BOOT RUBBER	Not Necessary	192.50 FL	*- FL
12	1		*BOOT EMBLEM	Necessary	59.10 FL	*59.10 FL
13	1		*BOOT MAZDA BADGE	Necessary	32.30 FL	*32.30 FL
14	1		*BOOT 6 BADGE	Necessary	26.30 FL	*26.30 FL
15	1		*BOOT SKYACTIV TECHNOLOGY BADGE	Necessary	39.00 FL	*39.00 FL
16	2		*REAR EXHAUST SILENCERS	Not Necessary	1,787.80 FL	*- FL
17	4		*REAR EXHAUST MOUNTINGS	Not Necessary	124.80 FL	*- FL
18	1		*SET REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
19	1		*SET REAR BUMPER CLIPS	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	9,524.00	1,641.50
- List Item Discount on L Items 20.00/20.00% (S\$)	1,826.80	280.30
Total Parts (S\$)	7,697.20	1,361.20

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CHECK ELECTRICAL WIRING	New	60.00	60.00
2	RENEW REAR EXHAUST SILENCER	New	180.00	-
3	REPAIR ACCIDENT DAMAGES AND RENEW ABOVE PARTS	New	880.00	600.00
4	SPRAY PAINT ON ACCIDENT AFFECTED PORTIONS	New	880.00	600.00
5	RUST PROOFING ON ACCIDENT AFFECTED PORTIONS	New	60.00	60.00
6	RENEW REVERSE SENSOR	New	80.00	60.00
Gross Labour Cost (S\$)			2,140.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >