

Page 1

ASSIGNMENT

REF: CS3/MSG18000713/G12302

NAVY

ASSIGNMENT

Meimen

Christina Wong

MSG

10/01/18 @ 2:28pm

Refused to Sign

Refused

OD/TP/WS/TP/RES/OD/RES/VA/EN/VA/IN/VA

To Inspect Vehicle No.

GY 5193D

SGR 2567R

at Workshop no.

Tat Heng Motor

6483 7103

at BLK 10, AMK Ind. Park 2A #02-09

Policy No.

827351564SMF

Vehicle No.

544872

Sum Insured

Excess

Make of Veh.

(Client's Record)

Make

04/01/2017

CA / REV / REF. / REV 24 HRS

Wps

15/01/2018 @ After 10am

LOD Confirmation

Date/Time

5:07pm @ 10/1/18

Person Conducted

Gina

Vehicle No. (OUT)

Date/Time

Action/Description

X E-Form

GY 5193D - NA/MSG18000713/NA

NA/NA 24/01/2018

SGR 2567R - NA/MSG18000713/NA

NA/NA 24/01/2018

01/02/2018 10:20am - Email to Christina Wong thru Meimen

MSIG

15/01/2018

GY5193D

(-2020,
05 May 2005

Estimated Date

01/01/2018

Vehicle Make/Model

Tat Heng Motor

Blk 10, AMK Ind. Park 2A #02-09

Insured

Policy No

Damage

Sum Insured

Excess


Claims Record

After 10am

Name of Ins

Policy Condition

Remarks: The vehicle has commenced its repair at the time of inspection



Basic Vehicle Value

DAQ Accident Report

Consistent? Yes or No

Good Condition

Consistent? Yes or No

Est. Repair

days

Repair

Yes or No

W/Lt Sup

At

Cost

Yes or No

DA REPAIR PER 24HRS lwp

Date

Person Contacted

Vehicle No. Out

The L.O. Chassis/frame Body Structure affected due to accident

Date/Time

Action/Inspection

\$3000 - \$4000.

Time of Day

Day of Week

Year

Month

Day of Month

Hour

Min

Sec

Day of Week

Month

Year

Time of Day

Day of Week

Month

Year

Time of Day

Month

Year

Time of Day

Month

Year

Time of Day

Month

Year

Time of Day

Month

Year

Time of Day

Month

Year

Time of Day

Month

Year

Time of Day

Month

Year

Time of Day

Month

Year

Time of Day

Month

Year

Nissan Cabstar

3153

Silver

47938

IN1SF4F23Z0854148

Gen. Date Code

Steering

Brake

W/Lt Sup

195 R15

155 R13

ES DUN EXNOVA GR PS LIA MIO DHTSL PR SUV

TOYO MOKO MAXXIS (F+)

Front

R/Ba

L/Ba

15-01-18

W/Lt Sup

3:30 pm

Des. of Damages

Front

CS

WS

UC

Repaired

CS

WS

UC

Repaired

CS

WS

UC

Repaired

CS

WS

UC

Repaired

CS

WS

UC

On The Forward

01-02-2018

On The Forward

Final Report

Final Report

Final Report

Days Of Repair

Reserve No. of Tire

Reserve No. of Tire

Reserve No. of Tire

Reserve No. of Tire

Reserve No. of Tire

Reserve No. of Tire

Reserve No. of Tire

Reserve No. of Tire

Reserve No. of Tire

Time Fee

Time Fee

Time Fee

Time Fee

Time Fee

Time Fee

Time Fee

Time Fee

Time Fee

PRS



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG18000713/Gd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 11-01-2018



Code : MSG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SGR 2567R	Veh. Inspected	GY 5193D
Policy No.	S27351564SMF	Coverage (\$)	0.00
Claim No.	544872	Excess (\$)	0.00
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	11/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	04/01/2018	Inspection Date
Survey held at	TAT HENG MOTOR WORKS BLK 10, ANG MO KIO INDUSTRIAL PARK 2A #02-09, ANG MO KIO POINT, SINGAPORE 568047	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Jan 2018		10 Jan 2018 14:28 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	TAN HUI XIAN RACHAEL (CHEN HUIXIAN), ID: S8337202H, Tel: +6593673344, Email: TANRACHAEL@YAHOO.COM.SG		
Main Claimant:	T MARKER (S) PTE. LTD., Co. Reg. No.: 201623262W		
Vehicle Reg. No.:	GY5193D	Date of Loss:	04/01/2018 20:00 - :59
Claim Type:	TP / 544872	Policy/Cover Note No.:	S27351564SMF (Comprehensive) Coverage: 27/07/2017 - 26/07/2018
Vehicle Reg. No. (Insured):	SGR2567R	Policy No. (Claimant):	
		Excess:	S\$1,500.00
Repairer:	Tat Heng Motor Works (HQ) Blk 10 Ang Mo Kio Ind Park 2A, #02-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 64837103		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 11/01/2018]		
Driver/Custodian (Insured):	TAN HUI XIAN RACHAEL (CHEN HUIXIAN) (34 / Female), NRIC: S8337202H, Tel: +6593673344		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS ☐

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

TAT HENG MOTOR WORKSHOP
BLK 10 ANG MO KIO INDUSTRIAL PARK 2A
#02-09 AMK AUTO POINT
TEL: 6483 7103 FAX: 64817732

REG/CS/PAY/FA
0.8 JAN 2018

Date: 8/1/18

By Fax (6827 2708) Only

MSG Attn: Claims Dept.

544938

Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS
PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES (NIMA)
ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES GY 5193D & SGR 2567R
ALONG Shenton Way at Cross Street Junction ON
4/1/2018 AT 20:20

We have been appointed by the owner, T Marker (S) Pte Ltd
to repair his/her motor vehicle no. GY 5193D

Please be informed that the said vehicle can be inspected at.

Name of workshop : TAT HENG MOTOR WORKS
Address :
Contact person : Gina
Telephone no. : 6483 7103
Fax no. :

Please note that if you fail to conduct the pre-repair inspection within the next 2 working days (excluding any intervening Saturday, Sunday and/or Public Holiday) you will be deemed to have waived your rights to a pre-repair inspection. We will commence repairs thereafter without further notice to you. The owner will also be entitled to claim for the additional loss of use/rental arising as a consequence of this notification.

Yours faithfully,

Gina
Name of workshop

cc: owner - by Post only

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/01/2018 15:33
Date Of Accident	04/01/2018 20:20
Exact Location Of Accident	SHENTON WAY OF CROSS STREET JUNCTION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GY5193D
Insured/Policyholder	
Name Of Registered Owner	T MARKER (S) PTE. LTD.
Co Reg No	201623262W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66849257
Vehicle Particulars	
Manufacturer	NISSAN
Model	CABSTAR
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5090808295
Cover Note Number	
Driver	
Name of Driver	ABU HAYDAR MOHAMMED MOSHARAF HAKMNH
Passport No/FIN	F7970912M
Date Of Birth	12/05/1976
Occupation	OUTDOOR
Date Of Driving Pass	09/02/2015
Driving Experience	2 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83858408
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 119 #03-132 MARSILING RISE
Postcode	730119
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	AFTER RAIN
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACHED ACCIDENT SKETCHPLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGR2567R
Vehicle Make/Model/Colour	LEXUS / BLACK
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	RACHAEL TAN HUI XIAN
NRIC/Passport Number	S8337202H
Contact Number	93673344
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRONT PORTION
No. Of Passenger (Including Driver)	1

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: SIEW HOON
NRIC/FIN No.:

05.01.2017 15:40HNS

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving GY 593 D at Shenton Way of Cross Street Junction on 4/1/2018 @ 20:20.

After the traffic light turned green, my veh start to move forward. But suddenly, a vehicle from my left (no. 4th lane) make an illegal turn to the right lane.

I had to apply emergency brakes, and therefore the veh SGR 2567R from behind hit onto my back.

A - GY 593 D
B - SGR 2567R
C - SLK 4200M Mazda 3 (black)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: SIEW HOON
NRIC/FIN No.:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	3262W

Vehicle Details

Vehicle No.:	GY5193D
Vehicle to be Exported:	No
Intended De-registration Date:	16 Jan 2018
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR
Primary Colour:	Silver
Manufacturing Year:	2005
Engine No.:	QD32206785
Chassis No.:	JN1SF4F23Z0854148
Maximum Power Output:	-
Open Market Value:	\$20,089.00
Original Registration Date:	05 May 2005
First Registration Date:	05 May 2005
Transfer Count:	2
Actual ARF Paid:	\$1,005.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	30 Apr 2020
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$27,653.00
COE Rebate Amount:	\$12,658.00
Total Rebate Amount:	\$12,658.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 16 Jan 2018

OK

View Sent Message

This mail is associated with :

***GY5193D (544872)**
[SGR2567R]

TP
T MARKER (S) PTE. LTD.
Jan 4 2018 8:00PM
[TAN HUI XIAN RACHAEL (CHEN HUIXIAN)]
Tat Heng Motor Works

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **01/02/2018 10:22 AM**.
To MSIG_CWSF1
Subject Pre-repair Inspection

Dear Christina,

Refer to your assignment on 10.01.2018 at 2.28PM.

Please be informed that we have inspected the vehicle GY 5193D on 15.01.2018 at 3.30PM.

At the time of inspection the repairer did not present their estimation to the damaged vehicle.

We will submit our report accordingly.

Best Regards,
Catherine Chong | Admin
LKK Auto Consultants Pte Ltd
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Jan 2018		10 Jan 2018 14:28 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS **[Created by Insurer]**

Insured:	TAN HUI XIAN RACHAEL (CHEN HUIXIAN) , ID: S8337202H, Tel: +6593673344, Email: TANRACHAEL@YAHOO.COM.SG		
Main Claimant:	T MARKER (S) PTE. LTD. , Co. Reg. No.: 201623262W		
Vehicle Reg. No.:	GY5193D	Date of Loss:	04/01/2018 20:00 - :59
Claim Type:	TP / 544872	Policy/Cover Note No.:	S27351564SMF (Comprehensive) Coverage: 27/07/2017 - 26/07/2018
Vehicle Reg. No. (Insured):	SGR2567R	Policy No. (Claimant):	
		Excess:	S\$1,500.00
Repairer:	Tat Heng Motor Works (HQ) Blk 10 Ang Mo Kio Ind Park 2A, #02-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 64837103		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 11/01/2018]		
Driver/Custodian (Insured):	TAN HUI XIAN RACHAEL (CHEN HUIXIAN) (34 / Female), NRIC: S8337202H, Tel: +6593673344		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GY5193D (544872)**
[SGR2567R]
TP
T MARKER (S) PTE. LTD.
Jan 4 2018 8:00PM
[TAN HUI XIAN RACHAEL (CHEN HUIXIAN)]
Tat Heng Motor Works

Upload Documents		Upload Photos	Compose New Letter	View <input type="button" value="View in Browser"/>	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	09/01/18 16:36	Accident Statement From:OD - Reg. No: SGR2567R, Claimant: TAN HUI XIAN RACHAEL (CHEN HUIXIAN)		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/02/18 10:21	General View		Load JPG	<input checked="" type="checkbox"/>
2	01/02/18 10:21	General View		Load JPG	<input checked="" type="checkbox"/>
3	01/02/18 10:21	General View		Load JPG	<input checked="" type="checkbox"/>
4	01/02/18 10:21	General View		Load JPG	<input checked="" type="checkbox"/>
5	01/02/18 10:21	General View		Load JPG	<input checked="" type="checkbox"/>
6	01/02/18 10:21	General View		Load JPG	<input checked="" type="checkbox"/>
7	01/02/18 10:21	General View		Load JPG	<input checked="" type="checkbox"/>
8	01/02/18 10:21	General View		Load JPG	<input checked="" type="checkbox"/>
9	01/02/18 10:21	General View		Load JPG	<input checked="" type="checkbox"/>
10	01/02/18 10:21	General View		Load JPG	<input checked="" type="checkbox"/>
11	01/02/18 10:21	General View		Load JPG	<input checked="" type="checkbox"/>
12	01/02/18 10:21	General View		Load JPG	<input checked="" type="checkbox"/>
13	01/02/18 10:21	General View		Load JPG	<input checked="" type="checkbox"/>
14	01/02/18 10:21	General View		Load JPG	<input checked="" type="checkbox"/>
15	01/02/18 10:21	General View		Load JPG	<input checked="" type="checkbox"/>
16	01/02/18 10:21	General View		Load JPG	<input checked="" type="checkbox"/>
17	01/02/18 10:21	General View		Load JPG	<input checked="" type="checkbox"/>
18	01/02/18 10:21	General View		Load JPG	<input checked="" type="checkbox"/>
19	01/02/18 10:21	General View		Load JPG	<input checked="" type="checkbox"/>
20	01/02/18 10:21	General View		Load JPG	<input checked="" type="checkbox"/>
21	01/02/18 10:21	General View		Load JPG	<input checked="" type="checkbox"/>
22	01/02/18 10:21	General View		Load JPG	<input checked="" type="checkbox"/>
23	01/02/18 10:21	General View		Load JPG	<input checked="" type="checkbox"/>
24	01/02/18 10:21	General View		Load JPG	<input checked="" type="checkbox"/>
25	01/02/18 10:21	General View		Load JPG	<input checked="" type="checkbox"/>
26	01/02/18 10:21	General View		Load JPG	<input checked="" type="checkbox"/>
27	01/02/18 10:21	General View		Load JPG	<input checked="" type="checkbox"/>
28	01/02/18 10:21	General View		Load JPG	<input checked="" type="checkbox"/>
29	01/02/18 10:21	General View		Load JPG	<input checked="" type="checkbox"/>
30	01/02/18 10:21	General View		Load JPG	<input checked="" type="checkbox"/>
31	01/02/18 10:21	General View		Load JPG	<input checked="" type="checkbox"/>

32	01/02/18 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>
33	01/02/18 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>
34	01/02/18 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>
35	01/02/18 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>
36	01/02/18 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>
37	01/02/18 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>
38	01/02/18 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>
39	01/02/18 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>
40	01/02/18 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>
41	01/02/18 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>
42	01/02/18 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>
43	01/02/18 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>
44	01/02/18 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>
45	01/02/18 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>
46	01/02/18 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>
47	01/02/18 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>
48	01/02/18 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>
49	01/02/18 10:21	Chassis Number	1	Load JPG	<input checked="" type="checkbox"/>
50	01/02/18 10:21	Odometer Reading	1	Load JPG	<input checked="" type="checkbox"/>
51	01/02/18 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>
52	01/02/18 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>
53	01/02/18 10:21	General View	1	Load JPG	<input checked="" type="checkbox"/>
				1 per page	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	09/01/18 16:36	TP GIA Report - GY5193D From: OD - Reg. No: SGR2567R, Claimant: TAN HUI XIAN RACHAEL (CHEN HUIXIAN)	1	Load PDF	
2	09/01/18 16:44	PRI	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18000713/GD3E2

Date: 07/02/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: S27351564SMF

Claimant Vehicle No : GY5193D

Insured Vehicle No : SGR2567R

Date of Loss: 04/01/2018

Nature of Claim: TP

Claim No: 544872

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GY5193D

Make & Model: NISSAN CABSTAR, 3.2 D (M)

Engine No: QD32206785

Reg. Date: 05/05/2005 (Man. Year: 2005)

Chassis No: JN1SF4F23Z0854148

Colour: Silver

Odometer: 47938 km

Engine Capacity: 3153 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 155 R13

Front Left Side: Maxxis 5 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: Maxxis 5 mm

Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 10/01/2018

Date Inspected: 15/01/2018 Inspected At:

Tat Heng Motor Works (HQ)
Blk 10 Ang Mo Kio Ind Park 2A, #02-09
AMK Autopoint
Singapore 568047

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 07 Feb 2018)
Parts: N/A NISSAN CABSTAR 3.2 D (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for GY5193D)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >