

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPRJ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTI (PAR
	9	1			STEP BOARD GARNISH LOWER LH			Broken	322		25		241.5	Rev
	10	1			STEP BOARD LOWER LH			Broken	220		25		165	Rev
	11	2			STEP BOARD BRACKET (1PCS ONLY)			Bent	325		25		487.5	Rev

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT
	1		TO REMOVE DAMAGED PANEL WITH ALL NECESSARY COMPONENTS / ATTACHMENTS APPLY HOT-WORKS WHERE NECESSARY STRAIGHTEN FRONT DOOR PILLAR, REPAIR / RESHAPE.	400	0	0	Reviewing	
	2		TO SPRAY PAINT REPLACED / REPAIRED BODY PANELS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS.	500	0	0	Reviewing	
	3		TO REMOVE, REPLACE AIR CON CONDENSER WITH ALL NECESSARY COMPONENTS.	0	0	0	Reviewing	
	4		TO CONDUCT HEADLAMP ALIGNMENT.	20	0	0	Reviewing	

Yes No

Detailed Assessment

Inspection Date *

01/15/2018



Condition of Vehicle at time of survey

General condition

Good

Total Loss

Yes No

Steering (Serviceable)

Yes No

Towing Charges

0

Footbrake (Serviceable)

Yes No

Voluntary Excess

0

Handbrake (Serviceable)

Yes No

Compulsory Excess

0

Engine Modification

Yes No

Young/Inexperienced/Unnamed Driver Excess

0

Pre-accident condition

-- none --

Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

295/80R22.5

Rear Tyre Size

295/80R22.5(D)

FNOL INFORMATION... 3 KALLANG WAY 2A FONG, 347493,
Singapore

POST SURVEY INFORMATION...

CATEGORY Address type

FNOL INFORMATION... Personal Correspondence

POST SURVEY INFORMATION...

CATEGORY Gender

FNOL INFORMATION... Male

POST SURVEY INFORMATION...

CATEGORY Marital status

FNOL INFORMATION... Unknown

POST SURVEY INFORMATION...

CATEGORY Identification #

FNOL INFORMATION... F7967310L

POLICY INFORMAT... TPVD MITSUBISHI

ASSESSMENT INFO...

MITSUBISHI

CATEGORY

Model

POLICY INFORMAT... FV51JJ

ASSESSMENT INFO...

FV51JJD4RDEA

CATEGORY

Type

POLICY INFORMAT...

ASSESSMENT INFO...



CATEGORY

Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY

Chassis No

POLICY INFORMAT...

ASSESSMENT INFO...

FV51JJA10195

CATEGORY

Date of Birth

FNOL INFORMATI...

June 20, 1975

POST SURVEY INF...

mm/dd/yyyy



CATEGORY

Age

FNOL INFORMATI...

43

POST SURVEY INF...

CATEGORY

Occupation

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Education Qualification

FNOL INFORMATI...

Other

POST SURVEY INF...

CATEGORY

Driving Experience

Pending verification -
Direct Settlement

NG Stacey
6568804351
stacey.ng@axa.com.sg

- Messages
- Invoices
- History

Additional Instructions

Add

Documents	Assessment	Metrics	Notes			
CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
User Portal	8/17/18 1:32 PM	2900	2900	Open	Share	Clone
NG Stacey	1/10/18 11:44 PM	3708.59	3708.59	Open	Share	Clone

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Email received from workshop with co_claimant.msg	Letters and Correspondence	Others	PATIL Amol	January 9, 2018

NG Stacey
6568804351
stacey.ng@axa.com.sg

Messages
Invoices
History

Pending verification -
Direct Settlement

Additional Instructions

Documents	Assessment	Metrics	Notes	Document Type	Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
EMAIL TO WSP DD 020818.pdf	Letters and Correspondence	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 2, 2018
EMAIL FROM OI DD 250618.pdf	Letters and Correspondence	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	July 20, 2018
LTA PARF COE Rebate Details.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	July 20, 2018
SPF REPLIED.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	July 20, 2018