

Menmen ^{marus.}
From (Person): Jowyn Tay

ASSIGNMENT (Office)

CTI

Date/Time: 11/01/18 @ 6:17pm

Estimated Cost:

Bill to:

OD ~~TP~~ WS TP RES / OD RES / EVA / DV / MV / CS

To Inspect Vehicle No:

SFC 7118L

Insured:

GBD 2333G

at Workshop in:

Autobay Pte. Ltd.

Tel:

9371 6693

of

1 Kaki Bkt Ave 6 # 02-11, 417883

Policy No:

DMCVSN3049.171700

Claim No:

SNM18D00169C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

08/01/2018

CA / REV / REP. / REV 24 HRS

'wp'

R.O.D. Endorsement

Date/Time:

12/01/18 @ 9:20am

Person Conducted:

Victor

Vehicle

IN OUT

Date/Time

Action/Instructions

✓

File

SFC 7118L - NA / FCI18000560 / r3

D.O.A: 08/01/2018

GBD 2333G - NA / FCI18000560 / r3

D.O.A: 08/01/2018

Surplus *mercup*

REF:

CT1

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: *SFC 7118L*
 at Workshop m/s: *Auto bay*
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seep: _____ Consistent?: Yes or No
 Est. Repairs: *4* days Res.: Yes or No
 Lum Sum: *20* % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: *SFC 7118L* Yr Regn: *5-13*
 Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or *CA*
 Make: *Volkswagen passat* c.o. *1390*
 Colour: *white* A/C: Insured / Std / NI / NA
 Sp. Reading: *81035* T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: *WVWZZZ3CZDP036028*
 Gen. Cond: ☒ Good / Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Modl: *Nil* / S/Rim / STD A/Rim or
 Tyre Size: F: *215/60R16*
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: *6* mm Rear: *6* mm
 R/Bal: *6* mm L/Bal: *6* mm
 D.O.A: *8/1/18* D.O.I: *12/1/18*
 Survey held at: _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear O/S
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

15/1/18 *21A 51455*
confined 2/5 @ 4500 with victor. (Red 10, 542.63, 707)

RECEIVED 6 JAN 2018

Date/Time. File Pass to? ☐ : Preli. Report
☐ : Final Report

Date/Time. File Return to?

2) *16/1- typist*

Report Format: *meri men*

Lump Sum / I.B.I: *4500/-*

Days Of Repair: *4*

Resurvey No. of Trip: *2*

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

Photos

Charts

220

Survey Department Check List (Case Handler)

Reference No. : CS / CTI 18000 T28 / Uvd3
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURA

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: Veron 16 / 1 / 18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18000728/Uvd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 12-01-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 2333G	Veh. Inspected	SFC 7118L
Policy No.	DMCVSN3049171700	Coverage (\$)	0.00
Claim No.	SNM18D00169C02	Excess (\$)	0.00
Assign From	MERIMEN (JOWYN TAY)	Assign Date	12/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	08/01/2018	Inspection Date	12/01/2018
Survey held at	AUTOBAY PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-11 SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Jan 2018		11 Jan 2018 18:17 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	IQUARTZ PTE LTD		
Main Claimant:	TEOH TIONG SAN, ID: S2504431B		
Vehicle Reg. No.:	SFC7118L	Date of Loss:	08/01/2018 09:00 - :59
Claim Type:	TP / SNM18D00169C02	Policy/Cover Note No.:	DMCVSN3049171700
Vehicle Reg. No. (Insured):	GBD2333G	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Autobay Pte Ltd (kaki Bukit) (HQ) 1 KAKI BUKIT AVE 6, #02-11, 417883 Kaki Bukit - Tel: 93716693		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 22/01/2018]		
Adj Asg. Remarks:	PLEASE SURVEY THIRD PARTY, CHECK CONSISTENCY OF THE DAMAGES ON WITHOUT PREJUDICE BASIS. KINDLY LET US HAVE YOUR RECOMMENDATION OF THE REPAIR AMOUNT IF THERE IS NO ESTIMATE PROVIDED DURING PRE REPAIR.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

CATHERINE LIM LLC

林 ADVOCATES & SOLICITORS
翠 NOTARY PUBLIC - 公证官
玲 COMMISSIONER FOR OATHS - 宣誓官
律
師 CATHERINE C.L.LIM
館 DIRECTOR
LL.B (HONS) SINGAPORE - 法律系 - 律師
M.B.A. (BUSINESS LAW) - 商业系 - 碩士

20 Havelock Road #03-01
Central Square Singapore 059765
UEN No. 201310922K

Tel: (65) 6438 5500
Fax: (65) 6438 0111
www.catherinelimllc.com
Email: info@catherinelimllc.com
CATHERINE LIM LLC is a law corporation
with limited liability

Your Ref: GBD 2333G
Our Ref: CL/180131/T/VAC.sg

10 January 2018

To: M/s China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909
Attn: Motor Claims Dept

via fax: 62247175 & by hand

Iquartz Pte Ltd
170 Woodlands Industrial Park E7
Woodlands Industrial Park E
Singapore 757871

CERTIFICATE OF POSTING
(Please be informed that all supporting documents
have been forwarded to your insurer.)

Dear Sir

RE: NOTICE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO
PRE-ACTION PROTOCOL FOR NON-INJURY MOTOR ACCIDENT CLAIMS (NIMA)

ACCIDENT INVOLVING SFC 7118L / GBD 2333G ON 8.1.2018 ALONG BOUNARY ROAD TOWARDS
YIO CHU KANG

We are instructed by **Teoh Tiong San** to notify you of a road traffic accident involving our client's vehicle No. SFC 7118L and vehicle No. GBD 2333G driven by you at the material time. A copy of the Singapore Accident Statement and/or Police Report is enclosed.

As a result of the accident, our client's motor vehicle has been damaged. Before our client proceed to repair the damaged motor vehicle, please let us know within **2 working days** of your receipt of this notice whether you/your insurer would like to conduct a pre-repair survey of the motor vehicle. If we do not receive any reply from you/your insurer within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please let us know your appointed surveyor.

Venue: AutoBay
1 Kaki Bukit Avenue 6
#02-11
Autobay @ Kaki Bukit
Singapore 417883

Contact: 93716639 / 93716693 (Victor) / 97602844 (James)

Yours faithfully

Enc
cc: clients

PDX Intercompany Exchange Pte Ltd



FROM CATHERINE LIM LLC
PDX Box No 8004

11 JAN 2018

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4431B
Vehicle Details	
Vehicle No.:	SFC7118L
Vehicle to be Exported:	No
Intended De-registration Date:	15 Jan 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	PASSAT 1.4 TSI DSG 3623A7
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	CAXB83058
Chassis No.:	WVWZZZ3CZDP036028
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,291.00
Original Registration Date:	16 May 2013
First Registration Date:	16 May 2013
Transfer Count:	0
Actual ARF Paid:	\$23,808.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 May 2023
PARF Rebate Amount:	\$17,856.00
Intended COE Rebate Details	
COE Expiry Date:	15 May 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$62,999.00
COE Rebate Amount:	\$33,599.00
Total Rebate Amount:	\$51,455.00

The information contained herein is correct as at 15 Jan 2018

OK

sgCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Articles

Forum

Tools & Tips

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

July 2016 Bmw 320i Gran Turismo From PML \$158.8K.



1 Owner, Low Mileage Done
11,000km, Full Serviced
Histories And Warranty By PML,
Faster Auto Trading StarAd

Browse by Category

Sort by Date Posted 20 results/page

7 vehicles

Volkswagen Passat

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Volkswagen Passat		Any	Any	2013	Any	Any	Any	Available



Volkswagen Passat 1.4A TSI

\$68,800

\$10,760 /yr

30-Apr-2013

1,390 cc

-

Luxury

Available

Elegant White, Serviced By Agent In July 2017, One Owner Only, Accident Free, Spacious Sedan, Very Well Maintained, Drive Away With Minimum Down Payment, Flexible In-House Loan Packages Available.

Prime Motor & Leasing

Posted: 13-Jan-2018

Tags: 2013 Volkswagen Passat, Volkswagen Passat, Volkswagen, Passat, Used Volkswagen



Volkswagen Passat 1.8A TSI

\$72,888

\$10,900 /yr

06-May-2013

1,798 cc

111,811 km

Luxury

Available

1 Owner, Gearbox Under VW Warranty Till May 2018, VW Agent Service And Maintain, Wear And Tear Parts Had Been Replaced, High Paper Value, STA Evaluation Welcome, PLS Call For Viewing! High Paper Value...

Posted: 12-Jan-2018

Tags: 2013 Volkswagen Passat, Volkswagen Passat, Volkswagen, Passat, Used Volkswagen



Volkswagen Passat CC 1.8A TSI

\$79,800

\$11,390 /yr

23-Apr-2013

1,798 cc

69,000 km

Luxury

Available

(Facelifted Model)! No Gimmicks!, Full VGS Service Record, 5 Seaters, Auto Parking Assist, Keyless Start/Entry, Auto HID Lights With LED DRL, Paddle Shift, Factory Bluetooth/GPS/Reverse Camera, Mileage...

Posted: 12-Jan-2018

Tags: 2013 Volkswagen Passat, Volkswagen Passat, Volkswagen, Passat, Used Volkswagen



Volkswagen Passat 1.4A TSI

\$70,000

\$11,610 /yr

31-Jan-2013

1,390 cc

62,000 km

Sedan

Available

Posted: 10-Jan-2018

Tags: 2013 Volkswagen Passat, Volkswagen Passat, Volkswagen, Passat, Used Volkswagen

DIRECT OWNER

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle



Volkswagen Passat 1.8A TSI

\$80,888

\$11,120 /yr

21-Nov-2013

1,798 cc

79,668 km

Luxury

Available

High Paper Value! Spacious And Reliable. Well Maintained And Service. No Further Repairs Needed. Beautiful Paintwork With Clean And Neat Interior. Bank Or In-House Loan Available.

Posted: 06-Jan-2018

Tags: 2013 Volkswagen Passat, Volkswagen Passat, Volkswagen, Passat, Used Volkswagen

PREMIUM AD



Volkswagen Passat 1.4A TSI

\$69,888

\$10,740 /yr

03-May-2013

1,390 cc

48,000 km

Luxury

Available

Selling At \$10.6K Yearly Depreciation Below Market! Maintained By Meticulous Ex Owner. Mechantronic Replaced At 38K Km Mileage In VW! Drive At Ease Without Fear Of Gearbox Issue. 6 Months Warranty Pro...

Tradit.Com Pte Ltd

Posted: 02-Jan-2018

Tags: 2013 Volkswagen Passat, Volkswagen Passat, Volkswagen, Passat, Used Volkswagen

PREMIUM AD



Volkswagen Passat 1.8A TSI

\$74,800

\$11,090 /yr

06-Jun-2013

1,798 cc

56,500 km

Luxury

Available

Excellent Condition. 100% Accident Free. Under VW Serviced And Maintenance With Gear Box Still Under Warranty. Jet Black Beauty With Interior Black Leather Combination, Low Mileage. Come With Original...

Posted: 30-Nov-2017

Tags: 2013 Volkswagen Passat, Volkswagen Passat, Volkswagen, Passat, Used Volkswagen

COMING AD

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

AUTO BAY PTE LTD

1 Kaki Bukit Ave 6, #02-11 AutoBay @ Kaki Bukit, Singapore 417883
Tel/Fax : 6636 5355

Vehicle No.: SFC 7118L

Model: VOLKSWAGEN PASSAT

Not Allowed
Here
2/5 @ 4500
4/2
17/1/18
Lump Sum After repair

QTY	List Price:	Prices \$
1	Rear bumper 1648.32	20/2e 1688.85
1	Rear bumper tow cover	11 28.80 X
2	Rear bumper chrome mouldings- R/L @ 182.65	o/s cne 365.30 12 C
1	Rear bumper lower spoiler	2e/2w 477.86
1	Rear bumper CTR guide	cna 105.50
2	Rear bumper side guide- R/L @ 68.50	o/s cne 137.00 12 C
2	Rear bumper side retainers- R/L @ 68.50	o/s cne 137.00 12 C
1	Rear bumper reinforcement	20 672.86
4	Rear bumper PDC sensor @ 261.33 235.12 x 2 = 470.24	shared 1045.32 2pos
1	Rear boot lid	1 2119.35 X
1	Rear boot chrome moulding	11 316.20 X
1	Rear boot emblem " PASSAT "	2e 89.95
2	Rear boot lamps- R/L @ 263.54	11 527.08 X
1	Rear boot inner lock	11 185.91 X
1	Rear boot w/strip	2e 191.60
1	Rear end panel	1 1221.72 X
1	Rear end panel garnish	11 211.65 X
1	Rear exhaust silencer	11 1085.60 X
2	Rear exhaust mountings	11 42.25 X
1	Rear exhaust insulator	11 120.63 X
1	Rear floor board	11 380.60 X
1	Rear floor compartment pan	11 641.50 X
2	Rear licence lamps @ 61.50	11 123.00 X
2	Rear taillamps- R/L @ 436.54	o/s cne 873.08 12 C
1	Rear smart keyless control sensor	shared 336.54
		13125.15
		(1312.52)
	Less 10%	Subtotal 11812.63

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display "damaged part(s)" during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No alteration/modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

4749.06
10%
4274.15
1380
4654.15
4523.32

Vehicle No.: SFC 7118L

Special Nett Items:

- 1 Set Rear no plate with holder
- 1 Set Rear bumper guide revet plug

but	60.00	40
nr	80.00	50
Subtotal	140.00	

Labour Charges:

- To checking rear electrical wiring
- To remove, refix interior trims to assist repair
- To remove, refix rear exhaust silencer
- To respray undercoating
- To respray painting and etc
- Panel beating, cut, weld, remove and replacing above parts

	50.00	30
	100.00	60
11	120.00	x
11	120.00	x
	1200.00	650
	1500.00	550
Subtotal	3090.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

15042.63

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118000728/UVD3N2
Date: 18/01/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3049171700
Claimant Vehicle No :	SFC7118L	Insured Vehicle No :	GBD2333G
Date of Loss:	08/01/2018	Nature of Claim:	TP
		Claim No:	SNM18D00169C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFC7118L	Engine No:	CAXB83058
Make & Model:	VOLKSWAGEN PASSAT, 1.4 TSI (B7) (A)	Chassis No:	WVWZZZ3CZDP036028
Reg. Date:	16/05/2013 (Man. Year: 2013)	Odometer:	81035 km
Colour:	White		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	11,952.63	4,364.15	7,588.48	63.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,090.00	1,290.00	1,800.00	58.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,042.63	5,654.15	9,388.48	62.41
Approved Total (Overridden) (\$\$)		4,500.00		
Nett Amount (\$\$)	15,042.63	4,500.00	10,542.63	70.09

INSPECTION

Date of Assignment:	11/01/2018	
Date Inspected:	12/01/2018	Inspected At: Autobay Pte Ltd (kaki Bukit) (HQ) 1 KAKI BUKIT AVE 6, #02-11 Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 Jan 2018)
Parts: 143	VOLKSWAGEN PASSAT 1.4 TSI (B7) (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFC7118L)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Dented/Deformed	1,688.85 FL	*1,648.32 FL
2	1	*REAR BUMPER TOW COVER	Not Necessary	28.80 FL	*- FL
3	1	*REAR BUMPER CHROME MOULDINGS-R/L	O/s Cracked	365.30 FL	*182.65 FL
4	1	*REAR BUMPER LOWER SPOILER	Deformed/Twisted	477.86 FL	*477.86 FL
5	1	*REAR BUMPER CTR GUIDE	Cracked	105.50 FL	*105.50 FL
6	1	*REAR BUMPER SIDE GUIDE-R/L	O/s Cracked	137.00 FL	*68.50 FL
7	1	*REAR BUMPER SIDE RETAINERS-R/L	O/s Cracked	137.00 FL	*68.50 FL
8	1	*REAR BUMPER REINFORCEMENT	Dented	672.86 FL	*672.86 FL
9	1	*REAR BUMPER PDC SENSOR (4 pcs)	Shorted (2 Pcs only)	1,045.32 FL	*470.24 FL
10	1	*REAR BOOT LID	Repair	2,119.35 FL	*- FL
11	1	*REAR BOOT CHROME MOULDING	Not Necessary	316.20 FL	*- FL
12	1	*REAR BOOT EMBLEM PASSAT	Necessary	89.95 FL	*89.95 FL
13	2	*REAR BOOT LAMPS-R/L	Not Necessary	527.08 FL	*- FL
14	1	*REAR BOOT INNER LOCK	Not Necessary	185.91 FL	*- FL
15	1	*REAR BOOT W/STRIP	Necessary	191.60 FL	*191.60 FL
16	1	*REAR END PANEL	Repair	1,221.72 FL	*- FL
17	1	*REAR END PANEL GARNISH	Not Necessary	211.65 FL	*- FL
18	1	*REAR EXHAUST SILENCER	Not Necessary	1,085.60 FL	*- FL
19	2	*REAR EXHAUST MOUNTINGS	Not Necessary	42.25 FL	*- FL
20	1	*REAR EXHAUST INSULATOR	Not Necessary	120.63 FL	*- FL
21	1	*REAR FLOOR BOARD	Not Necessary	380.60 FL	*- FL
22	1	*REAR FLOOR COMPARTMENT PAN	Not Necessary	641.50 FL	*- FL
23	2	*REAR LICENCE LAMPS	Not Necessary	123.00 FL	*- FL
24	1	*REAR TAILLAMPS-R/L	O/s Cracked	873.08 FL	*436.54 FL
25	1	*REAR SMART KEYLESS CONTROL SENSOR	Shorted	336.54 FL	*336.54 FL
26	1	*SET REAR NO PLATE WITH HOLDER	Bent	60.00 FS	*40.00 FS
27	1	*SET REAR BUMPER GUIDE REVET PLUG	Necessary	80.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,265.15	4,839.06
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,312.52	474.91
Total Parts (\$\$)	11,952.63	4,364.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECKING REAR ELECTRICAL WIRING	New	50.00	30.00
2	TO REMOVE,REFIX INTERIOR TRIMS TO ASSIST REPAIR	New	100.00	60.00
3	TO REMOVE,REFIX REAR EXHAUST SILENCER	New	120.00	-
4	TO RESPRAY UNDERCOATING	New	120.00	-
5	TO RESPRAY PAINTING AND ETC	New	1,200.00	650.00
6	PANEL BEATING,CUT,WELD,REMOVE AND REPLACING ABOVE PARTS	New	1,500.00	550.00
Gross Labour Cost (\$\$)			3,090.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >