

10/20/2018

ASS. REC. 1 VP

REF: CS3/FWD18000741/T1d3

range & days

ASSIGNMENT (Office)

From (Person): mermen Taufik clara Li of FWD Date/Time: 11/01/2018 @ 6:08pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBF 3170S Insured: FBL 4508P

at Workshop m/s: Tune In Motor Tel: 6753 4818

or: Blk 1016, Yishun Ind. Park A #01-214

Policy No: PNMC2017-00001288 Claim No: 1201800000957

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh:  
(Client's Record)

D/OA: 29/12/17  
19/01/18 @ 10-10:30am owner waiting

CA / REV / REP. / REV 24 HRS 'wp'

Date/Time: 9:16am @ 12/01/2018 Person Contacted: Linda

R.O.D. Endorsement

Vehicle ID: CT

Date/Time	Action/Inspection
	<u>X</u>
	<u>FBF 3170S - X</u>
	<u>FBL 4508P - X</u>

Taufik

FWD

ASSIGNMENT

Date: 19/6/2018

Estimated Cost: ①

TP / WS / TP RES / CD RES / EVA / INV / MV

To inspect vehicle No: FBF 3170S

at Workshop No: Tune In Motor

at Bldg 1016, Yishun Ind. Park A #01-214

Insured

Policy No

Claims No

Sum Insured Excess

Client's Record: Linda @ 6753 9818

Make of veh: 10-10-30am @ owner waiting

Policy Condition

Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value

DAO Accident Report: Consistent? Yes or No

Q/A - PR Seen: Consistent? Yes or No

Est. Repair: 3 days Res: Yes or No

Sum Supp: % 3 Val: Yes or No

QA / REV / REP: / 24 HRS lwp

Date Person Contacted

Vehicle IN / OUT

Ver No: FBF 3170S

Type: M/Car / ① / Cys / Bus / Van / Lorry / Taxi / Prime Mv / or

Truck / Trailer or

Make: Yamaha Rxz 133

Colour: Red

St Reading: 29206

Eng No: PMY5 RV100A00 32/15

C No

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: N/A / SRim / STD A/Rim or

Tyre Size: R: 2.75 R18  
R: 90/90 R18

BS / DUN / EXNOVA / GY / FS / LIZA / ① / MIZ / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: R Bal 5 mm L Bal mm

Rear: R Bal 5 mm L Bal mm

D.O.A: 19/6/18 @ 1130

Survey held at: Tune In Motor

Des. of Damages: Fnt / Rear / ① / BS / NIS / U/O / Rooftop or

The U/O / Chassis frame / Body Structure affected due to collision



Estimated repair range \$3,000 - \$3,800

18/6/2018

RECEIVED 18 JUN 2018

Date Time For Report: ☐ Prel. Report ☐ Final Report

Days Of Repair: 3

Resurvey No. of Trip: -

Date Time For Return:

Report Format: PRS

Lump Sum / Bkls

Add Fee: ☐ Ste. Insp. \$ ☐ Inten. Insp. \$ ☐ Tech. Insp. \$ ☐ Final Insp. \$

Survey Fee: ☐ Transport \$ ☐ Fuel \$ ☐ Other \$



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FWD SINGAPORE PTE LTD

Ref : CS3/FWD18000741/T1d3

6 TEMASEK BOULEVARD  
#18-01 SUNTEC TOWER 4 SINGAPORE 038986

Date : 12-01-2018



Code : FWD

### 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	FBL 4508P	Veh. Inspected	FBF 3170S
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CLARA LI	Assign Date	12/01/2018

### 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--

### 5. General Information

Accident Date	29/12/2017	Inspection Date
Survey held at	TUNE IN MOTOR BLK 1016 YISHUN PARK A #01-214 SINGAPORE 768758	

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

## Nivitha (LKK Auto)

---

**From:** clara.li@fwd.com  
**Sent:** Thursday, 11 January 2018 6:08 PM  
**To:** assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com  
**Subject:** FW: Our Ref: CY.FBF3170S.18.TI.wp(Lh); Your Ref: FBL 4508P

Hi LKK team,

Please refer to the email below and liaise with TP repairer for PRS.

Please create the case in Merimen.

Thank you.

Kind Regards

Clara Li  
Senior Executive, Claims

FWD Singapore Pte. Ltd.  
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722  
E clara.li@fwd.com  
W fwd.com.sg



	<b>Endowment Plan</b> Get the biggest guaranteed return for a 3 year plan available online. <b>Limited time offer!</b>		<b>2.02% p.a.</b> fwd.com.sg <b>save now</b>
--	--	--	--

**From:** Clara Li Zirong - SGUser  
**Sent:** Thursday, 11 January, 2018 6:08 PM  
**To:** 'Lheny'  
**Cc:** Motor Claims SG - SG Common  
**Subject:** RE: Our Ref: CY.FBF3170S.18.TI.wp(Lh); Your Ref: FBL 4508P

**WITHOUT PREJUDICE**

Dear Lheny,

We regret that we are objecting to your proposed list of surveyors.

We will be appointing, M/s LKK AUTO CONSULTANTS PTE LTD, to conduct the pre-repair survey (PRS) on your

client's vehicle, SLL2025K. We seek your cooperation to inform your client's workshop to arrange the vehicle readily for dismantling with repair estimates during the pre-repair survey.

If there is a change in your client's workshop, please inform us soon. We reserve our rights for re-inspection.

Kind Regards

Clara Li

Senior Executive, Claims

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722

E [clara.li@fwd.com](mailto:clara.li@fwd.com)

W [fwd.com.sg](http://fwd.com.sg)



	<b>Endowment Plan</b> Get the biggest guaranteed return for a 3 year plan available online. <b>Limited time offer!</b>		<b>2.02%</b> p.a. <a href="http://fwd.com.sg">fwd.com.sg</a> <b>save now</b>
--	--	--	--

**From:** Lheny [<mailto:lheny@yoga-legal.com>]

**Sent:** Thursday, 11 January, 2018 6:00 PM

**To:** Clara Li Zirong - SGUser

**Cc:** Motor Claims SG - SG Common

**Subject:** RE: Our Ref: CY.FBF3170S.18.Tl.wp(Lh); Your Ref: FBL 4508P

**WITHOUT PREJUDICE**

Dear Clara Li

We refer to your email on the even date.

Please be informed that we are not agreeable to your proposed motor surveyors. Instead we propose you choose a surveyor from our list of surveyors as appended below:-

1. Winson Goh
2. Amas Ong Poh Meng
3. Ong Ah Keng, Kent

Please be informed that if we do not hear from you **within 2 working days** from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors you will be deemed to have agreed to the any of the above motor surveyors as a "single joint expert".

We will accordingly inform you who the "single joint expert" is to facilitate your conduct of a pre-repair survey.

Best regards,

Lheny

M/s C YOGARAJAH LLC  
883 North Bridge Road  
#19-05 Southbank  
Singapore 198785

Tel: 6292 5838

Fax: 6292 5938

Email: [lheny@yoga-legal.com](mailto:lheny@yoga-legal.com)

---

**From:** [clara.li@fwd.com](mailto:clara.li@fwd.com) [<mailto:clara.li@fwd.com>]

**Sent:** Thursday, 11 January, 2018 5:55 PM

**To:** [lheny@yoga-legal.com](mailto:lheny@yoga-legal.com)

**Cc:** [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com)

**Subject:** RE: Our Ref: CY.FBF3170S.18.TI.wp(Lh); Your Ref: FBL 4508P

**WITHOUT PREJUDICE**

Dear Lheny,

We refer to your letter dated 11 January 2018 of the PRI Notice of your client's vehicle FBF3170S.

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. Appraisals Associates Pte Ltd
5. VICOM Ltd

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

Kind Regards

Clara Li

Senior Executive, Claims

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722

E [clara.li@fwd.com](mailto:clara.li@fwd.com)

W [fwd.com.sg](http://fwd.com.sg)



 <b>FWD</b> Insurance	<b>Endowment Plan</b> Get the biggest guaranteed return for a 3 year plan available online. <b>Limited time offer!</b>		<b>2.02%</b> p.a. fwd.com.sg <b>save now</b>
---	---	--	---

**From:** Lheny [<mailto:lheny@yoga-legal.com>]

**Sent:** Thursday, 11 January, 2018 3:04 PM

**To:** SG Corporate Contact

**Subject:** Our Ref: CY.FBF3170S.18.TI.wp(Lh); Your Ref: FBL 4508P

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES FBF 3170S & FBL 4508P ON 29.12.2017 @ 00:15HRS ALONG CUSCADEN ROAD**

We are instructed by ZURAN BIN KAMISO to notify you of a road traffic accident on 29.12.2017 @ 00:15hrs along Cuscaden Road involving our client's vehicle registration number FBF 3170S and vehicle registration number FBL 4509P driven by you at the material time. A copy of the Singapore accident statement is attached.

As the result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please be informed that our client's vehicle can be inspected at:

M/s. Tune In Motor.Com

Block 1016 Yishun Industrial Park A

#01-214

Singapore 768758

Ms. Linda (6753 4818)

Best regards,

Lheny

M/s C YOGARAJAH LLC

883 North Bridge Road

#19-05 Southbank

Singapore 198785

Tel: 6292 5838

Fax: 6292 5938

Email: [lheny@yoga-legal.com](mailto:lheny@yoga-legal.com)

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

**ATTENTION:**

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.





# SINGAPORE POLICE FORCE



T/20171229/2003

1 of 3

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20171229/2003

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 29/12/2017 01:28		Vide Report No.:		Station Diary No.:	
<b>Informant's Particulars</b>					
Name of Informant: ZURAN BIN KAMISO			Address: APT BLK 468 PASIR RIS DR 6 #06-408 HDB-PASIR RIS SINGAPORE 510468		
ID Type / ID No.: NRIC NO / S8007399B			Contact No.: Home/Office:		Mobile: 91184499
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 37	Date of Birth: 22/03/1980	Type of Informant: Driver		
Race: Malay			Language:		Institution / School Name:
Occupation: ICA OFFICER			Driving Licence Information: Class: 2B,3		Date of Expiry:

**General Information of the Accident**

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 29/12/2017 00:15	Type of Location: Car Park
Location: Along Road 1 CUSCADEN ROAD				
MING ARCADE CARPARK OPPOSITE HARD ROCK CARPARK				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBF3170S	Motorcycle	YAMAHA	RXZ	Red	Seriously Damaged	0
FBL4508P	Motorcycle	SUZUKI			No Damage	0

**Details of Vehicle Insurance**

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBF3170S	AXA INSURANCE SINGAPORE PTE LTD	P1190338	05/05/2017	04/05/2018



Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20171229/2003

**CONTINUATION OF REPORT**

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Driver</b>			
Name	ZURAN BIN KAMISO	ID No.	S8007399B
Related Vehicle	NIL	Contact No.	91184499
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

AT THE ABOVE MENTIONED TIME AND DATE

MY WIFE AND I JUST FINISHED WATCHING MY MOVIE AT AROUND 0015HRS AND WE WENT BACK TO THE CARPARK OF MING ARCADE TO RETRIEVE MY MOTORCYCLE TO GO HOME. HOWEVER WHEN I REACH MY MOTORCYCLE AND WANT TO TAKE MY HELMET OUT, MY WIFE HELMET DROPPED ON THE GROUND. IT WAS PLACED ON MY TANK ON THE RIGHT SIDE. AFTER THAT I SAW THE RIGHT SIDE MIRROR OF MY BIKE WAS DENTED, I ALSO SPOTTED THE FRONT PART OF MY BIKE HAD DAMAGES, AFTER THAT I CHECKED MY BIKE'S CONDITION. THERE ARE MAJOR SCRATCHES ON THE RIGHT SIDE PORTION OF MY BIKE, MY SIDE MIRROR AND MY FRONT HEAD GUARD HAD MAJOR DAMAGE. UPON CHECKING, MY KICKSTART LEVER WAS ALSO DAMAGED, THE WHOLE EXHAUST WAS ALSO DAMAGED AND DENTED. AFTER THAT I APPROACHED THE SECURITY GUARD ARUL TO FIND OUT MORE ABOUT WHAT HAPPENED TO MY BIKE HE TOLD ME THE VEHICLE NUMBER THAT HIT MY BIKE, MY WIFE SPOTTED THAT THERE WAS A CCTV THERE, WE ASKED TO VIEW BACK CCTV BUT WAS INFORMED BY ARUL THAT WE MUST CALL THE MANAGEMENT OF THE MING ARCADE CARPARK. CONTACT: MCST OFFICE 6734 6416. AFTER THAT, I LEFT MY CONTACT NUMBER AND NAME TO THE SECURITY GUARD TO THE STAFF ON DUTY.

THE CARPARK SECURITY SHOWED ME THE DUPLICATE COPY OF THE TICKET OF THE BIKE INVOLVED AND SHOWED THAT HE ENTERED AROUND 2302HRS ON 28/12/2017. AFTER THAT HE TOLD ME TO CALL THE MANAGEMENT TO SETTLE THIS THING. THE SECURITY GUARD ONLY KNEW ABOUT IT THROUGH THE PREVIOUS SHIFT SECURITY GUARD EDDY TELLING HIM.

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	7399B
<b>Vehicle Details</b>	
Vehicle No.:	FBF3170S
Vehicle to be Exported:	No
Intended De-registration Date:	18 Jun 2018
Vehicle Make:	YAMAHA
Vehicle Model:	RXZ
Primary Colour:	Red
Manufacturing Year:	2010
Engine No.:	5PV032115
Chassis No.:	PMY5PV100A0032115
Maximum Power Output:	-
Open Market Value:	\$2,420.00
Original Registration Date:	05 May 2011
First Registration Date:	05 May 2011
Transfer Count:	1
Actual ARF Paid:	\$363.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	04 May 2021
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$2,490.00
COE Rebate Amount:	\$716.00
<b>Total Rebate Amount:</b>	<b>\$716.00</b>

The information contained herein is correct as at 18 Jun 2018

OK

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Mar 2018 <a href="#">Edit Reg</a>		11 Jan 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b>			<b>[Created by adjuster]</b>						
Insured:	<b>MD ROSLAN BIN HASHIM</b> , ID: S7430898H								
Main Claimant:	-								
Vehicle Reg. No.:	<b>FBF3170S</b>	Date of Loss:	29/12/2017 00:00 - :59 <b>[79 Months and 24 Days From LTA Reg Date (Man Yr)]</b>						
Claim Type:	<b>TP / 1201800000957</b>	Policy/Cover Note No.:	PNMC2017-00001288 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	<b>FBL4508P</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Tune In Motor.com (HQ)</b> BLK 1016 YISHUN INDUSTRIAL PARK A.#01-215, 768758 Yishun - Tel:								
Handling Insurer:	<b>FWD Singapore Pte. Ltd. (HQ)</b> - Tel: 6727 5700 ... [Handled by <b>Clara Li Zi Rong</b> ]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... <b>[Final Rpt due 15/03/2018]</b>								
<b>ASSOCIATED MAIL RECEIVED</b>			<a href="#">View All</a>	<a href="#">Compose Case Mail</a>					
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>			<a href="#">View All</a>	<a href="#">Search Tasks</a>					
			<a href="#">Create New Task</a>	<a href="#">Complete</a>					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*FBF3170S (1201800000957)**  
**[FBL4508P]**

TP

-

































**Dec 29 2017 12:00AM**  
**[MD ROSLAN BIN HASHIM]**  
**Tune In Motor.com**

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

### Photos/Images

3 per page ▼

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/06/18 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
2	18/06/18 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
3	18/06/18 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
4	18/06/18 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
5	18/06/18 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
6	18/06/18 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
7	18/06/18 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
8	18/06/18 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
9	18/06/18 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
10	18/06/18 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
11	18/06/18 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
12	18/06/18 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
13	18/06/18 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
14	18/06/18 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
15	18/06/18 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
16	18/06/18 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
17	18/06/18 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
18	18/06/18 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
19	18/06/18 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
20	18/06/18 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
21	18/06/18 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
22	18/06/18 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
23	18/06/18 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
24	18/06/18 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
25	18/06/18 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
26	18/06/18 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
27	18/06/18 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
28	18/06/18 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
29	18/06/18 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
30	18/06/18 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
31	18/06/18 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
32	18/06/18 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
33	18/06/18 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
34	18/06/18 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
35	18/06/18 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images					<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
36	18/06/18 12:39	General View		Load JPG	<input checked="" type="checkbox"/>
37	18/06/18 12:39	General View		Load JPG	<input checked="" type="checkbox"/>
38	18/06/18 12:39	General View		Load JPG	<input checked="" type="checkbox"/>
39	18/06/18 12:39	General View		Load JPG	<input checked="" type="checkbox"/>
40	18/06/18 12:39	General View		Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page		<input checked="" type="checkbox"/>
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)		Thumbnail	Print
1	07/03/18 09:28	OI GIA Report		Load PDF	

## Documents Checklist

### DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD18000741/T1D3S2  
Date: 26/06/2018

## REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNMC2017-00001288  
Claimant Vehicle No: FBF3170S Insured Vehicle No: FBL4508P  
Date of Loss: 29/12/2017 Nature of Claim: TP Claim No: 1201800000957

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: FBF3170S Engine No: 5PV032115  
Make & Model: YAMAHA RXZ, 133cc (M) Chassis No: PMY5PV100A0032115  
Reg. Date: 05/05/2011 (Man. Year: 2010) Odometer: 29206 km  
Colour: Red  
Engine Capacity: 133 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 2.75 R18 Rear Tyre Size: 90/90 R18  
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm  
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 11/01/2018  
Date Inspected: 19/01/2018 Inspected At: Tune In Motor.Com  
Estimated Period of Repair: 3.0 days BLK 1016 YISHUN INDUSTRIAL PARK A.#01-214  
Singapore 768758

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$3,800.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Jun 2018)	
Parts:	N/A	YAMAHA RXZ 133cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBF3170S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >