

CS/CTI18000742/GT0307

Merimen

GA

ASSIGNMENT WORK

Chang Boon Sen

CTI

11/01/18 @ 4:58pm

Estimated Cost

OV / TP / WS / TP RES / OD RES / EVA / INV / MV / CR

To Inspect Vehicle No:

GBD 360R

GBD 9304 U

at Workshop no:

Bodyfix

64837430

at 10 AMK Ind Park 2A # 04-06

Policy No: DMCVSN3051631702

Order No: SNM18 D00196C02

Sum Insured

Excess

Make of Veh:

ICBent's Record

08/01/2018

15/01/2018 @ 2pm owner waiting

CA / REV / REP. / REV 24 HRS

wp?

Date/Time 9:12am @ 12/01/18

Vehicle Condition:

Yu zhen

Vehicle IN/OUT

Date/Time

Action/Inspection

✓

Inspector

GBD 360R x

GBD 9304U x

xbl

CTI

1722M

1510118

GBD 360R

30 Apr 2014


① VIS TR PES CO PES EWS

GBD 360R
Bodyfix
10, AMK Ind Prk 2A # 04-06

Nissan cabstar 2953
Silver
141564

INISC 2F24Z 0855 693

7pm @ owner waiting



Remark: The veh has commenced its recall at the time of inspection.

Est. Recalls
2 days Res Yes or No
20 days Res Yes or No
24 HRS 'up)

195 R 15 (MAXXIS)
165 R 13 (steel Radial)

TOYO YOKO

Front: RFBa 5, LFBa 5
Rear: RFBa 5, LFBa 5
15-01-18
w/s 2:30pm
o/s Frt

06/3 Finalized \$1350 with Yuzhen. (Red: 4299; 7690)

RECEIVED 2010

6B Typist
Final Report

Days Of Repair: 2
Reserve, No. of Tyres: -
220

TP
1350/-

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Jan 2018		11 Jan 2018 16:58 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:	HOCK HUAT SENG CONSTRUCTION PTE LTD, Co. Reg. No.: 201107956C								
Main Claimant:	KHOON ENGINEERING CONTRACTOR PTE. LTD., Co. Reg. No.: 198801722M								
Vehicle Reg. No.:	GBD360R	Date of Loss:	08/01/2018 07:00 - :59						
Claim Type:	TP / SNM18D00196C02	Policy/Cover Note No.:	DMCVSN3051631702 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBD9304U	Policy No. (Claimant):	5088171309						
		Excess:	S\$0.00						
Repairer:	Bodyfix (HQ) 10 ANG MO KIO INDUSTRIAL PARK 2A, #04-06, ANG MO KIO AUTO POINT, 568047 Ang Mo Kio - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 22/01/2018]								
Driver/Custodian (Insured):	MOKAZZAL OMOR HOSSAIN (53 / Male), NRIC: F7860710Q, Tel: +6585109210								
Adj Asg. Remarks:	NO EST, ASSIGN XING GUO QIANG AS SJE.								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS			View All	Search Tasks					
			Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD	Ref : CS/CTI18000742/Gtd3
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909	Date : 12-01-2018
	Code : CTI



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 9304U	Veh. Inspected	GBD 360R
Policy No.	DMCVSN3051631702	Coverage (\$)	0.00
Claim No.	SNM18D00196C02	Excess (\$)	0.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	12/01/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	08/01/2018	Inspection Date	
Survey held at	BODYFIX NO 10 ANG MO KIO INDUSTRIAL PARK 2A #04-06 AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
 B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/01/2018 14:14
Date Of Accident	08/01/2018 07:00
Exact Location Of Accident	PENJURU PLACE / JURONG PENJURU DORMITORY 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBD360R
Insured/Policyholder	
Name Of Registered Owner	KHOON ENGINEERING CONTRACTOR PTE. LTD.
Co Reg No	198801722M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-65708770

Vehicle Particulars

Manufacturer	NISSAN
Model	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Exact Purpose for which vehicle was being used at time of accident	GOING TO WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number *	5088171309
Cover Note Number	

Driver

Name of Driver	VENKATESAN RAJKUMAR
Passport No/FIN	G8090532M
Date Of Birth	25/05/1989
Occupation	OUTDOOR
Date Of Driving Pass	26/08/2014
Driving Experience	3 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98914100
Fax Number	
Contact Number	OTHERS-96927883
Email Address	NOEMAIL

Address 58 PENJURU PLACE
 BLK 50 #02-08 JURONG DORMITORY 1
 Postcode 608562
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own -
 Vehicle -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions RAINING
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO ACCIDENT STATEMENT AS ATTACHED.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBD9304U
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver MOK AZZAL
 NRIC/Passport Number 060793239
 Contact Number 85109210
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver) 4

Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: ANNE ANTOINET PEE UFD
NOC/EPN No: 18 01 2018

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 08.01.2018 @ 0700 HR, I came out from parking lot no. 41. vehicle "B" was parked, waiting to pick up his workers. I'm already out of the lot and was heading for the exit, suddenly vehicle "B" reversed & collided into my car. That's all.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's signature
Date & Time

[Signature]
Driver's Signature
(If driver is not the policyholder)
Date & Time

[Signature] 28.01.2018
Reporting Officer's Signature
Name: 28.01.2018
NRK/RN No: 28012018
ARAB AUTOPOINT 138 139

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1722M
Vehicle Details	
Vehicle No.:	GBD360R
Vehicle to be Exported:	No
Intended De-registration Date:	16 Jan 2018
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	ZD30337605K
Chassis No.:	JN1SC2F24Z0855693
Maximum Power Output:	-
Open Market Value:	\$25,799.00
Original Registration Date:	30 Apr 2014
First Registration Date:	30 Apr 2014
Transfer Count:	0
Actual ARF Paid:	\$1,290.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Apr 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$32,890.00
COE Rebate Amount:	\$20,675.00
Total Rebate Amount:	\$20,675.00

The information contained herein is correct as at 16 Jan 2018

OK

BODYFIX

NO 10 ANG MO KIO INDUSTRIAL PARK 2A #04-06
 AMK AUTOPOINT SINGAPORE 568047
 Tel No. : 62571289 Fax No. : 64837432
 E-Mail : bodyfix@singnet.com.sg
 Tax Reg. No. : 53010635C Buss. Reg. No. : 53010635C

CHINA TAIPING INSURANCE (SINPORE) PTE LTD
 3 ANSON ROAD #16-00 SPRINGLEAF TOWER
 S'079909

Estimate : ES180115

Attention : Motor Claim Department
 Contact : 63896111 Fax No. : 62221033

10%: 1256.85

Date : 15/01/2018
 Vehicle Num. : GBD 360 R
 Make/Model : NISSAN CABSTAR-2014
 Chassis/Eng# : JN1SC2F24Z0855693
 Accident Date : 08/01/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
NETT ITEMS :				
1.	1 PC	FRONT DOOR (RH) / <i>Beac</i>		1,396.50
2.	RH	FRONT DOOR WEATHER STRIP <i>x</i>		151.70
3.	1 PC	FRONT DOOR OUTER HANDLE (RH) <i>x</i> <i>NN</i>		170.00
4.	1 PC	FRONT DOOR LOCK (RH) <i>x</i>		166.70
5.	1 PC	POWER WINDOW MOTOR (FRONT RH) <i>x</i>		524.40
6.	1 PC	POWER WINDOW REGULATOR FRONT RH <i>x</i> <i>NN</i>		112.00
7.	1 PC	FRONT DOOR GLASS (RH) <i>x</i>		760.00
8.	1 PC	SIGNAL LAMP ASSY (FRONT RIGHT) <i>x</i> <i>NN</i>		53.40
9.	1 PC	FRONT CORNER PANEL (RH) <i>x</i>		389.90
10.	RH-FRT	STEP GARNISH <i>x</i>		139.40
Nett Total S\$:				3,864.00
SPECIAL NETT ITEMS :				
1.	1 PC	COMPANY ADDRESS STICKER / <i>acc</i>		25.00
Special Nett Total S\$:				25.00
LABOUR :				
RUST-PROOFING ON THE ACCIDENT AFFECTED PORTIONS				<i>NN x</i> 60.00
LABOUR TO REPLACE ABOVE PARTS, PANEL BEAT, REPAIR & RE-ALIGN DAMAGE PARTS				<i>250</i> 300 900.00
TO SPRAY PAINT RH FRONT DOOR, CORNER PANEL & AFFECTED AREAS				<i>200</i> 800.00
Labour Total S\$:				1,760.00
SingDollars : Five Thousand Six Hundred Forty-Nine Only				
			<i>1721.85</i>	
			1392.55	
			<i>20%</i> 100 1350 400	
E. & O.E.			Total S\$:	5,649.00

[Signature]
 for BODYFIX

2 Days.
Impsum Repair
After repair photos.
Guo Qiao - 82880282
15/1/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Jan 2018		11 Jan 2018 16:58 Edit Adj Rpt	S\$1,350.00 Edit Estimates	S\$1,350.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]
Insured:	HOCK HUAT SENG CONSTRUCTION PTE LTD , Co. Reg. No.: 201107956C			
Main Claimant:	KHOON ENGINEERING CONTRACTOR PTE. LTD. , Co. Reg. No.: 198801722M			
Vehicle Reg. No.:	GBD360R	Date of Loss:	08/01/2018 07:00 - :59	
Claim Type:	TP / SNM18D00196C02	Policy/Cover Note No.:	DMCVSN3051631702 (Comprehensive)	
Vehicle Reg. No. (Insured):	GBD9304U	Policy No. (Claimant):	5088171309	
		Excess:	S\$0.00	
Repairer:	Bodyfix (HQ) 10 ANG MO KIO INDUSTRIAL PARK 2A, #04-06, ANG MO KIO AUTO POINT, 568047 Ang Mo Kio - Tel:			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]			
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 22/01/2018]			
Driver/Custodian (Insured):	MOKAZZAL OMOR HOSSAIN (53 / Male), NRIC: F7860710Q, Tel: +6585109210			
Adj Asg. Remarks:	NO EST, ASSIGN XING GUO QIANG AS SJE.			

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS <input type="checkbox"/>										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***GBD360R (SNM18D00196C02)**
[GBD9304U]

TP

KHOON ENGINEERING CONTRACTOR PTE. LTD.

Jan 8 2018 7:00AM

[HOCK HUAT SENG CONSTRUCTION PTE LTD]

Bodyfix

View

Assessment Reports			1 per page	<input type="checkbox"/>	
No	Finalized On	AMK Autopoint Pte Ltd (HQ)		Thumbnail	Print
1	08/01/18 14:54	Accident Statement	<input type="checkbox"/>	Load HTM	
Photos/Images			3 per page	<input type="checkbox"/>	
No	Finalized On	AMK Autopoint Pte Ltd (HQ)		Thumbnail	Print
1	08/01/18 14:17	Accident Photo [Linked Accident Report Documents]	<input type="checkbox"/>	Load JPG	<input type="checkbox"/>
2	08/01/18 14:18	Accident Photo [Linked Accident Report Documents]	<input type="checkbox"/>	Load JPG	<input type="checkbox"/>
3	08/01/18 14:18	Accident Photo [Linked Accident Report Documents]	<input type="checkbox"/>	Load JPG	<input type="checkbox"/>
4	08/01/18 14:18	Accident Photo [Linked Accident Report Documents]	<input type="checkbox"/>	Load JPG	<input type="checkbox"/>
5	08/01/18 14:18	Accident Photo [Linked Accident Report Documents]	<input type="checkbox"/>	Load JPG	<input type="checkbox"/>
6	08/01/18 14:18	Accident Photo [Linked Accident Report Documents]	<input type="checkbox"/>	Load JPG	<input type="checkbox"/>
7	08/01/18 14:18	Accident Photo [Linked Accident Report Documents]	<input type="checkbox"/>	Load JPG	<input type="checkbox"/>
8	08/01/18 14:18	Accident Photo [Linked Accident Report Documents]	<input type="checkbox"/>	Load JPG	<input type="checkbox"/>
9	08/01/18 14:19	Accident Photo [Linked Accident Report Documents]	<input type="checkbox"/>	Load JPG	<input type="checkbox"/>
10	08/01/18 14:19	Accident Photo [Linked Accident Report Documents]	<input type="checkbox"/>	Load JPG	<input type="checkbox"/>
11	08/01/18 14:19	Accident Photo [Linked Accident Report Documents]	<input type="checkbox"/>	Load JPG	<input type="checkbox"/>
12	08/01/18 14:19	Accident Photo [Linked Accident Report Documents]	<input type="checkbox"/>	Load JPG	<input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	06/03/18 14:22	General View	<input type="checkbox"/>	Load JPG	<input type="checkbox"/>
2	06/03/18 14:22	General View	<input type="checkbox"/>	Load JPG	<input type="checkbox"/>
3	06/03/18 14:22	General View	<input type="checkbox"/>	Load JPG	<input type="checkbox"/>
4	06/03/18 14:22	General View	<input type="checkbox"/>	Load JPG	<input type="checkbox"/>
5	06/03/18 14:22	General View	<input type="checkbox"/>	Load JPG	<input type="checkbox"/>
6	06/03/18 14:22	General View	<input type="checkbox"/>	Load JPG	<input type="checkbox"/>
7	06/03/18 14:22	General View	<input type="checkbox"/>	Load JPG	<input type="checkbox"/>
8	06/03/18 14:22	General View	<input type="checkbox"/>	Load JPG	<input type="checkbox"/>
9	06/03/18 14:22	General View	<input type="checkbox"/>	Load JPG	<input type="checkbox"/>
10	06/03/18 14:22	General View	<input type="checkbox"/>	Load JPG	<input type="checkbox"/>
11	06/03/18 14:22	General View	<input type="checkbox"/>	Load JPG	<input type="checkbox"/>
12	06/03/18 14:22	General View	<input type="checkbox"/>	Load JPG	<input type="checkbox"/>
13	06/03/18 14:22	General View	<input type="checkbox"/>	Load JPG	<input type="checkbox"/>
14	06/03/18 14:22	General View	<input type="checkbox"/>	Load JPG	<input type="checkbox"/>

15	06/03/18 14:22	General View		Load JPG	
16	06/03/18 14:22	General View		Load JPG	
17	06/03/18 14:22	General View		Load JPG	
18	06/03/18 14:22	General View		Load JPG	
19	06/03/18 14:22	General View		Load JPG	
20	06/03/18 14:22	General View		Load JPG	
21	06/03/18 14:22	General View		Load JPG	
22	06/03/18 14:22	General View		Load JPG	
23	06/03/18 14:22	General View		Load JPG	
24	06/03/18 14:22	General View		Load JPG	
25	06/03/18 14:22	General View		Load JPG	
26	06/03/18 14:22	General View		Load JPG	
27	06/03/18 14:22	General View		Load JPG	

Documentation			1 per page		
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	11/01/18 13:33	OI GIA REPORT		Load PDF	
No	Finalized On	AMK Autopoint Pte Ltd (HQ)		Thumbnail	Print
1	08/01/18 14:43	Sketch Plan [Linked Accident Report Documents]		Load JPG	
2	08/01/18 14:43	Sketch Plan #2 [Linked Accident Report Documents]		Load JPG	

Linked Accident Report Documents

View View in Browser ▼

Assessment Reports			1 per page		
No	Finalized On	AMK Autopoint Pte Ltd (HQ)		Thumbnail	Print
1	08/01/18 14:54	Accident Statement		Load HTM	

Photos/Images			3 per page		
No	Finalized On	AMK Autopoint Pte Ltd (HQ)		Thumbnail	Print
1	08/01/18 14:17	Accident Photo		Load JPG	
2	08/01/18 14:18	Accident Photo		Load JPG	
3	08/01/18 14:18	Accident Photo		Load JPG	
4	08/01/18 14:18	Accident Photo		Load JPG	
5	08/01/18 14:18	Accident Photo		Load JPG	
6	08/01/18 14:18	Accident Photo		Load JPG	
7	08/01/18 14:18	Accident Photo		Load JPG	
8	08/01/18 14:18	Accident Photo		Load JPG	
9	08/01/18 14:19	Accident Photo		Load JPG	
10	08/01/18 14:19	Accident Photo		Load JPG	
11	08/01/18 14:19	Accident Photo		Load JPG	
12	08/01/18 14:19	Accident Photo		Load JPG	

Documentation			1 per page		
No	Finalized On	AMK Autopoint Pte Ltd (HQ)		Thumbnail	Print
1	08/01/18 14:43	Sketch Plan		Load JPG	
2	08/01/18 14:43	Sketch Plan #2		Load JPG	

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CT118000742/GTD3E2
Date: 09/03/2018**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3051631702		
Claimant Vehicle No :	GBD360R	Insured Vehicle No :	GBD9304U		
Date of Loss:	08/01/2018	Nature of Claim:	TP	Claim No:	SNM18D00196C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBD360R		Engine No:	ZD30337605K
Make & Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)		Chassis No:	JN1SC2F24Z0855693
Reg. Date:	30/04/2014 (Man. Year: 2014)		Odometer:	141564 km
Colour:	Silver			
Engine Capacity:	2953 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	165 R13
Front Left Side:	Maxxis 5 mm	Rear Left Side:	Steel Radial 5 mm
Front Right Side:	Maxxis 5 mm	Rear Right Side:	Steel Radial 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repalrer's	Adjuster's	Difference	Diff %	
Parts	3,889.00	1,271.85	2,617.15	67.30	
Miscellaneous Items	0.00	0.00	0.00		
Labour	1,760.00	450.00	1,310.00	74.43	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (\$\$)	5,649.00	1,721.85	3,927.15	69.52	
Approved Total (Overridden) (\$\$)		1,350.00			
	(\$\$)	5,649.00	1,350.00	4,299.00	76.10
	+ GST 7.00/7.00% (\$\$)	395.43	94.50	300.93	76.10
	Nett Amount (\$\$)	6,044.43	1,444.50	4,599.93	76.10

INSPECTION

Date of Assignment:	11/01/2018	
Date Inspected:	15/01/2018 Inspected At:	Bodyfix (HQ) 10 ANG MO KIO INDUSTRIAL PARK 2A, #04-06, ANG MO KIO AUTO POINT Singapore 568047
Estimated Period of Repair:	2.0 days	

3/9/2018

Adjuster Report

Adjuster: MA CHIN FOOK

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 09 Mar 2018)**Parts:** N/A NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for GBD360R)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR (RH)	Buckled	1,396.50 F	*1,396.50 FN
2	1		*RH FRONT DOOR WEATHERSTRIP	Not Necessary	151.70 F	*- FN
3	1		*FRONT DOOR OUTER HANDLE (RH)	Not Necessary	170.00 F	*- FN
4	1		*FRONT DOOR LOCK (RH)	Not Necessary	166.70 F	*- FN
5	1		*POWER WINDOW MOTOR (FRONT RH)	Not Necessary	524.40 F	*- FN
6	1		*POWER WINDOW REGULATOR FRONT RH	Not Necessary	112.00 F	*- FN
7	1		*FRONT DOOR GLASS (RH)	Not Necessary	760.00 F	*- FN
8	1		*SIGNAL LAMP ASSY (FRONT RIGHT)	Not Necessary	53.40 F	*- FN
9	1		*FRONT CORNER PANEL (RH)	Not Necessary	389.90 F	*- FN
10	1		*RH-FRT STEP GARNISH	Not Necessary	139.40 F	*- FN
11	1		*COMPANY ADDRESS STICKER	Necessary	25.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	3,889.00	1,411.50
- Nett Item Discount on N Items 0.00/10.00% (\$\$)	0.00	139.65
Total Parts (\$\$)	3,889.00	1,271.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RUST-PROOFING ON THE ACCIDENT AFFECTED PORTIONS	New	60.00	0.00
2	LABOUR TO REPLACE ABOVE PARTS, PANEL BEAT, REPAIR & RE-ALIGN DAMAGE PARTS	New	900.00	250.00
3	TO SPRAY PAINT RH FRONT DOOR, CORNER PANEL & AFFECTED AREAS	New	800.00	200.00
Gross Labour Cost (\$)			1,760.00	450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >