



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2011 PORSCHE CAYENNE TIPTRONIC (V6) PORXXX (SKH8649D)

Date of Loss

7 January 2018

Time of Loss

21.00

Loss Description

SKH8649D (INSD) C/W SLF9023B (TP)

Comment

Workshop Details

Total Rebate Amount

75691

Nett Loss Amount

\$87,309.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

07/05/2018



Days of work completion *

115



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SKH8649D

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

14/11/2011



Mileage

71022

Age of Vehicle

6

CATEGORY

Manufacturing Year

Driver Details

POLICY INFORMAT... 2011

CATEGORY

Driver Name

ASSESSMENT INFO...

2011

FNOL INFORMATI...

KONG YUEN YING SANDRA

CATEGORY

Make

POLICY INFORMAT...

PORSCHE CAYENNE TIPTRONIC (V6)

ASSESSMENT INFO...

PORSCHE

CATEGORY

Model

POLICY INFORMAT...

PORXXX

ASSESSMENT INFO...

CAYENNE TIPTRONIC (V6)

CATEGORY

Type

POLICY INFORMAT...

ASSESSMENT INFO...



CATEGORY

Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY

Chassis No

POLICY INFORMAT...

WP1ZZZ92ZCLA02825

POST SURVEY INF...

CATEGORY

Date of Birth

FNOL INFORMATI...

18 October 1970

POST SURVEY INF...

dd/mm/yyyy



CATEGORY

Age

FNOL INFORMATI...

47

POST SURVEY INF...

CATEGORY

Occupation

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Education Qualification

FNOL INFORMATI...

Other

POST SURVEY INF...



CATEGORY

Driving Experience

ASSESSMENT INFO...	WP1ZZZ92ZCLA02825
CATEGORY	Engine No
POLICY INFORMAT...	C03806
ASSESSMENT INFO...	C03806
CATEGORY	Engine Capacity
POLICY INFORMAT...	
ASSESSMENT INFO...	3598
CATEGORY	Sum Insured
POLICY INFORMAT...	176000
ASSESSMENT INFO...	0
CATEGORY	Market Value
POLICY INFORMAT...	0
ASSESSMENT INFO...	163000

FNOL INFORMATI...	0
POST SURVEY INF...	
CATEGORY	Driver License #
FNOL INFORMATI...	
POST SURVEY INF...	
CATEGORY	License Type
FNOL INFORMATI...	
POST SURVEY INF...	
CATEGORY	License Issue Date
FNOL INFORMATI...	
POST SURVEY INF...	dd/mm/yyyy
CATEGORY	License Expiration Date
FNOL INFORMATI...	
POST SURVEY INF...	dd/mm/yyyy
CATEGORY	Address

FNOL INFORMATI... 23 ST MARTIN'S DRIVE, 258004,
Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Residential

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Female

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Single

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

S7038459J



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Detailed Assessment

Inspection Date *

15/01/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

2000

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

255/55R18

Condition of Vehicle at time of survey

General condition

Fair



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair



Tyre Condition

Spare wheel

Rear Tyre Size

255/55R18

Front left side

MICHELIN6mm

Front right side

MICHELIN6mm

Rear left side

MICHELIN6mm

Rear right side

MICHELIN6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

☒ Yes ☐ No

Save

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

Add

Approve

Deny

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)
☐		1	1			BARE DOOR SHELL RIGHT FRON			Buckled	2767.4		20		2213.92	Reviewir
☐		2	1			BLIND RIVET			Necessary	1.1		20		0.88	Reviewir
☐		3	2			BLIND RIVET NUT			Necessary	1.7		20		2.72	Reviewir
☐		4	2			BLIND RIVET NUT			Necessary	2.8		20		4.48	Reviewir
☐		5	1			EXPANDER NUT			Necessary	1.5		20		1.2	Reviewir
☐		6	2			INSULATION DOOR			Necessary	15.4		20		24.64	Reviewir
☐		7	1			(WH17) ADHESIVE TAPE DOOR IN WHIT			Serviceable	0	0	0	0	0	Deny
☐		8	3			NUT SPECIAL NUT			Necessary	1.2		20		2.88	Reviewir
☐		9	1			DOOR SEAL OUTER DOOR FRONT			Necessary	390.3		20		312.24	Reviewir
☐		10	1			CAVITY PRESERVATION			Serviceable	0	0	0	0	0	Deny
☐		11	9			GROMMET			Necessary	2.2		20		15.84	Reviewir
☐		12	1			BLIND RIVET			Necessary	1.1		20		0.88	Reviewir

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		13	1			P958-533-012-00-GRV/BARE DOOR SHELL RIGH			Bent	2682.1		20		2145.68	Reviewir
		14	1			BLIND RIVET			Necessary	1.1		20		0.88	Reviewir
		15	2			BLIND RIVET NUT			Necessary	2.8		20		4.48	Reviewir
		16	1			EXPANDER NUT			Necessary	1.5		20		1.2	Reviewir
		17	3			NUT SPECIAL NUT			Necessary	1.2		20		2.88	Reviewir
		18	2			INSULATION DOOR			Necessary	15.4		20		24.64	Reviewir
		19	1			(WH17) ADHESIVE TAPE DOOR IN WHIT			Serviceable	0	0	0	0	0	Deny
		20	1			DOOR SEAL OUTER DOOR REAR			Necessary	331.9		20		265.52	Reviewir
		21	1			CAVITY PRESERVATION			Serviceable	0	0	0	0	0	Deny
		22	9			GROMMET			Necessary	2.2		20		15.84	Reviewir
		23	1			REAR RH DOOR SEAL, FRONT			Necessary	83.6		20		66.88	Reviewir
		24	1			DOOR SEAL OUTER REAR			Serviceable	0	0	0	0	0	Deny
		25	1			P958-559-478-01-7Z7/COVER SIDE WINDOW RE			Necessary	243.1		20		194.48	Reviewir

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)
		26	1			COVER SIDE WINDOW FRONT RI			Necessary	243.1		20		194.48	Reviewir
		27	1			WHEEL COVER SIDE SECTION R			Serviceable	0	0	0	0	0	Deny
		28	1			STRIP DOOR REAR RIGHT			Damaged	339.4		20		271.52	Reviewir
		29	1			STRIP DOOR FRONT RIGHT			Damaged	536.8		20		429.44	Reviewir
		30	1			ADHESIVE TAPE			Necessary	28.2		20		22.56	Reviewir
		31	1			STICKER			Necessary	16.4		20		13.12	Reviewir

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REM
		1		TO REMOVE / REPLACE RH FRONT / REAR DOOR & OTHER AFFECTED BODY PARTS, INCLUDING PANEL BEAT / STRAIGHTEN B PILLAR & FITTINGS WHICHEVER NECESSARY INCLUDING ALIGNMENT OF BODY STRUCTURE	4680	0	0	Reviewing		
		2		TO SPRAY PAINT RH FRONT / REAR DOOR & B PILLAR	2750	0	0	Reviewing		
		3		TO CARRY OUT BODY CAVITY PRESERVATION TO LL AFFECTED AREAS	100	0	0	Reviewing		
		4		TO REMOVE, REPLACE, REFIT DOORS INCLUDE TRANSFER WINDOW MECHANISM FROM DAMAGE DOOR TO NEW DOOR & CHECK FUNCTION ABILITY	1560	0	0	Reviewing		

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REM
	 	5		TO RE-PROGRAMMED SYSTEM & ERASE FAULT CODES AFTER ACCIDENT REPAIR	600	0	0	Reviewing		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

EDIT

SR
NO

NAME

ACTION

AMOUNT

COMMENT

REMOVE



1

DAYS OF
REPAIR : 7
DAYS

Reviewing



2

SUNDRIES

Reviewing

50

NECESSARY



Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount \$13,973.28

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$9,690.00	\$9,690.00
Spare Parts	\$6,233.28	\$6,233.28
Miscellaneous	\$50.00	\$50.00
Excess	-\$2,000.00	-\$2,000.00

Submit for Review