



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/LCR18000760/Ujs3		
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120		Date : 12-01-2018		
		Code : LCR		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLR 967Z	Veh. Inspected	SKG 3514Y	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	12/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	10/01/2018	Inspection Date	12/01/2018	
Survey held at	FOCUS AUTO PTE LTD NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-48 SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883
 TEL: 6886 9097 FAX: 6886 9095 Email: focus.autopteltd@yahoo.com.sg
 GST:201004495R RCB NO:201004495R

Not Authorized
 1/3 @ 9600/1
 8day
 12/1/18

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
 TEL: 6419 3000 FAX: 6835 7416
 ATTN: Motor Claim Department
 Your Ref No: SKG3514Y
 Claim Type: Third Party
 Accident Date: 10/01/2018
 TP Veh Reg No: SLR967Z

Estimate No: EST0000565
 Date: 13 Jan 2018
 Policy No: 7VPCP1734340
 Veh Reg No: SKG3514Y
 Make/Model: VOLKSWAGEN JETTA
 Chassis No: WVWZZZ16ZCM150608
 Engine No: CAXB31340
 Reg. Date: 24/08/2012

Estimate Repair Cost to Vehicle No :SKG3514Y

PAGE:1/2

Description	U/Price	Quantity	List Price SS	Amount SS
SKG3514Y VOLKSWAGEN JETTA				
List Price				
1 Front Bonnet	816.3000	1 PC	816.30	✓
2 Front Bonnet Lock	174.5000	1 PC	174.50	✓
3 Front Bonnet Lock Catch	75.5000	1 PC	75.50	✓
4 Front Support Panel	908.7000	1 PC	908.70	✓
5 Front Head Lamp	681.2000	2 PC	1,362.40	✓
6 Front Head Lamp Top Panel	46.5000	2 PC	93.00	✓
7 Front Support Centre Bracket	115.5000	1 PC	115.50	✓
8 Front Bumper	890.0000	1 PC	890.00	✓
9 Front Bumper Side Retainer	35.8000	2 PC	71.60	✓
10 Front Bumper Reinforcement	670.1000	1 PC	670.10	✓
11 Front Support Panel Side Garnish	40.2000	2 PC	80.40	✓
12 Front Aircon Condenser	865.0000	1 PC	865.00	✓
13 Front Radiator	601.2000	1 PC	601.20	✓
14 Front Number Plate Support	40.2000	1 PC	40.20	✓
15 Rear Boot	1,450.0000	1 PC	1,450.00	✓
16 Rear Boot Lock	143.5000	1 PC	143.50	✓
17 Rear Boot Rubber	263.8000	1 PC	263.80	✓
18 Rear Boot Emblem (Jetta)	35.4000	1 PC	35.40	✓
19 Rear Boot Emblem (Tsi)	35.4000	1 PC	35.40	✓
20 Rear End Panel	962.5000	1 PC	962.50	✓
21 Rear Bumper	1,123.0000	1 PC	1,123.00	✓
22 Rear Bumper Side Bracket	89.5000	1 PC	89.50	✓
23 Rear Bumper Lower Pad	540.0000	1 PC	540.00	✓
24 Rear Bumper Reinforcement	640.0000	1 PC	640.00	✓
25 Rear Bumper Inner Top beam	124.2000	1 PC	124.20	✓
26 Rear Bumper Top Corner Bracket	48.2000	1 PCS	48.20	✓
			12,219.90	
Less 10%			1,221.99	10,997.91
Special Net				
27 Front Number Plate	50.0000	1 PC	50.00	✓
28 Rear Bumper Sensor	300.0000	1 set	300.00	✓
			350.00	350.00

10200
 940

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883
 TEL: 6886 9097 FAX: 6886 9095 Email: focus.autopte ltd@yahoo.com.sg
 GST: 201004495R RCB NO: 201004495R

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
TEL: 6419 3000 **FAX:** 6835 7416
ATTN: Motor Claim Department
Your Ref No: SKG3514Y
Claim Type: Third Party
Accident Date: 10/01/2018
TP Veh Reg No: SLR967Z

Estimate No: EST0000565
Date: 13 Jan 2018
Policy No: 7VPCP1734340
Veh Reg No: SKG3514Y
Make/Model: VOLKSWAGEN JETTA
Chassis No: WVVZZZ16ZCM150608
Engine No: CAXB31340
Reg. Date: 24/08/2012

Estimate Repair Cost to Vehicle No :SKG3514Y

PAGE:2/2

Description	U/Price	Quantity	List Price <u>SS</u>	Amount <u>SS</u>
Labour				
29 Panel Beating	1,800.0000	1 PC	1,800.00	1200
30 Check Wiring & Diagnostic Check	180.0000	1 PC	180.00	30
31 Rust Proofing	100.0000	1 PC	100.00	80
32 To Remove & Replace Air Con Condenser and Change Gas	160.0000	1 PC	160.00	100
33 To Remove and Replace Radiator	80.0000	1 PC	80.00	10
34 To Remove & Replace Bumper Sensor	80.0000	1 PC	80.00	10
35 Spray Painting	1,200.0000	1 PC	1,200.00	1
			3,600.00	3,600.00
			Total	SS 14,947.91

TOTAL: SINGAPORE DOLLAR FOURTEEN THOUSAND NINE HUNDRED FORTY SEVEN AND CENTS NINETY ONE ONLY

For FOCUS AUTO PTE LTD

Focus Auto Pte Ltd
 No 1 Kaki Bukit Ave 6 Auto Bay
 #02-50 Singapore 417883
 AUTHORIZED SIGNATURE
 Tel: 66349895

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

2008 Nov Hyundai Avante 1.6M At Only \$10.5K Cheapest.



Low Mileage, Immaculate Inside
And Out. Recently Serviced,
Road Tax Paid! Cheap.
Direct Owner StarAd



Browse by Category

« Back (1 2) Next »

Sort by Date Posted

20 results/page

31 vehicles

Volkswagen Jetta

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Volkswagen Jetta		Any	Any	2012	Any	Any	Any	Available
	Volkswagen Jetta	Jetta Sport 1.4A TSI	\$59,800	\$10,050 /yr	04-Oct-2012	1,390 cc	120,000 km	Sedan	Available
1 Owner, High PARF Value, 158BHP Sports Model, Well Maintained, Interior Look And Feel Clean And Neat, Well Maintained By Previous Owner. Kindly Contact Our Professional And Friendly Sales Executives ...									
Posted: 12-Jan-2018 Tags: 2012 Volkswagen Jetta, Volkswagen Jetta, Volkswagen, Jetta, Used Volkswagen									
	Volkswagen Jetta	Jetta 1.4A TSI	\$48,500	\$9,440 /yr	18-Jan-2012	1,390 cc	135,305 km	Sedan	Available
Downpay Merely \$4850, \$952 For 47 Month. Tempest Blue Metallic Paint With Black Interior. Well Maintained By Meticulous Owner! Sparkling Condition! Shelter Parked. STA Evaluation Welcome! Drive With A...									
Car Buyers Automotive Pte Ltd									
Posted: 11-Jan-2018 Tags: 2012 Volkswagen Jetta, Volkswagen Jetta, Volkswagen, Jetta, Used Volkswagen									
	Volkswagen Jetta	Jetta 1.4A TSI	\$46,888	\$9,290 /yr	03-Feb-2012	1,390 cc	86,000 km	Sedan	Available
90% Loan Available, 1 Owner, Classic White On Black Interior, Low Mileage Done At 14300Km Yearly, Immaculate Condition, Well Maintained, Trade In Welcome, Call Now!									
Posted: 11-Jan-2018 Tags: 2012 Volkswagen Jetta, Volkswagen Jetta, Volkswagen, Jetta, Used Volkswagen									
	Volkswagen Jetta	Jetta 1.4A TSI Comfort	\$55,800	\$9,280 /yr	27-Nov-2012	1,390 cc	81,000 km	Sedan	Available
Limited Edition Comfort Unit At Only \$6k At Super Low Depreciation. Meticulous Condition, 1 And Only Owner, Full VW Serviced And Maintained With Full Records To Boot, Not To Mention Genuine Super Low ...									
Posted: 10-Jan-2018 Tags: 2012 Volkswagen Jetta, Volkswagen Jetta, Volkswagen, Jetta, Used Volkswagen									
Car Buying	Car Selling	Car Aftermarket							
Car Ownership	On The Move	Lifestyle							
	Volkswagen Jetta	Jetta 1.4A TSI	\$52,700	\$9,500 /yr	19-Jun-2012	1,390 cc	130,000 km	Sedan	Available
Sure Win CNY Ang Bao Draw With Every Purchase With Us! Up To \$888 In Cash And Prizes! Regularly Maintained! Sporty And Comfortable Drive! Fuel Efficient And Low Maintenance! Low Downpayment! Hot Sell...									
Euro Performance Asia Pte Ltd									
Posted: 10-Jan-2018 Tags: 2012 Volkswagen Jetta, Volkswagen Jetta, Volkswagen, Jetta, Used Volkswagen									
	Volkswagen Jetta	Jetta 1.4A TSI	\$54,800	\$9,840 /yr	12-Jul-2012	1,390 cc	69,986 km	Sedan	Available
No Gimicks: Down Payment \$5480 With Monthly \$998! Full VW Service Record, 1 Owner, Mileage Done 12800km Yearly, Paddle Shifters, Multi Function Steering, Turbo Charged Engine, Silver In Colour, Last ...									
Posted: 10-Jan-2018 Tags: 2012 Volkswagen Jetta, Volkswagen Jetta, Volkswagen, Jetta, Used Volkswagen									
Volkswagen Jetta 1.4A TSI	\$55,800	\$9,520 /yr	12-Oct-2012	1,390 cc	67,339 km	Sedan	Available		



Compare

Graded B by SFR

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5520Z
Vehicle Details	
Vehicle No.:	SKG3514Y
Vehicle to be Exported:	No
Intended De-registration Date:	12 Jan 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	JETTA 1.4 TSI AT 1623G5
Primary Colour:	Black
Manufacturing Year:	2012
Engine No.:	CAXB31340
Chassis No.:	WVWZZZ16ZCM150608
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$21,157.00
Original Registration Date:	24 Aug 2012
First Registration Date:	24 Aug 2012
Transfer Count:	0
Actual ARF Paid:	\$21,157.00 10578
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Aug 2022
PARF Rebate Amount:	\$14,809.00
Intended COE Rebate Details	
COE Expiry Date:	23 Aug 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$56,501.00
COE Rebate Amount:	\$26,063.00
Total Rebate Amount:	\$40,872.00

The information contained herein is correct as at 12 Jan 2018

OK

Focus Auto Pte Ltd
Business Reg. No. 201004495R
GST Reg. No. 201004495R
Tel: 6886 9097 Fax: 6481 9095
Email: focus.autopteltd@yahoo.com.sg

Date: 23/1/2018

BY E-MAIL

Your ref: SLR967Z
Our ref: SKG3514Y

WITHOUT PREJUDICE

M/S AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way, #07-16
Singapore 079120

Dear Sir/Madam,

ACCIDENT INVOLVING : (SKG3514Y & SLR967Z) ALONG PIE TWDS CHANGI BEFORE EUNOS EXIT
DOA: 10/01/18 TIME: 2030 HOURS

We refer to the above matter and write on behalf of SELAMAT BIN MOHAMAD, the registered owner of SKG3514Y in respect of the above accident.

We are instructed that the above accident was caused by your insured's negligent driving/ or management of your insured vehicle. Your insured's vehicle SLR967Z collided onto the rear portion of our client's vehicle SKG3514Y. As a result of the accident, our client has been put to loss and expenses, particulars of which are as follows:-

1. Cost of repair	(\$9600 + 7% GST)	\$	10,272.00
2. Loss of Used	(10 days x \$80)	\$	800.00
3. LTA search		\$	7.45
4. Incidentals		\$	88.00

Total Amount: \$ 11,167.45

Enclosed are the following documents for your perusal.

- 1) Driver's driving license/ Identity card
- 2) Certificate of Insurance
- 3) GIA report
- 4) LTA Search (SLR967Z)
- 5) Original repair claim
- 6) Car Rental Agreement/ Receipt (NIL)

Our company is not the authorized workshop of any of the GIA member companies and we are writing in purely for amicable sake.

The demand herein is in respect of our client's for damages pertaining to his motor vehicle and any settlement following or subsequent to this demand shall not prejudice any claim in respect of personal injuries.

Kindly acknowledge receipt of the above said documents within 7 days and your favourable reply is deeply appreciated.

Yours faithfully,


Laura

**MSIG**

MSIG Insurance (Singapore) Pte. Ltd. (Co. Reg. No. 200412213G)
 4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
 Tel +65 6827 7888, Fax +65 6827 7800
 www.msig.com.sg

CERTIFICATE OF INSURANCE

Motor Vehicles (Third Party Risks And Compensation) Act (Chapter 189)
 Motor Vehicles (Third Party Risks And Compensation) Rules, 1960
 Road Transport Act, 1987 (Malaysia)
 Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia)

10 Aug 2017

R0074-001

NOTORPMAE P1039

CERTIFICATE No.

TVE-001-14340

1. Make, Mark and Registration Number of Vehicle: 8D035147
 2. Chassis Number of Vehicle: WUWSS01630M130508
 3. Name of Policyholder: SSIAMAT SITI NURHANA

4. Effective date of the Commencement of Insurance for the purposes of the Act: 02 AUG 2017 00:01:30

5. Date of Expiry of Insurance: 02 AUG 2018

6. Persons or Classes of Persons entitled to drive*

(a) The Policyholder.

(b) Any other person who is driving on the Policyholder's order or with its permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

And provided further that the Motor Vehicle is registered and licensed under the Road Traffic Act and its registration and licensing under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

7. Limitations as to Use*

Use only for social, domestic & pleasure purposes and for the Policyholder's business.

The Policy does not cover use for hire or reward, tuition, driving test, racing, pace-making reliability trial, speed-testing, the carriage of goods (other than samples) in connection with any trade, or business or use for any purpose in connection with the Motor Trade.

*Limitations rendered inoperative by Section 3 of the Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks & Compensation) Act (Chapter 189) and the Road Transport Act, 1987 (Malaysia).



For MSIG Insurance (Singapore) Pte. Ltd.

Not valid unless countersigned by Authorized Person

Approved Insurer

IMPORTANT NOTICE

This Certificate is not transferable to a new owner of the vehicle.

If for any reason the Insurance is terminated during its currency, the Certificate must be returned to the Insurer, or if the Certificate has been lost or destroyed a Statutory Declaration to that Effect must be made. Failure to comply with this obligation is an offence under the compulsory Insurance Legislation.

This Certificate must be returned if the Insurance is suspended during its currency.

If you are involved in an accident, full details must be forwarded immediately to the Company.

FORM MLX.1 (001)

(For the Issuance of Motor Certificate of Insurance only)

A8035719QMY

Print Received Message

This mail is associated with :

***SKG3514Y (4437430404SG)
[SLR967Z]**

TP
SELAMAT BIN MOHAMAD
Jan 10 2018 12:00AM
[LCRF PTE LTD]
Focus Auto Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 14/03/2018 10:27 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$10879.45) - SKG3514Y - Claim Handler: Khoo, Kay-Eng

Approved:10879.45.

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Tuesday, 16 January 2018 3:36 PM
To: 'Insurance LCR SG'
Cc: Admin A
Subject: ACCIDENT INVOLVING SLR 967Z AND SKG 3514Y ON 10.01.2018

Our Ref: CC6/LCR18000760/Ujs3

Your Vehicle : **SLR 967 Z**
Third-Party : SKG 3514Y
Date of Accident : 10 Jan 2018
Time of Accident : 20:30
Location of Accident : PIE EUNOS EXIT

Dear Sir/Madam,

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be withheld for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6749-5792 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.


LETTER OF AUTHORIZATION

To: **FOCUS AUTO PTE LTD**
RE: **ACCIDENT INVOLVING** SKG 3514Y & SLR 967Z **ALONG / AT**
PIE Tuwts Changi before aunos exit **ON** 10/01/2018
I / WE Selamat Bin Mohamed **NRIC NO.** 57435520Z
OF 179 Jln Loyang Besar #03-09 3 (506926)

The owner of the motor vehicle no. SKG 3514Y hereby authorize FOCUS AUTO PTE LTD to commence repairs of the said vehicle forthwith. I / We agree to assign the whole proceeds of my / our third party claim to FOCUS AUTO PTE LTD including any claim for loss of use if a vehicle had been provided by FOCUS AUTO PTE LTD during the period of repairs to my / our vehicle is applicable, my / our solicitors (To be appointed by FOCUS AUTO PTE LTD on my / our behalf) shall accept this as my / our irrevocable authority to pay the amount compensated direct to FOCUS AUTO PTE LTD after deduction of their costs a solicitor & client basis. **I / We undertake to co-operate fully with FOCUS AUTO PTE LTD and / or my / our solicitors and also with a true Motor Accident Report / Police Report until the claim to a successful conclusion including writing to court, failing which, I / We undertake to bear repair costs, rental, legal costs at any incidentals incurred.**

1. If the 3rd party claim is unsuccessful or partly successful as the case may be I / We hereby instruct and authorize FOCUS AUTO PTE LTD to claim direct from my / our insurance company on my / our vehicle immediately without any delay.
2. If for any reason my / our insurers' are not willing to settle the repair costs either in part or in whole I / We undertake to pay FOCUS AUTO PTE LTD for the incidentals cost incurred of the abovementioned motor accident claims.
3. In alternative to serial number 1 and serial number 2 above, if the 3rd party claims fails or only partly successful then I / We undertake to pay FOCUS AUTO PTE LTD for the difference in amount of the claim.
4. I / We authorize FOCUS AUTO PTE LTD to sign all discharge vouchers / indemnity forms and all necessary papers on my / our behalf in connection with the abovementioned claim.
5. I / We also authorize FOCUS AUTO PTE LTD to appoint such firm of Solicitors on my / our behalf as FOCUS AUTO PTE LTD deem fit to purpose of 3rd party / own insurance claims.
6. I / We undertake to inform FOCUS AUTO PTE LTD and / or the Solicitors appointed by FOCUS AUTO PTE LTD on my / our behalf in the event the third's party insurance company communicate with me / us directly by telephone or in writing and I / We further undertake not to accept any monies, offer or settlement from third party's insurers without first communicate with FOCUS AUTO PTE LTD.

DATED THIS 15 DAY OF 03, 2018.



Signature of Owner
(Company's Stamp - If any)



Signature of Witness
Name of Witness:

LETTER OF AUTHORIZATION

DATE : 15/3/2018

To : _____

RE: ACCIDENT INVOLVING VEHICLE NO. SKG 3514Y & SLR 967Z

ALONG PIE Trucks Changi Before Eunos Exit ON 10/01/2018

I/WE Selamat Bin Mohamed of (NRIC/ROC NO.) 57435520Z

OF 179 Jln Loyang Besar H03-09 3 (506926)

Owner of vehicle no. SKG 3514Y in consideration of M/S **FOCUS AUTO PTE LTD**

Repairing my / our vehicle SKG 3514Y at my / our instruction and hereby authorize

FOCUS AUTO PTE LTD to demand claim settle receive whatever amount settled / payable

by the Insurance Company and / or third party or to commence legal proceeding. If necessary, under

my name, for the cost of repairs, car rental and / or loss of use, etc and to their appointing Solicitor to

act for me / us in respect of the said accident / claim and all claimed and / or settled shall belong to

them absolutely.

I further agree and undertake to indemnify them against the above mentioned claim cost which may
arisen therewith.

Signature of Owner : 
(Company's chop - if any)

Name of Owner : Selamat Bin Mohamed

NRIC No : 57435520Z

Provide always that this discharge of my claim for damages relating to the damage to my vehicle shall not prejudice or affect or preclude me from making a further claim for general and special damages for my personal injuries sustained in the same accident.

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **FOCUS AUTO PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$10,272.00** (Repair Cost), **S\$600.00** (Loss of Use) **\$7.45** (Disbursement), for vehicle no. **SKG 3514Y** that was damaged pursuant to the accident which occurred on **10/01/2018** (date) along **PIE EUNOS EXIT** (location) involving vehicle no/s **SLR 967Z**. This is pursuant to the inspection conducted on **12/01/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **SELAMAT BIN MOHAMAD** ("the third party claimant") of vehicle no. **SKG 3514Y** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SKG 3514Y** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 15 (day) of 03 (month) **2018** (year)


Signed by appointed surveyor

Focus Auto Pte Ltd
No 1 Kaki Bukit Ave 6 Auto Bay
#02-50 Singapore 417883
Tel: 66349695

Signed by "the workshop" (with chop)

Focus Auto Pte Ltd

Business Reg. No: 201004495R

GST Reg. No: 201004495R

No 1 Kaki Bukit Ave 6 Autobay

#02-50 Singapore 417883

Date: 23/1/2018

SELAMAT BIN MOHAMAD

C/O NO 1 KAKI BUKIT AVENUE 6

AUTOBAY #02-48/50

SINGAPORE 417883

MOTOR VEHICLE NO: SKG3514Y VOLKSWAGEN JETTA

REPAIR CLAIM

\$ 9,600.00

LUMP SUM

Sub- total: \$ 9,600.00

7% GST: \$ 672.00

Total: \$ 10,272.00

SINGAPORE DOLLARS:

TEN THOUSAND TWO HUNDRED AND SEVENTY-
TWO DOLLARS ONLY

Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 11 Jan 2018 / 11:03:11

Receipt Date/Time : 11 Jan 2018 / 11:03:11

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180111-000548

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLR967Z				
As at 10 Jan 2018/20:30:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SLR967Z Enquiry Fee 20180111110209090230	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	20180111110217971	Direct Debit: eNETS Debit (Internet Banking)		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Jan 2018 Edit Reg		12 Jan 2018 00:00 Edit Adj Rpt	\$59,600.00 Edit Estimates	\$59,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Main Claimant:	SELAMAT BIN MOHAMAD, ID: S7435520Z		
Vehicle Reg. No.:	SKG3514Y	Date of Loss:	10/01/2018 00:00 - :59
Claim Type:	TP / 4437430404SG	Policy/Cover Note No.:	0999994988
Vehicle Reg. No. (Insured):	SLR967Z	Policy No. (Claimant):	7VPCP1734340
	Excess:		
Repairer:	Focus Auto Pte Ltd (Kaki Bukit) NO 1 KAKI BUKIT AVE 6(AUTOBAY) #02-50, 417883 Kaki Bukit - Tel: 68869097		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Khoo, Kay-Eng - 6419 1026] Kay-Eng.Khoo@aig.com		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 23/01/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG_EXPRESS (14/03/2018): Alert - Adj Mandate Approved (\$510879.45) - SKG3514Y - Claim Handler: Khoo, Kay-...
- AIG_SG (15/01/2018): Request for TP GIA Report

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKG3514Y (4437430404SG)**
[SLR967Z]
TP
SELAMAT BIN MOHAMAD
Jan 10 2018 12:00AM
[LCRF PTE LTD]
Focus Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	(Draft)		Third Party Express Settlement – Payment Breakdown												1			Edit		
Assessment Reports															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail			Print		
1	15/01/18 14:40		Accident Statement <small>From: SC - Reg. No: SLR967Z, Claimant: LCRF PTE LTD</small>												1			Load HTM		
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	13/01/18 12:54		Odometer Reading												1			Load JPG		
2	13/01/18 12:54		General View												1			Load JPG		
3	13/01/18 12:54		Chassis Number												1			Load JPG		
4	13/01/18 12:54		General View												1			Load JPG		
5	13/01/18 12:54		General View												1			Load JPG		
6	13/01/18 12:54		General View												1			Load JPG		
7	13/01/18 12:54		General View												1			Load JPG		
8	13/01/18 12:54		General View												1			Load JPG		
9	13/01/18 12:54		General View												1			Load JPG		
10	13/01/18 12:54		General View												1			Load JPG		
11	13/01/18 12:54		General View												1			Load JPG		
12	13/01/18 12:55		General View												1			Load JPG		
13	13/01/18 12:55		General View												1			Load JPG		
14	13/01/18 12:55		General View												1			Load JPG		
15	13/01/18 12:55		General View												1			Load JPG		
16	13/01/18 12:55		General View												1			Load JPG		
17	13/01/18 12:55		General View												1			Load JPG		
18	13/01/18 12:55		General View												1			Load JPG		
19	13/01/18 12:55		General View												1			Load JPG		
20	13/01/18 12:55		General View												1			Load JPG		
21	13/01/18 12:55		General View												1			Load JPG		
22	13/01/18 12:55		General View												1			Load JPG		
23	13/01/18 12:55		General View												1			Load JPG		
24	13/01/18 12:55		General View												1			Load JPG		
25	13/01/18 12:55		General View												1			Load JPG		
26	13/01/18 12:55		General View												1			Load JPG		
27	13/01/18 12:55		General View												1			Load JPG		
28	13/01/18 12:55		General View												1			Load JPG		

29	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
30	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
31	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
32	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
33	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
34	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
35	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
36	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
37	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
38	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
39	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
40	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
41	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
42	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
43	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
44	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
45	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
46	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
47	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
48	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
49	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
50	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
51	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
52	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
53	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
54	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
55	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
56	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
57	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
58	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
59	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
60	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
61	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
62	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
63	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
64	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
65	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
66	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
67	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
68	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
69	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
70	13/01/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
71	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
72	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
73	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
74	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
75	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
76	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
77	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
78	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>

79	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
80	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
81	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
82	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
83	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
84	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
85	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
86	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
87	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
88	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
89	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
90	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
91	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
92	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
93	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
94	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
95	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
96	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
97	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
98	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
99	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
100	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
101	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
102	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
103	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
104	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
105	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
106	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
107	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
108	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
109	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
110	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
111	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
112	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
113	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
114	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
115	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
116	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
117	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
118	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
119	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
120	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
121	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
122	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
123	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
124	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
125	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
126	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
127	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
128	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>

129	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
130	13/01/18 12:55	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/01/18 18:17	TP GIA REPORT	1	Load PDF	
2	16/01/18 15:44	LETTER TO INSURED	1	Load PDF	
3	20/02/18 15:13	LTA SEARCH	1	Load PDF	
4	20/02/18 15:13	LETTER TO OI	1	Load PDF	
5	19/03/18 10:25	WORKSHOP INVOICE	1	Load PDF	
6	19/03/18 10:25	AUTHORISATION TO ACT FORM	1	Load PDF	
7	19/03/18 10:25	Release Voucher	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLR967Z (Insd veh)	Model:	VOLKSWAGEN JETTA 1.4
	SKG3514Y (TP veh)		TSI (A)
Date of Accident:	10/01/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	: \$	15,994.26	
Final Repair Cost	: \$	10,272.00	
Loss of Use	: \$	600.00	10.00 days at \$60.00 per day
Rental (if any)	: \$	0.00	days
LTA / GIA Search Fee	: \$	7.45	
Others:	: \$	0.00	
	: \$		
Final Settlement Sum	: \$	10,879.45	
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability ____ 100 ____ (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: ____ (%)		Assessed Liability (*): ____ 100 ____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Focus Auto Pte Ltd	: \$	10,879.45
2)		: \$	
3)		: \$	
4)		: \$	

JOANNE LEE KHANG MIN

19 Mar
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR18000760/UJS3Q2

Date: 19/03/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994988
 Claimant Vehicle No: SKG3514Y Insured Vehicle No: SLR967Z
 Date of Loss: 10/01/2018 Nature of Claim: TP Claim No: 4437430404SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKG3514Y
 Make & Model: VOLKSWAGEN JETTA, 1.4 TSI (A) Engine No: CAXB31340
 Reg. Date: 24/08/2012 (Man. Year: 2012) Chassis No: VVVZZZ16ZCM150608
 Colour: Black Odometer: 114748 km
 Engine Capacity: 1390 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/55 R16 Rear Tyre Size: 225/55 R16
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,347.91	9,420.00	1,927.91	16.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,600.00	2,660.00	940.00	26.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,947.91	12,080.00	2,867.91	19.19
Approved Total (Overridden) (S\$)		9,600.00		
(S\$)	14,947.91	9,600.00	5,347.91	35.78
+ GST 7.00/7.00% (S\$)	1,046.35	672.00	374.35	35.78
Nett Amount (S\$)	15,994.26	10,272.00	5,722.26	35.78
+ Loss of Use (10.0 x S\$60.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		10,879.45		

INSPECTION

Date of Assignment: 12/01/2018
 Date Inspected: 12/01/2018 Inspected At: Focus Auto Pte Ltd (Kaki Bukit)
 NO 1 KAKI BUKIT AVE 6(AUTOBAY) #02-

50
Singapore 417883

Estimated Period of Repair: 8.0 days

Adjuster: MARCUS CHUA

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented / Bent	816.30 FL	*816.30 FL
2	1		*FRONT BONNET LOCK	Twisted	174.50 FL	*174.50 FL
3	1		*FRONT BONNET LOCK CATCH	Not Necessary	75.50 FL	*- FL
4	1		*FRONT SUPPORT PANEL	Cracked	908.70 FL	*840.00 FL
5	2		*FRONT HEAD LAMP	Cracked	1,362.40 FL	*1,362.40 FL
6	2		*FRONT HEAD LAMP TOP PANEL	Bent	93.00 FL	*93.00 FL
7	1		*FRONT SUPPORT CENTRE BRACKET	Bent	115.50 FL	*115.50 FL
8	1		*FRONT BUMPER	Dented / Deformed	890.00 FL	*890.00 FL
9	2		*FRONT BUMPER SIDE RETAINER	Bent	71.60 FL	*71.60 FL
10	1		*FRONT BUMPER REINFORCEMENT	Dented	670.10 FL	*670.10 FL
11	2		*FRONT SUPPORT PANEL SIDE GARNISH	Torn	80.40 FL	*80.40 FL
12	1		*FRONT AIRCON CONDENSER	Bent / Punctured	865.00 FL	*865.00 FL
13	1		*FRONT RADIATOR	Serviceable	601.20 FL	*- FL
14	1		*FRONT NUMBER PLATE SUPPORT	Buckled	40.20 FL	*40.20 FL
15	1		*REAR BOOTLID	Dented / Bent	1,450.00 FL	*1,450.00 FL
16	1		*REAR BOOT LOCK	Twisted / Shorted	143.50 FL	*143.50 FL
17	1		*REAR BOOT RUBBER	Not Necessary	263.80 FL	*- FL
18	1		*REAR BOOT EMBLEM (JETTA)	Necessary	35.40 FL	*35.40 FL
19	1		*REAR BOOT EMBLEM (TSI)	Necessary	35.40 FL	*35.40 FL
20	1		*REAR END PANEL	Repair	962.50 FL	*- FL
21	1		*REAR BUMPER	Dented / Deformed	1,123.00 FL	*1,123.00 FL
22	1		*REAR BUMPER SIDE BRACKET	Bent	89.50 FL	*89.50 FL
23	1		*REAR BUMPER LOWER PAD	Deformed	540.00 FL	*540.00 FL
24	1		*REAR BUMPER REINFORCEMENT	Dented	640.00 FL	*640.00 FL
25	1		*REAR BUMPER INNER TOP BEAM	Twisted	124.20 FL	*124.20 FL
26	1		*REAR BUMPER TOP CONER BRACKET	Not Necessary	48.20 FL	*- FL
27	1		*FRONT NUMBER PLATE	Bent	50.00 FS	*40.00 FS
28	1		*SET REAR BUMPER SENSOR	Shorted	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,569.90	10,440.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,221.99	1,020.00
Total Parts (\$\$)	11,347.91	9,420.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,800.00	1,200.00
2	CHECK WIRING & DIAGNOSTIC CHECK	New	180.00	30.00
3	RUST PROOFING	New	100.00	80.00
4	TO REMOVE & REPLACE AIR CON CONDENSER AND CHANGE GAS	New	160.00	100.00
5	TO REMOVE AND REPLACE RADIATOR	New	80.00	0.00
6	TO REMOVE & REPLACE BUMPER SENSOR	New	80.00	50.00
7	SPRAY PAINTING	New	1,200.00	1,200.00
Gross Labour Cost (S\$)			3,600.00	2,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >