

INSURANCE

INS. CASE OWNER:

shawn

CC 4 / AIG18000757 RI

b3
PSB

LKK:
IDAC:

Surveyor:

Rasul

DOI:

ASSIGNMENT

7/2/18

Date / Time:

10/01/18

Registered in Merimen:

12/01/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLT 5749X

Claim No.:

959074403355

Name of Insured:

CYNTHIA GOH HWEI KIM

Policy No.:

1700070543

Insured Tel No.:

HP: 9848 8448

Make / Model:

MITSUBISHI SPACE STAR - 1.2 CUT (A)

Excess Sec II : \$5

D.O.A.: 01/12/17

Place of Accident:

BOON LAY WAY (CHINESE GARDEN MRT)
LAKE SIDE MRT

Is driver the owner?

(YES) / NO

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO, TP GIA REPORT: YES / NO

Insured Liability:

% Final? Yes / No

CB6078R



INSRS:

WSP: LYS Engineering

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

| Date/Time | | STAGE | DATE / PIC |
|---------------|---|--|------------|
| 17/01/18 (HT) | CB 6078R - C51207004669/R601 DIA: 20/06/08 - Number 001753241 DIA: 19/06/08 SLT 5749X - X | Non-Reporting Itr (1st): Non-Reporting Itr (2nd): Non-Reporting Itr (Final): Notification Itr (if non-pickup): Call OI: After call Itr to OI: | |
| 18/1/18 | Request of video from AIG. | Documentation Check List: Handler | Typist |
| 19/1/18 | OI video uploaded in Merimen. @ 5:00pm - OI changed Itr. Call OI - Not pick up. | Notification Itr (if non-pickup): After call Itr to OI: Authorisation To Act: Release Voucher: Final Repair Bill: Car Rental Invoice: Towing Invoice: LTA / GIA: Medical Bill: PIR: Mandate/Reject Instruction: LOD: Payment Breakdown Form: Post-Repair Photos: Others: | |
| 19/5/18 | Check with TP WSP: Steven, only finalise quantum then pass to lawyer for settlement | | |
| 14/5/18 | File pass to close (up) | | |

RECEIVED 14 MAY 2018

| | | | |
|--------------------------------------|--------------------------|-----------------------------------|--------------------------|
| PRELIMINARY ADVICE Date/Time: | | Sent By: | |
| FINALIZATION Date/Time: | | Confirm with: | |
| Repair Cost: | \$5 | (days) Reduction: | % |
| FINAL SETTLEMENT Date/Time: | | Confirm with: | |
| Final Liability: | % | (Agreed / Assessed) BOLA S/N No.: | 15 |
| Repair Cost: | \$5 | | |
| Loss of Rental (LOR): | \$5 | (days) | |
| Loss of Use (LOU): | \$5 | (5 x days) | |
| Loss of Income (LOI): | \$5 | (5 x days) | |
| LOR only | <input type="checkbox"/> | LOU only | <input type="checkbox"/> |
| LOR + LOU | <input type="checkbox"/> | LOR + LO | <input type="checkbox"/> |
| [Tick only one] | | | |
| GIA/LTA Search | \$5 | | |
| Medical: | \$5 | | |
| Disbursement: | \$5 | (e.g. Tow/ Independent) | |
| Legal Cost | \$5 | | |
| Total: | \$5 | Global Sum \$5: | |
| FINAL PAYMENT Date/Time: | | Confirm with: | |
| Payee 1: | \$5 | Name 1: | |
| Payee 2: (Strike if N.A.) | \$5 | Name 2: | |
| Payee 3: (Strike if N.A.) | \$5 | Name 3: | |

- checked by CS - HsiangTong
- CHT.
- 14/5/18

1) Claim status: Normal/Reject/Private Settle (up)
2) Report Format: TP
3) Survey fee: \$250 + \$20



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|--|-----------------------------|---|
| AIG ASIA PACIFIC INSURANCE PTE LTD | | Ref : CC4/AIG18000797/R1ps3 | |
| 78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120 | | Date : 12-01-2018 |  |
| | | Code : AIG | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | SLT 5748X | Veh. Inspected | CB 6078R |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 12/01/2018 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. | |
| Chassis No. | | Colour | |
| Odometer | - | Steering | |
| Brakes | | Modification | |
| General | | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |
| 4. Description of Damages | | | |
| | | | |
| 5. General Information | | | |
| Accident Date | 01/12/2017 | Inspection Date | 07/03/2018 |
| Survey held at | LYS ENGINEERING BLK 138 #11-411 BUKIT BATOK WEST AVE 6 SINGAPORE 650138 | | |
| 5a. Remarks | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |

LYS ENGINEERING

WORKSHOP : 7 SOON LEE STREET #01-19 ISPACE S 627608

HP : 97308695 Fax : 66748695

Specialize In Repairing All Kinds Of Motor Vehicles, Spray Painting, Welding
And Agent To Claim Damages From Motor Insurance

QUOTATION

Date : 24/04/18

To : LKK Auto Consultants P/L

Attn : Mr Rasul Fax : rasul@lkkauto.com

Insurance Company :

Tel :

Fax :

Attn : M/V Claim Department

Lump Sum Repair

VEHICLE NO : CB6078R (

We are pleased to quote you for the following services/repairs cost for the above mentioned vehicle :

| ITEM | QTY | DESCRIPTION | U-PRICE | AMOUNT |
|-----------|------|---|------------|------------|
| 1. | 1 Pc | Front Left Door Company Logo | S\$ 120.00 | S\$ 120.00 |
| SUB-TOTAL | | | | 120.00 |
| 2. | | To Spray Painting Three Co Bumper Assy & Front Bumper Assy & Front Left Door Assy | | 800.00 |
| 3. | | Labour Charges : | | 400 |
| | | -Dismantle & Repair Front Bumper Assy | | 650.00 |
| | | -Dismantle, Repair & Beating Front Left Door Assy | | 300 |
| TOTAL | | | | 1,570.00 |

Please do not hesitate to contact us if you have any queries.

Thank You.

LYS ENGINEERING

Yours faithfully,

Note :
Repair Work 4 Days

Rasul
Hp 90010068
3 days
P/P
07/03/18 @ 1105
Resing after repair

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Thursday, 18 January 2018 12:41 PM
To: 'Wui, Shawnkaijye'
Subject: Your Ref: 9590744033SG *LKK REF: CC4/AIG18000797/ps3 [ACCIDENT INVOLVING SLT 5748X(AIG) & CB 6078R ON 01/12/2017]

Hi Sahwn,

We refer to the above matter,

Kindly assist to upload OI's video in Merimen for our viewing.

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAUTO)

From: Wui, Shawnkaijie <Shawnkaijie.Wui@aig.com>
Sent: Thursday, 18 January 2018 2:05 PM
To: Hsiao Tong (LKKAUTO)
Subject: RE: Your Ref: 9590744033SG *LKK REF: CC4/AIG18000797/ps3 [ACCIDENT INVOLVING SLT 5748X(AIG) & CB 6078R ON 01/12/2017]

Hi Hsiao Tong,

Video has been uploaded.

Please refer to Merimen.

Thanks and Regards,
Shawn Wui
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way, #08-16, Singapore 079120

Tel +(65) 6419 1959 | Fax +(65) 6835 7416

Shawnkaijie.Wui@aig.com | www.aig.com.sg

IMPORTANT NOTICE

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Thursday, January 18, 2018 12:41 PM
To: Wui, Shawnkaijie
Subject: Your Ref: 9590744033SG *LKK REF: CC4/AIG18000797/ps3 [ACCIDENT INVOLVING SLT 5748X(AIG) & CB 6078R ON 01/12/2017]

Hi Shawn,

We refer to the above matter.

Kindly assist to upload OI's video in Merimen for our viewing.

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Catherine Chong (LKK Auto)

From: Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>
Sent: Wednesday, 10 January, 2018 11:21 AM
To: assignments@lkkauto.com; admin-a@lkkauto.com
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Lim, Sheng Yang; Md Ishak, Mohd Imran; Chan, Yoke Shi
Subject: AIGENCRYPT - Pre repair inspection request - CB6078R VS SLT5748X (OI) DOA 01/12/2017
Attachments: Our Ref: CB 6078 R, Yr Ref: 9590744033SG003, Acc Inv: CB 6078 R & SLT 57... (6.84 KB); FaxDC5D.TIF

Hi,

Please refer to the enclosed request from **BONNIE KWOK LLC**.

Claim no : 9590744033SG003
Case Owner : Shawn Wui

If you have any queries/concerns, please let us know.
Kindly assist to assign Mohamed Taufikh as Single Joint Expert as requested.

Thank you.

Best Regards,

Mariesa Abu Kassim
AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services
AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1012202 | Fax +6 03 2685 5898

NoorMariesa.AbuKassim@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

1201501
veh not in stock
'DS'

LYS ENGINEERING

MAILING ADDRESS: BLK 138 #11-411 BUKIT BATOK WEST AVE 6 S650188
HP: 97308695 FAX: ~~68992276~~ 6674896Y

Specialise In Repairing All Kinds Of Motor Vehicles. Spray Painting. Welding
And Agents To Claim Damages From Motor Insurance

Your Vehicle: SLT 5748X (3rd Party Vehicle)

Our Vehicle CB 6078R

Date: 09/01/18

M/s AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#09-16 AIG Building
Singapore 079120

* By Fax Only *

Dear Sir,

ACCIDENT INVOLVING CB 6078R & SLT 5748X ON 01/12/17 12:00 pm

We refer to the above matter.

I hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle

CB 6078R at

Please call Steven Loo @ HP 97308695.

Yours faithfully,



24 Sg Kadat

ST 4

S 729050

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Monday, 14 May 2018 9:17 AM
To: Wui, Shawnkaijye
Subject: RE: Your Ref: 9590744033SG *LKK REF: CC4/AIG18000797/ps3 [ACCIDENT INVOLVING SLT 5748X(AIG) & CB 6078R ON 01/12/2017]

Hi Shawn,

We refer to the above matter.

Please be informed that "No Direct Settlement" for this case. Third party only agreed LKK as SJE and they will get their lawyer to handle for settlement.

In view of this, we will proceed to close file and submit wp report to your good office.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wui, Shawnkaijye [mailto:Shawnkaijye.Wui@aig.com]

Sent: Thursday, 18 January 2018 2:05 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: RE: Your Ref: 9590744033SG *LKK REF: CC4/AIG18000797/ps3 [ACCIDENT INVOLVING SLT 5748X(AIG) & CB 6078R ON 01/12/2017]

Hi Hsiao Tong,

Video has been uploaded.

Please refer to Merimen.

Thanks and Regards,

Shawn Wui

AIG

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way, #08-16, Singapore 079120

Tel +(65) 6419 1959 | Fax +(65) 6835 7416

Shawnkaijye.Wui@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Hsiao Tong (LKKAuto) [<mailto:chewht@lkkauto.com>]

Sent: Thursday, January 18, 2018 12:41 PM

To: Wui, Shawnkaijye

Subject: Your Ref: 9590744033SG *LKK REF: CC4/AIG18000797/ps3 [ACCIDENT INVOLVING SLT 5748X(AIG) & CB 6078R ON 01/12/2017]

Hi Sahwn,

We refer to the above matter.

Kindly assist to upload Ol's video in Merimen for our viewing.

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRE

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|---|---------------|--|--|--|------------|---|
| Main | 05 Dec 2017 Edit Reg | | 10 Jan 2018 00:00 Edit Adj Rpt | S\$800.00 Edit Estimates | S\$800.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|--|------------------------|---|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by adjuster] | | | | | | | | | |
| Insured: | CYNTHIA GOH HWEE KIM , ID: S7612833B | | | | | | | | |
| Main Claimant: | TAN SUNG FOON , ID: S1107491Z | | | | | | | | |
| Vehicle Reg. No.: | CB6078R | Date of Loss: | 01/12/2017 00:00 - :59 [185 Months From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / 9590744033SG | Policy/Cover Note No.: | 1700070543 (Comprehensive) Coverage: 02/11/2017 - 01/11/2018 | | | | | | |
| Vehicle Reg. No. (Insured): | SLT5748X | Policy No. (Claimant): | 5054460673-05 | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: | Lys Engineering (HQ) 138 Bukit Batok West Ave 6, #11-411, 650138 Bukit Batok - Tel: 65605653 | | | | | | | | |
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-KJ] Shawnkaijye.Wui@aig.com | | | | | | | | |
| Claimant's Insurer: | NTUC Income Insurance Co-operative Ltd (HQ) - Tel: | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 23/01/2018] | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| • AIG_SG (15/01/2018): Request for TP GIA Report | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

***CB6078R (9590744033SG)**
[SLT5748X]
TP
TAN SUNG FOON
Dec 1 2017 12:00AM
[CYNTHIA GOH HWEE KIM]
Lys Engineering

| Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio | | | View View in Browser | |
|---|-----------------|--|---|-------------------------------------|
| Video | | | 1 per page <input type="checkbox"/> <input checked="" type="checkbox"/> | |
| No | Finalized On | AIG Asia Pacific Insurance Pte. Ltd. (SG) | Thumbnail | Print |
| 1 | 18/01/18 14:03 | Video - Accident <small>From: OD - Reg. No: SLT5748X, Claimant: CYNTHIA GOH HWEE KIM</small> | Load MP4 | |
| Assessment Reports | | | 1 per page <input type="checkbox"/> <input checked="" type="checkbox"/> | |
| No | Finalized On | AIG Asia Pacific Insurance Pte. Ltd. (SG) | Thumbnail | Print |
| 1 | 15/01/18 09:43 | Accident Statement <small>From: OD - Reg. No: SLT5748X, Claimant: CYNTHIA GOH HWEE KIM</small> | Load HTM | |
| Photos/Images | | | 3 per page <input type="checkbox"/> <input checked="" type="checkbox"/> | |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 12/05/18 09:35 | Odometer Reading | Load JPG | <input checked="" type="checkbox"/> |
| 2 | 12/05/18 09:35 | Chassis Number | Load JPG | <input checked="" type="checkbox"/> |
| 3 | 12/05/18 09:35 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 4 | 12/05/18 09:35 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 5 | 12/05/18 09:35 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 6 | 12/05/18 09:35 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 7 | 12/05/18 09:35 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 8 | 12/05/18 09:35 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 9 | 12/05/18 09:35 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 10 | 12/05/18 09:35 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 11 | 12/05/18 09:35 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 12 | 12/05/18 09:35 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 13 | 12/05/18 09:35 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 14 | 12/05/18 09:35 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 15 | 12/05/18 09:35 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 16 | 12/05/18 09:35 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 17 | 12/05/18 09:35 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 18 | 12/05/18 09:35 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 19 | 12/05/18 09:35 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 20 | 12/05/18 09:35 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 21 | 12/05/18 09:35 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 22 | 12/05/18 09:35 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 23 | 12/05/18 09:35 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 24 | 12/05/18 09:35 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 25 | 12/05/18 09:35 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 26 | 12/05/18 09:35 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 27 | 12/05/18 09:35 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 28 | 12/05/18 09:35 | General View | Load JPG | <input checked="" type="checkbox"/> |

| Video | | | 1 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|--|--|-------------------------------------|
| No | Finalized On | AIG Asia Pacific Insurance Pte. Ltd. (SG) | Thumbnail | Print |
| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 12/01/18 18:10 | EMAIL FROM LAWYER DD 10.01.2018 |  Load PDF | |
| 2 | 12/01/18 18:10 | ACKNOWLEDGEMENT EMAIL TO AIG DD 10.01.2018 |  Load PDF | |
| 3 | 12/01/18 18:10 | NOTIFICATION FROM WORKSHOP |  Load PDF | |
| 4 | 17/01/18 09:15 | TP GIA REPORT |  Load PDF | |
| 5 | 16/05/18 09:41 | LETTER TO OI |  Load PDF | |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> | | | |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | | | |

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18000797/R1PB3Q2

Date: 16/05/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700070543
Claimant Vehicle No : CB6078R **Insured Vehicle No :** SLT5748X
 Date of Loss: 01/12/2017 Nature of Claim: TP Claim No: 9590744033SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **CB6078R**
 Make & Model: TOYOTA HIACE, 3.0 (A) Engine No: 5L5209582
 Reg. Date: 01/07/2002 (Man. Year: 2001) Chassis No: LH1726105927
 Colour: Multi-colour Odometer: 941192 km
 Engine Capacity: 2985 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
 Front Left Side: Maxtrek 6 mm Rear Left Side: Maxtrek 6 mm
 Front Right Side: Maxtrek 6 mm Rear Right Side: Maxtrek 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|------------------------------------|-----------------|---------------|---------------|--------------|
| Parts | 120.00 | 100.00 | 20.00 | 16.67 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,450.00 | 700.00 | 750.00 | 51.72 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 1,570.00 | 800.00 | 770.00 | 49.04 |
| Global Sum Settlement (S\$) | | 0.00 | | |

INSPECTION

Date of Assignment: 10/01/2018
 Date Inspected: 07/03/2018 Inspected At: 15 PIONEER WALK
 Repairer: Lys Engineering (HQ)
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|------------------------------|-----|----------|-------------------------------|-----------|------------|------------|
| 1 | 1 | | *FRONT LEFT DOOR COMPANY LOGO | Necessary | 120.00 FS | *100.00 FS |
| F=Franchise part. S=SpcNett. | | | | | | |
| Total Parts (\$\$) | | | | | 120.00 | 100.00 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------|---|----------|------------|--------|
| Labour Items | | | | |
| 1 | TO SPRAY PAINTING THREE CO BUMPER ASSY & FRONT BUMPER ASSY & FRONT LEFT DOOR ASSY | New | 800.00 | 400.00 |
| 2 | LABOUR CHARGES-DISMANTLE & REPAIR FRONT BUMPER ASSY -DISMANTLE ,REPAIR & BEARING FRONT LEFT DOOR ASSY | New | 650.00 | 300.00 |
| Gross Labour Cost (\$\$) | | | 1,450.00 | 700.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >