

12/01/18

ASS. REC. BY

REF: CS/MSG18000815/K1rd3ⁿ²

Speed Information

Meimen Kalvin ASSIGNMENT (Office)
From (Person): Irene Tan of MSIG Date/Time: 12/1/18 @ 4:35pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SH7194K Insured: SJE 4242Y

at Workshop in: Comfort Delgro Tel: 6214 8300

of 59 Juyong Drive

Policy No: A80446748 QMX Claim No: 545740

Sum Insured: _____ Excess: _____

Make of Veh: _____ DOA: 11/01/18
(Client's Record) _____ 15/01/18

CA / REV / REP. / REV 24 HRS up R.O.F. Exemption: _____

Date/Time: 5:27pm @ 12/1/18 Person Contacted: _____ OUT

Date/Time	Action/Inspection	Remarks
	SH-7194K - CC4/III/6013474 / Tipg3q2	D.O.A: 11/07/2016
	SJE 4242Y - CF/AIG08022629 / Uqj	D.O.A: 27/07/2005

17/1/18 Sent preli through meimen

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Jan 2018		12 Jan 2018 16:35 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	CHIA KOON SENG, ID: S8511518I								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SH7194K	Date of Loss:	11/01/2018 18:00 - :59						
Claim Type:	TP / 545740	Policy/Cover Note No.:	A80446748QMX (Comprehensive) Coverage: 27/10/2017 - 26/10/2018						
Vehicle Reg. No. (Insured):	SJE4242Y	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 13/01/2018]								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18000815/K1rd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 15-01-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJE 4242Y	Veh. Inspected	SH 7194K
Policy No.	A81446748QMX	Coverage (\$)	0.00
Claim No.	545740	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAN)	Assign Date	15/01/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	11/01/2018	Inspection Date	15/01/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 17 Jan 2018

Preliminary Advice

Insured Vehicle No	: SJE4242Y	Accident Date	: 11/01/2018
TP Vehicle No	: SH7194K	Assignment Date	: 12/01/2018
Make	: HYUNDAI SONATA	Est. Duration of Repair	: 3.00
Date of Inspection	: 15/01/2018		
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) 59 LOYANG DRIVE SINGAPORE 508969		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,784.36
Revised Amount	:S\$	2,274.36
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,274.36
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/01/2018 10:12
Date Of Accident	11/01/2018 18:30
Exact Location Of Accident	JALAN ANGIN LAUT IN THE DIRECTION TWDS SIMEI AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SH7194K
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	SONATA-2.0 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

Driver

Name of Driver	PERIAKARUPPAN S/O MURUGANDI
NRIC No	S2501977F
Date Of Birth	26/01/1949
Occupation	OUTDOOR
Date Of Driving Pass	16/12/1976
Driving Experience	41 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 778 YISHUN AVENUE 2 #10-1549
Postcode	760778
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJE4242Y
Vehicle Make/Model/Colour	HONDA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHIA KOON SENG
NRIC/Passport Number	S8511518I
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	RH FRONT

No. Of Passenger (Including Driver)

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R


Ruchanjan

Lim Ee Soon
CSO


Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Handwritten signature and name in the accident description area.

[Signature]
[Name]

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

CMTRAC Sketch Plan Form 2

SH 7194 K

- ACCIDENT STATEMENT

Yesterday evening (11/01/2018), I drove to No 79, Jalan Angin Laut in response to a taxi booking call.

It was drizzling upon arrival at the destination and after a female Chinese boarded my taxi, I set to move off embarking on a journey to Changi Airport.

As seen in the video footage, Jalan Angin Laut was a single lane 2-way road and wary of the road situation, I drove at slow speed.

I was following closely behind a private car SJC 1438J moving towards the direction of Simei Avenue when I saw car B(SJE 4242Y) stopping with its left signal blinking behind a parked car SKJ 9028D.

As car B did not move, hence the car in front my taxi overtook it when it was clear traffic on opposite lane.

I followed suit but as a precautionary measure, I sounded the horn amid overtaking car B.


However, I felt an impact when it was car B that veered off from stationary position to crash against my taxi despite I had kept the distance from it in the process of overtaking.

Clearly, the driver of car B failed to read the road situation before moving off from its standstill position on the road.

The impact damaged the left rear portion of my taxi while the right front to car B sustained dents.

No report of injury.

I affirmed the above-statement is true and correct.



Driver name : Periakaruppan
NRIC NO : S 2501977F
Date: 12/01/2018

Recorded by Alex Lim





Team: IN ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO: 305106311

CUSTOMER MR/MS COMFORT TRANSPORTATION PTE LTD CUSTOMER NO 7010045 ADDRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 TEL (R) 65508755 (O) (P) DISCOUNT CARD NO.	REGN NO: SH 7194K	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....
	MODEL SONATA 12.01.2018 09:05	DATE/TIME IN
	YR OF MANU 14.04.2011	TARGET DATE
	CHASSIS CODE KMHE141VMBA807305	COMPLETION DATE/TIME

JOB DESCRIPTION

Accident Date: 11.01.2018
 NATURE: 3P 11.01.2018

S/NO	LABOR CODE	DESCRIPTION
------	------------	-------------

CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Name:
 I/C No.: SH 7194K CHIANG @
 Vehicle No.:

Vehicle No.: SH 7194K

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

To be returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

VEHICLE NO : SH 7194K

DATE 12/1/2018 11:55

M S L T

MAKE :

MODEL : HYUNDAI SONATA

Chang

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Door (LH) <i>net</i>			\$ 1,294.70
	Rear Door Protector(LH) <i>net</i>			\$ 54.50
	<i>Front Door (LH) x repair</i>			
	<i>Rear Fender (LH) x repair</i>			
	SUB TOTAL			\$ 1,349.20
	LESS 20%			\$ 269.84
	DISCOUNTED TOTAL			\$ 1,079.36
	Rear Door Tel No. Sticker (LH) <i>net</i>			\$ 10.00 Nett
	Front Door Coloured Comfort Logo (LH) <i>net</i>			\$ 75.00 Nett
	Front Door Advertisement Logo (LH) <i>net</i>			\$ 100.00 Nett
	Front Fender Advertisement Logo(LH/RH) <i>net</i>		\$ 100.00	\$ 200.00 Nett
	<i>Rear Fender Advertisement Logo (LH) net</i>		\$ 100	\$ 100.00 Nett
				\$ 385.00
	Labour Charge			
	Panel Beating- Repair Fender			\$ 500.00 <i>400</i>
	Spray Painting Charge			\$ 600.00 <i>580</i>
	Wiring Charge			\$ 50.00 <i>X</i>
	Tuff Kote			\$ 50.00 <i>20</i>
	Transfer of Door			\$ 120.00 <i>50</i>
	TOTAL LABOUR			\$ 1,320.00
	ESTIMATE TOTAL			\$ 2,784.36
				<i>2884.36</i>

Kalai R K R
M 15/1/18 1030 L
3 Pys
L/S
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during re-survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- No illegal modifications is allowed
- Supplemental items must be surveyed and is subject to final approval from the insurance company

Acknowledged by Repairer:
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive, Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305106311
Date : 17/01/18


FINALIZATION FORM

To : LKK Fax : _____
Attn : KALVIN
Vehicle Reg No. : SH 7194K 11/01/18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: MSIG SJE4242Y
2. The finalized amount shall be:
 - (a) Spare Parts after List discount _____
 - (b) Labour Charges _____
 - Total for Part-By-Part Repair Cost** _____
 - (c) Lumpsum Repair (if applicable) _____
 - Total for Lumpsum repair cost after Less: 20% _____
 - Final Lumpsum Repair cost** \$1,900.00
3. Estimated normal period for repairs: 3 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : CHIANG
Tel : 62148314
Fax : 65468156

Signature : 
Name : Kalvin
Date : 17/1/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18000815/K1RD3N2

Date: 19/01/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A80446748QMX
Claimant Vehicle No :	SH7194K	Insured Vehicle No :	SJE4242Y
Date of Loss:	11/01/2018	Nature of Claim:	TP
			Claim No: 545740

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH7194K	Engine No:	D4EAA849105
Make & Model:	HYUNDAI SONATA, 2.0 CRDI (A)	Chassis No:	KMHET41VMBA807305
Reg. Date:	14/04/2011 (Man. Year: 2011)	Odometer:	81864 km
Colour:	Blue		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	West Lake 7 mm	Rear Left Side:	West Lake 7 mm
Front Right Side:	West Lake 7 mm	Rear Right Side:	West Lake 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,564.36	1,364.36	200.00	12.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,320.00	1,010.00	310.00	23.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,884.36	2,374.36	510.00	17.68
Approved Total (Overridden) (S\$)		1,900.00		
(S\$)	2,884.36	1,900.00	984.36	34.13
+ GST 7.00/7.00% (S\$)	201.91	133.00	68.91	34.13
Nett Amount (S\$)	3,086.27	2,033.00	1,053.27	34.13

INSPECTION

Date of Assignment:	12/01/2018	
Date Inspected:	15/01/2018 Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 19 Jan 2018)
Parts: 143	HYUNDAI SONATA 2.0 CRDI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH7194K)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR DOOR (LH)	Dented	1,294.70 FL	*1,294.70 FL	
2	1		*REAR DOOR PROTECTOR (LH)	Cracked	54.50 FL	*54.50 FL	
3	1		*REAR FENDER (LH)(NPA)	Repair	0.00 FL	*- FL	
4	1		*FRONT DOOR (LH)(NPA)	Repair	0.00 FL	*- FL	
5	1		*REAR DOOR TEL NO STICKER (LH)	Necessary	10.00 FS	*10.00 FS	
6	1		*FRONT DOOR COLOURED COMFORT LOGO (LH)	Necessary	75.00 FS	*75.00 FS	
7	1		*FRONT DOOR ADVERTISEMENT LOGO (LH)	Necessary	100.00 FS	*100.00 FS	
8	2		*FRONT FENDER ADVERTISEMENT LOGO (LH/RH)	Not Necessary	200.00 FS	*- FS	
9	1		*REAR FENDER ADVERTISEMENT LOGO (LH)	Necessary	100.00 FS	*100.00 FS	
					Sub Total (S\$)	1,834.20	1,634.20
					- List Item Discount on L Items 20.00/20.00% (S\$)	269.84	269.84
					Total Parts (S\$)	1,564.36	1,364.36

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING-REPAIR FENDER	New	500.00	400.00
2	SPRAY PAINTING CHARGE	New	600.00	540.00
3	WIRING CHARGE	New	50.00	-
4	TUFF KOTE	New	50.00	20.00
5	TRANSFER OF DOOR	New	120.00	50.00
Gross Labour Cost (S\$)			1,320.00	1,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >