

ASSIGNMENT (Office)

From (Person): Aini of FCI Date/Time: 15/01/18 @ 9:47am

Estimated Cost: _____ Bill to: _____

OD: ☒ WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SKU 82794 Insured: SHA 8660Sat Workshop no: Moya Automotive Tel: 6272 3892 | 9191 7073of Blk 100P, Bkt Meruh Lane 3 # 01-04/06Policy No: _____ Claim No: SHA 8660S (DOA: 5/1/18)

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 05/01/2018
(Client's Record)CA / REV / REP. / REV 24 HRS 'wp' 22.01.2018

H.O.D. Endorsement: _____

Date/Time: 10:18am @ 15/01/18 Person Contacted: NithaVehicle IN ☒ OUTDate/Time: _____ Action/Instruction: ☒ Pending OUI ID's video to determine liabilitySKU 82794-xSHA 8660S-CS/FCI17016561/Urbn2 D.O.A.: 21/05/201723/1/18 Email preli revised to Aini12/2/18 @ 4:19pm Final fig \$400 confirmed with Jici Yu (Reel 150, 279)

Taylor

ASSIGNMENT

From: Date: 22/01/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKU 8279 U
at Workshop m/s: Mova Automotive
of Blk 1008, Blk Merah Lane 3 # 01-04/06

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Pending OUT ID's video to determine liability

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Ball or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS (wp)

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKY82794 (Ref: 2015 Aug)

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Elantra 159/

Colour: Blue A/C Insured / Std / NI / NA

So. Reading: 45325 T-Radio: Insured / Std / NI / NA

Eng No:

C No: KMHPH41CM G4596634

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

Rear:

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A:

D.O.I:

Survey held at: Mova BM 22/1/18 @ 1530

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

RECEIVED 14 FEB 2018

Date/Time: File Pass to:

☐

Prel. Report

1:

☐

Final Report

Date/Time: File Return to:

14/2 - typist

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

100 - 100

1000

10000

100000

1000000

Report Format:

TP

Lump Sum / 1/1/18

400/2

Add Fee:

☐

Site Insp: \$

☐

Interview: \$

☐

Tech. Fee: \$

☐

Weekend: \$

90
50
50
16

206



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18000819/T1vd3		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 15-01-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8660S	Veh. Inspected	SKU 8279U	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	AINI (FCI)	Assign Date	15/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	05/01/2018	Inspection Date		
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: PLEASE ADVISED
Our ref: CS/FCI18000819/T1vd3

Date: 23/1/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SKU 8279U


We thank you for your instruction on 15/1/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 22/1/2018 at the premises of M/s MOVA AUTOMOTIVE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$550.00
Revised Estimate Amount	: S\$400.00
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear o/s portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMAD TAUFIKH
M.MATAL, AMSAE-A
Automobile Assessor

Survey Department Check List (Case Handler)

Reference No. : CS/FCS 18000 819 Tlvc3

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By:

VERON

14/2/18

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014

Nivitha (LKK Auto)

From: Aini Binte Md Min <Aini@msfirstcapital.com.sg>
Sent: Monday, 15 January 2018 9:47 AM
To: 'assignments@lkkauto.com'
Cc: nitha@nova.com.sg
Subject: NEW ASSIGNMENT (O/REF: SHA8660S)
Attachments: 15012018094440-0001.pdf; RE: TP CLAIMS - SKU8279U AGAINST SHA8660S ON 05/01/18 AT CLEMENTI TOWARD... (30.8 KB)

Dear Sirs

New survey assignment for your handling.

Thanks & Regards

Aini
Motor Claims Department

First Capital Insurance Ltd | 36 Robinson Road, City House, #16-01 Singapore 068877 | TEL: 6507 3848
Fax: 6507 3849 | Company Reg. No. 195000106C

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to www.first-insurance.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

MOTOR SURVEY ASSIGNMENT

Date 12.1.18

Our Ref No. SHA86605

Accident Date 5.1.18

Claim Type THIRD PARTY

Insured Vehicle SHA86605

Third Party Vehicle SK482794

Survey Location MOVA AUTOMOTIVE
BLK 1008 BUKIT MERAH LANE 3
#01-04/06/08, S(159722)

Contact Person ENNY LEE

Contact No. 62723892

Fax No.

Survey Type Without Prejudice: Pending on ID's video to determine liability

10:18am
est - Nithin
UNI

Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD

Contact Person

Fax No. 68416315

Contact Number 62563561

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

Encl. 3P SURVEY REQUEST

Cc : Workshop MOVA AUTOMOTIVE

Attention

Officer In charge *[Signature]* Irene Jau
13/01/2018

IMPORTANT NOTE

Kindly submit the survey report by email only to surveyor@first-insurance.com.sg within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 23 January 2018 12:52 PM
To: 'Aini Binte Md Min'
Cc: SUR
Subject: RE: NEW ASSIGNMENT (O/REF: SHA8660S) (TP VEHICLE SKU 8279U)
Attachments: SKU 8279U PRELI ADVISED.pdf

Dear Aini,

Enclosed preliminary revised of vehicle SKU 8279U

Date of survey: 22/1/2018

Number of days: 2 days

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAUTO)
Sent: Monday, 15 January 2018 10:21 AM
To: 'Aini Binte Md Min' <Aini@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: NEW ASSIGNMENT (O/REF: SHA8660S)

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,
G.Nivitha | Admin
LKK Auto Consultants Pte Ltd
Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Aini Binte Md Min [mailto:Aini@msfirstcapital.com.sg]
Sent: Monday, 15 January 2018 9:47 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: nitha@nova.com.sg
Subject: NEW ASSIGNMENT (O/REF: SHA8660S)

Dear Sirs

New survey assignment for your handling.

Thanks & Regards

Aini
Motor Claims Department

First Capital Insurance Ltd | 36 Robinson Road, City House, #16-01 Singapore
068877 | TEL: 6507 3848
Fax: 6507 3849 | Company Reg. No. 195000106C

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data.

Please refer to www.first-insurance.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel : (65) 6476 3333
 Fax : (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

Tel : (65) 6272 3892
 Fax : (65) 6270 8314

Co. Reg: 198904033G
 GST Reg: M2-008864-2

Estimate

08/01/2018

FIRST CAPITAL INSURANCE LTD
 36 Robinson Road
 #16-01 City House
 Singapore 068877.

Attention :- XA026

Page # :- 1
 Veh # :- SKU8279U
 Veh Model :- HYUNDAI ELANTRA
 Estimate# :- CK416879
 Claim # :-
 ACC. Date :- 05/01/18
 Terms :- C.O.D Days
 Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BUMPER - REPAIR	1	PC	
	LIST TOTAL S\$			
	20% DISCOUNT S\$			
LABOUR :				
	TO REPAIR REAR BUMPER & REALIGN AFFECTED AREA		200	250.00
	TO SPRAY PAINT REAR BUMPER.		200	300.00
	LABOUR TOTAL S\$			550.00

E. & O.E

NON-TAX AMOUNT S
 AMOUNT S\$ 550.00
 GST @ 7 % 38.50
 AMOUNT DUE S\$ 588.50

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Tan Jiah 97495749
 WP
 22/1/18 @ 1350 23/1/18
 Resurvey after repair
 2 days.
 Sur @ Tanauto.com




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18000819/T1vd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 20-02-2018		
Code : FCI2				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8660S	Veh. Inspected	SKU 8279U	
Policy No.		Coverage (\$)	0.00	
Claim No.	SHA8660S (DOA:5/1/2018)	Excess (\$)	0.00	
Assign From	AINI	Assign Date	15/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI ELANTRA	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KMHDH41CMGU590634	Colour	BLUE	
Odometer	45325	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/01/2018	Inspection Date	22/01/2018	
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 8279U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REPLACEMENT OF PARTS	TO REPAIR SEE LABOUR		
	REAR BUMPER (NPA)		-	-
	LESS 20% DISCOUNT		-	-
			-	-
	LABOUR			
	TO REPAIR REAR BUMPER & REALIGN AFFECTED AREA.		250.00	200.00
	TO SPRAY PAINT REAR BUMPER.		300.00	200.00
			550.00	400.00
GRAND TOTAL			550.00	400.00
RECOMMENDED COST OF REPAIRS				400.00

Report Ref No. CS/FCI18000819/T1vd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.