

ASS. REC. BY:

REF:

CS/GA118000818/Uqbn2

Special Instruction:

Surveyor:

## ASSIGNMENT (Office)

From (Person): Kelvyn Ngian of GA Date/Time: 16/01/2018 11:52am

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SKH 8673A Insured: YN 2735Eat Workshop m/s Fastech Auto Tel: 6746 5405of Bk 1 kaki Bukit Ave 6 #01-45Policy No: \_\_\_\_\_ Claim No: YN 2735E

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 10-01-2018  
(Client's Record)CA / REV / REP. / REV 24 HRS WPI H.O.D. Endorsement: \_\_\_\_\_Date/Time: \_\_\_\_\_ Person Contacted: Nancy Vehicle OUT

Date/Time	Action/Instruction (✓) Estimate
	SKH 8673A - NA / LPC 18000 (55/hu) DCA: 10/01/2018
	YN 2735E - x
17/1/18C 5.57pm	Informed Kelvyn, we are pending estimate from repairer.
25/1/18C 3.58pm	revised to Kelvyn by email.

Surveillance mercul

REF:

6A1

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: SKH8693A  
 at Workshop m/s FL.  
 of \_\_\_\_\_  
 Insured: YN 2735E  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDA / Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GLE / PR Seen: ✓ Consistent? : Yes or No  
 Est. Repairs: 4 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

8053A

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SKH8693A Yr Regn: 1 13  
 Type: CA M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or CA  
 Make: BMW 316i cc 1598  
 Colour: Grey A/C: \_\_\_\_\_ Insured / Std / NI / NA  
 Sp. Reading: 106831 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: WBA3A12010J719505  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Order / Jammed / Leaked / Burnt or  
 Brake: Order / Jammed / Leaked / Burnt or  
 Modl: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: \_\_\_\_\_ R: 275/30ZR19  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front: 6 mm Rear: 6 mm  
 R/Bal: \_\_\_\_\_ mm L/Bal: 6 mm  
 D.O.A: 10.1.18 D.O.I: 15/1/18  
 Survey held at: 16  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Rear  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

have video. have G17 only.  
25/1/18 4/5 + 2820 confirmed with Alan. (Rec'd \$11019.82, 79%)

RECEIVED 20 JAN 2018

Date/Time: File Pass to? ☐ : Prel. Report  
25/1/18 turnover ☐ : Final Report  
 Date/Time: File Return to?

Days Of Repair: 4

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: ☐ : Site Insp \$  
☐ : Interview \$  
☐ : Tech. Insp \$  
☐ : Weekend \$

1-3-PR \$

Phone

Other

Report Format: TP

Lump Sum / I.B.I. \$ 2850

TOTAL



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI18000828/Uqb

3 TEMASEK AVENUE  
#16-01 CENTENNIAL TOWER  
SINGAPORE 039190

Date : 15-01-2018



Code : GAI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 2735E	Veh. Inspected	SKH 8693A
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	KELVYNA NGIAN	Assign Date	15/01/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer		Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	10/01/2018	Inspection Date	15/01/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: YN 2735E

Date: 25 January 2018

Our Ref: CS/GAI18000828/Uqb

The Motor Claims Department  
Great American Insurance Company

Attn: Kelvyna

Dear Sirs/Mdm

**PRELIMINARY ADVICE OF VEHICLE NO. SKH 8693A**


We thank you for the instruction on 16/01/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 15/01/2018 at the premises of M/s FASTECH AUTO and have the following to report:-

Workshop Estimate Amount	: S\$ <u>13,869.82</u>
Revised Estimate Amount	: S\$ <u>2,850.00 (Lump Sum)</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
Salvage Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages consistent.

We have NOT authorise repair.

Yours faithfully

CHUA KANG SENG  
Licensed Appraiser

# Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin** (Cethu): Case handler to make sure all Information created by the assignment team are ACCURATE.

## (1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

**Surveyor** (Mawin): Case handler to make sure the surveyor completed all required information.

## (1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

## (2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

## (3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓			
✓			
✓			
✓			
✓			
✓			

## (4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

Cethu 25/1/18

Case Handler

Date

\*C: Critical \*N: Non-Critical

21/05/2014

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Thursday, 25 January 2018 3:58 PM  
**To:** 'Ngian, Kelvyna'; SUR  
**Cc:** assignments  
**Subject:** RE: Insd YN2735E: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKH8693A  
**Attachments:** CSGAI18000828Uqb.pdf

Dear Kelvyna,

Enclosed herewith preliminary advice of SKH 8693A.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Wednesday, 17 January 2018 5:57 PM  
**To:** 'Ngian, Kelvyna' <[Kelvyna.Ngian@sg.gaig.com](mailto:Kelvyna.Ngian@sg.gaig.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Cc:** assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Subject:** RE: Insd YN2735E: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKH8693A

Dear Kelvyna,

Please be informed that we have inspected the vehicle SKH 8693A on 15/01/2018.

We are pending for estimate from repairer.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Tuesday, 16 January 2018 12:06 PM  
**To:** 'Ngian, Kelvyna' <[Kelvyna.Ngian@sg.gaig.com](mailto:Kelvyna.Ngian@sg.gaig.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Cc:** assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Subject:** RE: Insd YN2735E: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKH8693A

Dear Kelvyna,

Thank you for the assignment.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

## Catherine Chong (LKK Auto)

---

**From:** Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>  
**Sent:** Tuesday, 16 January, 2018 11:52 AM  
**To:** 'SUR'; Ashley Chong (LKK Auto)  
**Subject:** Insd YN2735E: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKH8693A  
**Attachments:** YN2735E.pdf; SKH8693A.pdf

Hi team

Please conduct TP survey

Thanks  
Kelvyna

---

**From:** Nancy Lam [mailto:nancy.lam@fastechauto.com.sg]  
**Sent:** Friday, January 12, 2018 5:34 PM  
**To:** Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>  
**Subject:** RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKH8693A

Dear Ngian

Please arrange LKK Auto Consultants to survey the car.

Regards,  
Nancy Lam  
Fastech Auto Pte Ltd  
Tel: 6746 5405  
Fax: 6745 8520

---

**From:** Ngian, Kelvyna [mailto:Kelvyna.Ngian@sg.gaig.com]  
**Sent:** Friday, January 12, 2018 5:17 PM  
**To:** Nancy Lam <nancy.lam@fastechauto.com.sg>  
**Subject:** RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKH8693A

WP

Dear Nancy

We append the following list of our panel surveyors to conduct the survey on a without prejudice basis:-

1. AJAX Adjusters & Surveyors Pte Ltd
2. L.B.S. Automotive Appraisal Pte Ltd
3. Priority Services
4. RT Appraisal Pte Ltd
5. LKK Auto Consultants

Please advise your preferred

Thanks  
Kelvyna

---

**From:** Nancy Lam [<mailto:nancy.lam@fastechauto.com.sg>]  
**Sent:** Friday, January 12, 2018 5:13 PM  
**To:** Ngian, Kelvyna <[Kelvyna.Ngian@sg.gaig.com](mailto:Kelvyna.Ngian@sg.gaig.com)>  
**Subject:** RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKH8693A

WITHOUT PREJUDICE

Dear Ngian

Please refer to the attachment of GIA report

Regards,  
Nancy Lam  
Fastech Auto Pte Ltd  
Tel: 6746 5405  
Fax: 6745 8520

---

**From:** Ngian, Kelvyna [<mailto:Kelvyna.Ngian@sg.gaig.com>]  
**Sent:** Friday, January 12, 2018 4:39 PM  
**To:** Nancy Lam <[nancy.lam@fastechauto.com.sg](mailto:nancy.lam@fastechauto.com.sg)>  
**Subject:** RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKH8693A

WITHOUT PREJUDICE

Dear Nancy

Could you forward a copy of your client's accident report for us to review first?

Thanks  
Kelvyna

---

**From:** Ngian, Kelvyna  
**Sent:** Thursday, January 11, 2018 5:12 PM  
**To:** 'Nancy Lam' <[nancy.lam@fastechauto.com.sg](mailto:nancy.lam@fastechauto.com.sg)>  
**Subject:** RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKH8693A

WITHOUT PREJUDICE

Dear Nancy,

Your notification came in January 11, 2018 11:26 AM, the provision is within 2 days of the notice

Thanks  
Kelvyna

---

**From:** Nancy Lam [<mailto:nancy.lam@fastechauto.com.sg>]  
**Sent:** Thursday, January 11, 2018 4:44 PM



**To:** Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>

**Subject:** FW: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKH8693A

WITHOUT PREJUDICE

*Dear Kelvyna*

*There was no reply from you.*

*Shall we arrange independence survey?*

Regards,  
Nancy Lam  
Fastech Auto Pte Ltd  
Tel: 6746 5405  
Fax: 6745 8520

---

**From:** Nancy Lam [mailto:nancy.lam@fastechauto.com.sg]

**Sent:** Thursday, January 11, 2018 3:20 PM

**To:** 'Ngian, Kelvyna' <Kelvyna.Ngian@sg.gaig.com>

**Subject:** RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKH8693A

WITHOUT PREJUDICE

*Dear Kelvyna*

*Please arrange survey for me instead of your insured not report yet.*

Regards,  
Nancy Lam  
Fastech Auto Pte Ltd  
Tel: 6746 5405  
Fax: 6745 8520

---

**From:** Ngian, Kelvyna [mailto:Kelvyna.Ngian@sg.gaig.com]

**Sent:** Thursday, January 11, 2018 2:48 PM

**To:** Nancy Lam <nancy.lam@fastechauto.com.sg>

**Subject:** RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKH8693A

WITHOUT PREJUDICE

Dear Nancy

Our insured has not report yet

Thanks  
Kelvyna

---

**From:** Nancy Lam [mailto:nancy.lam@fastechauto.com.sg]

**Sent:** Thursday, January 11, 2018 11:26 AM

To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>

Subject: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKH8693A

Hi Sir

My client claiming your insured YN 2735E.

Please kindly arrange PRS for SKH 8693A .

Date of accident 10.01.2018

In accordance to APPENDIX C Pre-action Protocol for Non-Injury Motor Accident Cases of PRACTICE DIRECTIONS AMENDMENT NO. 1 OF 2016 paragraph 2.3, you are require to provide a list of at least 10 motor surveyors within 2 days of the notice.

Regards,  
Nancy Lam  
Fastech Auto Pte Ltd  
Tel: 6746 5405  
Fax: 6745 8520

---

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

---

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

---

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

---

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Wednesday, 17 January 2018 5:57 PM  
**To:** 'Ngian, Kelvyna'; SUR  
**Cc:** assignments  
**Subject:** RE: Insd YN2735E: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKH8693A

Dear Kelvyna,

Please be informed that we have inspected the vehicle SKH 8693A on 15/01/2018.

We are pending for estimate from repairer.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Tuesday, 16 January 2018 12:06 PM  
**To:** 'Ngian, Kelvyna' <[Kelvyna.Ngian@sg.gaig.com](mailto:Kelvyna.Ngian@sg.gaig.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Cc:** assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Subject:** RE: Insd YN2735E: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKH8693A

Dear Kelvyna,

Thank you for the assignment.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Ngian, Kelvyna [<mailto:Kelvyna.Ngian@sg.gaig.com>]  
**Sent:** Tuesday, 16 January, 2018 11:52 AM  
**To:** 'SUR' <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; Ashley Chong (LKK Auto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Subject:** Insd YN2735E: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKH8693A

Hi team

Please conduct TP survey

Thanks

Kelvyna

---

**From:** Nancy Lam [<mailto:nancy.lam@fastechauto.com.sg>]  
**Sent:** Friday, January 12, 2018 5:34 PM

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8053G
Vehicle Details	
Vehicle No.:	SKH8693A
Vehicle to be Exported:	No
Intended De-registration Date:	15 Jan 2018
Vehicle Make:	B.M.W.
Vehicle Model:	316i 1.6 AT D/AB 4DR ABS HID
Primary Colour:	Grey
Manufacturing Year:	2012
Engine No.:	B425J361N13B16A
Chassis No.:	WBA3A12010J719505
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,146.00
Original Registration Date:	25 Jan 2013
First Registration Date:	25 Jan 2013
Transfer Count:	0
Actual ARF Paid:	\$23,146.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Jan 2023
PARF Rebate Amount:	\$17,359.00
Intended COE Rebate Details	
COE Expiry Date:	24 Jan 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$92,100.00
COE Rebate Amount:	\$46,272.00
Total Rebate Amount:	\$63,631.00

The information contained herein is correct as at 15 Jan 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	11/01/2018 12:01
Date Of Accident	10/01/2018 14:20
Exact Location Of Accident	YEW TEE MRT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKH8693A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAN YI LING EVELYN
NRIC No	S8228053G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97944676
Alternative Phone No	OFFICE-97944676

### Vehicle Particulars

Manufacturer	BMW
Model	316i
Exact Purpose for which vehicle was being used at time of accident	PARKED VEHICLE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z16VP05008512
Cover Note Number	-

### Driver

Name of Driver	LIM JUN HEE ADAM (LIN JUNXI ADAM)
NRIC No	S8323549G
Date Of Birth	02/08/1983
Occupation	INDOOR
Date Of Driving Pass	31/10/2003
Driving Experience	14 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97944676
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 630 JURONG WEST ST 65 #10-412
Postcode	640630
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO ATTACHED STATEMENT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN2735E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Accident Sketch Plan

### SKETCH PLAN




### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


on 10/01/2012 at 2.21pm, I parked my car (A) at the year  
Tee MRT suddenly vehicle B reversed and hit on my  
rear portion.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

SKH 8693A

Not Authorized  
Lahr  
2/5 2850  
4 day  
take photo after repair

QTY	Part Price	Prices \$
1	BOOTLID	1232.29 X
1	BOOTLID REAR LOGO	62.00 ✓
1	BOOTLID '320I' EMBLEM	58.00 X
1	BOOTLID INNER LOCK	245.32 X
1	BOOTLID WEATHERSTRIP	193.60 X
1	REAR BUMPER	1043.23 ✓
1	REAR BUMPER REINFORCEMENT	566.01 ✓
1 SET	REAR BUMPER CLIPS	50.00 ✓
1	REAR BUMPER TOW COVER	35.00 X
4	REAR BUMPER PDC SENSOR @\$235.00	940.00 2 pcs
1	REAR BUMPER PDC SERNOR WIRE	295.00 X
1	REAR BUMPER TOP GUIDE	161.23 ✓
2	REAR BUMPER REINFORCEMENT BRACKETS @\$125.00	250.00 X
2	REAR BUMPER SIDE HOLDERS @\$65.00	130.00 ✓
1	REAR END PANEL	820.00 X
1	REAR END PANEL TOP GARNISH	192.08 X
2	TAILLAMPS @\$528.03	1056.06 X
1	REAR EXHAUST	1150.00 X
1	REAR EXHAUST CHROME PIPE TWIN N/S	650.00 X
1	REAR END PANEL SEALER	50.00 X
1	REAR BUMPER LOWER SPOILER SPORT	1500.00 X
		10679.82

(52)

SUBTOTAL 10679.82

2482.47  
2328.34

## LABOUR CHARGES:

TO CHECK WIRING	50.00 -20
TO R&R REVERSE SENSOR	80.00 -50
TO R&R BOOTLID MECHANISM	11 100.00 X
TO R&R SEAT, CUSHION UPHOLSTERY	180.00 60
TO R&R REAR EXHAUST	11 100.00 X
TO SPRAY RUST PROOFING	11 100.00 X
LABOUR FOR PANEL BEATING	1080.00 500
TO PUTTY & SPRAY PAINTING	1500.00 600
	SUBTOTAL 3190.00

3588.34

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

13869.82

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY			Ref : CS/GAI18000828/Uqbn2	
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190			Date : 26-01-2018	
			Code : GAI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	YN 2735E	Veh. Inspected	SKH 8693A	
Policy No.		Coverage (\$)	0.00	
Claim No.	YN 2735E	Excess (\$)	0.00	
Assign From	KELVYNA NGIAN	Assign Date	16/01/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	B.M.W.316I (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	WBA3A12010J719505	Colour	GREY	
Odometer	106831	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	275/30 ZR19	MICHELIN	6 mm	
L/H Front Tyre	275/30 ZR19	MICHELIN	6 mm	
R/H Rear Tyre	275/30 ZR19	MICHELIN	6 mm	
L/H Rear Tyre	275/30 ZR19	MICHELIN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	10/01/2018	Inspection Date	16/01/2018	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKH 8693A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	BOOTLID (N)	TO REPAIR SEE LABOUR	1,232.29	-
1	BOOTLID REAR LOGO (N)	NECESSARY	62.00	62.00
1	BOOTLID "320I" EMBLEM (N)	NOT FITTED	58.00	-
1	BOOTLID INNER LOCK (N)	NOT NECESSARY	245.32	-
1	BOOTLID WEATHERSTRIP (N)	NOT NECESSARY	193.60	-
1	REAR BUMPER (N)	DENTED / DEFORMED	1,043.23	1,043.23
1	REAR BUMPER REINFORCEMENT (N)	DENTED	566.01	566.01
1	SET REAR BUMPER CLIPS (N)	NECESSARY	50.00	50.00
1	REAR BUMPER TOW COVER (N)	NOT NECESSARY	35.00	-
4	REAR BUMPER PDC SENSOR @\$235.00 (N)	SHORTED (2 PCS ONLY)	940.00	470.00
1	REAR BUMPER PDC SENSOR WIRE (N)	NOT NECESSARY	295.00	-
1	REAR BUMPER TOP GUIDE (N)	CRACKED	161.23	161.23
2	REAR BUMPER REINFORCEMENT BRACKETS @\$125.00 (N)	NO SUCH PARTS	250.00	-
2	REAR BUMPER SIDE HOLDERS @\$65.00 (N)	BENT	130.00	130.00
1	REAR END PANEL (N)	TO REPAIR SEE LABOUR	820.00	-
1	REAR END PANEL TOP GARNISH (N)	NOT NECESSARY	192.08	-
2	TAILLAMPS @\$528.03 (N)	NOT NECESSARY	1,056.06	-
1	REAR EXHAUST (N)	TO REPAIR SEE LABOUR	1,150.00	-
1	REAR EXHAUST CHROME PIPE TWIN N/S (N)	NOT NECESSARY	650.00	-
1	REAR END PANEL SEALER (N)	NOT NECESSARY	50.00	-
1	REAR BUMPER LOWER SPOILER SPORT (N)	TO REPAIR SEE LABOUR	1,500.00	-
LESS 5% DISCOUNT			-	-124.12
			10,679.82	2,358.35
<b><u>LABOUR</u></b>				
TO CHECK WIRING.			50.00	20.00
TO R&R REVERSE SENSOR.			80.00	50.00
TO R&R BOOTLID MECHANISM.			100.00	-
TO R&R SEAT,CUSHION UPHOLSTERY.			180.00	60.00
TO R&R REAR EXHAUST.			100.00	-

Report Ref No. CS/GAI18000828/Uqbn2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY RUST PROOFING.	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING, INCLUSIVE OF THE REPAIR OF BOOTLID, REAR END PANEL, REAR EXHAUST AND REAR BUMPER LOWER SPOILER SPORT.		1,080.00	500.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	600.00
			3,190.00	1,230.00
GRAND TOTAL			13,869.82	3,588.35
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,850.00

Report Ref No. CS/GAI18000828/Uqbn2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.