

Singapore mercantile

REF:

MS/10 / CC3/MS(1)S000829/Urbbn2

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJL 857

at Workshop m/s FT.

of _____

Insured: SJT 3658J

Policy No. A287480LSAVW

Claims No. 546103

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 140k.

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum. Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 7674J

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJL 857 Yr Regn: 1 / 15

Type: M.Cycle / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or CA

Make: Mer Benz E250 cc 1991

Colour: Grey A/C Insured / Std / NI / NA

Sp. Reading: 97704 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WD.721203823 077797

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/40ZR18
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA MIC OHTSU / PIR / SUMI / TOYO / YOKO or

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 12/1/18 D.O.I. 15/1/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Rear & H.A.S.
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction LTA 91915 7yrs. next 480k

16/1/18 Email GIA to Reshitha

RECEIVED 26 JAN 2018

25/1/18 conf. and 2/5 \$ 18,000 with Alan. (Fee) 28,058.60, 60%

25/1/18 send preli revised by merimen

Reshitha
25/1/2018

Date/Time, File Pass to? : Preli. Report

: Final Report

Date/Time, File Return to?

2) 25/1 - typist

Report Format: merimen

Lump Sum / I.B.I: (\$ 18,000)

Days Of Repair: 10

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

3 - RS - SI

Photos:

Other:

450
10
460

Survey Department Check List (Case Handler)

Reference No.: CC3/MSG/8000829/UVB
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (_____ **):** Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (_____ **):** Case handler to make sure the surveyor completed all required information.

(1) Assignment Form		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)					
C	Damaged Vehicle Photographs Uploaded	✓			

(3) Workshop Estimate/Assignment Form					
N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)					
C	Resurvey photo Uploaded	✓			

Check By: VERON 25/1/18
 Case Handler Date

*C: Critical *N: Non-Critical



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CC3/MSG18000829/Uvb

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 15-01-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJT 3658J	Veh. Inspected	SJL 85Z
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	15/01/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	12/01/2018	Inspection Date	15/01/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Jan 2018		24 Jan 2018 17:42				Pending for Survey Report Cancel Case
			Edit Adj Rpt				

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	KHOO AH HOCK, ID: S2196823D, Tel: +6597906388, Email: NOEMAIL		
Main Claimant:	CHUA PECK HOONG, ID: S1607674J		
Vehicle Reg. No.:	SJL85Z	Date of Loss:	12/01/2018 15:00 - :59
Claim Type:	TP / 546103	Policy/Cover Note No.:	A28748015AVW (Comprehensive) Coverage: 09/06/2017 - 08/06/2018
Vehicle Reg. No. (Insured):	SJT3658J	Policy No. (Claimant):	
		Excess:	
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Imm.Advice due 25/01/2018]		
Driver/Custodian (Insured):	KHOO AH HOCK (59 / Male), NRIC: S2196823D, Tel: +6597906388		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			
ALL ASSOCIATED TASKS		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Monica Chung Pei Zhen	Date: 25 Jan 2018
<u>Preliminary Advice</u>	

Insured Vehicle No	: SJT3658J	Accident Date	: 12/01/2018
TP Vehicle No	: SJL85Z	Assignment Date	: 24/01/2018
Make	: MERCEDES-BENZ E250	Est. Duration of Repair	: 10.00
Date of Inspection	: 15/01/2018		
Inspection At	: FASTECH AUTO PTE LTD (HQ) 1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear and front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	46,058.60
Revised Amount	:S\$	18,000.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00

Lump Sum Repair	:S\$	18,000.00
-----------------	------	-----------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

The vehicle is economical/not economical for repair.

The above survey was conducted on a 'without prejudice' basis.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 16 January 2018 12:29 PM
To: Rashitha Binte Shahuthuman
Cc: SUR; KKLau; Accounts (LKKAuto); 'Christopher Chionh'
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 12/1/2018 ,SJL 85Z (TP VEHICLE), SJT 3658J (OI VEHICLE)
Attachments: SJL 85Z (GIA).pdf

Dear Rashitha,

Please be informed that we had inspected the vehicle SJL 85Z at M/s: FASTECH AUTO PTE LTD ,1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 15/1/2018.

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	7674J

Vehicle Details

Vehicle No.:	SJL85Z
Vehicle to be Exported:	No
Intended De-registration Date:	15 Jan 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E250 SEDAN (R18)
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	27492030258855
Chassis No.:	WDD2120362B077797
Maximum Power Output:	155.0 kW (207 bhp)
Open Market Value:	\$48,905.00
Original Registration Date:	12 Jan 2015
First Registration Date:	12 Jan 2015
Transfer Count:	0
Actual ARF Paid:	\$55,467.00 27733

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Jan 2025
PARF Rebate Amount:	\$41,600.00

Intended COE Rebate Details

COE Expiry Date:	11 Jan 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$71,990.00
COE Rebate Amount:	\$50,315.00
Total Rebate Amount:	\$91,915.00

The information contained herein is correct as at 15 Jan 2018

OK

A-Assurance
Assurance in Insurance

Car Insurance Expiring?
We get you the cheapest insurance renewal

Click to get quote



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Lexus GS450h Hybrid Luxury, 1 Owner, Low Mileage.



Full Service Record By
Lexus, Last Serviced On Oct
2017, Best Colour Combination.
Speedo Motoring StarAd

Lake View Credit Pte Ltd [View our cars](#)

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category

Sort by Date Posted 20 results/page

9 vehicles

e 250

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status	
Search Selection	e 250		Any	Any	2015	Any	Any	Any	Available	
	Mercedes-Benz	E-Class E250	\$158,300	\$17,790 /yr	18-Jun-2015	1,991 cc	47,000 km	Luxury	Available	
	One And Only Unique Mystic Blue. 1 Owner Unit, Fully Serviced & Maintained By C&C. Comes With Agent Warranty. Daily Meticulously Grooming. Always Parked Under Shelter. Immaculate Condition. Feel The E...									
	Posted: 13-Jan-2018 Tags: 2015 Mercedes-Benz E250, Mercedes-Benz E250, Mercedes-Benz, E250, Used Mercedes-Benz									
	Lexus	ES250 Luxury	\$139,800	\$15,900 /yr	28-Apr-2015	2,494 cc	48,000 km	Luxury	Available	
	1 Owner. 100% Accident Free, Fully Serviced And Maintained By Agent, come With 5 Years Warranty And Free Servicing. Low Mileage Done, Original Paintwork. Pristine Interior Condition, Excellent Running ...									
	Posted: 05-Jan-2018 Tags: 2015 Lexus ES250, Lexus ES250, Lexus, ES250, Used Lexus									
	Mercedes-Benz	E-Class E250	\$156,999	\$17,760 /yr	16-Apr-2015	1,991 cc	44,675 km	Luxury	Available	
	1 Owner, Fully Maintained And Warranty By Agent (cnc). 2.48% Intrest Rate, ARF At \$56,412, Call Or Sms Joime For More Information Or Viewing. Premium Automobiles									
	Posted: 04-Jan-2018 Tags: 2015 Mercedes-Benz E250, Mercedes-Benz E250, Mercedes-Benz, E250, Used Mercedes-Benz									
	Kia	K2500 Single-Cab	\$49,800	\$6,410 /yr	22-Oct-2015	2,497 cc	-	Truck	Available	
	Fuel Type: Diesel View To Office, price Negotiable, 1 Owner With Full Canopy, A1 Condition. View To Believe. ABWIN (1994) Pte Ltd									
	Posted: 28-Dec-2017 Tags: 2015 Kia K2500, Kia K2500, Kia, K2500, Used Kia									
Car Buying	Car Selling	Car Aftermarket	Buying a pre-owned car, but Unsure of its Condition? Get, STA Car Evaluation							
Car Ownership	On The Move	Lifestyle								
	Mercedes-Benz	C-Class C250 AMG Line	\$181,000	\$21,450 /yr	03-Jun-2015	1,991 cc	53,000 km	Luxury	Available	
	1 Owner, Special Indent Unit From C&C. The Only Unit In The Market. Fully Maintained By C&C With Full History And Agent Warranty Till 2018! 100% Accident Free, Never Driven To Malaysia. High Optioned ...									
	Posted: 16-Dec-2017 Tags: 2015 Mercedes-Benz C250, Mercedes-Benz C250, Mercedes-Benz, C250, Used Mercedes-Benz									
	Mercedes-Benz	E-Class E250	\$150,000	\$17,570 /yr	13-Jan-2015	1,991 cc	57,300 km	Luxury	Available	
	One Of The Best Condition In The Market, Full AMG Options. P.I Unit. Flexible Down Payment, Bank/In House Loan Available, Flexible Loan Available At Low Interest Rate, Loan Tenure Up To 7 Years Accide...									
	Posted: 16-Dec-2017 Tags: 2015 Mercedes-Benz E250, Mercedes-Benz E250, Mercedes-Benz, E250, Used Mercedes-Benz									
	Mercedes-Benz	V-Class V250 BlueTec	\$229,000	\$24,190 /yr	18-Sep-2015	2,143 cc	-	MPV	Available	
	Fuel Type: Diesel (Euro 5 Engine and Above) With 3 Years Agent Warranty And Servicing. Easy In House Financing Available. Check With Our Friendly Consultants For More Information!									
Compare										

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/01/2018 18:07
Date Of Accident	12/01/2018 15:10
Exact Location Of Accident	ALONG PIE TOWARDS CHANGI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJL85Z
Insured/Policyholder	
Name Of Registered Owner	CHUA PECK HOON
NRIC No	S1607674J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96383093
Alternative Phone No	OTHERS-96383093

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E250-2.0 SEDAN (R18) (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA009798/1
Cover Note Number	

Driver

Name of Driver	OH BENG KWANG
NRIC No	S1593471I
Date Of Birth	25/04/1963
Occupation	INDOOR
Date Of Driving Pass	09/01/1981
Driving Experience	37 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96383093
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address 178 CACTUS ROAD
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured SPOUSE
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions RAINING
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: VIDEO WITH OWNER
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJT3658J
 Vehicle Make/Model/Colour VOLKSWAGEN JETTA GP 1.4 TSI 90 A/T TL 1632G5
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLR941Y

Vehicle Make/Model/Colour	MITSUBISHI LANCER EX 1.6 AT LED TAIL LAMP
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	FBG324E
Vehicle Make/Model/Colour	YAMAHA SNIPER T150
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	OH BENG KWANG
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SJL85Z
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Sketch Plan

1/15/2018

img-114155407-0001.jpg

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

3. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claim;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any inquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If Driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: *S. J. Lim*
NRIC/FIN No: *S8020222A*

Sketch Plan #2

1/15/2018

img-114155407-0002.jpg

SKETCH PLAN



A - 5JL55Z
 B - 5ST3658'S
 C - 5L8941Y
 D - FB6324E

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 12/6/2018 at 15:10 hrs. I was driving my vehicle (A) along PIE towards cherry. suddenly a motor-cycle slipped and fell. I stop my car immediately, then I felt an impact from behind. Then I realized that there were 4 vehicles involved in an accident.



DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (if driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name: Subhas
 NRC/ID No: 380403771



FASTECH AUTO PTE LTD

VEHICLE NO: SJL85Z

not authorized
 Make
 1/5 @ 18,000
 10 day.
 15/11/18

Qty Particular

Amount S\$

List Item:

Qty	Particular	Amount S\$
1 PCS	BOOTLID <i>DD/Warpak</i> 2439.10	\$ 3,882.13 ✓
1 PCS	BOOTLID 'E250' EMBLEM <i>neu</i> 80.67	\$ 75.00 ✓
1 PCS	BOOTLID '7G-TRONIC' EMBLEM <i>neu</i>	\$ 78.00 ✓
1 PCS	BOOTLID C&C LOGO <i>neu</i>	\$ 42.00 ✓
1 PCS	BOOTLID REAR LOGO <i>neu</i> 45.56	\$ 95.00 ✓
1 PCS	BOOTLID OUTER CHROME MOULDING <i>neu</i> 132.49	\$ 382.00 ✓
2 PCS	BOOTLID REFLECTORS @\$385 <i>n1</i>	\$ 770.00 X
1 PCS	BOOTLID INNER LOCK <i>twi/shut</i> 499.10	\$ 645.00 ✓
1 PCS	BOOTLID INSULATOR <i>n1</i>	\$ 388.00 X
1 SET	BOOTLID INSULATOR CLIPS <i>n1</i>	\$ 50.00 X
1 PCS	BOOTLID WEATHERSTRIP <i>twi</i> 315.60	\$ 382.13 ✓
1 PCS	REAR BUMPER <i>DD</i> 1871.55	\$ 1,885.00 ✓
1 PCS	REAR BUMPER REINFORCEMENT <i>DD/Reel</i> 745.32	\$ 945.00 ✓
1 PCS	REAR BUMPER CHROME MOULDING CENTRE <i>one</i> 188.22	\$ 310.00 ✓
2 PCS	REAR BUMPER CHROME MOULDING SIDES @\$185 <i>neu</i> 115 x 2 = 230	\$ 370.00 ✓
1 PCS	REAR BUMPER LOWER DIFFUSER <i>Bodson</i> 466.35	\$ 845.00 ✓
4 PCS	REAR BUMPER PARKING SENSORS @\$250 <i>shut</i> 223 x 3 = 669	\$ 1,000.00 3 pcs
1 PCS	REAR BUMPER PARKING SENSOR WIREHARNES <i>n1</i>	\$ 342.00 X
1 PCS	REAR BUMPER INNER RETAINER <i>one</i> 148.23	\$ 182.00 ✓
2 PCS	REAR BUMPER SIDE RETAINERS @\$89.50 <i>shut</i>	\$ 179.00 ✓
1 PCS	REAR END PANEL <i>Bodson</i> 1271.55	\$ 1,465.00 ✓
1 PCS	REAR END PANEL TOP GARNISH <i>twi</i> 340	\$ 366.00 ✓
1 PCS	REAR FLOOR PANEL <i>n</i>	\$ 1,650.00 X
1 PCS	REAR FLOOR PANEL RECESS CENTRE <i>one</i>	\$ 316.00 ✓
1 PCS	REAR FLOOR PANEL TOP BOARD <i>warpak</i> 712.39	\$ 820.00 ✓
2 PCS	TAILLAMPS @\$895.11 <i>one</i> 667.14 x 2 = 1334.28	\$ 1,790.22 ✓
1 PCS	REAR FENDER O/S <i>n</i>	\$ 1,485.00 X
1 PCS	REAR FENDER INNER TRIM O/S <i>Re/trim</i> 533.62	\$ 655.12 ✓
2 PCS	REAR EXHAUSTS @\$2450 <i>o/s DD/twi</i> 2362.12	\$ 4,900.00 1 PC
2 PCS	REAR EXHAUST CHROMES @\$380 <i>o/s reel</i> 280	\$ 760.00 1 PC
2 PCS	REAR EXHAUST MOUNTINGS @\$50 <i>n1</i>	\$ 100.00 X
1 PCS	REAR EXHAUST HEAT SHIELD O/S <i>n</i>	\$ 245.00 X
1 PCS	REAR BOOTLID LOCK PUMP <i>Daged toto</i>	\$ 822.00 ✓
1 PCS	FRONT BUMPER <i>DD/Re</i> 1645.32	\$ 1,812.00 ✓
1 PCS	FRONT BUMPER CHROME MOULDING CENTRE <i>neu</i> 193.60	\$ 211.00 ✓
2 PCS	FRONT BUMPER SIDE RETAINERS @\$95 <i>n1</i>	\$ 190.00 X
1 PCS	FRONT BUMPER CENTRE GRILLE <i>To-n</i>	\$ 228.00 ✓
1 PCS	FRONT BUMPER FOG LAMP GRILLE N/S <i>twi</i> 118.30	\$ 145.00 ✓
1 PCS	FRONT BUMPER PARKING SENSOR N/S <i>shut</i>	\$ 215.00 X
1 PCS	FRONT BUMPER REINFORCEMENT <i>n</i>	\$ 895.00 X
1 PCS	FRONT BUMPER SPONGE <i>To-n</i> 266.20	\$ 282.00 ✓
1 PCS	FRONT BUMPER TOP RETAINER <i>n1</i>	\$ 184.00 X
1 PCS	HEADLAMP N/S <i>one</i> 2955.20	\$ 3,805.00 ✓
1 PCS	FRONT GRILLE <i>n1</i>	\$ 830.00 X

10%

1 PCS FRONT SUPPORT PANEL *^* *10%* \$ 1,020.00 *x*
 List Item Total: \$ 38,038.60

Special Nett Item:

1 PCS REAR END PANEL SEALANT *nu* \$ 80.00 *50*
 1 PCS REAR REVERSE CAMERA *su* \$ 500.00 *x*
 Special Nett Total: \$ 580.00

Labour Charge:

TO CHECK WIRING \$ 80.00 *30*
 TO DISMANTLE & REPLACE REVERSE SENSOR \$ 100.00 *50*
 TO TRANSFER BOOTLID MECHANISM \$ 120.00 *80*
 TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY \$ 150.00 *80*
 TO DISMANTLE & REFIX PETROL TANK *^^* \$ 100.00 *x*
 TO DISMANTLE & REPLACE REAR EXHAUST \$ 180.00 *80*
 TO MOUNT VEHICLE ON CAR O-LINER *^^* \$ 380.00 *x*
 TO SPRAY RUST PROOFING \$ 180.00 *60*
 TO REFILL AIRCON GAS *^^* \$ 150.00 *x*
 LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS \$ 3,000.00 *1500*
 TO PUTTY & SPRAY PAINTING \$ 3,000.00 *1600*
 Labour Charge Total: \$ 7,440.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 46,058.60 *3530*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18000829/UVBN2
Date: 30/01/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28748015AVW
Claimant Vehicle No :	SJL85Z	Insured Vehicle No :	SJT3658J
Date of Loss:	12/01/2018	Nature of Claim:	TP
			Claim No: 546103

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJL85Z	Engine No:	27492030258855
Make & Model:	MERCEDES-BENZ E250, 2.0 SEDAN (A)	Chassis No:	WDD2120362B077797
Reg. Date:	12/01/2015 (Man. Year: 2014)	Odometer:	97704 km
Colour:	Grey		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/40ZR18	Rear Tyre Size:	245/40ZR18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	38,618.60	19,402.79	19,215.81	49.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,440.00	3,480.00	3,960.00	53.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	46,058.60	22,882.79	23,175.81	50.32
Approved Total (Overridden) (S\$)		18,000.00		
(S\$)	46,058.60	18,000.00	28,058.60	60.92
+ GST 7.00/7.00% (S\$)	3,224.10	1,260.00	1,964.10	60.92
Nett Amount (S\$)	49,282.70	19,260.00	30,022.70	60.92

INSPECTION

Date of Assignment:	24/01/2018	
Date Inspected:	15/01/2018 Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883

Estimated Period of Repair: 10.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 Jan 2018)
Parts: 143	MERCEDES-BENZ E250 2.0 SEDAN (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJL85Z)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented/Warped	3,882.13 F	*2,439.10 FL
2	1		*BOOTLID E250 EMBLEM	Necessary	75.00 F	*75.00 FL
3	1		*BOOTLID 7G-TRONIC EMBLEM	Necessary	78.00 F	*78.00 FL
4	1		*BOOTLID C&C LOGO	Necessary	42.00 F	*42.00 FL
5	1		*BOOTLID REAR LOGO	Necessary	95.00 F	*45.56 FL
6	1		*BOOTLID OUTER CHROME MOULDING	Necessary	382.00 F	*132.49 FL
7	2		*BOOTLID REFLECTORS	Not Necessary	770.00 F	*- FL
8	1		*BOOTLID INNER LOCK	Twisted/Shorted	645.00 F	*499.10 FL
9	1		*BOOTLID INSULATOR	Not Necessary	388.00 F	*- FL
10	1		*SET BOOTLID INSULATOR CLIPS	Not Necessary	50.00 F	*- FL
11	1		*BOOTLID WEATHERSTRIP	Twisted	382.13 F	*315.60 FL
12	1		*REAR BUMPER	Distorted	1,885.00 F	*1,871.55 FL
13	1		*REAR BUMPER REINFORCEMENT	Dented/Bent	945.00 F	*745.32 FL
14	1		*REAR BUMPER CHROME MOULDING CENTRE	Cracked	310.00 F	*188.22 FL
15	2		*REAR BUMPER CHROME MOULDING SIDES	Necessary	370.00 F	*230.00 FL
16	1		*REAR BUMPER LOWER DIFFUSER	Badly Dented	845.00 F	*466.35 FL
17	1		*REAR BUMPER PARKING SENSORS (4 Pcs)	Shorted (3 Pcs only)	1,000.00 F	*669.00 FL
18	1		*REAR BUMPER PARKING SENSORS WIREHARNES	Not Necessary	342.00 F	*- FL
19	1		*REAR BUMPER INNER RETAINER	Cracked	182.00 F	*148.23 FL
20	2		*REAR BUMPER SIDE RETAINERS	Bent	179.00 F	*179.00 FL
21	1		*REAR END PANEL	Badly Dented	1,465.00 F	*1,271.55 FL
22	1		*REAR END PANEL TOP GARNISH	Twisted	366.00 F	*340.00 FL
23	1		*REAR FLOOR PANEL	Repair	1,650.00 F	*- FL
24	1		*REAR FLOOR PANEL RECESS CENTRE	Cracked	316.00 F	*316.00 FL
25	1		*REAR FLOOR PANEL TOP BOARD	Warped	820.00 F	*712.39 FL
26	2		*TAILLAMPS	Cracked	1,790.22 F	*1,334.28 FL
27	1		*REAR FENDER O/S	Repair	1,485.00 F	*- FL
28	1		*REAR FENDER INNER TRIM O/S	Deformed/Torn	655.12 F	*533.62 FL
29	1		*REAR EXHAUSTS	O/s Dented/Twisted	4,900.00 F	*2,362.12 FL
30	1		*REAR EXHAUST CHROMES	O/s Bent	760.00 F	*280.00 FL
31	2		*REAR EXHAUST MOUNTINGS	Not Necessary	100.00 F	*- FL
32	1		*REAR EXHAUST HEAT SHIELD O/S	Repair	245.00 F	*- FL
33	1		*REAR BOOTLID LOCK PUMP	Damaged	822.00 F	*822.00 FL
34	1		*FRONT BUMPER	Dented/Deformed	1,812.00 F	*1,645.32 FL
35	1		*FRONT BUMPER CHROME MOULDING CENTRE	Necessary	211.00 F	*193.60 FL
36	2		*FRONT BUMPER SIDE RETAINERS	Not Necessary	190.00 F	*- FL
37	1		*FRONT BUMPER CENTRE GRILLE	Torn	228.00 F	*228.00 FL
38	1		*FRONT BUMPER FOG LAMP GRILLE N/S	Twisted	145.00 F	*118.30 FL
39	1		*FRONT BUMPER PARKING SENSOR N/S	Serviceable	215.00 F	*- FL
40	1		*FRONT BUMPER REINFORCEMENT	Repair	895.00 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*FRONT BUMPER SPONGE	Torn	282.00 F	*266.20 FL
42	1		*FRONT BUMPER TOP RETAINER	Not Necessary	184.00 F	*- FL
43	1		*HEADLAMP N/S	Cracked	3,805.00 F	*2,955.20 FL
44	1		*FRONT GRILLE	Not Necessary	830.00 F	*- FL
45	1		*FRONT SUPPORT PANEL	Repair	1,020.00 F	*- FL
46	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*50.00 FS
47	1		*REAR REVERSE CAMERA	Serviceable	500.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	38,618.60	21,553.10
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	2,150.31
Total Parts (\$\$)	38,618.60	19,402.79

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACE REVERSE SENSOR	New	100.00	50.00
3	TO TRANSFER BOOTLID MECHANISM	New	120.00	80.00
4	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY	New	150.00	80.00
5	TO DISMANTLE & REFIX PETROL TANK	New	100.00	-
6	TO DISMANTLE & REPLACE REAR EXHAUST	New	180.00	80.00
7	TO MOUNT VEHICLE ON CAR-O LINER	New	380.00	-
8	TO SPRAY RUST PROOFING	New	180.00	60.00
9	TO REFILL AIRCON GAS	New	150.00	-
10	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS	New	3,000.00	1,500.00
11	TO PUTTY & SPRAY PAINTING	New	3,000.00	1,600.00
Gross Labour Cost (S\$)			7,440.00	3,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >