MTLM18006183 / Tan Lim Motor Pte Ltd - Defu ENTRY DATE & TIME: 12/01/2018 15:47 SUBMITTED BY: Sam Low Pui Mun

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.					
	ACCIDENT STATEMENT				
Date Of Report	12/01/2018 15:47				
Date Of Accident 11/01/2018 16:30					
Exact Location Of Accident	SLIP ROAD OF AYE AND LOWER DELTA ROAD				
Country/State of Loss	SINGAPORE				
	DETAILS OF OWN VEHICLE				
Vehicle Registration Number	SLS8078G				
Insured/Policyholder					
Name Of Registered Owner GRAB RENTALS PTE LTD					
Co Reg No	o 201617200G				
Email Address	NOEMAIL				

Mobile Phone No

OFFICE-98235008 Alternative Phone No

Vehicle Particulars

MAZDA Manufacturer

3-1.5 SEDAN EU6 (A) Model

Exact Purpose for which vehicle was being used at

time of accident

PERSONAL USED

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY PRIVATE HIRE

Insurance Company

Vehicle Category

Name of Insurance Company

GREAT AMERICAN INSURANCE COMPANY

Type Of Coverage COMPREHENSIVE

YES Fleet Policy

Policy Number

Cover Note Number

Name of Driver

Driver

HO PENG KWANG

S1791646G NRIC No Date Of Birth 25/09/1967 **OUTDOOR** Occupation 29/06/1988 Date Of Driving Pass

29 YEARS AND 6 MONTHS **Driving Experience**

Gender MALE

Mobile Number (LOCAL) +65-90285569

Fax Number

Contact Number

NOEMAIL **EMail Address**

Address

BLOCK 127C KIM TIAN ROAD

#38-541

Postcode

163127

Was driver an employee of the Insured's Company NO If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

DRIZZLING

Road Surface

WET

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: MS HO

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

HOUGANG NEIGHBOURHOOD POLICE POST

Police Station Address

ROAD: BLK 357 HOUGANG AVENUE 7 #01-805, POSTCODE: 530357,

COUNTRY: SINGAPORE

Police Station Contact

TEL NO: 1800-2869999 - FAX NO: 63822066

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

Refer to sketch plan and police report T/20180112/2049

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

SD CARD WITH TRAFFIC POLICE

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SHC7494B

Vehicle Make/Model/Colour

Details Of Properties

TAXI

Vehicle Category Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

GV5363X

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SLG7828D

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number

S6744CB

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 5

Vehicle Registration Number

SLQ6827K

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

DETAILS OF INJURED PERSON 1

Name

HO PENG KWANG

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLS8078G

Were seat belts worn?

YES

Was this injured conveyed to hospital by

ambulance?

NO

Address

Postcode

DETAILS OF INJURED PERSON 2

Name

MS HO

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLS8078G

Were seat belts worn?

YES

Was this injured conveyed to hospital by

ambulance?

NO

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims:
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Ce

Name:

NRIC/FIN No .:

SKETCH PLAN
Clower Data Flyover
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT
On 11/01/2018, @ 16:30 hrs., I came to a stop at the traffic light of the slip road of AYE and hower Delter Road, waiting for Green Itaht. About 5 seconds, a sudden hard impact on my right rear and the next moment, a continuous deaging noise or my left til I saw a yellow vehicle passed thru my vehicle's right portion. It was a (ity rab (B:SHCT194B)) and the favoi continued to pass mid-lumbian and lift the traffic light, a vehicle (SLQ 6827E) travelling from Lower Delta Road hit the City cab as the rity cab stopped at the junction. I also when and enalised it involved another 3 more vehicles on the centre lane. The driver of SHC T494B was not moving at all. The Civil Defence, ambulance and police came to the scene and the driver was conveyed to hosportal by ambulance. My daughter is in my car and both of us were injured.
DECLARATION I/We declare the foregoing particulars are true in every respect.
Policyholder's Signature Date & Time: Date

GIARNIC SketchPlanForm_VE

Police report Pg. 1



Police Station Of Origin: Paya Lebar NPP 114 Hougang Avenue 1 #01-1270 SINGAPORE 530114 Tel No: 1800-2899999

Report No. T/20180112/2049

REPORT OF A TRAFFIC ACCIDENT

	Date/Time Report Made: 12/01/2018 12:22			Vide Report No.: A/20180111/0068		Station Diary No.:			
78000	Informant	s Particu	ars are		138130257				
	Name of Informant: HO PENG KWANG			Address: APT BLK 127C KIM TIAN ROAD #38-541 SINGAPORE 163127					
•	ID Type / ID No NRIC NO / \$1791646G			Contact No.: Home/Office:	Mobile: 9	90285569			
	Nationality: SINGAPOR		īN .	Email:	8				
	Sex: Male	Age: 50	Date of Birth: 25/09/1967	Type of Informant: Driver					
	Race: Chinese			Language:	Institution	n / School Name:			
	Occupation:			Driving Licence Information: Class: Date of Expiry:					

Type of Accident: Injury Attended by Police	Drink Date/Time of Accident: No 11/01/2018 16:3			Type of Location Slip Road		
Location: Along Road 1 AYER RAJAH EXPRESSWAY SLIP ROAD OF AYE & LOWER DEL	TA ROAL).).				
Weather: Raining		Surface:			Roa	d Speed Limit:
Traffic Flow: One Way		Control: ontrolled	٠		Traff Ligh	fic Volume: t
Type of Collision: Between Moving Vehicles - Head To	Rear					one conveyed by ulance:

/ehicle No:	Type	Make	Model	Color	Conditio	n. No of	Passeng
SHC7494B	Car					0	
SLS8078G	Car				• •	. 0	

Police report Pg. 2



Police Station Of Origin: Paya Lebar NPP 114 Hougang Avenue 1 #01-1270-SINGAPORE 530114 Tel.No: 1800-2899999



Report No. T/20180112/2049

CONTINUATION OF REPORT

Brief Details.

On 11/01/2018 at about 1630hrs, I was driving my vehicle along Lower Delta Road. My vehicle was stationary at the extreme left lane, first vehicle as it was red light. While waiting, I felt an impact from the rear right and when I looked towards my right, I discovered that there was a CityCab (SHC7494B) drove passed me and hit onto the traffic light. I alight my vehicle and discovered that there were several vehicle were been hit also as the Citycab had drove in between lane 3 and lane 2. I made a check on the driver however he was not responsive. When Ambulance arrived, he was been conveyed to hospital. I wish to state that there is camera installed in my vehicle and it was already been taken away by TP. I am lodging this report as instructed by TP IO Clarence, c/n: 65476195, reference: A/20180111/0068.

Police report Pg. 3



T/20180112/2049

Police Station Of Origin: Paya Lebar NPP 114 Hougang Avenue 1 #01-1270 SINGAPORE 530114 Tel No: 1800-2899999 3 of 3 Report No. T/20180112/2049

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the <u>report number</u> as reference.

Signature Of Officer Recording The Report: F / Sgt 2 JANSEN KWOK SHU HAO	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 12/01/2018 12:22
Officer In Charge Of Case: TP / GIT / Sgt 3 LIM ENG KUAN, CLARENCE Contact No.: 65476195	Classification Of Case:
Authentication Stamp NP168 Signature: Signature:	