

INS. CASE OWNER:

cc<sup>3</sup>, AXA 800 0843 K ja3

LKK:

IDAC:

Surveyor: Kenneth


DOI: ASSIGNMENT  
M/18

Date / Time: 2/1/18

Registered in Merimen: \_\_\_\_\_

Pre-assign / CCU / FTE

PC 25610



Insured Vehicle No. : \_\_\_\_\_

Claim No. : \_\_\_\_\_

Name of Insured : \_\_\_\_\_

Policy No. : \_\_\_\_\_

Insured Tel No. : \_\_\_\_\_ HP: \_\_\_\_\_

Make / Model : \_\_\_\_\_

Excess Sec II :SS \_\_\_\_\_ D.O.A: 10-1-18

Place of Accident : \_\_\_\_\_

Is driver the owner? ( YES / NO ) Nature of Accident : \_\_\_\_\_


If NO, Driver Name / Age : \_\_\_\_\_

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : \_\_\_\_\_ (V/L: YES / NO)

Insured Liability : % Final ? Yes / No

STAD 121



INSRS: trans-Gab  
WSP: \_\_\_\_\_  
Tel : \_\_\_\_\_  
Liability : \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS:  
WSP: \_\_\_\_\_  
Tel : \_\_\_\_\_  
Liability : \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS:  
WSP: \_\_\_\_\_  
Tel : \_\_\_\_\_  
Liability : \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS:  
WSP: \_\_\_\_\_  
Tel : \_\_\_\_\_  
Liability : \_\_\_\_\_  
RMKS: \_\_\_\_\_

Date/ Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	<b>Documentation Check List:</b> Handler Typist	
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OI:	<input type="checkbox"/>
	Authorisation To Act:	<input type="checkbox"/>
	Release Voucher:	<input type="checkbox"/>
	Final Repair Bill:	<input type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/>
	Towing Invoice	<input type="checkbox"/>
	LTA / GIA :	<input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/>
	LOD	<input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
<b>PRELIMINARY ADVICE</b> Date/Time: _____ Sent By: _____	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>
<b>FINALIZATION</b> Date/Time: _____ Confirm with: _____ Confirm by: _____		
Repair Cost: S\$ _____ ( _____ days) Reduction: _____ % Email <input type="checkbox"/> Call <input type="checkbox"/>		
<b>FINAL SETTLEMENT</b> Date/Time: _____ Confirm with _____ Email <input type="checkbox"/> Call <input type="checkbox"/>		
Final Liability: % _____ (Agreed / Assessed) BOLA S/N No. : _____ If NO or B 28, Ass. Lia :		
Repair Cost: S\$ _____		
Loss of Rental (LOR): S\$ _____ ( _____ days)		
Loss of Use (LOU): S\$ _____ (\$ x days)		
Loss of Income (LOI): S\$ _____ (\$ x days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one]		
GIA/LTA Search S\$ _____		
Medical: S\$ _____		
Disbursement: S\$ _____ (e.g. Tow/ Independent)		
Legal Cost S\$ _____		
<b>Total:</b> S\$ _____ <b>Global Sum S\$:</b> _____		
<b>FINAL PAYMENT</b> Date/Time: _____ Confirm with: _____ Email <input type="checkbox"/> Call <input type="checkbox"/>		
Payee 1: S\$ _____ Name 1: _____		
Payee 2: (Strike if N.A.) S\$ _____ Name 2: _____		
Payee 3: (Strike if N.A.) S\$ _____ Name 3: _____		

ASS. REC. BY:

REF: AA1

Kenneth

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Trans Cob

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 2 1/2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: S1401217 Yr Regn: 04 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or

Make: Chvrolet Epica c.c. 1991

Colour: White / Red A/C: Insured / Std / NI / NA

Sp. Reading: 093112 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KL1LA6PRTBB 089714

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or Giti

Front R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 10/1/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or N/S 157

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>15/1</u>	<u>File pass to Customer</u> <u>27 Sep @ 2950h</u>

Date/Time, File Pass to?  : Prell. Report  
 : Final Report

1) \_\_\_\_\_  
Date/Time, File Return to?  
2) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)

Survey Fee:	_____
Transportation:	_____ \$ + RS _____ \$
Photos	_____
Others	_____
TOTAL	_____

Report Format : \_\_\_\_\_  
Lump Sum / I.B.I: (\$ \_\_\_\_\_)