

ASSIGNMENT (Office)

From (Person): Kenneth
Katherine Wong MSIG Date/Time: 15/01/18 @ 2:10pm

Estimated Cost: Bill to:

OD (TP) WS/TP RES / OD RES / EVA / DV / MV / CS

To Inspect Vehicle No: SKD G965A Insured: SLM 24734

at Workshop ref: Falcon-Air Auto Services Tel: 6452 0880

of 176 Sin Ming Drive # 01-06

Policy No: 29039974 QMY Claim No: 545797

Sum Insured: Excess:

Make of Veh: D.O.A. 12/01/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS (up) 17/01/2018 @ 12-1pm owner writing

Date/Time: 249pm @ 15/01/18 Person Contacted: Florence Vehicle In (OUT)

Date/Time	Action/Inspection	Estimate
	SKD G965A - CCG/AIG/1017631 Kwgy 3s2	D.O.A. 12/09/2014
	SLM 24734-X	

18/1/18 Sand preti revised by merimen

19/4 81356.75 Confirmed by email (Red 1119, 459) (No LS)

MSIG

ASSIGNMENT

Date 17/01/2018

Estimated Cost

OD / P / NS / TP / RES / CD / RES / EVA / INV / AM /

To inspect Vehicle No SKD 6965A
at Workshop Falcon-Air Auto Services
of 176, Sin Ming Drive # 01-06

Insured

Policy No

Claims No

Sum Insured

Excess

Clients Record

12pm - 1pm @ Owner
waiting

Make of Ven

Policy Condition

Remark: The veh had commenced its
repair at the time of inspection.

Sal on Market Value

DAD Accident Report Consistent? Yes or No

GIA / PR Seen Consistent? Yes or No

Est. Recars: 02 days Res: Yes or No

Accident 1-11-18 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

'wp'

Date

Person Contacted

Vehicle IN / OUT

SKD 6965A 12-11

Type Car / M Cycle Bus Van / Lorry Taxi Prime/Motor

Truck Trailer

Make

Audi A1 1390

Colour

White RQ Insured Exp NI NA

St Reading

141055 Radio Insured Exp NI NA

Eng No

C No

WAAUZZZ8X1BB026792

Gen Cond Good / Fair / Poor / Burnt

Steering In order / Jammed / Leaked / Burnt or

Brake In order / Jammed / Leaked / Burnt or

Mod Nil / S Rim / STD / Slim or

Tyre Size

Realstone 225/45R18
R: 7070

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI

TOYO / YOKO or

Front

R Bal

J

mm

Rear

R Bal

7

L Bal

J

mm

L Bal

7

D O A

12/1/18

D O A

17/1/18

Survey held at

Des of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear N/S

The UIC / Chassis frame / Body Structure affected due to collision

Date Time Action Instruction

18/1 15h pass to Catherine

RECEIVED 20 APR 2018

Date Time Ref Pass No

☐
☐

Prel. Report

Final Report

Date Time Ref Return No

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee

Particulars

200
10

19/4 - typist

Add Fee:

☐
☐
☐
☐

Site Visit \$

Inter View \$

Tech Visit \$

Resurvey \$

Report Format

Lump Sum / IE /

merimen

P/P \$1356.75

210

Survey Department Check List (Case Handler)

Reference No.: CS/MSG/8000857/Kvd3
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type				
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)	✓			
C	Days of repair	✓			
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By:

VERON

19/4/18

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18000852/Kvd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 15-01-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLM 2473U	Veh. Inspected	SKD 6965A
Policy No.	29039974QMY	Coverage (\$)	0.00
Claim No.	545797	Excess (\$)	0.00
Assign From	MERIMEN (KATHERINE WONG)	Assign Date	15/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	12/01/2018	Inspection Date
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD (HQ) 176 SIN MING DRIVE #01-06/07/13, SIN MING AUTOCARE SINGAPORE 575721	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Jan 2018 Sendback Est	13 Jan 2018 10:46 S\$2,251.50	15 Jan 2018 14:10 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	Fung Kok Kiang Henry, ID: S0135609G		
Main Claimant:	MUHAMMAD SUFIYAN BIN RAHMAD, ID: S8632829A		
Vehicle Reg. No.:	SKD6965A	Date of Loss:	12/01/2018 08:00 - :59
Claim Type:	TP / 545797	Policy/Cover Note No.:	29039974QMY Coverage: 25/10/2017 - 05/11/2018
Vehicle Reg. No. (Insured):	SLM2473U	Policy No. (Claimant):	MT000109
		Excess:	
Repairer:	Falcon-Air Auto Services Pte Ltd (Sin Ming) 176 Sin Ming Drive #01-06, Sin Ming Autocare, 575721 Sin Ming - Tel: 6452 0880		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 16/01/2018]		
Driver/Custodian (Insured):	FUNG SHUFEN CHRISTEL (), NRIC: S9205720H		
Adj Asg. Remarks:	Please Survey - Owner waiting 2pm on 17/1/18. Thank you		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Katherine Wong Chew Shong	Date: 18 Jan 2018
<u>Preliminary Advice</u>	

Insured Vehicle No : SLM2473U	Accident Date : 12/01/2018
TP Vehicle No : SKD6965A	Assignment Date : 15/01/2018
Make : AUDI A1	Est. Duration of Repair : 2.00
Date of Inspection : 17/01/2018	
Inspection At : FALCON-AIR AUTO SERVICES PTE LTD (SIN MING) 176 SIN MING DRIVE #01-06, SIN MING AUTOCARE SINGAPORE 575721	

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,251.50
Revised Amount	:S\$	1,132.50
Check Items (Estimated)	:S\$	138.00
Total	:S\$	1,270.50
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2829A
Vehicle Details	
Vehicle No.:	SKD6965A
Vehicle to be Exported:	Yes
Intended De-registration Date:	13 Jan 2018
Vehicle Make:	AUDI
Vehicle Model:	A1 1.4 TFSI S-TRONIC
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	CAX668718
Chassis No.:	WAUZZZ8X1BB026792
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$27,134.00
Original Registration Date:	28 Dec 2011
First Registration Date:	28 Dec 2011
Transfer Count:	2
Actual ARF Paid:	\$27,134.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Dec 2021
PARF Rebate Amount:	\$17,637.00
Intended COE Rebate Details	
COE Expiry Date:	27 Dec 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$52,392.00
COE Rebate Amount:	\$20,717.00
Total Rebate Amount:	\$38,354.00

The information contained herein is correct as at 13 Jan 2018

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/01/2018 12:53
Date Of Accident	12/01/2018 08:10
Exact Location Of Accident	ALONG TPE (TOWARDS CHANGI)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKD6965A
Insured/Policyholder	
Name Of Registered Owner	MUHAMMAD SUFIYAN BIN RAHMAD
NRIC No	S8632829A
Email Address	MUHDSUFIYAN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-82187171
Alternative Phone No	OTHERS-NOPHONE

Vehicle Particulars

Manufacturer	AUDI
Model	A1 1.4 TFSI S-TRONIC
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT000109
Cover Note Number	

Driver

Name of Driver	MUHAMMAD SUFIYAN BIN RAHMAD
NRIC No	S8632829A
Date Of Birth	06/11/1986
Occupation	INDOOR
Date Of Driving Pass	23/02/2007
Driving Experience	10 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82187171
Fax Number	
Contact Number	OTHERS-NOPHONE
Email Address	MUHDSUFIYAN@GMAIL.COM

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



John

Policyholder's Signature
Date & Time:

John

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



FALCON - AIR AUTO SERVICES PTE LTD
CO. REG. No.: 1995-01140-D

TP INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)
UNKNOWN
UNKNOWN
Singapore

Claimant Insurer: Tokio Marine Insurance Singapore Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	12/01/2018
Vehicle Reg. No.:	SKD6965A	Driveable?	
Party At Fault:	THIRD PARTY		
Driver (TP):	MUHAMMAD SUFIYAN BIN RAHMAD	Driver (Insured):	FUNG SHUFEN CHRISTEL
Make/Model:	AUDI A1, 1.4 TFSI S-TRONIC (185BHP) (A)	Vehicle Reg. Date:	28/12/2011
Vehicle Colour:	WHITE		
Engine No:	CAX668718	Chassis No:	WAUZZZ8X1BB026792
Odometer:	1 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5-7 days		
Description of Accident/Loss	REFER TO SKETCH PLAN.		
Present Location:	FALCON-AIR AUTO SERVICES PTE LTD (SIN MING)		

Not Authorised
Passing By going
18/1/18

COST OF CLAIMS	Amount
Parts	1,001.50
Miscellaneous Items	0.00
Labour	1,250.00
Paintwork Labour	0.00
Towing	0.00
	2475.75
Gross Total (S\$)	2,251.50
+ GST 7.00% (S\$)	157.61
Nett Amount (S\$)	2,409.11

This claim is handled by: GAIL NG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Jan 2018)

Parts: 144 AUDI A1 1.4 TFSI S-TRONIC (185BHP) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Falcon-Air Auto Services Pte Ltd/SKD6965A/13/01/2018 10:46

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*REAR BUMPER	0.00	0.00	*450.00 F	✓
2	10		*REAR BUMPER CLIP	0.00	0.00	*30.00 F	✗
3	2		*REAR BUMPER SIDE RETAINER	0.00	0.00	*40.00 F	✗
4	1		*REAR BUMPER LOWER GARNISH	0.00	0.00	*90.00 F	✗
5	1		*REVERSE SENSOR	0	0.00	*300.00 FS	

F=Franchise part. S=SpcNett.

Sub Total (S\$) 910.00

+ Margin on L,N Items 15.00% (S\$) 91.50

Total Parts (S\$) 1,001.50

Falcon-Air Auto Services Pte Ltd/SKD6965A/13/01/2018 10:46. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			151
1	To check rear wiring	New	50.00
2	To straighten bootlid, rear inner panel include replacement of parts	New	500.00
3	to spray paint bootlid, rear bumper, rear end panel	New	700.00
Gross Labour Cost (S\$)			1,250.00

Falcon-Air Auto Services Pte Ltd/SKD6965A/13/01/2018 10:46. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Mar 2018)
 Parts: 144 AUDI A1 1.4 TFSI S-TRONIC (185BHP) (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Falcon-Air Auto Services Pte Ltd/SKD6965A/23/03/2018 14:25
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Rear Bumper Reinforcement	0.00	0.00	*160.00 F
2	1		*LH Rear End Panel Ventilator	0.00	0.00	*35.00 F
F=Franchise part.						
Sub Total (\$)						195.00
+ Margin on L,N Items 15.00% (\$)						29.25
Total Parts (\$)						224.25

Falcon-Air Auto Services Pte Ltd/SKD6965A/23/03/2018 14:25. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Falcon-Air Auto Services Pte Ltd/SKD6965A/23/03/2018 14:25. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

FALCON-AIR AUTO SERVICES PTE LTD
 (a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 80, 176 Sin Ming Drive #01-08/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0800 / 6458-0800 Fax: 6454-7982
 Branches: Tampines Bl 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop S(128228) Tel: 6779-5955 Fax: 6779-1110
 Website: www.falconair.com.sg Email: email@falconair.com.sg



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9600



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Silliper (Made In Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made In Japan)

FALCON AIR AUTO SERVICES PTE LTD
176 #01-06 SIN MING AUTOCARE COMPLEX
SIN MING DRIVE

SINGAPORE 575721

TEL : 64520880 FAX : 64547862

ATTN : JOSHUA/GAIL

WAUZZZ8X1BB026792

SKD 6965A

TAX INVOICE : AR201801-14790
DATE : 24/01/2018
CUSTOMER ID : FALCOD-1
VEH REG. NO. : SKD6965A
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SO STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 8X0807309	REAR BUMPER REINFORCEMENT	CC	1	160.00	160.00
		CC5-F-080			

SUB-TOTAL : 160.00
ADD GST 7.00 % 11.20

E. & O.E

TOTAL AMOUNT SGD : 171.20

[P] 25/01/2018 12:56:00PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 24/01/2018 3:03:01PM

JAE Auto Pte. Ltd.

Sales Executive: ANN

This is computer generated document.

No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 8791 / 6745 9838



Dept Direct: 6305 9810

Dept Direct: 6305 9611

Dept Direct: 6417 9792

TOYOTA
GENUINE PARTS

LEXUS

DAIHATSU



Dept Direct: 6417 8794

Dept Direct: 6417 8795

Dept Direct: 6417 8796

Dept Direct: 6417 8793

Wiper blade: NWB (Nippon Wiper blade), Silliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made In Japan)

FALCON AIR AUTO SERVICES PTE LTD
176 #01-06 SIN MING AUTOCARE COMPLEX
SIN MING DRIVE

SINGAPORE 575721
TEL : 64520880 FAX : 64547862
ATTN : JOSHUA/GAIL

WAUZZZ8X1BB026792

TAX INVOICE : AR201801-14496
DATE : 24/01/2018
CUSTOMER ID : FALCOD-1
VEH REG. NO. : SKD6965A
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SO STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1 8X0807067 GRU	REAR BUMPER	CC CC4-J-08B	1	450.00	450.00

SUB-TOTAL : 450.00
ADD GST 7.00 % 31.50

E. & O.E

TOTAL AMOUNT SGD : 481.50

[P] 24/01/2018 11:44:27AM

Goods Sold are not refundable for Cash

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 24/01/2018 11:40:28AM

JAE Auto Pte. Ltd.

Sales Executive: ANN



This is computer generated document.
No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9761 / 6745 9839



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Sliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

FALCON AIR AUTO SERVICES PTE LTD
176 #01-06 SIN MING AUTOCARE COMPLEX
SIN MING DRIVE

SINGAPORE 575721

TEL : 64520880 FAX : 64547862

ATTN : JOSHUA/GAIL

WAUZZZ8X1BB026792

TAX INVOICE : AR201801-15409
DATE : 25/01/2018
CUSTOMER ID : FALCOD-1
VEH REG. NO. : SKD6965A
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1 6X0819465D/E	REAR FENDER AIR VENT LH	U1 2D5-C	1	35.00	35.00

SUB-TOTAL : 35.00
ADD GST 7.00 % 2.45

E. & O.E

TOTAL AMOUNT SGD : 37.45

[P] 25/01/2018 12:53:48PM

[E] 25/01/2018 12:53:08PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

IAE Auto Pte. Ltd.

Sales Executive : ANN



* AR201801-15409 *

This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18000852/KVD3N2

Date: 20/04/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29039974QMY
Claimant Vehicle No :	SKD6965A	Insured Vehicle No :	SLM2473U
Date of Loss:	12/01/2018	Nature of Claim:	TP
		Claim No:	545797

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKD6965A	Engine No:	CAX668718
Make & Model:	AUDI A1, 1.4 TFSI S-TRONIC (185BHP) (A)	Chassis No:	WAUZZZ8X1BB026792
Reg. Date:	28/12/2011 (Man. Year: 2010)	Odometer:	141055 km
Colour:	White		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R18	Rear Tyre Size:	225/45R18
Front Left Side:	Roadstone 8 mm	Rear Left Side:	Toyo 7 mm
Front Right Side:	Roadstone 8 mm	Rear Right Side:	Toyo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,225.75	941.75	284.00	23.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,250.00	415.00	835.00	66.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	2,475.75	1,356.75	1,119.00	45.20
+ GST 7.00/7.00% (\$\$)	173.31	94.97	78.34	45.20
Nett Amount (\$\$)	2,649.06	1,451.72	1,197.34	45.20

INSPECTION

Date of Assignment:	15/01/2018	Present Location:	Falcon-Air Auto Services Pte Ltd (Sin Ming)
Date Inspected:	17/01/2018	Inspected At:	Falcon-Air Auto Services Pte Ltd (Sin Ming) 176 Sin Ming Drive #01-06, Sin Ming Autocare Singapore 575721
Estimated Period of Repair:	2.0 days		

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 20 Apr 2018)
Parts: 144	AUDI A1 1.4 TFSI S-TRONIC (185BHP) (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKD6965A)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (WCP)	Buckled	450.00 F	*450.00 F
2	10		*REAR BUMPER CLIP (WCP)	Not Necessary	30.00 F	*- F
3	2		*REAR BUMPER SIDE RETAINER (WCP)	Serviceable	40.00 F	*- F
4	1		*REAR BUMPER LOWER GARNISH (WCP)	Serviceable	90.00 F	*- F
5	1		*REVERSE SENSOR	Cracked	300.00 FS	*200.00 FS
Supplementary #1						
6	1		*Rear Bumper Reinforcement (WCP)	Bent	160.00 F	*160.00 F
7	1		*LH Rear End Panel Ventilator (WCP)	Cracked	35.00 F	*35.00 F
					Sub Total (\$\$)	1,105.00 845.00
					+ Margin on L,N Items 15.00/15.00% (\$\$)	120.75 96.75
					Total Parts (\$\$)	1,225.75 941.75

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To check rear wiring	New	50.00	15.00
2	To straighten bootlid, rear inner panel include replacement of parts	New	500.00	200.00
3	to spray paint bootlid, rear bumper, rear end panel	New	700.00	200.00
Gross Labour Cost (\$\$)			1,250.00	415.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >