

INS. CASE OWNER:

CC 4 / AIG1800

LKK:
IDAC

Surveyor:

Fenneth

DOI:

12/1/18

Date / Time:

12/1/18

Registered in Merimen:

12/1/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKQ 8197T

Name of Insured:

TAN YEW LEE, William

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

10/1/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

TSAT PHUA Tinnq

Driver Tel No.:

(V/L: YES/NO)

Claim No.:

AG1654429054

Policy No.:

200440463-02

Make / Model:

VWVO

Place of Accident:

BET BATOIC EAST RD 6

OI GIA REPORT:

(YES / NO)

TP GIA REPORT:

(YES / NO)

Insured Liability:

%

Final? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

HWA
SING



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

12/1/18
YMS

SKQ 8197T-X

SKQ 8197T-X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

22/01/18

After call ltr to OI:

Documentation Check List:

Handler

Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PBR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

7,000

(8 days)

Reduction:

54 %

Email

Call

FINAL SETTLEMENT

Date/Time:

07/03/18

Confirm with:

Boon

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

5

If NO or B 28, Ass. Lia:

Repair Cost

SS

7,000.00

Loss of Rental (LOR):

SS

1,100.00

(11 days)

8 + 3 days

Loss of Use (LOU):

SS

(5 x days)

Loss of Income (LOI):

SS

(5 x days)

LOR only

☒

LOU only

☐

LOR + LOU

☐

LOR + LOI

☐

(Tick only one)

GIA/LTA Search

SS

7.45

Medical

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

8,174.5

Global Sum SS:

8,000/-

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

8,000.00

Name 1:

Hwa Seng Spray Painting Co.

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

CONFIRM
12/2/18

ASS. REC. BY:

REF:

A/G 1

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGJ 4479R Yr Regn: 07.06

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Hyundai Getz cc 1086Colour: A. Green A/C: Insured / Std / NI / NASp. Reading: 170988 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KM14B751GR6U568893Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/55R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____

R/Bal. 3 mmL/Bal. 3 mmD.O.A. 10/1/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S FR & UIC

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

15/1 File part to Customer

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/AIG18000883/Kyb3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 15-01-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKQ 8197T	Veh. Inspected	SGJ 4479R	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	15/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	10/01/2018	Inspection Date	13/01/2018	
Survey held at	HWA SENG SPRAY PAINTING COMPANY 160 SIN MING DRIVE #05-11 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

HWA SENG SPRAY PAINTING CO

180 Sin Ming Drive, #05-11,

Sin Ming Autocity

SINGAPORE 575722

(COMPANY REGISTRATION NO. 09574400B)

TEL: 64533100

FAX: 62669932

Ky

Not Authored
61 Day @ 7000
Referring After Point

Accident Date: 10/01/2018

Your Insured

Vehicle No: SKQ 8197 T

Estimate repair cost to HYUNDAI GETZ reg no :SGJ 4479 R

1pc o/s/f door	\$5
1pc o/s/f door rubber	
1pc o/s/f door protector	
2pcs o/s/f door hinges	(\$536.10/pc)
1pc o/s/f door power window motor	
1pc o/s/f door power window regulator	
1pc o/s/f door check	
1pc o/s 'A' pillar	
1pc o/s/f fender	
1pc o/s/f fender inner shield	
1pc o/s/f fender mudflap	
1pc o/s headlamp	
1pc bonnet	
1pc front bumper	
1pc front bumper o/s retainer	
1pc support panel	
1pc bonnet o/s hinges	
1pc wiper washer container assy	
1pc wiper washer motor	
1pc steering rack and pinion	
1pc cross member	
1pc o/s/f stabilizer bar	
1pc o/s/f lower arm	
1pc o/s/f driveshaft	
1pc o/s/f knuckle	
1pc o/s/f bearing	
1pc o/s/f bearing hub	
1pc o/s/f front tie rod	
1pc o/s/f stabilizer link	
1pc o/s/f absorber	
1pc front bumper reinforcement	
1pc front windscreen moulding	

Ry	1200.80	✓
Sn	96.50	✗
My	44.30	✓
Ry	72.20	✓
Sn	195.20	✗
Sn	260.40	✗
Dr	52.20	✓
R	1496.40	✗
Ry	348.30	✓
CM	78.00	✓
Dr/Br	37.60	✓
CM	288.40	✓
R	981.20	✗
CM	333.90	✓
Dr	10.20	✓
R	718.00	✗
R	23.80	✗
Sn	36.20	✗
Sn	81.90	✗
Br/My	1661.70	✓
Bu	943.90	✓
Ry	227.20	✓
Ry	250.00	✓
Ry	940.00	✓
Ry	247.80	✓
Ry	108.30	✓
Ry	150.40	✓
Dr	91.30	✓
Dr	62.60	✓
Ry	191.70	✓
R	178.20	✗
Nu	105.00	✗
	11513.60	
	1151.36	

Less 10%

10362.24

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before the spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

HWA SENG SPRAY PAINTING CO

11 Ming Drive, #05-11,
Ming Autocity
SINGAPORE 575722
COMPANY REGISTRATION NO. 095744008)
TEL: 64533100
FAX: 62669932

Estimate repair cost to HYUNDAI GETZ reg no :SGJ 4479 R

c/t.....

10362.24

Labour & misc charges

Towing	100.00	501
1pc o/s sport rim	By 400.00	2501
1pc o/s tyre	Pr 200.00	3011 6011
Labour to remove front windscreen	nn 160.00	7
Sealant and clip	nn 80.00	2
Inner seal	nn 60.00	X
Labour to remove and install dashboard	nn 200.00	X
Labour to remove and install air con system	nn 160.00	X
Labour to remove and install door trim	120.00	601
Labour to remove and install under carriage	450.00	3201
Computer wheel alignment	120.00	601
Wire checking	50.00	201
Panel knocking	1200.00	11001
Spray painting	1400.00	10001
Tuff kot	180.00	901

15242.24

HWA SENG SPRAY PAINTING COMPANY



HWA SENG SPRAY PAINTING CO

1 of 2

160 Sin Ming Drive, #05-11,

Sin Ming Autocity

SINGAPORE 575722

(COMPANY REGISTRATION NO. 095744008)

TEL: 64533100

FAX: 62669932

*Not Authored
L1 Sup B?
Recovery After Paint*

Accident Date: 10/01/2018

Your Insured

Vehicle No: SKQ 8197 T

Estimate repair cost to HYUNDAI GETZ reg no :SGJ 4479 R

1pc o/s/f door	SS	Ry	1200.80	✓
1pc o/s/f door rubber			96.50	?
1pc o/s/f door protector		h, 1	44.30	✓
2pcs o/s/f door hinges	(SS\$36.10/pc)	Ry	72.20	✓
1pc o/s/f door power window motor			195.20	?
1pc o/s/f door power window regulator			260.40	?
1pc o/s/f door check		D, 1	52.20	✓
1pc o/s 'A' pillar			1496.40	?
1pc o/s/f fender		Ry	348.30	✓
1pc o/s/f fender inner shield		CM	78.00	✓
1pc o/s/f fender mudflag		D, 1/Ry	37.60	✓
1pc o/s headlamp		CM	288.40	✓
1pc bonnet		R	981.20	X
1pc front bumper		CM	333.90	✓
1pc front bumper o/s retainer		D, 1	10.20	✓
1pc support panel			718.00	?
1pc bonnet o/s hinges		R	23.80	X
1pc wiper washer container assy			36.20	?
1pc wiper washer motor			81.90	?
1pc steering rack and pinion			1661.70	?
1pc cross member			943.90	?
1pc o/s/f stabilizer bar			227.20	?
1pc o/s/f lower arm		Ry	250.00	✓
1pc o/s/f driveshaft			940.00	?
1pc o/s/f knuckle		Ry	247.80	✓
1pc o/s/f bearing		Ry	108.30	✓
1pc o/s/f bearing hub		Ry	150.40	✓
1pc o/s/f front tie rod			91.30	?
1pc o/s/f stabilizer link			62.60	?
1pc o/s/f absorber		Ry	191.70	✓
1pc front bumper reinforcement		R	178.20	X
1pc front windscreen moulding			105.00	?
			11513.60	
			1151.36	

Less 10%

20%

UKC Auto Consultants hence **10362.24**

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

HWA SENG SPRAY PAINTING CO

2 of 2

160 Sin Ming Drive, #05-11,

Sin Ming Autocity

SINGAPORE 575722

(COMPANY REGISTRATION NO. 095744008)

TEL: 64533100

FAX: 62669932

Estimate repair cost to HYUNDAI GETZ reg no :SGJ 4479 R

c/f.....

10362.24

Labour & misc charges

Towing

1pc o/s sport rim

1pc o/s tyre

Labour to remove front windscreen

Sealant and clip

Inner seal

Labour to remove and install dashboard

Labour to remove and install air con system

Labour to remove and install door trim

Labour to remove and install under carriage

Computer wheel alignment

Wire checking

Panel knocking

Spray painting

Tuff kot

	100.00	501
By	400.00	2 Sam
Pu	200.00	301in
	160.00	7
	80.00	7
	60.00	7
	200.00	7
	160.00	7
	120.00	601
	450.00	3201
	120.00	601
	50.00	201
	1200.00	11001
	1400.00	10001
	180.00	901

15242.24

HWA SENG SPRAY PAINTING COMPANY





Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 12 Jan 2018 / 10:35:38

Receipt Date/Time : 12 Jan 2018 / 10:35:38

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180112-000542

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
Result of Insurance Enquiry - SKQ8197T				
As at 10 Jan 2018/07:10:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SKQ8197T Enquiry Fee 20180112103418598159	7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
Paid By				
	xxxxxx6419	Credit Card:		7.45
		Visa/MasterCard		
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Date: 10/01/2018

Fan Tuck Chai

160 Sin Ming Drive, #05-11

Sin Ming Authority

S'pore 575722

Attn: Motor Claim Dept.

Your Ref:

ALG ASIA PACIFIC INSURANCE PTE LTD

ALG BUILDING

78 Shenton Way

#09-16

S'pore 049120

Dear Sirs/Madam,

Direct Settlement

Accident on 10/01/2018 involving vehicle no.: SGJ 4479R & SKQ 8197T
At Junction of Bukit Batok East Ave 6 and 2

I/We refer to my/our letter date

Arising out of the above accident, as a assessment on the damaged to my/our vehicle no:
SGJ 4479R was being conducted by your appointed panel surveyor.

Due to the negligence/fault of your insured/driver of vehicle no: SKQ 8197T, I/We
am/are now claiming against you for the repair and other consequential suffered by me/us.

For the purpose of a amicable settlement, I/We quantified my/our claim as follow:-

- a) Cost of repair at
- b) Loss of use for 1 days at rate of \$100/day
- c) Police/Rov fee
- d) Others

SG\$ 7,000.00

SG\$ 1,200.00 2 weekend (Sunday)

SG\$ -

3 working day (PRI)

SG\$ 7.45.

Total Cost

SG\$ 8,207.45


I/We enclose herewith copies of all relevant documents for your perusal.

Kindly also direct all correspondence or liaise with my repairer's Messrs

Hwa Seng Spray Painting Co relating to the said accident without any
further reference to me/us.

Thanking you and awaiting your favourable response.

Yours Faithfully,



SIGNED WITHOUT PREJUDICE FOR
ONLY PROPERTY CLAIM



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC4/AIG18000883/Kyb3

22 JANUARY 2018

TAN YEW LEK, WILLIAM
82 HILLVIEW AVE
SINGAPORE 669581

Dear Sir/Madam,

**ACCIDENT INVOLVING SKQ 8197T & SGJ 4479R ALONG/AT BUKIT BATOK
EAST AVE 6 ON 10/01/2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Kindly note that we have reviewed this matter and would like to advise that you and/or your authorized driver may not be absolved from blame for this accident.

If you have evidence/information to prove that we should not settle the third party claim, kindly let us have them in writing within the next 10 days i.e. by **01/02/2018**, after we shall proceed with negotiation with Third Party claimant on the **without prejudice basis** and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Jas Khine
Case Handler
DID: 6841 2928
FAX: 6741 4108
Email: jaskhine@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

Letter of Authorization

To whom it may Concern

Accident on 10/01/2018 involving SGJ4479R & SKQ8197T
along Junction of Bukit Batok East Ave 6 and 2
I/We Fan Yoke Chai NRIC NO 81285354G of
BIK 343 #11-104, Bukit Batok St 34, 8pore 650343
owner of motor vehicle registration no SGJ 4479R insured by
NTUC Income Insurance Co-Op Ltd under policy no 5092335991
do hereby authorize M/s Hwa Seng Spray Painting Co as my/our
representative with full authority to write, negotiate and settle claim for damages on my/our
behalf against the owner and/or driver of Motor Vehicle No SKQ 8197T
in regard to the above mentioned accident.

I/We also consent to the agreed settlement sum be made in favour of my/our representative,
M/s Hwa Seng Spray Painting Co and the said
payment be forwarded to them to be construed as full and final discharge of my/our claim.


Owner Signature & Company Stamp

10/01/2018

Date

SIGNED WITHOUT PREJUDICE FOR
ONLY PROPERTY CLAIM

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, HWA SENG SPRAY PAINTING CO. ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$8,000.00 (Global Sum), for vehicle no. SGJ 4479R that was damaged pursuant to the accident which occurred on 10/01/2018 (date) along/at BUKIT BATOK EAST AVE 6 (location) involving vehicle no/s SKO 8197T.

This is pursuant to the inspection conducted on 13/01/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner FAN TUCK CHOI ("the third party claimant") of vehicle no. SGJ 4479R make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SGJ 4479R (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 07 (day) of 01 (month) 2018 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

SIGNED WITHOUT PREJUDICE FOR
ONLY PROPERTY CLAIM

HWA SENG SPRAY PAINTING CO.

160 Sin Ming Drive, #05-11, Sin Ming Autocity
Singapore 575722
Tel No. : 64533100 Fax No. : 62669932
Buss. Reg. No. : 095744/00B

FAN TUCK CHOI
BLK 343, #11-104, BUKIT BATOK ST 34,
650343

Attention : Motor Claim Department
Contact : 81194266

Final Repair Bill : H00008

Date : 12/02/2018
Vehicle Num. : SGJ 4479 R
Make/Model : HYUNDAI GETZ
Chassis/Eng# :
Accident Date : 10/01/2018
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LABOUR :				
On lump basis repair inclusive of spare parts, panel knocking, spray painting plus misc charges.....				7,000.00
Labour Total S\$:				7,000.00

E. & O.E.

Total S\$: 7,000.00

for HWA SENG SPRAY PAINTING CO.

SIGNED WITHOUT PREJUDICE FOR
ONLY PROPERTY CLAIM

CHIN HUI CAR RENTAL

BLK 7, SUN-MING INDUSTRIAL ESTATE, SECTOR C, #01-76,
SINGAPORE 575642. TEL: 6453 4680
REGN. NO.: S3090791K

VEHICLE RENTAL AGREEMENT

NO: 8015

HIRER'S PARTICULAR

Hirer: Tan Tuck Chai
 NRIC / Passport No: S 2832716 Date of Birth: 11/09/1958
 Address: Blk 343 B1 Pagar 57 34
11-104 S (600303)
 Driving License No: S 2832716 Pass Date: 15/09/2022
 Contact Number: _____

Vehicle No: ED747A Mileage Out: 18818
 Make & Model: TOYOTA AUV ☒ Auto ☐ Manual
 OUT: Date: 11/01/18 OUT: Time: 5.35pm
 Replaces Veh No: _____ Mileage Out: _____
 OUT: Date: _____ OUT: Time: _____

DRIVERS PARTICULARS
(if different from Hirer)

Appointed Driver: Tan Shuntan
 NRIC / Passport No: S 28407961 Date of Birth: 11.11.1989
 Address: Blk 343 B1 Pagar 57 34
11-104 S (600303)
 Driving License No: S 28407961 Pass Date: 07/03/2011
 Contact Number: _____

CHARGES

Daily	R @ \$100/-	per day	1200.00
Weekly	@ \$	per week	
Monthly	@ \$	per month	
Hours	@ \$	per hour	
Others	@ \$		
SUB-TOTAL \$			1200.00

Now Insurance Policy Terms & Conditions as at 08-12-2010

1. NOT PERMITTED TO DRIVE - Not Covered
 Driver Age 22 years old and below
 Driver above Age 70 years old
 Driver less than 2 years Driving Experience

2. ADDITIONAL EXCESS - S\$3000.00
 Driver Age 23 to 25 years old with 2 years driving experience
 Driver Age 65 to 70 years old with 2 years driving experience

PETROL LEVEL

Out	E	1/4	1/2	3/4	F
In	E	1/4	1/2	3/4	F

TOTAL CHARGES \$ 1200.00

REMARKS

IMPORTANT!
FOR SINGAPORE USE ONLY

Excess Liability: S\$2500.00
 Malaysia Excess (With Prior Consent): Not Allowed

Hirer's Signature: [Signature]
 Additional Driver's Signature: [Signature]

I have read and agree to the terms and condition on both sides of this agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infractions may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given CHIN HUI CAR RENTAL in connection with this agreement is true.

- * IMPORTANT**
- ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER, AND ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
 - THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF CONFINEMENT WHERE APPLICABLE.
 - VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY, AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY CHIN HUI CAR RENTAL.
 - IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY, IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.

RETURN OF VEHICLE: THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER / DRIVER" DURING WHICH THE DAY AND TIME INSERTED BELOW SHALL BE DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO CHIN HUI CAR RENTAL AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	SIGNATURE OF HIRER / DRIVER
28/01/18	17:00hrs	190041	<u>[Signature]</u>	<u>[Signature]</u>

CHIN HUI CAR RENTAL

REGN. NO.: 53090791X

BLK 7, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-76, SINGAPORE 575642. TEL: 6453 4680

OFFICIAL RECEIPT

M/s FAN TUCK CHOI

No: 272909

BLK 3436 BT BATOK ST 34

#11-104, SINGAPORE 650343.

Date: 23.12.2017

S/No.	Description	Amount
1	RENTAL FEES FOR SJD 7147A VRA NO. 8015	<u>\$ 1,200.00</u>

SINGAPORE DOLLARS ONE THOUSAND TWO HUNDRED ONLY

PAYMENT MODE:

CASH

CHEQUE -


Chin Hui Car Rental

Receipt

12/018



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 12 Jan 2018 / 10:35:38
Receipt Date/Time : 12 Jan 2018 / 10:35:38

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180112-000542

Previous Receipt No. :

S/N Item Description/
Business Transaction Reference
No.

Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - SKQ8197T

As at 10 Jan 2018/07:10:00

Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.

1 Insurance Enquiry - SKQ8197T
Enquiry Fee
20180112103418598169

	7.00	0.49	7.49
Sub-Total	7.00	0.49	7.49
Total Before Rounding	7.00	0.49	7.49
Rounding Difference			0.04
Total Amount Payable			7.45

Paid By

xxxxxxxxxxxx6419

Credit Card:
Visa/MasterCard

7.45

Total

7.45

Cash Change

0.00

Tendered Amount

7.45

Excess Refundable Amount

0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Jan 2018 Edit Reg		13 Jan 2018 00:00 Edit Adj Rpt	S\$7,000.00 Edit Estimates	S\$7,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:		Tan Yew Lek, William, ID: S1717314F							
Main Claimant:		FAN TUCK CHOI, ID: S1283757G							
Vehicle Reg. No.:		SGJ4479R	Date of Loss:	10/01/2018 07:00 - :59					
Claim Type:		TP / 9516599490SG	Policy/Cover Note No.:	2100446463 (Comprehensive) Coverage: 29/12/2017 - 28/12/2018					
Vehicle Reg. No. (Insured):		SKQ8197T	Policy No. (Claimant):	5092335991					
		Excess:							
Repairer:		Hwa Seng Spray Painting Co (160 SIN MING) 160 SIN MING DRIVE, #05-11 SIN MING AUTOCITY, 575722 Sin Ming - Tel:							
Handling Insurer:		AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com							
Claimant's Insurer:		NTUC Income Insurance Co-operative Ltd (HQ) - Tel:							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 24/01/2018]							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGJ4479R (9516599490SG)
[SKQ8197T]
TP
FAN TUCK CHOI
Jan 10 2018 7:00AM
[Tan Yew Lek, William]
Hwa Seng Spray Painting Co

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Video															1 per page		☒			
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print				
1	07/03/18 15:23	Video - Accident From: OD - Reg. No: SKQ8197T, Claimant: TAN YEW LEK, WILLIAM													Load MOV					
Letters/Correspondences															1 per page		☒			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	(Draft)	Third Party Express Settlement - Payment Breakdown													Edit					
Assessment Reports															1 per page		☒			
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print				
1	16/01/18 10:48	Accident Statement From: OD - Reg. No: SKQ8197T, Claimant: TAN YEW LEK, WILLIAM													Load HTM					
Photos/Images															3 per page		☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	28/02/18 16:39	General View													Load JPG	☒				
2	28/02/18 16:39	Odometer Reading													Load JPG	☒				
3	28/02/18 16:39	General View													Load JPG	☒				
4	28/02/18 16:39	General View													Load JPG	☒				
5	28/02/18 16:39	General View													Load JPG	☒				
6	28/02/18 16:39	General View													Load JPG	☒				
7	28/02/18 16:39	General View													Load JPG	☒				
8	28/02/18 16:39	General View													Load JPG	☒				
9	28/02/18 16:39	General View													Load JPG	☒				
10	28/02/18 16:39	General View													Load JPG	☒				
11	28/02/18 16:39	General View													Load JPG	☒				
12	28/02/18 16:39	General View													Load JPG	☒				
13	28/02/18 16:39	General View													Load JPG	☒				
14	28/02/18 16:39	General View													Load JPG	☒				
15	28/02/18 16:39	General View													Load JPG	☒				
16	28/02/18 16:39	General View													Load JPG	☒				
17	28/02/18 16:39	General View													Load JPG	☒				
18	28/02/18 16:39	General View													Load JPG	☒				
19	28/02/18 16:39	Chassis Number													Load JPG	☒				
Documentation															1 per page		☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	15/01/18 17:52	EMAIL FROM AIG DD 12012018.													Load PDF					
2	15/01/18 17:52	TP EST & GIA REPORT													Load PDF					
3	15/01/18 18:22	TP ESTIMATE- MARKED													Load PDF					

4	28/02/18 15:01	Police Investigation Result	1	Load PDF	
5	19/03/18 07:28	WORKSHOP INVOICE	1	Load PDF	
6	19/03/18 07:28	AUTHORISATION TO ACT FORM	1	Load PDF	
7	19/03/18 07:28	Release Voucher	1	Load PDF	
8	19/03/18 07:28	RENTAL RECEIPT	1	Load PDF	
9	19/03/18 07:28	LTA SEARCH	1	Load PDF	
10	19/03/18 07:28	LETTER TO OI	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
^ v
Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKQ8197T (Insd veh)	Model:	HYUNDAI GETZ 1.1 1.1 5M
	SGJ4479R (TP veh)		(M)
Date of Accident:	10/01/2018		

Global Sum Settlement	:	☒ [X] Yes	☐ [] No	
Repair Estimate	:	\$	15,242.24	
Final Repair Cost	:	\$	8,000.00	
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$		11 days
LTA / GIA Search Fee	:	\$		
Others:	:	\$		
	:	\$		
Final Settlement Sum (Global Sum)	:	\$	8,000.00	

Is Third Party Workshop GIA Registered? ☐ [] YES ☒ [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Hwa Seng Spray Painting Co.	:	\$ 8,000.00
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

19 Mar
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18000883/KYB3Q2

Date: 19/03/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100446463
 Claimant Vehicle No: SGJ4479R Insured Vehicle No: SKQ8197T
 Date of Loss: 10/01/2018 Nature of Claim: TP Claim No: 9516599490SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGJ4479R
 Make & Model: HYUNDAI GETZ, 1.1 1.1 5M (M) Engine No: G4HG6137407
 Reg. Date: 12/07/2006 (Man. Year: 2006) Chassis No: KMHBT51GR6U568893
 Colour: Metallic Maroon Odometer: 170988 km
 Engine Capacity: 1086 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R15 Rear Tyre Size: 185/55 R15
 Front Left Side: Goodyear 3 mm Rear Left Side: Goodyear 7 mm
 Front Right Side: Goodyear 3 mm Rear Right Side: Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,102.24	6,182.64	4,919.60	44.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,140.00	2,700.00	1,440.00	34.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,242.24	8,882.64	6,359.60	41.72
Approved Total (Overridden) (S\$)		7,000.00		
Nett Amount (S\$)	15,242.24	7,000.00	8,242.24	54.07
+ Car Rental (11.0 x S\$100.00/day) (S\$)		1,100.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,107.45		
Global Sum Settlement (S\$)		8,000.00		

INSPECTION

Date of Assignment: 13/01/2018
 Date Inspected: 13/01/2018 Inspected At: Hwa Seng Spray Painting Co (160 SIN MING)
 160 SIN MING DRIVE, #05-11 SIN MING

AUTOCITY
Singapore 575722

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG

Manager: Jasmine Khine Phoo Wai

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*O/S/F DOOR	Bent	1,200.80 FL	*1,200.80 FL
2	1		*O/S/F DOOR RUBBER	Serviceable	96.50 FL	*- FL
3	1		*O/S/F DOOR PROTECTOR	Missing	44.30 FL	*44.30 FL
4	2		*O/S/F DOOR HINGES	Bent	72.20 FL	*72.20 FL
5	1		*O/S/F DOOR POWER WINDOW MOTOR	Serviceable	195.20 FL	*- FL
6	1		*O/S/F DOOR POWER WINDOW REGULATOR	Serviceable	260.40 FL	*- FL
7	1		*O/S/F DOOR CHECK	Distorted	52.20 FL	*52.20 FL
8	1		*O/S A PILLAR	Repair	1,496.40 FL	*- FL
9	1		*O/S/F FENDER	Bent	348.30 FL	*348.30 FL
10	1		*O/S/F FENDER INNER SHIELD	Cracked	78.00 FL	*78.00 FL
11	1		*O/S/F FENDER MUDFLAG	Distorted / Dented	37.60 FL	*37.60 FL
12	1		*O/S HEADLAMP	Cracked	288.40 FL	*288.40 FL
13	1		*BONNET	Repair	981.20 FL	*- FL
14	1		*FRONT BUMPER	Cracked	333.90 FL	*333.90 FL
15	1		*FRONT BUMPER O/S RETAINER	Distorted	10.20 FL	*10.20 FL
16	1		*SUPPORT PANEL	Repair	718.00 FL	*- FL
17	1		*BONNET O/S HINGES	Repair	23.80 FL	*- FL
18	1		*WIPER WASHER CONTAINER ASSY	Serviceable	36.20 FL	*- FL
19	1		*WIPER WASHER MOTOR	Serviceable	81.90 FL	*- FL
20	1		*STEERING RACK AND PINION	Bent / Jammed	1,661.70 FL	*1,661.70 FL
21	1		*CROSS MEMBER	Buckled	943.90 FL	*943.90 FL
22	1		*O/S/F STABILIZER BAR	Bent	227.20 FL	*227.20 FL
23	1		*O/S/F LOWER ARM	Bent	250.00 FL	*250.00 FL
24	1		*O/S/F DRIVESHAFT	Bent	940.00 FL	*940.00 FL
25	1		*O/S/F KNUCKLE	Bent	247.80 FL	*247.80 FL
26	1		*O/S/F BEARING	Bent	108.30 FL	*108.30 FL
27	1		*O/S/F BEARING HUB	Bent	150.40 FL	*150.40 FL
28	1		*O/S/F FRONT TIE ROD	Distorted	91.30 FL	*91.30 FL
29	1		*O/S/F STABILIZER LINK	Distorted	62.60 FL	*62.60 FL
30	1		*O/S/F ABSORBER	Bent	191.70 FL	*191.70 FL
31	1		*FRONT BUMPER REINFORCEMENT	Repair	178.20 FL	*- FL
32	1		*FRONT WINDSCREEN MOULDING	Not Necessary	105.00 FL	*- FL
33	1		*O/S SPORT RIM	Bent	400.00 FS	*250.00 FS
34	1		*O/S TYRE (30%)	Punctured	200.00 FS	*60.00 FS
35	1		*SEALANT AND CLIP	Not Necessary	80.00 FS	*- FS
36	1		*INNER SEAL	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,253.60	7,650.80
- List Item Discount on L Items 10.00/20.00% (\$\$)	1,151.36	1,468.16
Total Parts (\$\$)	11,102.24	6,182.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING	New	100.00	50.00
2	LABOUR TO REMOVEFRONT WINDSCREEN	New	160.00	0.00
3	LABOUR TO REMOVE AND INSTALL DASHBOARD	New	200.00	0.00
4	LABOUR TO REMOVE AND INSTALL AIR CON SYSTEM	New	160.00	0.00
5	LABOUR TO REMOVE AND INSTALL DOOR TRIM	New	120.00	60.00
6	LABOUR TO REMOVE AND INSTALL UNDERCARRIAGE	New	450.00	320.00
7	COMPUTER WHEEL ALIGNMENT	New	120.00	60.00
8	WIRE CHECKING	New	50.00	20.00
9	PANEL KNOCKING	New	1,200.00	1,100.00
10	SPRAY PAINTING	New	1,400.00	1,000.00
11	TUFF KOTE	New	180.00	90.00
Gross Labour Cost (S\$)			4,140.00	2,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >