

Inspected

ASS. REC. BY:

REF: CS3/AIG18000908/R1d3ez

Special Instruction

DAR 2 days

merman Rasul

ASSIGNMENT (Office)

From (Person): Winnie Fan

of AIG

Date/Time: 16/1/18 @ 10:51am

Estimated Cost:

Bill to:

OD ☒ WS ☐ IP RES / OD RES / EVA / DV / MV / CS

To Inspect Vehicle No: SDW 5583 H

Insured: SJS 1343K

at Workshop no: Car Doctor

Tel: 66355773

of Blk 3, 391A Woodlands Rd, Yew Tee

Policy No: 2100154329

Claim No: 5784852970.SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

DOA 14/01/18

CA / REV / REP. / REV 24 HRS

'wp'

R.O.D. Indemnity

Date/Time: 11:28am @ 16/1/18

Person Contacted: Sylvester

Veh: ☒ IN ☐ OUT

Date/Time

Action/Instruction

X

SDW 5583 H-X

SDW 5583 H-X

SJS 1343K-X

Pase

94774

ASSIGNMENT

From: *16/01/2018*

Ref No: *SDW5583H* Page: *2010 July*

Estimated Cost:

Type: *MCycle/Bike/Van/Lorry/Truck/Prime Mover*

OD: *TP* WS/TP RES/OD RES/EVA/INV/MV

Truck/Trailer

To inspect Vehicle No: *SDW 5583H*

Name: *Hyundai Tucson 2.0* 1998

at Workshop (m/s): *Car Doctor*

Colour: *white*

BK3,391A Woodlands Rd, Yew Tee

So. Reading: *112389*

Insured:

Eng No:

Policy No:

C No: *KMH3U81BM Bu101377*

Claims No:

Gen. Cond: Good *(F)* Poor/Burnt

Sum Insured:

Excess:

Steering: In Order *(S)* Jammed/Leaked/Burnt or

Client's Record:


Sylvester @ 6635 5773

Brake: In Order *(S)* Jammed/Leaked/Burnt or

Make of Veh:

Mod: *NII / EPR / STD A/Rim or*

(Policy Condition)



Remark: The veh had commenced its repair at the time of inspection.

Tyre Size: *R 225/65R17*

BS/DUN/EXNOVA *(G)* PS/LIZA/MIC/OHTSU/RR/SUMI

TOYO/YOKO or

Sell or Market Value:

Front: *6* Rear: *6*

DAQ Accident Report Consistent? Yes or No

R.Bal: *6* mm L.Bal: *6* mm

GLA / RR Seen? Consistent? Yes or No

D.O.A. *14/01/18* D.O. *16/01/18*

Est. Repair days Res: Yes or No

Survey held at: *CAR DOCTOR*

Lum. Survy % 3 Val: Yes or No

Des. of Damages: Frt *(Red)* O/S N/S U/C Roof top or

CA / REV / REP. / 24 HRS *'up'*

Vehicle: IN / OUT

Date: Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision

Date Time Action Instruction

20/10 Submit DAR report.

RECEIVED 20 APR 2018

Date Time File Pass to:

☐ Prel. Report

Days Of Repair: *3*

☐ Final Report

Resurvey No. of Trip: *1*

Survey Fee

180

Date Time File Return to:

Add Fee:

☐ Stained: *5*

Transportation

☐ Ignition: *5*

Oil & Filter

☐ Repair: *5*

Paint

☐ Rep. Brk: *5*

Wheel

20

Report Format: *DAR*

Comp. Sum. (B): *5*

☐

Wash

200

**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE
SJS1343K AND SDW5583H ON 14/01/2018**

From: Fan, Winnie-LW
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Fong, Andy-SY, Chin, Lee-Ying
Sent: 16/1/2018 10:51:42 AM
Attachments:  [20180115151549483.pdf](#)

Hi LKK,

Kindly assist to survey.

Winnie Fan
AIG
Claims Service Associate
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Fax +(65) 6835 7416
winnie-lw.fan@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

CHIA S ARUL LLC
ADVOCATES & SOLICITORS
UEN 201330709H

ARULCHELVAN S

Our Ref : SDW 5583H(AY)

Your Ref :

15 January 2018

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#08 - 16
Singapore 079120


BY FACSIMILE ONLY
(Fax: 6835 7416)

Dear Sir,

RE: PROPERTY DAMAGE CLAIM
CLAIMANT : ANG SHUN LIE TERENCE (WENG SHUNLIE TERENCE)
ACCIDENT INVOLVING SDW 5583H & SJS 1343K ALONG PIE NEAR ENG
NEO EXIT TOWARDS JURONG 14 JANUARY 2018

1. We act for ANG SHUN LIE TERENCE (WENG SHUNLIE TERENCE), the owner of motor vehicle no. SDW 5583H, which was involved in the aforesaid accident.
2. We hereby give you **NOTICE** that we are claiming against your insured motor vehicle no. SJS 1343K for damages, costs and disbursements as a result of your insured driver's negligence.
3. Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at M/s Car Doctor Pte Ltd at Blk 3, 391A Woodlands Road Yew Tee Industrial Estate Singapore 677968 and kindly arrange with Mr Sylvester at 6635 5773.
4. If we do not hear from you within the next **two (2) working days**, we shall advise our client to proceed with their own inspection and repairs.
5. Please reply either by fax at 6733 8183 or by email to alywin@chiaarul.com.

Yours faithfully,


MR ARULCHELVAN S
cc: Client (By Email)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9477G
Vehicle Details	
Vehicle No.:	SDW5583H
Vehicle to be Exported:	No
Intended De-registration Date:	20 Apr 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	LM TUCSON 2.0L AUTO ABS D/AB S/R
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	G4KDAU012091
Chassis No.:	KMHJU81BMBU101377
Maximum Power Output:	122.0 kW (163 bhp)
Open Market Value:	\$18,786.00
Original Registration Date:	23 Jul 2010
First Registration Date:	23 Jul 2010
Transfer Count:	1
Actual ARF Paid:	\$18,786.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Jul 2020
PARF Rebate Amount:	\$11,271.00
Intended COE Rebate Details	
COE Expiry Date:	22 Jul 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$42,889.00
COE Rebate Amount:	\$9,673.00
Total Rebate Amount:	\$20,944.00

The information contained herein is correct as at 20 Apr 2018

OK

MOTORCAR (Rear)

Near Portion

Vehicle No: SDW 5583 H

[illegible]

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Jan 2018 Edit Reg		16 Jan 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS

Insured:

Heo Ai May, ID: S1378330F

Main Claimant:

ANG SHUN LIE TERENCE (WENG SHUNLIE TERENCE), ID: S8439477G

Vehicle Reg. No.:

SDW5583H

Claim Type:

TP / 5784852970SG

Vehicle Reg. No. (Insured):

SJS1343K

Repairer:

M/s Car Doctor Pte Ltd (HQ) BLK3, 391A Woodlands Road Yew Tee, industrial estate, 677695 Woodlands - Tel:

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 15/03/2018]

Date of Loss:

14/01/2018 14:00 - :59
[89 Months and 22 Days From LTA Reg Date (Man Yr)]

Policy/Cover Note No.:

2100154329 (Comprehensive)

Policy No. (Claimant):

Excess:

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

- AIG_SG (13/03/2018): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SDW5583H (5784852970SG)

[SJS1343K]

TP

ANG SHUN LIE TERENCE (WENG SHUNLIE TERENCE)

Jan 14 2018 2:00PM

[Heo Ai May]

M/s Car Doctor Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio		View View in Browser
Assessment Reports		1 per page ☐
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)
1	13/03/18 15:46	Accident Statement From: SC - Reg. No: SJS1343K, Claimant: HEO AI MAY
		1 Load HTM
Photos/Images		3 per page ☐
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)
1	06/04/18 16:39	Odometer Reading
2	06/04/18 16:39	Chassis Number
3	06/04/18 16:39	General View
4	06/04/18 16:39	General View
5	06/04/18 16:39	General View
6	06/04/18 16:39	General View
7	06/04/18 16:39	General View
8	06/04/18 16:39	General View
9	06/04/18 16:39	General View
10	06/04/18 16:39	General View
11	06/04/18 16:39	General View
12	06/04/18 16:39	General View
13	06/04/18 16:39	General View
14	06/04/18 16:39	General View
15	06/04/18 16:39	General View
16	06/04/18 16:39	General View
17	06/04/18 16:39	General View
18	06/04/18 16:39	General View
19	06/04/18 16:39	General View
20	06/04/18 16:39	General View
21	06/04/18 16:39	General View
22	06/04/18 16:39	General View
23	06/04/18 16:39	General View
24	06/04/18 16:39	General View
25	06/04/18 16:39	General View
26	06/04/18 16:39	General View
27	06/04/18 16:39	General View
28	06/04/18 16:39	General View
29	06/04/18 16:39	General View
30	06/04/18 16:39	General View
31	06/04/18 16:39	General View
32	06/04/18 16:39	General View
33	06/04/18 16:39	General View

Assessment Reports			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
34	06/04/18 16:39	General View	 Load JPG	☒
35	06/04/18 16:39	General View	 Load JPG	☒
36	06/04/18 16:39	General View	 Load JPG	☒
37	06/04/18 16:39	General View	 Load JPG	☒
38	06/04/18 16:39	General View	 Load JPG	☒
39	06/04/18 16:39	General View	 Load JPG	☒
40	06/04/18 16:39	General View	 Load JPG	☒
41	06/04/18 16:40	Photo After Spray	 Load JPG	☒
42	06/04/18 16:40	Photo After Spray	 Load JPG	☒
43	06/04/18 16:40	Photo After Spray	 Load JPG	☒
44	06/04/18 16:40	Photo After Spray	 Load JPG	☒
45	06/04/18 16:40	Photo After Spray	 Load JPG	☒
46	06/04/18 16:40	Photo After Spray	 Load JPG	☒
47	06/04/18 16:40	Photo After Spray	 Load JPG	☒
48	06/04/18 16:40	Photo After Spray	 Load JPG	☒
49	06/04/18 16:40	Photo After Spray	 Load JPG	☒
50	06/04/18 16:40	Photo After Spray	 Load JPG	☒
51	06/04/18 16:40	Photo After Spray	 Load JPG	☒
52	06/04/18 16:40	Photo After Spray	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18000908/R1D3E2

Date: 23/04/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100154329

Claimant Vehicle
No : SDW5583H

Insured Vehicle No : SJS1343K

Date of Loss: 14/01/2018

Nature of Claim:

TP

Claim No: 5784852970SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SDW5583H

Make & Model:

HYUNDAI TUCSON, 2.0 (A)

Reg. Date:

23/07/2010 (Man. Year: 2010)

Colour:

White

Engine Capacity:

1998 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$):

Market Value/New Car Price

Engine No:

G4KDAU012091

Chassis No:

KMHJU81BMBU101377

Odometer:

112389 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

225/65 R17

Rear Tyre Size:

225/65 R17

Front Left Side:

Goodyear 6 mm

Rear Left Side:

Goodyear 6 mm

Front Right Side:

Goodyear 6 mm

Rear Right Side:

Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

16/01/2018

Date Inspected:

16/01/2018 Inspected At:

M/s Car Doctor Pte Ltd (HQ)

BLK3, 391A Woodlands Road Yew Tee,

industrial estate

Singapore 677695

Estimated Period of Repair:

3.0 days

Adjuster: MOHD RASUL

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER LOWER	Damaged	0.00 F	*- F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	1		*REAR BUMPER BRACKET	Cracked	0.00 F	*- F
5	1		*REAR BUMPER SIDE RETAINER	Cracked	0.00 F	*- F
6	1		*REAR BUMPER REINFORCEMENT	* Check	0.00 F	*- F
7	1		*REVERSE SENSOR	Cracked	0.00 F	*- F
8	1		*TAILGATE	Repair	0.00 F	*- F
9	1		*TAILGATE LOCK	Distorted	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >