

ASS. REC. BY:

REF: CS/FCI18000913/T19d3e2 Special Instruction:

Surveyor: Taufik

ASSIGNMENT (Office)

From (Person): Teo Swee Keong

of FCI

Date/Time: 15/01/18 @ 6:10pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / ENV / MV / CS

To Inspect Vehicle No:

GV 5363X

Insured:

SHC 7494B

at Workshop m/s

Sin Sheng Engineering

Tel:

6863 9595

of 3 Tech Park Crescent, Tech Park

Policy No:

Claim No:

SHC 7494B

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 11/01/18

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement:

Date/Time: 9:18am @ 16/1/18

Person Contacted:

Susan

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

GV 5363X-X

SHC 7494B-CS/FCI18000911/VD3

D.O.A. 11/01/2018

17/1/18 @ 5:27pm revised to Teo Swee Keong by email.

LS \$ 2400, 5 days (red to body. 17, 35%)

Tanfah

REF:

FCI

ASSIGNMENT

CoE 2022 Feb

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV  
 To inspect/Vehicle No: \_\_\_\_\_  
 at Workshop no: \_\_\_\_\_  
 of: \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

N/S	O/S

Bel. or Market Value: 923K \*  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / FR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 5 days Res: Yes or No  
 Lump Sum: \_\_\_\_\_ % 3 Val: Yes or No  
 CA / REV / REP / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

WP'

Van No: GV 5363X Reg: 2002 July  
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover  
 Truck / Trailer or:

Make: Toyota Hiace : 2986  
 Colour: white A/C: \_\_\_\_\_ Insured: Std / NI / NA  
 So Reading: 654123 T-Radio: Insured: Std / NI / NA

Eng No: \_\_\_\_\_  
 C No: LH1621006627

Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Mod: NY / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_ R: 185/R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Hustone

Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R. Bal: 6 mm R. Bal: 6 mm  
 L. Bal: 6 mm L. Bal: 6 mm  
 D.O.A: \_\_\_\_\_ D.O.I: 16/1/18 @ 1545

Survey held at: Sin Sheng Tuo Tech Park

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or  
Rear N/S

The UIC / Chassis frame / Body Structure affected due to collision:

Date Time Action / Instruction

RECEIVED 13 APR 2018

Date/Time File Pass to: ☐ : Preli. Report  
☐ : Final Report

Date/Time File Return to:

By:

Days Of Repair: 5  
 Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ Site Insp: \$  
☐ Rep. Exp: \$  
☐ Tech. Insp: \$  
☐ Travelling: \$

Survey Fee

Transportation

Sub-Total

Grand

Total

Report Format: TP

Lump Sum / J.B. / \$ 2400

130
50
23
203

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18000913/T1qd3

36 ROBINSON ROAD

#16-01 CITY HOUSESINGAPORE 068877

Date : 16-01-2018



Code : FCI2

1.

**Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	SHC 7494B	Veh. Inspected	GV 5363X
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	TEO SWEE KEONG	Assign Date	16/01/2018

2.

**Vehicle Particulars & Condition**

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3.

**Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4.

**Description of Damages**

--	--

5.

**General Information**

Accident Date	11/01/2018	Inspection Date	16/01/2018
Survey held at	SIN SHENG ENGINEERING SERVICES 3 TECH PARK CRESCENT TUAS TECK PARK SINGAPORE 638129		

5a.

**Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## Nivitha (LKK Auto)

---

**From:** Teo Swee Keong <TeoSweeKeong@msfirstcapital.com.sg>  
**Sent:** Monday, 15 January 2018 6:10 PM  
**To:** 'assignments@lkkauto.com'  
**Cc:** Aini Binte Md Min  
**Subject:** NEW SURVEY ASSIGNMENT - (TPD 1) - SHC7494B on 11/01/2018  
**Attachments:** MOTOR SURVEY ASSIGNMENT.pdf; FW: Accident Involving GV5363X with SHC7494B on 11/01/2018 (1.21 MB)

Dear Sirs

New survey request for your handling – TPD 1.

Thanks and Regards,

**SK Teo**  
**Motor Claims Dept**

MS First Capital Insurance Ltd | 36 Robinson Road #16-01 City House Singapore 068877 | DID : 6507 3848 | Fax No. : 6507 3849 |

A member of **MS&AD** INSURANCE GROUP

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data.

Please refer to [www.msfirstcapital.com.sg](http://www.msfirstcapital.com.sg) for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

**From:** sinsheng engineering services [mailto:sinsheng1981@gmail.com]  
**Sent:** Saturday, January 13, 2018 10:56 AM  
**To:** Aini Binte Md Min <aini@first-insurance.com.sg>  
**Subject:** Re: FW: Accident Involving GV5363X with SHC7494B on 11/01/2018

Hi Ms Aini,

We are selected LKK Auto Consultant

Thank You  
Regards

Susan  
Sin Sheng Engineering Services  
3 Tech Park Crescent  
Tuas Tech Park  
Singapore 638129  
Tel: 6863 9595  
Fax: 6863 6477

On 12 January 2018 at 12:14, Aini Binte Md Min <[aini@first-insurance.com.sg](mailto:aini@first-insurance.com.sg)> wrote:

Dear Sirs,

We refer to your survey request dated 12.1.18.

Please find below our list of surveyors for your reference. Kindly select from our list below and inform us of your choice within the next 2 days.

1. LKK Auto Consultants Pte Ltd
2. Vicom Ltd

Once you inform us of your choice, the surveyor will be appointed within 2 working days of your email.

If you do not agree to any of the surveyors above, you may proceed to appoint your own surveyor. In this instance, we will also appoint a surveyor from our list above to conduct the PRI. Upon completion of repairs, please contact our appointed surveyor to conduct a physical re-inspection of the vehicle.

Thanks & Regards

Aini

Motor Claims Department

**First Capital Insurance Ltd** | 36 Robinson Road, City House, #16-01 Singapore 068877 | DID: 6507 3848

Fax: 6507 3849 | Company Reg. No. 195000106C

A member of **MS&AD** INSURANCE GROUP

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data.

Please refer to [www.first-insurance.com.sg](http://www.first-insurance.com.sg) for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

---

**From:** sinsheng engineerservices [mailto:sinsheng1981@gmail.com]  
**Sent:** 12 January 2018 08:14 AM  
**To:** Claim Workflow System  
**Subject:** Accident Involving GV5363X with SHC7494B on 11/01/2018

Dear Officer Incharge,

We are repairer of motor vehicle GV5363X . Enclosed Accident Statement and LTA search fee for your attention please. Kindly assist to arrange for the Pre-Repair Inspection to be conducted within two (2) workings days upon received this email.

Kindly let us have your list of 10 norminated surveyors to conduct the Single-Joint Inspection.

Kindly assist to revert the liability issue or offer if direct settlement is in order

Thank You  
Regards

Susan  
Sin Sheng Engineering Services  
3 Tech Park Crescent  
Tuas Tech Park  
Singapore 638129  
Tel: 6863 9595  
Fax: 6863 6477

"Please note that this email, including any attachments, is intended solely for the individual (s) or entity (ies) to whom they are addressed and may contain information that is private, confidential and privileged. In case you are not the intended recipient, request you to notify the sender by reply mail and delete this email, including any copies or attachments from your system. Any unauthorized dissemination, disclosure and/or use of the contents of this communication to anyone is strictly prohibited and punishable by law.

Opinions, conclusions and statements of intent expressed in this e-mail are of the sender and ICICI Lombard

General Insurance Company Limited (Company) does not accept liability for the views expressed in this email unless confirmed by an authorized representative of the Company independently of this communication or for the consequences of any viruses that may be transmitted with this email."

MOTOR SURVEY ASSIGNMENT

Date 12.1.18  
Accident Date 11.1.18  
Insured Vehicle SHC 7494B  
Survey Location SIN SHENG ENGINEERING  
3 TECH PARK CRESCENT  
TUAS TECH PARK, S(635129)  
Contact No. 68639595  
Our Ref No. SHC 7494B  
Claim Type THIRD PARTY  
Third Party Vehicle GVS363X  
Contact Person SUSAN  
Fax No.

Survey Type Without Prejudice

Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD  
Contact Person  
Contact Number 62563561  
Fax No. 68416315

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

Encl. ACCDT REPORTS

Cc : Workshop SIN SHENG ENGINEERING  
Officer in charge AUNG YIN MIN

Attention

IMPORTANT NOTE

Kindly submit the survey report by email only to [surveyor@first-insurance.com.sg](mailto:surveyor@first-insurance.com.sg) within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.



## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Wednesday, 17 January 2018 5:27 PM  
**To:** 'Teo Swee Keong'; assignments  
**Cc:** 'Aini Binte Md Min'; SUR  
**Subject:** RE: NEW SURVEY ASSIGNMENT - (TPD 1) - SHC7494B on 11/01/2018  
**Attachments:** CSFCI18000913T1qd3.pdf

Dear Mr Teo,

Enclosed herewith preliminary advice of GV 5363X.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Tuesday, 16 January 2018 9:05 AM  
**To:** 'Teo Swee Keong' <[TeoSweeKeong@msfirstcapital.com.sg](mailto:TeoSweeKeong@msfirstcapital.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'Aini Binte Md Min' <[Aini@msfirstcapital.com.sg](mailto:Aini@msfirstcapital.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: NEW SURVEY ASSIGNMENT - (TPD 1) - SHC7494B on 11/01/2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Teo Swee Keong [<mailto:TeoSweeKeong@msfirstcapital.com.sg>]  
**Sent:** Monday, 15 January 2018 6:10 PM  
**To:** 'assignments@lkkauto.com' <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** Aini Binte Md Min <[Aini@msfirstcapital.com.sg](mailto:Aini@msfirstcapital.com.sg)>  
**Subject:** NEW SURVEY ASSIGNMENT - (TPD 1) - SHC7494B on 11/01/2018

Dear Sirs

New survey request for your handling – TPD 1.

Thanks and Regards,

**SK Teo**



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: SHC 7494B

Date: 17 January 2018

Our Ref: CS/FCI18000913/T1qd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. GV 5363X.**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 16/01/2018 at the premises of M/s SIN SHENG ENGINEERING, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,704.17</u>
Revised Estimate Amount	: S\$ <u>2,992.73</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

**Description of Damage:**

The vehicle sustained damages at the rear n/s portion.



Yours faithfully

Taufikh  
Automotive Assessor

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1196N
Vehicle Details	
Vehicle No.:	GV5363X
Vehicle to be Exported:	No
Intended De-registration Date:	17 Jan 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE DIESEL
Primary Colour:	White
Manufacturing Year:	2002
Engine No.:	5L5230648
Chassis No.:	LH1621006627
Maximum Power Output:	-
Open Market Value:	\$21,936.00
Original Registration Date:	24 Jul 2002
First Registration Date:	24 Jul 2002
Transfer Count:	0
Actual ARF Paid:	\$1,097.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Feb 2022
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10

PQP Paid:	\$40,549.00
COE Rebate Amount:	\$16,690.00
Total Rebate Amount:	\$16,690.00

The information contained herein is correct as at 17 Jan 2018

OK

SGCARMART.COM

New Cars

Used Cars

Sell My Car

Directory

Products

Articles

- Sony Xperia Series phones
- Advice needed for New Zealand road trip
- 2016 Audi A4 sedan & avant

Toyota Hiace

Price Range

Depreciation

> 10 year(s) ol

Vehicle Type

Home » Used Cars » Thiam Heng Motor » Toyota Hiace (COE till 04/2022)

## Toyota Hiace (COE till 04/2022)

### Tools & Tips

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

### Car Tyres



### Overview

### Financial

### Accessories

### Similar

### Research

### Photos

### Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

### Car Details

Price	\$25,800	?
Depreciation	\$6,020 /yr	
Reg Date	23-May-2001 (4yrs 3mths 13days COE left)	
Lifespan	22-May-2021	?
Manufactured	2001	
Mileage	-	
Transmission	Manual	
Engine Cap	2,985 cc	?
Curb Weight	1,500 kg	
Fuel type	Diesel	
Features	11 Seater PH Bus.	
Accessories	CD Player.	
Description	Well Kept, HDB Parking, In House Loan Available.	?
COE	\$24,005	?
OMV	\$28,501	?
ARF	\$1,426	?
Dereg Value	\$20,572 as of today (change)	?
No. of Owners	3	
Type of Veh	Bus/Mini Bus	
Category	COE Car	
Availability	Available	

Add to Shortlist

Add to Compare

Add a Note

Posted on: 04-Jan-2018 | Last Updated on: 16-Jan-2018

Tags: Toyota Hiace, 2001 Toyota Hiace, Toyota, Hiace, Used Toyota

Compare

### Seller Informat

Company

Address

Location

Office No

Contact Person(s)

Useful Services



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	11/01/2018 22:30
Date Of Accident	11/01/2018 16:05
Exact Location Of Accident	SLIP ROAD OF AYE, LOWER DELTA FLYOVER
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GV5363X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	GOLDBELL LEASING PTE LTD
Co Reg No	199001196N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64942833

### Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE-2.5 (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	29004183
Cover Note Number	

### Driver

Name of Driver	SUN YANLEI
Passport No/FIN	G2480220K
Date Of Birth	18/08/1986
Occupation	OUTDOOR
Date Of Driving Pass	03/09/2014
Driving Experience	3 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97777585
Fax Number	
Contact Number	
Email Address	NOEMAIL

Vehicle Registration Number	SHC7494B
Vehicle Make/Model/Colour	
Details Of Properties	VEH B
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLG7828D
Vehicle Make/Model/Colour	
Details Of Properties	VEH C
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

#### DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	S6744CD
Vehicle Make/Model/Colour	HONDA
Details Of Properties	VEH D
Vehicle Category	GOVERNMENT
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number	SLS8078G
Vehicle Make/Model/Colour	MAZDA
Details Of Properties	VEH E
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Sun Yan lei +

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

GV 5363 X



Reporting Centre Personnel's Signature  
Name:  
NRIC/PN No.:



# Police Report



**SINGAPORE  
POLICE FORCE**



T/20180111/2198

1 of 4

Police Station Of Origin:  
Clementi N.P.C  
20 Clementi Avenue 5 SINGAPORE 129858  
Tel No: 1800-8729999

Report No: T/20180111/2198

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 11/01/2018 20:05	Vide Report No: A/20180111/0068	Station Diary No: 194
--	------------------------------------	--------------------------

### Informant's Particulars

Name of Informant: SUN YANLEI			Address: C/O 231 PANDAN LOOP SINGAPORE 128418		
ID Type / ID No.: FIN NO / G2480220K			Contact No.: Home/Office: Mobile: 97777585		
Nationality: CHINESE			Email:		
Sex: Male	Age: 31	Date of Birth: 18/08/1986	Type of Informant: Driver		
Race: Chinese			Language: English	Institution / School Name:	
Occupation: Other heavy truck and lorry drivers			Driving Licence Information: Class: 3,4		Date of Expiry:

### General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 11/01/2018 16:05	Type of Location: Flyover
Location: Along Road 1 AYER RAJAH EXPRESSWAY  TOWARDS TUAS AT THE SLIP ROAD OF LOWER DELTA FLYOVER TURNING RIGHT TO JALAN BUKIT MERAH				
Weather: Raining		Road Surface: Wet	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

### Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GV5363X	Van				Slightly Damaged	1
S6744CD	Car				Slightly Damaged	0
SHC7494B	Car				Slightly Damaged	0
SLG7828D	Car				Slightly Damaged	1
SLQ6827K	Car				Slightly Damaged	2

Police Report

Date:



**SINGAPORE  
POLICE FORCE**



T/20180111/2198

3 of 4

Report No: T/20180111/2198

Police Station Of Origin:  
Clementi N.P.C  
20 Clementi Avenue 5 SINGAPORE 129858  
Tel No: 1800-8729999

CONTINUATION OF REPORT

Traffic Accident report

I wish to state that this is the first time I met an accident with the involving vehicles and there is no on-board camera install inside my van. Currently, my passenger and I felt some pain at the back of our body and considering going for medical check-up.

# SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002369

Date : 15/01/2018

Vehicle Num. : GV5363X

Make/Model : TOYOTA LH 162-2002

Chassis/Eng# : LH1621006627/5L5230648

Accident Date : 11/01/2018

Claim No. :

Reference :

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BUMPER		377.40 <i>cm</i>
2.	1	BUMPER SIDE BRACKET		78.20 <i>nd</i>
3.	1	REAR LAMP, LHS		332.60 <i>cm</i>
4.	1	REAR LAMP PANEL		495.26 <i>BRX</i>
5.	1	SIDE PANEL, LHS		1,568.50 <i>BRX</i>
6.	1	MUDFLAP		153.60 <i>de</i>
List Total S\$ :				3,005.56
25.00% Discount S\$ :				751.39
				2,254.17
LABOUR :				600
TO PANEL BEAT/REPAIR LH BODY				750.00
TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS				
TUFF KOTE				150.00
SPRAY PAINTING				450
LOSS OF USE : 5 DAYS @ 4 120/DAY				550.00
Labour Total S\$ :				1,450.00

SIN SHENG ENGINEERING SERVICES

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item is subject to resurvey and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total S\$ : 3,704.17

*Tanjin 97495749 WP*  
*16/1/18 @ 1545*  
*Wimpson*  
*Resurvey before after repair*  
*5 days*  
*tanjin@lkkauto.com*




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18000913/T1qd3e2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 13-04-2018		
		Code : FCI2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 7494B	Veh. Inspected	GV 5363X	
Policy No.		Coverage (\$)	0.00	
Claim No.	SHC 7494B	Excess (\$)	0.00	
Assign From	TEO SWEE KEONG	Assign Date	15/01/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA HIACE	c.c	2986	
Engine No.	HIDDEN	Year of Reg.	2002	
Chassis No.	LH1621006627	Colour	WHITE	
Odometer	654123	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185 R14	AUSTONE	6 mm	
L/H Front Tyre	185 R14	AUSTONE	6 mm	
R/H Rear Tyre	185 R14	AUSTONE	6 mm	
L/H Rear Tyre	185 R14	AUSTONE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	11/01/2018	Inspection Date	16/01/2018	
Survey held at	SIN SHENG ENGINEERING SERVICES 3 TECH PARK CRESCENT TUAS TECK PARK SINGAPORE 638129			
<b>5a. Remarks</b>				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GV 5363X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	REAR BUMPER	CRACKED	377.40	377.40
1	BUMPER SIDE BRACKET	NECESSARY	78.20	78.20
1	REAR LAMP, LHS	CRACKED	332.60	332.60
1	REAR LAMP PANEL	TO REPAIR SEE LABOUR	495.26	-
1	SIDE PANEL, LHS	BUCKLED	1,568.50	1,568.50
1	MUDFLAP	DEFORMED	153.60	153.60
	LESS 25% DISCOUNT		-751.39	-627.58
			2,254.17	1,882.72
	<b>LABOUR</b>			
	TO PANEL BEAT/ REPAIR LH BODY. TO DISMANTLE / REPLACE ABOVE MENTIONED PARTS. INCLUSIVE OF THE REPAIR OF REAR LAMP PANEL.		750.00	600.00
	TUFF KOTE.		150.00	60.00
	SPRAY PAINTING.		550.00	450.00
			1,450.00	1,110.00
	<b>GRAND TOTAL</b>		<b>3,704.17</b>	<b>2,992.72</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,400.00</b>

Report Ref No. CS/FCI18000913/T1qd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.