

22/09/2002

ASS. REC. BY:

REF:

CS/MSG18000926/Kqb¹⁷

Special Instruction:

Survivor:
Mumen

Kenneth

ASSIGNMENT (Office)

From (Person): Catherine Tina

of

MSL1

Date/Time: 16/01/2018 10:38am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJP 7126Y

Insured:

SKR 6246T

at Workshop m/s

Massive Trading

Tel:

9108 7728

of

Blk 5038 ANIK Ind Park 2 #01-405

Policy No:

B2794 8849 QMY

Claim No:

545996

Sum Insured:

Excess:

Make of Veh:

D.O.A.

13012018

(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

17-01-2018

H.O.D. Endorsement:

Date/Time:

16/01/2018 11:40am

Person Contacted:

Anthony

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SJP 7126Y - X

SKR 6246T - CS/MSG17015994/Gib02

DA: 160817

18/1/18 @ 6.07pm revised to Catherine Tina via Mumen.

MSIG

ASSIGNMENT

Page: Date: 17/01/2018

Estimated Cost:

OD ☒ WS / TR RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJP 7126Y

at Workshop/ins: Massive Trading

of: Blk 5038, AMK Ind Prk 2# 01-105

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

Client's Record:

Make of Ven:

(Policy Condition)

Remarks: The veh had commenced its repair at the time of inspection.



Sal. or Market Value: 824k

IDAO Accident Report: Consistent? : Yes or No

GIA / PP Seen: Consistent? : Yes or No

Est. Repairs: 04 days Pass: Yes or No

Lum Sum: 20 % 3 val: Yes or No

CA / REV / REP: 24 HRS wpr

Date: Person Contacted:

Vehicle IN / OUT

SJP 7126Y 04 09

Type: M/Cat: M/Cycle: Bus/Van/Lorry: Taxi: Prime Mover:

Truck/Trailer:

Make:

Honda Stream

MPV

1799

Colour:

White

H/O

Insured

Std

N/A

So Resing:

185438

H/O

Insured

Std

N/A

Eng No:

JHMRN08809S200966

Gen Cond:

Good

Fair

Poor

Burnt

Steering:

In order

Jammed

Leaked

Burnt

Brake:

In order

Jammed

Leaked

Burnt

Mod:

Nil

S/Rin

STD

A/Rin

Tyre Size:

R:

215/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PR / SUM /

TOYO / YOKO or

Dayton

Front:

Rear:

R.Bal:

P

mm

R.Bal:

7

L.Bal:

P

mm

L.Bal:

7

D.O.A:

13/1/18

D.O:

17/1/18

Survey held at:

✓

Des. of Damages: Frt / Rear / O/S / N/S / U/O / Rooftop or

The U/O / Chassis frame / Body Structure affected due to collision

Date Time Action Instruction

18/1/18 File pass to Corburne, GIA & en not ready
 23/1/18 8:27a encl & corburne (tel 8 4507.72, 67%)
 275a

RECEIVED 24 JAN 2018

Date Time File Pass to: ☐ Preli. Report23/1/18 8:27a ☐ Final Report

Date Time File Pass to:

Days Of Repair: 4

Resurvey No. of Trip: 1

Sur. & Fee:

Characteristics:

Add Fee:

☐

Steering:

☐

Brake:

☐

Tyre:

☐

Body:

Report Format:

MER-TP

Lump Sum:

2750

200

10

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18000926/Kqb

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 16-01-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|--------------------------|----------------|------------|
| Insured Veh. | SKR 6246T | Veh. Inspected | SJP 7126Y |
| Policy No. | B27948849QMY | Coverage (\$) | 0.00 |
| Claim No. | 545996 | Excess (\$) | 0.00 |
| Assign From | MERIMEN (CATHERINE THIA) | Assign Date | 16/01/2018 |

2. Vehicle Particulars & Condition

| | | |
|--------------|--------|--------------|
| Make & Model | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. |
| Chassis No. | | Colour |
| Odometer | - | Steering |
| Brakes | | Modification |
| General | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |

4. Description of Damages

| |
|--|
| |
|--|

5. General Information

| | | | |
|----------------|---------------------------------|-----------------|------------|
| Accident Date | 13/01/2018 | Inspection Date | 17/01/2018 |
| Survey held at | BLK 5038 AMK IND PARK 2 #01-405 | | |
| Repairer | MASSIVE TRADING & AUTO | | |

5a. Remarks

| |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

21/05/2014

...CLAIM SUBFOLDER...(New Assignment)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--|---------|---------------|------------|--|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
| Main | 15 Jan 2018 | | 16 Jan 2018 10:38 Assign | | | | New Assignment Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|-----------|---|-------------------------------|---|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by insurer] | | | | | | | | | |
| Insured: | | JASON KOH SHENG XIONG, ID: S8932020H, Tel: +6591479070 | | | | | | | |
| Main Claimant: | | OWN BUSINESS, Co. Reg. No.: 53322688X | | | | | | | |
| Vehicle Reg. No.: | | SJP7126Y | Date of Loss: | 13/01/2018 13:00 - :59 | | | | | |
| Claim Type: | | TP / 545996 | Policy/Cover Note No.: | B27948849QMY (Comprehensive) Coverage: 26/08/2017 - 25/08/2018 | | | | | |
| Vehicle Reg. No. (Insured): | | SKR6246T | Policy No. (Claimant): | | | | | | |
| | | Excess: | S\$1,000.00 | | | | | | |
| Repairer: | | Massive Trading & Auto () Blk 5038 #01-405, Ang Mo Kio Industrial Pk 2, 569541 Ang Mo Kio - Tel: | | | | | | | |
| Handling Insurer: | | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545] | | | | | | | |
| Adjuster: | | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 17/01/2018] | | | | | | | |
| Driver/Custodian (Insured): | | JASON KOH SHENG XIONG (28 / Male), NRIC: S8932020H, Tel: +6591479070 | | | | | | | |
| Adj Asg. Remarks: | | Appoint Mr Kenneth Kong to conduct the survey . Please contact Mr Anthony @ 9108 2728 to arrange for survey. | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 18 Jan 2018

Preliminary Advice

| | | | |
|--------------------|-------------------|-------------------------|--------------|
| Insured Vehicle No | : SKR6246T | Accident Date | : 13/01/2018 |
| TP Vehicle No | : SJP7126Y | Assignment Date | : 16/01/2018 |
| Make | : HONDA STREAM | Est. Duration of Repair | : 4 |
| Date of Inspection | : 17/01/2018 | | |
| Inspection At | : MASSIVE TRADING | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 7,257.72 |
| Revised Amount | :S\$ | 3,348.04 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 3,348.04 |

| | | |
|-----------------|------|--|
| Lump Sum Repair | :S\$ | |
|-----------------|------|--|

Total Loss Consideration

| | | |
|--------------------|------|--|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | |
| COE / PARF Rebate | :S\$ | |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | |

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|--------------------------------|------------------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Business |
| Owner ID: | 2688X |
| Vehicle Details | |
| Vehicle No.: | SJP7126Y |
| Vehicle to be Exported: | No |
| Intended De-registration Date: | 18 Jan 2018 |
| Vehicle Make: | HONDA |
| Vehicle Model: | STREAM 1.8L SUNROOF ALLOY WHEEL AT |
| Primary Colour: | White |
| Manufacturing Year: | 2008 |
| Engine No.: | R18A13800970 |
| Chassis No.: | JHMRN68809S200966 |
| Maximum Power Output: | 103.0 kW (138 bhp) |
| Open Market Value: | \$27,948.00 |
| Original Registration Date: | 01 Apr 2009 |
| First Registration Date: | 01 Apr 2009 |
| Transfer Count: | 1 |
| Actual ARF Paid: | \$27,948.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 31 Mar 2019 |
| PARF Rebate Amount: | \$15,371.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 31 Mar 2019 |
| COE Category: | B - Car (1601cc & above) |
| COE Period(Years): | 10 |
| QP Paid: | \$5,101.00 |
| COE Rebate Amount: | \$612.00 |
| Total Rebate Amount: | \$15,983.00 |

The information contained herein is correct as at 18 Jan 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|--------------------------|
| Date Of Report | 15/01/2018 16:06 |
| Date Of Accident | 13/01/2018 12:45 |
| Exact Location Of Accident | AMK AVE 6 TWDS AMK AVE 1 |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------|
| Vehicle Registration Number | SJP7126Y |
| Insured/Policyholder | |
| Name Of Registered Owner | OWN BUSINESS |
| Co Reg No | 53322688X |
| Email Address | NOEMAIL |
| Mobile Phone No | (LOCAL) +65-81574577 |
| Alternative Phone No | OFFICE-81574577 |

Vehicle Particulars

| | |
|--|--------------|
| Manufacturer | HONDA |
| Model | STREAM |
| Exact Purpose for which vehicle was being used at time of accident | PRIVATE USED |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE HIRE |

Insurance Company

| | |
|---------------------------|--|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | 5091935326 |
| Cover Note Number | |

Driver

| | |
|----------------------|----------------------|
| Name of Driver | SOON WEIHAO, KEVIN |
| NRIC No | S8408594D |
| Date Of Birth | 06/04/1984 |
| Occupation | INDOOR |
| Date Of Driving Pass | 12/05/2010 |
| Driving Experience | 7 YEARS AND 8 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-81574577 |
| Fax Number | |
| Contact Number | |
| Email Address | NOEMAIL |

| | |
|---|--------------------------------|
| Address | BLK 260 YISHUN ST 22 #04-93 |
| Postcode | 760260 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OTHER - BROTHER IN-LAW |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| Insurance Company of Driver's Own Vehicle | - |

General Information of the Accident

| | |
|--------------------|-----------------|
| Type Of Accident | CHAIN COLLISION |
| Weather Conditions | RAINING |
| Road Surface | WET |

Other Information

| | |
|---|--|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles involved in the accident | |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 4 |
| Passenger 1 | NAME: : NEO CUI FANG GENDER: : FEMALE |
| Passenger 2 | NAME: : NEO KIM KHEOW GENDER: : MALE |
| Passenger 3 | NAME: : KOH BEE HUA GENDER: : FEMALE |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

REFER TO SKETCH PLAN - CIRCUMSTANCES OF THE ACCIDENT.

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-----------------------------|-----------------------|
| Vehicle Registration Number | SKR6246T |
| Vehicle Make/Model/Colour | VOLKSWAGEN |
| Details Of Properties | |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | JASON KOH SHENG XIONG |
| NRIC/Passport Number | S8932020H |
| Contact Number | 91479070 |

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SKA5127A

Vehicle Make/Model/Colour

TOYOTA

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 13/1/2018 @ about 1245hrs, I was travelling along Ang Mo Kio Ave 6 towards AMK Ave 1. After the junction of AMK Ave 3, due to heavy traffic, I slowed down my vehicle and eventually came to a stopped. Suddenly, I felt an impact from the rear of my vehicle. I got out of my vehicle and realised it was a collision of 3 vehicles. I also wish to state that my wife Joo Cui Fang, IC 8607707H and my parents-in-law Mr Joo Kim Kheow, IC 1147147/A and Mdm Koh Bee Hua, IC 51579862I was on board of my vehicle at the time of the accident.

DECLARATION

I/We declare the following particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Massive Trading & Auto

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225

H/P 91082728

Fax : 64816131

Own Business
Blk 260 Yishun St 22
#04-93
Singapore 760260

Vehicle No : SJP 7126 Y
Make : Honda Stream
Year : 2008

Not Authorized
11 Sing @ 2750h
Resurvey After Paint

4 days

19/1/2010

| Qty | Description | Unit Price | Amount |
|-----|-------------|------------|--------|
|-----|-------------|------------|--------|

Estimate Cost Of Repair

| | | |
|-------|-------------------------------|-------------------------|
| 1 pc | Rear tail-gate assy | dent 903-00 |
| 1 pc | Rear tail-gate inner lock | faulty |
| 1 pc | Rear tail-gate glass moulding | nee |
| 2 pcs | Rear tail-lamp assy | ? |
| 1 pc | Rear end panel | ? |
| 1 pc | Rear end panel inner garnish | ? |
| 1 pc | Rear boot rubber | 50% 588.90 |
| 1 pc | Rear bumper | dent |
| 2 pcs | Rear bumper side retainer | ole cracks 911 |
| 1 pc | Rear tow cover | dent |
| 2 pcs | Rear bumper bracket | ? |
| 1 pc | Rear exhaust silencer | rust refer photo 541.50 |

| | | |
|-----------|------------|---------|
| R | \$1,250.70 | ✓ |
| R | \$255.30 | ✓ |
| nee | \$55.20 | ✓ |
| 485.10 | \$970.20 | X |
| R | \$482.30 | X |
| R | \$185.70 | X |
| Sm | \$165.80 | X |
| CR | \$950.70 | X |
| 65.20 | \$130.40 | X 65.20 |
| Red | \$25.70 | X |
| 48.60 | \$97.20 | X |
| R | \$846.70 | ✓ |
| | \$5,415.90 | |
| Less 20 % | \$1,083.18 | |
| | \$4,332.72 | |

S. Nett Item

| | | |
|--------|-------------------------|-----|
| 4 pcs | Rear reverse sensor | ? |
| 1 pc | Rear windscreen sealant | nee |
| 1 pc | Rear no plate | |
| 10 pcs | Rear bumper clip | nee |

| | | |
|-----------|----------|----------|
| Red/short | \$300.00 | ✓ |
| nee | \$55.00 | ✓ 4 days |
| Sm | \$45.00 | X |
| 2.50 | \$25.00 | ✓ |
| | \$425.00 | |

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

| | | |
|-------------|------------|-----|
| balance c/f | \$1,000.00 | 500 |
| | \$5,757.72 | |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SJP 7126 Y

balance b/f \$5,757.72

Labour Charges

To putty & spray paint on accident affected portion.

\$1,000.00 6001

Check/reconnect wiring.

\$40.00 201

To spray anti rust on accident affected portion.

\$120.00 301

Remove/renew rear windscreen glass

\$100.00 ✓

Remove/refit rear boot upholstery to facilitate repair

\$120.00 501

Remove/renew rear exhaust silencer

\$120.00 601

Total \$7,257.72

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18000926/KQBN2

Date: 24/01/2018

REFERENCE

| | | | |
|-----------------------|--------------------------------------|----------------------|--------------|
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. | Policy No: | B27948849QMY |
| Claimant Vehicle No : | SJP7126Y | Insured Vehicle No : | SKR6246T |
| Date of Loss: | 13/01/2018 | Nature of Claim: | TP |
| | | Claim No: | 545996 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-------------------------------|-------------|-------------------|
| Reg No: | SJP7126Y | Engine No: | R18A13800970 |
| Make & Model: | HONDA STREAM, 1.8 Sunroof (A) | Chassis No: | JHMRN68809S200966 |
| Reg. Date: | 01/04/2009 (Man. Year: 2008) | Odometer: | 185438 km |
| Colour: | White | | |
| Engine Capacity: | 1799 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size: | 215/55R17 | Rear Tyre Size: | 215/55R17 |
| Front Left Side: | Dayton 8 mm | Rear Left Side: | Dayton 7 mm |
| Front Right Side: | Dayton 8 mm | Rear Right Side: | Dayton 7 mm |

The above values represent the remaining tyre treads depth

COST OF CLAIMS

| | Repairer's | Adjuster's | Difference | Diff % |
|--|-----------------|-----------------|-----------------|--------------|
| Parts | 4,757.72 | 2,108.60 | 2,649.12 | 55.68 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,500.00 | 1,360.00 | 1,140.00 | 45.60 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 7,257.72 | 3,468.60 | 3,789.12 | 52.21 |
| Approved Total (Overridden) (S\$) | | 2,750.00 | | |
| Nett Amount (S\$) | 7,257.72 | 2,750.00 | 4,507.72 | 62.11 |

INSPECTION

| | | |
|---------------------|--------------------------|---|
| Date of Assignment: | 16/01/2018 | |
| Date Inspected: | 17/01/2018 Inspected At: | Massive Trading & Auto Blk 5038 #01-405, Ang Mo Kio Industrial Pk 2 Singapore 569541 |

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|--|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 24 Jan 2018) |
| Parts: | M1-MPV | HONDA STREAM 1.8 Sunroof (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SJP7126Y) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--------------------------------|----------------|-------------|------------|
| 1 | 1 | | *REAR TAIL-GATE ASSY | Bent | 1,250.70 FL | *903.00 FL |
| 2 | 1 | | *REAR TAIL-GATE INNER LOCK | Repair | 255.30 FL | *- FL |
| 3 | 1 | | *REAR TAIL-GATE GLASS MOULDING | Necessary | 55.20 FL | *55.20 FL |
| 4 | 2 | | *REAR TAIL-LAMP ASSY | Serviceable | 970.20 FL | *- FL |
| 5 | 1 | | *REAR END PANEL | Repair | 482.30 FL | *- FL |
| 6 | 1 | | *REAR END PANEL INNER GARNISH | Serviceable | 185.70 FL | *- FL |
| 7 | 1 | | *REAR BUMPER | Cracked | 950.70 FL | *588.90 FL |
| 8 | 1 | | *REAR BUMPER SIDE RETAINER | O/s Distorted | 130.40 FL | *65.20 FL |
| 9 | 1 | | *REAR TOW COVER | Dented | 25.70 FL | *25.70 FL |
| 10 | 2 | | *REAR BUMPER BRACKET | Repair | 97.20 FL | *- FL |
| 11 | 1 | | *REAR EXHAUST SILENCER | Bent | 846.70 FL | *541.50 FL |
| 12 | 1 | | *REAR BOOT RUBBER | Serviceable | 165.80 FL | *- FL |
| 13 | 4 | | *REAR REVERSE SENSOR | Dented/Shorted | 300.00 FS | *300.00 FS |
| 14 | 1 | | *REAR WINDSCREEN SEALANT | Necessary | 55.00 FS | *40.00 FS |
| 15 | 1 | | *REAR NO PLATE | Serviceable | 45.00 FS | *- FS |
| 16 | 10 | | *REAR BUMPER CLIP | Necessary | 25.00 FS | *25.00 FS |

F=Franchise part, S=SpcNett, L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$\$) | 5,840.90 | 2,544.50 |
| - List Item Discount on L Items 20.00/20.00% (\$\$) | 1,083.18 | 435.90 |
| Total Parts (\$\$) | 4,757.72 | 2,108.60 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------|---|----------|------------|----------|
| Labour Items | | | | |
| 1 | TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION | New | 1,000.00 | 600.00 |
| 2 | CHECK/RECONNECT WIRING | New | 40.00 | 20.00 |
| 3 | TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION | New | 120.00 | 30.00 |
| 4 | REMOVE/RENEW REAR WINDSCREEN GLASS | New | 100.00 | 100.00 |
| 5 | REMOVE/REFIT REAR BOOT UPHOLSTERY TO FACILITATE REPAIR | New | 120.00 | 50.00 |
| 6 | REMOVE/RENEW REAR EXHAUST SILENCER | New | 120.00 | 60.00 |
| 7 | REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING,WELDING & CUTTING | New | 1,000.00 | 500.00 |
| Gross Labour Cost (S\$) | | | 2,500.00 | 1,360.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >