

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐	 5	SET REVERSE SENSOR	Reviewing	0	SERVICEABLE	
☐	 6	WHEEL RIM (NPA)	Reviewing	0	NOT NECESSARY	
☐	 7	WINDSCREEN SEALANT	Reviewing	0	NOT NECESSARY	

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPRJ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
	9	1			REAR BUMPER SIDE RETAINER (LONG) RH			Serviceable	0		25		0
	10	1			REAR BUMPER REFLECTOR RH			Serviceable	0		25		0
	11	1			TAILGATE			Repair	0		25		0
	12	1			TAILGATE WEATHERSTRIP			Serviceable	0		25		0
	13	1			TAILGATE LETTERING "ESTIMA"			Necessary	66.95		25		50.21
	14	1			TAILGATE LETTERING "AERAS"			Necessary	57.8		25		43.35
	15	1			TAILGATE EMBLEM			Necessary	66.7		25		50.03
	16	1			SET REAR WINDSCREEN MOULDING			Serviceable	0		25		0
Labour													

Add

Approve

Deny

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT
	1		PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS, PANEL BEAT, CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS.	400	0	0	Reviewing	
	2		PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES.	660	0	0	Reviewing	

Detailed Assessment

Inspection Date *

01/15/2018



Condition of Vehicle at time of survey

General condition

Good

Total Loss

Yes No

Steering (Serviceable)

Yes No

Towing Charges

0

Footbrake (Serviceable)

Yes No

Voluntary Excess

0

Handbrake (Serviceable)

Yes No

Compulsory Excess

0

Engine Modification

Yes No

Young/Inexperienced/Unnamed Driver Excess

0

Pre-accident condition

Good

Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

225/50R18

Rear Tyre Size

225/50R18

FNOL INFORMATION

Singapore

POST SURVEY INFORMATION

CATEGORY

Address type

FNOL INFORMATION

Personal Correspondence

POST SURVEY INFORMATION

CATEGORY

Gender

FNOL INFORMATION

Unknown

POST SURVEY INFORMATION

CATEGORY

Marital status

FNOL INFORMATION

Unknown

POST SURVEY INFORMATION

CATEGORY

Identification #

FNOL INFORMATION

S6975929G

POLICY INFORMAT... TPVD TOYOTA

ASSESSMENT INFO...

TOYOTA

CATEGORY

Model

POLICY INFORMAT... ESTIMA-2.4

ASSESSMENT INFO...

ESTIMA AERAS PREMIUM 2.4 CVT ABS

CATEGORY

Type

POLICY INFORMAT...

ASSESSMENT INFO...



CATEGORY

Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY

Chassis No

POLICY INFORMAT...

ASSESSMENT INFO...

ACR500185480

CATEGORY

Date of Birth

FNOL INFORMATI...

POST SURVEY INF...



mm/dd/yyyy

CATEGORY

Age

FNOL INFORMATI...

0

POST SURVEY INF...

CATEGORY

Occupation

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Education Qualification

FNOL INFORMATI...

Other

POST SURVEY INF...

CATEGORY

Driving Experience

Pending verification -
Direct Settlement

NG Stacey
6568804351
stacey.ng@axa.com.sg

- Messages
- Invoices
- History

Additional Instructions

Add

Documents	Assessment	Metrics	Notes	STATUS	SHARE	CLONE
CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT			
NG Stacey	1/25/18 9:41 AM	1525.39	1525.39	In Review	Share	Clone

NG Stacey
6568804351
stacey.ng@axa.com.sg

Messages

Invoices

History

Additional Instructions

Pending verification -
Direct Settlement

Documents	Assessment	Metrics	Notes	Document Type	Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
TP LOD.pdf	Legal	Letter of Demand/Notice of Proceedings	SHAH Kushal	March 8, 2018
TP_ESTIMATE- _MARKED.pdf	Forms / Claim Documents	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	January 25, 2018
Preliminary Advice.pdf	Forms / Claim Documents	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	January 25, 2018
FW pre repair inspection (OUR VEHICLE - SKR5995X YOUR VEHICLE - FBC8024P) S8M006YZ.msg	Other	Other	TAN Kwee May	January 15, 2018