

ASS. REC. BY:

REF:

CS3 / CTL18000953 / Wb84

Special Instruction:

range 2 days.

Survivor:

Wilson

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CTL

Date/Time:

16/01/2018 10:12 am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLU 14938R

Insured:

GBE 14951D

at Workshop m/s

N-51 Automotive

Tel:

6842 0051

of

2 Kaki Bukit Ave 2 #01-17

Policy No:

DMCVSN 3095521700

Claim No:

SNM18D00243C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

11-01-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp1

H.O.D. Endorsement:

Date/Time:

16/01/2018 11:44 am

Person Contacted:

Elynn

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SLU 14938R - X

GBE 14951D - X

Dismantle: 17/1/2018

After repair: 18/1/2018

PRS
Signature: Wilson
maximin

REF: CTL

ASSIGNMENT

From: _____ Date: 16/01/2018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLU 4938R

at Workshop m/s: N-51 Automotul

of: 2 Kaki Bukit Ave 2 #01-17

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLU 4938R Yr Regn: 19/11/2008

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis C.C. 1595

Colour: White A/C Insured / Std / NI / NA

Sp. Reading: 92738 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR053 213E 106114691

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55/R16

R: 205/55/R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken (P) / (R)

Front

Rear

R/Bal. 3 mm R/Bal. 4 mm

L/Bal. 3 mm L/Bal. 4 mm

D.O.A. 11/1/2018 D.O.I. 16/1/2018

Survey held at As Above

Des. of Damages: Frt Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range \$3500 - \$4000

4 Days

[Signature]
4/4/2018

RECEIVED 10 APR 2018

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

\$ - RS \$

Photos

Others

TOTAL

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Wear and (\$

Report Format: PRE

Lump Sum / I.B.I.: (\$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Jan 2018		16 Jan 2018 10:12 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	M/S RENSAR ENGINEERING SERVICES PTE LTD, Co. Reg. No.: 201212057C								
Main Claimant:	TEO CHEW KUNG, ID: S0222975G								
Vehicle Reg. No.:	SLU4938R	Date of Loss:	11/01/2018 19:00 - :59						
Claim Type:	TP / SNM18D00243C02	Policy/Cover Note No.:	DMCVSN3095521700						
Vehicle Reg. No. (Insured):	GBE4951D	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/01/2018]								
Adj Asg. Remarks:	DEAR MARCUS, PLEASE SURVEY THIRD PARTY, CHECK CONSISTENCY OF THE DAMAGES ON WITHOUT PREJUDICE BASIS. KINDLY LET US HAVE YOUR RECOMMENDED REPAIR AMOUNT IF THERE IS NO ESTIMATE PROVIDED DURING PRE REPAIR.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

MSME18006308 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 12/01/2018 17:06
 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/01/2018 17:06
Date Of Accident	11/01/2018 19:30
Exact Location Of Accident	BKW TWDS WOODLANDS CHECKPOINT AFTER MANDAI EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLU4938R
Insured/Policyholder	
Name Of Registered Owner	TEO CHEW KUNG
NRIC No	S0222975G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98193758
Alternative Phone No	HOME-67936509

Vehicle Particulars

Manufacturer	TOYOTA
Model	ALTIS

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	ERGO INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPC17S023082
Cover Note Number	

Driver

Name of Driver	TEO CHEW KUNG
NRIC No	S0222975G
Date Of Birth	23/06/1954
Occupation	INDOOR
Date Of Driving Pass	28/01/1976
Driving Experience	41 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98193758
Fax Number	
Contact Number	HOME-67936509
Email Address	NOEMAIL

Address BLK 646 JURONG WEST ST 61 #05-148
 Postcode 640646
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions RAINING
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : NG SIOK ENG
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name KAMPONG UBI NEIGHBOURHOOD POLICE POST
 Police Station Address ROAD: BLK 9 EUNOS CRESCENT #01-2687 , POSTCODE: 400009 ,
 COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-7479999 - FAX NO: 67453410
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT: T/20180112/2095.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBE4951D
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name TEO CHEW KUNG

Approximate Age

Injuries Sustain

Injured person in which vehicle? SLU4938R

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 2

Name NG SIOK ENG

Approximate Age

Injuries Sustain

Injured person in which vehicle? SLU4938R

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode


Sketch Plan Pg. 1


SKETCH PLANIMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As per Police Spd no: 7/20180112/2015

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #3 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180112/2095

1 of 3

Police Station Of Origin:
Kampong Ubi NPP
9 Eunos Crescent #01-2687 SINGAPORE
400009
Tel No: 1800-7479999

Report No. T/20180112/2095

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 12/01/2018 15:10	Vide Report No.:	Station Diary No.: 38
--	------------------	--------------------------

Informant's Particulars

Name of Informant: TEO CHEW KUNG			Address: APT BLK 646 JURONG WEST STREET 61 #05-148 SINGAPORE 640646		
ID Type / ID No.: NRIC NO / S0222975G			Contact No.: Home/Office: Mobile: 98193758		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 63	Date of Birth: 23/06/1954	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Cleaner in offices and other establishments nec			Driving Licence Information: Class: 2B,2A,2,3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 11/01/2018 19:30	Type of Location: EXPRESSWAY
Location: Along Road 1 BUKIT TIMAH EXPRESSWAY				
ALONG BKE HEADING TOWARDS WOODLANDS CHECKPOINT, JUST AFTER MANDAI ROAD EXIT				
Weather: Raining		Road Surface: Wet	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBE4951D	Lorry	TOYOTA	DYNA 3.0 DIESEL TURBO M/T 2WD LORRY	Silver	Slightly Damaged	0
SLU4938R	Car	TOYOTA	COROLLA ALTIS 1.6 AUTO	White	Seriously Damaged	1

Sketch Plan #4 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180112/2095

Police Station Of Origin:
Kampong Ubi NPP
9 Eunos Crescent #01-2687 SINGAPORE
400009
Tel No: 1800-7479999

2 of 3

Report No. T/20180112/2095

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLU4938R	SHC INSURANCE PTE. LTD.	DMPC17S023082	05/12/2017	04/12/2018

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	TEO CHEW KUNG		ID No. S0222975G
Related Vehicle	SLU4938R (Car)		Contact No. 98193758
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL		Class of Driving Licence & Expiry Date Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	12/01/2018		Date Discharge 12/01/2018
No. of Days granted Medical Leave	04	Degree of Injury	Slight

Brief Details.

On 11th of January 2018 at around 1930hrs, I was driving my vehicle, SLU4938R, along BKE heading towards Woodlands Checkpoint direction. As it has been raining non-stop the whole day, the road surface was quite wet and there was a massive traffic jam. I was driving along the 3rd lane of the expressway. I had stopped my vehicle just after Mandai Road exit. Immediately after, I felt an impact from the rear of my vehicle. I then got out and discovered that a lorry had hit onto the rear of my vehicle. The particulars of the driver as follows: Ranganathan Manikandan, G8114848T, Male, DOB: 14/1/1987, working for Fast Track Construction Pte Ltd. We then exchanged particulars. The damages of the vehicles involved are as follows:

- 1) SLU4938R - rear portion slightly to the rear left side, centre bonnet was badly dented, side panel above rear left tyre was dented and rear bumper almost dropped
- 2) GBE4951D - front portion slightly to the right, slightly dented.

I wish to state that there is in-car camera inside my vehicle, however, I didn't noticed the lorry having an in-car camera. On the 12th of January 2018, I then went to Ng Teng Fong General Hospital to seek treatment as I felt some pain on my neck area, shoulder area, and hand areas. I then got 4 days of outpatient sick leave from 12th of January 2018 till 15th of January 2018.

Sketch Plan #5 Pg. 1

SINGAPORE
POLICE FORCE

T/20180112/2095

3 of 3

Police Station Of Origin:
Kampong Ubi NPP
9 Eunus Crescent #01-2687 SINGAPORE
400009
Tel No: 1800-7479999

Report No. T/20180112/2095

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 2 MUHAMMAD ARIF BIN HAIRUDIN

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

12/01/2018 15:10

Officer In Charge Of Case:

TP / AEIT /

Sgt 2 YEO KIA HUAT

Contact No.: 65476325

Classification Of Case:

Authentication Stamp

NP168

SINGAPORE
POLICE FORCE

SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est. Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Jan 2018		16 Jan 2018 10:12 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main		Reference		Claim Details		Documents		Show All
------	--	-----------	--	---------------	--	-----------	--	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	M/S RENSAR ENGINEERING SERVICES PTE LTD , Co. Reg. No.: 201212057C		
Main Claimant:	TEO CHEW KUNG , ID: S0222975G		
Vehicle Reg. No.:	SLU4938R	Date of Loss:	11/01/2018 19:00 - :59 [109 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D00243C02	Policy/Cover Note No.:	DMCVSN3095521700
Vehicle Reg. No. (Insured):	GBE4951D	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Final Rpt due 25/01/2018]		
Adj Asg. Remarks:	DEAR MARCUS, PLEASE SURVEY THIRD PARTY, CHECK CONSISTENCY OF THE DAMAGES ON WITHOUT PREJUDICE BASIS. KINDLY LET US HAVE YOUR RECOMMENDED REPAIR AMOUNT IF THERE IS NO ESTIMATE PROVIDED DURING PRE REPAIR.		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLU4938R (SNM18D00243C02)**
[GBE4951D]

TP

TEO CHEW KUNG

Jan 11 2018 7:00PM

[M/S RENSAR ENGINEERING SERVICES PTE LTD]
N-51 Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/04/18 10:50	LKK SURVEYOR PHOTO 1	 Load PDF	
2	10/04/18 13:43	LKK SURVEYOR PHOTO 2	 Load PDF	
3	10/04/18 13:43	LKK SURVEYOR PHOTO 3	 Load PDF	
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/01/18 10:16	INSURED SAS REPORT GBE4951D	 Load PDF	
2	16/01/18 10:16	THIRD PARTY SLU4938R -FROM N-51 -PRS LTR	 Load PDF	
3	16/01/18 10:18	THRID PARTY SAS REPORT SLU4938R	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118000953/WBS2
 Date: 13/04/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN3095521700
 Claimant Vehicle No: SLU4938R Insured Vehicle No: GBE4951D
 Date of Loss: 11/01/2018 Nature of Claim: TP Claim No: SNM18D00243C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLU4938R Engine No: 3ZZ4784862
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Chassis No: MR053ZEE106114691
 Reg. Date: 19/11/2008 (Man. Year: 2008) Odometer: 92738 km
 Colour: White
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
 Front Left Side: Falken 3 mm Rear Left Side: Falken 4 mm
 Front Right Side: Falken 3 mm Rear Right Side: Falken 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 16/01/2018
 Date Inspected: 16/01/2018 Inspected At: N-51 Automotive Pte Ltd (HQ)
 BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB
 Singapore 417921
 Estimated Period of Repair: 4.0 days

Adjuster: Teo Cheng Ming Wilson

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/13/2018

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500.00 - \$4,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Apr 2018)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLU4938R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >