

ASS. REC. BY:

REF:

TJ /

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lump Sum: _____

1.5.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

SGG 946

Yr Regn: _____

04.16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Honda Odyssey

C.C

2356

Colour

M. Grey

A/C

Insured / Std / NI / NA

Sp. Reading

23848

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

JHMRC1890 GC 203121

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inop / Jammed / Leaked / Burnt or

Brake: Inop / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size: _____

F: _____

215/55R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. _____

8 mm

R/Bal. _____

8 mm

L/Bal. _____

8 mm

L/Bal. _____

8 mm

D.O.A. _____

12/1/18

D.O.I. _____

29/1/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rt o/s door

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

30/1 File pass to Catherine

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee

Transportation

S - RS - SI

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 9752D

Vehicle Details

Vehicle No.: SGQ94G

Vehicle to be Exported: Yes

Intended De-registration
Date: 19 Jan 2018

Vehicle Make: HONDA

Vehicle Model: ODYSSEY 2.4 EXV-S CVT
SR

Primary Colour: Grey

Manufacturing Year: 2016

Engine No.: K24W72011421

Chassis No.: JHMRC1890GC203121

Maximum Power Output: 129.0 kW (172 bhp)

Open Market Value: \$30,432.00

Original Registration Date: 07 Apr 2016

First Registration Date: 07 Apr 2016

Transfer Count: 0

Actual ARF Paid: \$34,605.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 06 Apr 2026

PARF Rebate Amount: \$25,953.00

Intended COE Rebate Details

COE Expiry Date: 06 Apr 2026

COE Category: B - Car above 1600cc or
97kW (130bhp)

COE Period(Years): 10

QP Paid: \$46,502.00

COE Rebate Amount: \$37,201.00

Total Rebate Amount: \$63,154.00

The information contained herein is correct as at 19 Jan 2018

OK