

INSURANCE

INS. CASE OWNER:

Zuhairah

CC4 / III18000960 / KWS3

LKK:

IDAC:

Surveyor:

KSU

DOI:

ASSIGNMENT

24/1/18

Date / Time:

15/01/18

Registered in Merimen:

16/01/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHA 671H

Claim No.:

Name of Insured:

CTPL

Policy No.:

Insured Tel No.:

HP:

Make / Model:

HYUNDAI SONATA - 2.0 (A)

Excess Sec II : \$5

D.O.A: 12/01/18

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

LO NAM FATT

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

% Final ? Yes / No

GO 945



INSRS:

WSP: Cheng Hoe Motor

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

13/01/18 (Wian) * Please verify the place of accident.

14/01/18

seek liability via merimen

20/01/18

Mandate approve via merimen

28/01/18

File pass to typist type report

3/01/18

seek mandate via merimen

5/01/18

Mandate approve via merimen

* Wt figure not tally.

RECEIVED 20 NOV 2018

PRELIMINARY ADVICE Date/Time:

Sent By:

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

20/01/18

Confirm with

200

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No. : 26

If NO or B 28, Ass. Lia :

Repair Cost:

\$5

3432.47

Loss of Rental (LOR):

\$5

(days)

Loss of Use (LOU):

\$5

300.00

(S 100 x 3 days)

Loss of Income (LOI):

\$5

(S x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

\$5

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/ Independent)

Legal Cost

\$5

Total:

\$5

3732.47

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5

3732.47

Name 1:

Cheng Hoe Motor Pte Ltd

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

043 days

Res.: Yes or No

Lum Sum: _____

1.5.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

SGA 946

Yr Regn: _____

04, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

Honda Odyssey

c.c

2356

Colour: _____

N. Grey

A/C

Insured / Std / NI / NA

Sp. Reading: _____

23848

T/Radio: Insured / Std / NI / NA

Eng No: _____

C/No: _____

JHMRC1890 GC 203121

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order? / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

215/55R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal: _____

8

mm

Rear

R/Bal: _____

8

mm

L/Bal: _____

8

mm

L/Bal: _____

8

mm

D.O.A. _____

12/1/18

D.O.I. _____

29/1/18

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rt O/S door

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

30/1 File pass to Catherine

83207.92 Cashm Erida

Low

(3X100)

(201. \$ 625.92
17%)

Data/Time, File Pass to?



: Prel. Report



: Final Report

1)

Data/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: _____



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee

Transportation:

S - RS, SI

Phone

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I. (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CC4/III18000960/Kws3

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 16-01-2018



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 6971H	Veh. Inspected	SGQ 94G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	16/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	12/01/2018	Inspection Date	29/01/2018
Survey held at	CHENG HOE MOTOR PTE LTD 10 ANG MO KIO IND PARK 2A #01-04 ANG MO KIO AUTOPOINT . SINGAPORE 568047		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9752D
Vehicle Details	
Vehicle No.:	SGQ94G
Vehicle to be Exported:	Yes
Intended De-registration Date:	19 Jan 2018
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 EXV-S CVT SR
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	K24W72011421
Chassis No.:	JHMRC1890GC203121
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$30,432.00
Original Registration Date:	07 Apr 2016
First Registration Date:	07 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$34,605.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Apr 2026
PARF Rebate Amount:	\$25,953.00
Intended COE Rebate Details	
COE Expiry Date:	06 Apr 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,502.00
COE Rebate Amount:	\$37,201.00
Total Rebate Amount:	\$63,154.00

The information contained herein is correct as at 19 Jan 2018

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST 201001158E RCB NO:201001158E

M/S : INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100

FAX: 62247743

ATTN: Motor Claim Department

Estimate No: ES1890095/AMK

Date: 29 Jan 2018

Policy No: A28929261QMX

Veh Reg No: SGQ94G

Make/Model: HONDA ODYSSEY 2.4L
A

WS Ref: TP/INDIA/AMK

Claim Type: Third Party

Accident Date: 12/01/2018

TP Veh Reg No: SHA6971H

Chassis No: JHMRC1890GC203121

Engine No: K24W72011421

Reg. Date: 07/04/2016

Estimate Repair Cost to Vehicle No :SGQ94G

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 FRONT RH DOOR	897.80	1 PC	897.80	✓
2 FRONT RH DOOR WINDOW GLASS	542.80	1 PC	542.80	✓
3 FRONT RH DOOR SIDE MIRROR ASSY	1,304.00	1 PC	1,304.00	✓
4 FRONT RH DOOR SIDE MIRROR OUTER COVER	74.70	1 PC	74.70	✓
5 FRONT RH DOOR OUTER MOULDING	82.30	1 PC	82.30	✓
6 FRONT RH DOOR POWER WINDOW MOTOR WITH REGULATOR	392.60	1 PC	392.60	✓
7 FRONT RH DOOR FRAME STICKER	35.60	1 PC	35.60	✓
			3,329.80	
		Less 20%	665.96	2,663.84
Special Net				
8 FRONT RH DOOR WINDOW GLASS TINTED FILM	100.00	1 PC	100.00	✓
			100.00	100.00
Labour				
9 REMOVE & REFIX FRT RH DOOR & ATTACHMENTS; KNOCKING & REPAIR FRT RH FENDER & REALIGN THE SAME	500.00	1 LA	500.00	400
10 PUTTY & RESPRAY FRT RH FENDER, FRT RH DOOR & SIDE MIRROR & ALL AFFECTED AREAS	500.00	1 LA	500.00	450
11 REMOVE & REFIX FRT RH DOOR WINDOW GLASS & RESET CENTRAL LOCKING	60.00	1 LA	60.00	✓
12 RUSTPROOFING	60.00	1 LA	60.00	30
			1,120.00	1,120.00

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST: 201001158E RCB NO: 201001158E

M/S : INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100

FAX: 62247743

ATTN: Motor Claim Department

WS Ref: TP/INDIA/AMK

Claim Type: Third Party

Accident Date: 12/01/2018

TP Veh Reg No: SHA6971H

Estimate No: ES1890095/AMK

Date: 31 Jan 2018

Policy No: A28929261QMX

Veh Reg No: SGQ94G

Make/Model: HONDA ODYSSEY 2.4L
A

Chassis No: JHMRC1890GC203121

Engine No: K24W72011421

Reg. Date: 07/04/2016

Estimate Repair Cost to Vehicle No :SGQ94G

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
Supplementary 1				
List Price				
1 FRONT RH DOOR SIDE MIRROR LOWER COVER	47.90	1 PC	<i>mit</i> 47.90 ✓	
			47.90	
		Less 20%	9.58	38.32
Total				SS 38.32
GST Amount				SS 2.68
Total Amount Payable				SS 41.00

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before spray painting
• To display damaged parts during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST 201001158E RCB NO 201001158E

M/S: INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100

FAX: 62247743

ATTN: Motor Claim Department

Estimate No: ES1890095/AMK

Date: 29 Jan 2018

Policy No: A28929261QMX

Veh Reg No: SGQ94G

Make/Model: HONDA ODYSSEY 2.4L A

Chassis No: JHMRC1890GC203121

Engine No: K24W72011421

Reg. Date: 07/04/2016

WS Ref: TP/INDIA/AMK

Claim Type: Third Party

Accident Date: 12/01/2018

TP Veh Reg No: SHA6971H

Estimate Repair Cost to Vehicle No :SGQ94G

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 FRONT RH DOOR	897.80	1 PC	897.80	✓
2 FRONT RH DOOR WINDOW GLASS	542.80	1 PC	542.80	?
3 FRONT RH DOOR SIDE MIRROR ASSY	1,304.00	1 PC	1,304.00	✓
4 FRONT RH DOOR SIDE MIRROR OUTER COVER	74.70	1 PC	74.70	✓
5 FRONT RH DOOR OUTER MOULDING	82.30	1 PC	82.30	✓
6 FRONT RH DOOR POWER WINDOW MOTOR WITH REGULATOR	392.60	1 PC	392.60	?
7 FRONT RH DOOR FRAME STICKER	35.60	1 PC	35.60	✓
			3,329.80	
		Less 20%	665.96	2,663.84
Special Net				
8 FRONT RH DOOR WINDOW GLASS TINTED FILM	100.00	1 PC	100.00	?
			100.00	100.00
Labour				
9 REMOVE & REFIX FRT RH DOOR & ATTACHMENTS; KNOCKING & REPAIR FRT RH FENDER & REALIGN THE SAME	500.00	1 LA	500.00	400
10 PUTTY & RESPRAY FRT RH FENDER, FRT RH DOOR & SIDE MIRROR & ALL AFFECTED AREAS	500.00	1 LA	500.00	450
11 REMOVE & REFIX FRT RH DOOR WINDOW GLASS & RESET CENTRAL LOCKING	60.00	1 LA	60.00	✓
12 RUSTPROOFING	60.00	1 LA	60.00	30
			1,120.00	1,120.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO 201001158E

M/S : INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100 FAX: 62247743

ATTN: Motor Claim Department

WS Ref: TP/INDIA/AMK

Claim Type: Third Party

Accident Date: 12/01/2018

TP Veh Reg No: SHA6971H

Estimate No: ES1890095/AMK

Date: 29 Jan 2018

Policy No: A28929261QMX

Veh Reg No: SGQ94G

Make/Model: HONDA ODYSSEY 2.4L
A

Chassis No: JHMRC1890GC203121

Engine No: K24W72011421

Reg. Date: 07/04/2016

Estimate Repair Cost to Vehicle No :SGQ94G

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
		Total		S\$ 3,883.84
		Add GST @ 7%		271.87
		Total Amount Payable		<u>S\$ 4,155.71</u>

VEHICLE LYING AT :
NO.10 ANG MO KIO INDUSTRIAL PARK 2A
#01-04 AMK AUTOPOINT
SINGAPORE 568047
TEL : 64812001

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE

03/10/2018

View Received Message

This mail is associated with :

***SGQ94G (MCT18010371)**
[SHA6971H]

TP

CHOW WEI CHOO

Jan 12 2018 12:00AM

[COMFORT TRANSPORTATION PTE LTD]

Cheng Hoe Motor Pte Ltd


[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 03/10/2018 15:08 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (\$3732.47) - SGQ94G - Claim Handler: Zuhaidah Bte Samsuri

Approved:3732.47.

DOCUMENTS SUMMARY

There are no documents.



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

Date: 25 AUG 2018

India Int'l Insurance Pte Ltd
C/O LLK Auto Consultants

Attn : THE MOTOR CLAIMS DEPT

Dear Sir / Madam

**ACCIDENT INVOLVING VEHICLE NO. SGQ94G & SHA6971H ON 12/01/2018
21A JALAN KECHOT.**

We are authorized by SGQ94G for their above matter.

Record reveals that you are the insurer of SHA6971H. We therefore wish to seek compensation from you as below:-

1. Cost of Repairs	S\$ 3432.50
2. Loss of Use (3 x \$100/day)	S\$ 300.00
3. Hire of Vehicle	S\$ 0.00
4. LTA Search Fee/GIA Reports	S\$ 0.00
TOTAL	S\$ 3732.50

Please let us have your reply soonest possible.

Thank you.

Yours faithfully



LETTER OF AUTHORISATION

(FOR PROPERTY DAMAGE CLAIM ONLY)

Re: Motor Insurance Claim SGQ94G
in respect of the traffic accident on 12/01/2018
at/along 21A Jalan Kechot

I/We, Chow Wei Choo
NRIC S7009752D of 1 Jalan Chempedak S578384

owner of motor vehicle SGQ94G, insured by MSIG Insurance (S)
Pte Ltd under policy no. A28929261QMX

hereby authorise **M/s CHENG HOE MOTOR PTE LTD** on Blk 1019 Yishun Industrial Park A #01-374 Singapore 768761, to act as my/our representative in my/our claim against the owner /driver of motor vehicle SHA6971H in respect of the above-mentioned accident.

I/We further authorise that any payment due to me/us from the aforesaid claim is to be directed to my/our abovenamed representative.

And I/We hereby indemnify my/our abovenamed representative against any claim and/or damage which may arise from any action taken on my/our behalf.

I/We affirm all the above by my/our signature below.

Signed : 
Date : 13/01/2018

Adm: Joy

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MCT18010371
Claimant Ref: SGA 94G

This Discharge Voucher applies strictly for Claimant's claim for property damages only and does not constitute a full discharge for any other claims or further claims whatsoever present or future that may manifest arising directly or indirectly from this accident.

This settlement terms herein is without an admission of liability on the part of the claimant and the settlement terms should not be used as evidence in any related suits or claims arising from this accident.

We/I, Cheng Hoe Motor Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 3,432.47 (repair cost), S\$ 300.00 (loss of use/~~cost~~); S\$ NIL (search fee), vehicle no. SGQ 94G that was damaged pursuant to the accident which occurred on 12/01/2018 (date) at 21A JALAN KECHOT (location) involving vehicle no. SGA 8871H (insured vehicle). This is pursuant to the inspection conducted on 29/01/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner CHOW WEI CHOO ("the third party claimant") of vehicle no. SGA 94G to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SGQ 94G (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 3,732.47 to Cheng Hoe Motor Pte Ltd

Dated this day of 01 2018 20

CLAIMANT:

Signature: *Wendy Ng*

Name: Wendy Ng

NRIC: S7017853B

Address: c/o Blk 1019 Yishun Ind
Park A #01-374 S 768761

Nationality: Singapore

Occupation: _____

WITNESS:

Signature: *KSC*

Name: _____

NRIC: _____

Address: _____

Nationality: _____

Occupation: _____

Signed by appointed Surveyor

51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761

TEL: 67556142 (YIS) FAX: 67557719 (YIS)

Email: chmotor@singnet.com.sg

GST:201001158E RCB NO:201001158E

PAGE:1

1/0 LKR (V/M in)

M/S : INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET

#04/#05 IOB BUILDING

SINGAPORE 049711

TEL: 63476100 FAX: 62247743

ATTN: THE MOTOR CLAIMS DEPT

TAX INVOICE

NO :ST1881285
DATE :25/11/2018
A/C CODE: :INDIA
JOB NO :JC1598676
WS REF :TP III
SALESMAN :JUNE
VEH REG :SGQ94G
MILEAGE :0KM
MAKE/MODEL :HONDA ODYSSEY 2.4L A

Description	Quantity	Unit Price	Amount
		<u>S\$</u>	<u>S\$</u>
1 SUPPLY ALL NECESSARY PARTS, PERFORM NECESSARY PANEL BEATING AND RESPRAY PAINTING (As recommended by your appointed surveyor)	1 PC	3,207.92	3,207.92

TOTAL QTY: 1 PC TOTAL **S\$ 3,207.92**
ADD GST @ 7% 224.55
GRAND TOTAL **S\$ 3,432.47**

For Cheng Hoe Motor Pte Ltd



AUTHORISED SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Jan 2018 Edit Reg		15 Jan 2018 00:00 Edit Adj Rpt	S\$3,207.92 Edit Estimates	S\$3,207.92 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	CHOW WEI CHOO, ID: S7009752D								
Vehicle Reg. No.:	SGQ94G	Date of Loss:	12/01/2018 00:00 - :59 [21 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18010371	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHA6971H	Policy No. (Claimant):	A28969261QMX						
		Excess:							
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Bldg 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 25/01/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (03/10/2018): Alert - Adj Mandate Approved (S\$3732.47) - SGQ94G - Claim Handler: Zuhaidah Bte ... - III_SG (22/01/2018): Alert - Adj Mandate Approved (S\$0.00) - SGQ94G - Claim Handler: Zuhaidah Bte Sam...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGQ94G (MCT18010371)
[SHA6971H]
TP
CHOW WEI CHOO
Jan 12 2018 12:00AM
[COMFORT TRANSPORTATION PTE LTD]
Cheng Hoe Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Photos/Images									3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	03/10/18 14:57	General View								☒	
2	03/10/18 14:57	General View								☒	
3	03/10/18 14:57	General View								☒	
4	03/10/18 14:57	General View								☒	
5	03/10/18 14:57	General View								☒	
6	03/10/18 14:57	General View								☒	
7	03/10/18 14:57	General View								☒	
8	03/10/18 14:57	General View								☒	
9	03/10/18 14:57	General View								☒	
10	03/10/18 14:57	General View								☒	
11	03/10/18 14:57	General View								☒	
12	03/10/18 14:57	Reinspection Photo								☒	
13	03/10/18 14:57	Reinspection Photo								☒	
14	03/10/18 14:57	Reinspection Photo								☒	
15	03/10/18 14:57	Reinspection Photo								☒	
16	03/10/18 14:57	Reinspection Photo								☒	
17	03/10/18 14:57	Reinspection Photo								☒	
Documentation									1 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	16/01/18 16:04	ACKNOWLEDGEMENT EMAIL TO III DD 15.01.2018								☒	
2	16/01/18 16:04	TP GIA REPORT								☒	
3	31/01/18 09:29	TP ESTIMATE- MARKED								☒	
4	27/09/18 14:11	LOD								☒	
5	29/11/18 08:56	WORKSHOP INVOICE								☒	
6	29/11/18 08:56	AUTHORISATION TO ACT FORM								☒	
7	29/11/18 08:56	DISCHARGE VOUCHER								☒	
No	Finalized On	India International Insurance Pte Ltd (HQ)							Thumbnail	Print	
1	17/01/18 08:57	Singapore Accident Statement								☒	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

--

Show Remarks To: ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18000960/KWA3Q2

Date: 29/11/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

MCOM0015

Claimant Vehicle No : SGQ94G

Insured Vehicle No : SHA6971H

Date of Loss: 12/01/2018

Nature of Claim:

TP

Claim No: MCT18010371

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SGQ94G

Make & Model:

HONDA ODYSSEY, 2.4 EXV-S CVT SR (A)

Engine No:

K24W72011421

Reg. Date:

07/04/2016 (Man. Year: 2016)

Chassis No:

JHMRC1890GC203121

Colour:

Metallic Grey

Odometer:

23848 km

Engine Capacity:

2356 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

215/55 R17

Rear Tyre Size:

215/55 R17

Front Left Side:

Dunlop 8 mm

Rear Left Side:

Dunlop 8 mm

Front Right Side:

Dunlop 8 mm

Rear Right Side:

Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,802.16	2,267.92	534.24	19.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,120.00	940.00	180.00	16.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,922.16	3,207.92	714.24	18.21
+ GST 7.00/7.00% (S\$)	274.55	224.55	50.00	18.21
Nett Amount (S\$)	4,196.71	3,432.47	764.24	18.21
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
Nett Liability (S\$)		3,732.47		

INSPECTION

Date of Assignment:

15/01/2018

Date Inspected:

29/01/2018 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)

Blk 1019 #01-374/382, Yishun Industrial Park A

Singapore 768761

Estimated Period of Repair:

3.0 days

Adjuster: KENNETH KONG**Manager:** VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Sep 2018)
Parts:	M1-SUV	HONDA ODYSSEY 2.4 EXV-S CVT SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGQ94G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Bent	897.80 FL	*897.80 FL
2	1		*FRONT RH DOOR WINDOW GLASS	Serviceable	542.80 FL	*- FL
3	1		*FRONT RH DOOR SIDE MIRROR ASSY	Broken	1,304.00 FL	*1,304.00 FL
4	1		*FRONT RH DOOR SIDE MIRROR OUTER COVER	Missing	74.70 FL	*74.70 FL
5	1		*FRONT RH DOOR OUTER MOULDING	Dented	82.30 FL	*82.30 FL
6	1		*FRONT RH DOOR POWER WINDOW MOTOR WITH REGULATOR	Mtg Cracked	392.60 FL	*392.60 FL
7	1		*FRONT RH DOOR FRAME STICKER	Necessary	35.60 FL	*35.60 FL
8	1		*FRONT RH DOOR WINDOW GLASS TINTED FILM	Not Necessary	100.00 FS	*- FS
9	1		*FRONT RH DOOR SIDE MIRROR LOWER COVER	Missing	47.90 FL	*47.90 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					3,477.70	2,834.90
- List Item Discount on L Items 20.00/20.00% (S\$)					675.54	566.98
Total Parts (S\$)					2,802.16	2,267.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIX FRT RH DOOR & ATTACHMENTS KNOCKING & REPAIR FRT RH FENDER & REALIGN THE SAME	New	500.00	400.00
2	PUTTY & RESPRAY FRT RH FENDER ,FRT RH DOOR & SIDE MIRROR & ALL AFFECTED AREAS	New	500.00	450.00
3	REMOVE & REFIT FRT RH DOOR WINDOW GLASS & RESET CENTRAL LOCKING	New	60.00	60.00
4	RUSTPROOFING	New	60.00	30.00
Gross Labour Cost (S\$)			1,120.00	940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >