Surveyor: XLL.

REF: ASM (AXA)

C15397 (-2020)

ASSIGNMENT

From: Date: 17/4/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: PC 5550R

at Workshop m/s Lexbuild

of No. 2 Woodland Sector 1 #05-12 Singapore 738068

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

10.30am - 11.30am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: PC 5550R Yr Regn: 04 Aug 2010

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: King long XMQ6117K 6653

Colour Silver A/C: Insured / Std / NI / NA

Sp.Reading 407322 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: LA6R1FSH3AB101782

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 11R 22.5

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	17-04-18

Survey held at W/S 11:15 AM

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or N/S FA

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
17/4	Finalized $1160 with Elson

Date/Time. File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time. File Return to?

2)

Report Format :

Lump Sum / I.B.I: ($)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp ($) ☐ Interview ($) ☐ Tech. Invs ($) ☐ Weekend ($)

Survey Fee:

Transportation: ___S + RS___SI

Photos

Others

TOTAL