Tanjhin REF: III

ASSIGNMENT

From: Date: 22/01/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKX 8238 Y

at Workshop m/s: Cycle & Carriage Automotive

of: 209 Pandan Gardens

Insured:

Policy No.:

Claims No.:

Sum Insured: Excess:

(Client's Record): After 2.30 pm.

Make of Veh:

(Policy Condition)

N/S	O/S
	X

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKX8238Y Yr Regn: 2015 Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Mitsubishi ASX D.O: 1998

Colour: Silver A/C: Insured / Std / NI / NA

So.Reading: 36050 T.Radio: Insured / Std / NI / NA

Eng/No:

C/No: JMFXTGA2WFZ008677.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55R18

R: " "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	22/1/18 @ 1630

Survey held at: C&C Pandan Gdns.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction

Date/Time File Pass to?

1)

Date/Time File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp $ ☐ Interview $ ☐ Tech Inv $ ☐ Weekend $

Survey Fee

Transportation

Photos

Other

TOTAL

Report Format :

Lump Sum / I.B / $