

CS/MSIG18001006/Tlqdzcz

m & m

Merimen

Taufik

Fievel Foo

MSIG

17/01/2018 @ 9:18am

Ref: 18001006

OBJ: (1) WS/TMHS, GP/LS, DVA, DVA, DVA, DVA

To: Dept of Transport

XB 8426H (TRB 8989X)

SKQ 5059D

By: Mr. M. M.

Public Trailer Equipment Suppliers

9099 9979

At:

56 tuas Road

Ref: 18001006

28990449 MCY

546368

Sum Insured:

Make of Vch:

Chassis Brand:

15/01/2018

CA - REV - REP. / REV 24 HRS

'wp'

Insp: 28 Jalan Buroh

Time: 9:35am

@ 17/1/18

Steven

(1)

Time: 9:35am

At: 56 tuas Road

✓

By: Mr. M. M.

VR 8426H - X

SKQ 5059D - Y

18/01/18 @ 6:00pm revised to Fievel Foo via Merimen.

Taufik finalised with workshop final fig & 2351, 6 days.

(had to 2085, 47%)

Tagline

MSIG

Form Date 17/10/2018

XB8426H.

Page 2 of 3 at

Estimated Date

MS/TP RES CD RES EVALUATION

To inspect vehicle No XB8426H  
at location of Public Trailer Equipment Suppliers  
28 Jalan Buroh, 619484

Insured

Policy No

Claims No

Sum Insured

Excess

Client's Record


Steven @ 9099 9979

Make of car

After 12pm

Policy Condition

Remark: The veh had commenced its  
repair at the time of inspection.



Ball or Market Value

CAD Accident Report Consistent? Yes or No

GIA PP Report Consistent? Yes or No

Est. Repairs 6 days Rep: Yes or No

Est. Sum 3% 3 Year Yes or No

CA REV REP 24 HRS 'wp'

Date Person Contacted

Vehicle IN/OUT

Truck Trailer

Make Mitsubishi FP517

11945

Color Red

Se Reading

Eng No

C No

FP517DRZKDER

Gen. Cond Good Fair Poor Burnt

Steering In order Jammed Leaked Burnt

Brakes In order Jammed Leaked Burnt

Mod 1.8 SRM STD A/R

Tyre Size

10.00 R15

R

27 (0)

BS/DUN/EXNOVA G/MS LIZA/MLO/HTS/PR/SUM

TOYO/YOKO or

Double Gin.

Front

Rear

R Ba

8

R Ba

8/8

L Ba

8

L Ba

8/8

DCA

DCA

Survey report

28 Jln Buroh. 17/11/18

Des of Damages Fr

Rear

OS NIS UG Roof hood

The U/G Chassis frame

Body Structure affected due to collision

Signature

7/3/2018

RECEIVED 24/11/2018

One Time Fee Pass

☐

Prel. Report

☐

Final Report

See Time Rep Return

Days Of Repair 6

Reserve No of Tyre 1

Add Fee

☐

Service Fee

☐

Repair Fee

☐

Material Fee

☐

Other Fee

Survey Fee

Transport Fee

Other Fee

Other Fee

Other Fee

Other Fee

Other Fee

Other Fee

200

10

210




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18001006/T1qd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 17-01-2018	
			Code : MSG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SKQ 5059D	Veh. Inspected	XB 8426H	
Policy No.	28990449MCY	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	MERIMEN (FIEVEL FOO)	Assign Date	17/01/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		C.C	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	15/01/2018	Inspection Date	17/01/2018	
Survey held at	28 JALAN BUROH			
Repairer	PUBLIC TRAILER EQUIPMENT SUPPLIES P/L			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Reference No. : 9/MSG/18001006/TL9A3  
Policy Type: OD / TP / TP RES / TL / EVA

XB 8476H

**Typist**

**(1) Office Assign Form**

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code	✓			
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

### (1) Assignment Form

C	Vehicle No	✓		
C	Regn Month/Year	✓		
N	Vehicle Type	✓		
N	Make & Model	✓		
C	Engine Capacity. (C.C)	✓		
N	Colour	✓		
C	Odometer. (Sp.Reading)			
C	Chassis No	✓		
N	General Condition	✓		
N	Steering	✓		
N	Brake	✓		
N	Modification (Modi)	✓		
C	Tyre Size	✓		
N	Tyre Make	✓		
C	Tyre Balance	✓		
C	Date of Inspection	✓		
N	Survey held	✓		
N	Des.of Damages	✓		

### C Damaged Vehicle Photographs Uploaded

N	ALL Parts condition
C	Market Value for OD cases
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)
C	Days of repair
C	Finalised Amount
C	Re-inspection Cases to Finalize within 5 Days

**C** Resurvey photo Uploaded

Chr 09/3/18

Date \_\_\_\_\_

21/05/2014

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Jan 2018		17 Jan 2018 09:18 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	<b>BORNEO MOTORS (S) PTE LTD,</b> Co. Reg. No.: 196700086Z		
Main Claimant:	<b>VAS TRANS SERVICES PTE LTD</b>		
Vehicle Reg. No.:	<b>XB8426H</b>	Date of Loss:	15/01/2018 16:00 - :59
Claim Type:	<b>TP</b>	Policy/Cover Note No.:	28990449MCY (Comprehensive) Coverage: 01/07/2017 - 30/06/2018
Vehicle Reg. No. (Insured):	<b>SKQ5059D</b>	Policy No. (Claimant):	
		Excess:	
Repairer:	<b>Public Traller Equipment Suppliers Pte Ltd (HQ)</b> 56 Tuas Road, Tuas - Tel:		
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... <b>[Imm.Advice due 18/01/2018]</b>		
Adj Asg. Remarks:	Survey today, anytime after 12pm		

### ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Eileen Ang

---

**From:** Foo Ai Ngoh  
**Sent:** Tuesday, 16 January, 2018 4:16 PM  
**To:** Eileen Ang  
**Cc:** Fievel Foo  
**Subject:** FW: ACCIDENT INVLG SKQ5059D & XB8426H (TRB8989X) ON 15.01.18  
**Attachments:** TRB8989X\_ACC\_180116\_QT.pdf; Authorisation Letter\_PTES\_XB8426H\_TRB8989X\_SKQ5059D.jpg

Dear Eileen,  
For your action please.....

Ai Ngoh

**From:** Public Trailer [mailto:publictrailer@gmail.com]  
**Sent:** Tuesday, 16 January, 2018 3:45 PM  
**To:** Foo Ai Ngoh <aingoh\_foo@sg.msig-asia.com>  
**Subject:** ACCIDENT INVLG SKQ5059D & XB8426H (TRB8989X) ON 15.01.18

Dear Ms Foo,

As spoke, please find attached attachments.


Kindly assist.

Thank you.

Regards,  
Steven  
hp: 9099 9979

---

Public Trailer Equipment Supplies Pte Ltd  
Yard: 28 Jalan Buroh S(619484)  
Mailing/Billing Address: Blk 454 Choa Chu Kang Ave 4 #14-117 S(680454)  
Tel: 68631728 Fax: 68631773  
[www.publictrailer.com](http://www.publictrailer.com)



---

### CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Note: This document has not been finalised.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Fievel Foo Wenyao

Date: 18 Jan 2018

**Preliminary Advice**

Insured Vehicle No	: SKQ5059D	Accident Date	: 15/01/2018
TP Vehicle No	: XB8426H	Assignment Date	: 17/01/2018
Make	: ISUZU NHR69EU3ES	Est. Duration of Repair	: 6
Date of Inspection	: 17/01/2018		
Inspection At	: PUBLIC TRAILER EQUIPMENT SUPPLIER		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,436.00
Revised Amount	:S\$	2,351.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,351.00
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 0956C

### Vehicle Details

Vehicle No.: XB8426H

Vehicle to be Exported: No

Intended De-registration Date: 18 Jan 2018

Vehicle Make: MITSUBISHI

Vehicle Model: FP517DR2RDEB

Primary Colour: White

Manufacturing Year: 2003

Engine No.: 6D24338903

Chassis No.: FP517DA03752

Maximum Power Output: -

Open Market Value: \$62,644.00

Original Registration Date: 16 Oct 2003

First Registration Date: 16 Oct 2003

Transfer Count: 1

Actual ARF Paid: \$3,133.00

### Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

### Intended COE Rebate Details

COE Expiry Date: 15 Oct 2018

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 5

PQP Paid: \$34,609.00

COE Rebate Amount: \$5,124.00

Total Rebate Amount: \$5,124.00

### Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 18 Jan 2018

OK



(Draft)

MSAT18008306 / Sng Ah Tee Motor & Panel Service Pte Ltd - Pioneer  
 ENTRY DATE & TIME: 17/01/2018 09:37  
 SUBMITTED BY: [To Be Confirmed]

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report 17/01/2018 09:37  
 Date Of Accident 15/01/2018 16:50  
 Exact Location Of Accident ALEXANDRA ROAD  
 Country/State of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number XB8426H  
**Insured/Policyholder**  
 Name Of Registered Owner VAS TRANS SERVICES PTE LTD  
 Co Reg No 199500956C  
 Email Address MENA.CHONG\_VAS@YAHOO.COM.SG  
 Mobile Phone No  
 Alternative Phone No Office-63395583

### Vehicle Particulars

Manufacturer MITSUBISHI  
 Model FP517DR2RDEB-11.9 D (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.  
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT  
 Fleet Policy NO  
 Policy Number DMCVSN1668751701  
 Cover Note Number

### Driver

Name of Driver LIU ZHONGSHAN  
 Passport No/FIN G5288477U  
 Date Of Birth 17/08/1976  
 Occupation OUTDOOR  
 Date Of Driving Pass 24/09/2012  
 Driving Experience 5 YEARS AND 3 MONTHS  
 Gender MALE  
 Mobile Number (LOCAL) +65-85357814  
 Fax Number  
 Contact Number  
 EMail Address NOEMAIL  
 Address NIL  
 Postcode

1/17/2018

E-FILE

Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

**General Information of the Accident**

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

**Other Information**

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

**Details of Police Action**

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

**Circumstances of Accident**

ON 15/01/2018 @ ABT 1650HRS. I WAS WAITING THE TRAFFIC LIGHT CHANGE TO GREEN WITH MY COMPANY PRIME MOVER (XB8426H) WITH ENGAGE A LOADED 40FT TRAILER(TRB8989X) ALONG ALEXANDRA ROAD ON THE SECOND LANE. WHILE WAITING, SUDDENLY I FELT AN IMPACT FROM BEHIND, I THEN CAME DOWN FROM MY PRIME MOVER & DISCOVERED THAT THERE IS VEHICLE B (SKQ5059D) KNOCKED ONTO MY TRAILER. NO ONE WAS INJURED. THAT'S ALL.

**Attachment(s)**

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	SKQ5059D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2


## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

I AM AWARED THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

## QUOTATION

To: MSIG Insurance (Singapore) Pte Ltd  
Attn: Motor Claims Department

Quotation No. Q180087  
Terms COD  
Date 16/01/2018  
Vehicle No. TRB8989X VAS

As per your request, we are pleased to quote as follows:

Description	Quantity	Unit Price	Total
CAR-CARRIER RAMP CYLINDER ASSY - LH & RH <i>LH-X m RH-bt</i>	2.00	\$1,485.00	\$2,970.00
LABOUR & EQUIPMT - REMOVE & REFIT WORK - FOR LHS & RHS CYLINDERS	2.00	\$400.00	\$800.00 <i>400</i>
RESPRAY PAINTING - W/ ONE COAT PRIMER & ONE COAT FINISHING - COL: VAS RED	1.00	\$450.00	\$450.00 <i>250</i>
V OIL, HYD 68, 18L	2.00	\$108.00	\$216.00
			<i>2351</i>
		Subtotal	\$4,436.00
		GST (%)	7%
		GST	\$310.52
		Grand Total	\$4,746.52

Remarks: This is an estimated cost of repair for the vehicle reg. no. TRB8989X (XB8426H) which damages caused by your insured vehicle no. SKQ5059D on 15/1/2018 along Alexandra Road, kindly arrange for survey of the above vehicle or contact me at tel: 68631728, hp: 90999979 should you need any clarification.

We trust that the above are in order and we look forward to your confirmation and job number/PO.

Thank you and best regards,  
STEVEN

E.S.O.E

To reply, please endorse & fax back to us.  
Confirmed and accepted by:

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Tan Kah 97495749/62563561  
WP

17/1/18 @ 1730

6 days

\* Resurvey new part  
sur@lkkauto.com

Name / Signature and Company Stamp

*[Signature]*  
19/1/18



# Public Trailer Equipment Supplies

Workshop: 28 Jalan Buroh Singapore 619484

Mailing address: Blk 454 Choa Chu Kang Ave 4 #14-117 Singapore 680454

Tel: +65 6863 1728 / 2298 Fax: +65 6863 1773 Email: publictrailer@gmail.com

Website: www.publictrailer.com Co. Reg. No: 199202033N GST Reg No: M2-010631F-6

## QUOTATION

MSIG Insurance (Singapore) Pte Ltd

Motor Claims Department

Quotation No. Q180087

Terms COD

Date 16/01/2018

Vehicle No. TR88889X VAS

At your request, we are pleased to quote as follows:

**XB8426**

Description	Quantity	Unit Price	Total
L-CARRIER RAMP CYLINDER ASSY - LH & RH <i>LH-X in RH-bc</i>	2.00	\$1,485.00	\$2,970.00
OUR & EQUIPMENT - REMOVE & REFIT WORK - FOR LHS & RHS CYLINDERS	2.00	\$400.00	\$800.00 <i>400</i>
IPRAY PAINTING - W/ ONE COAT PRIMER & ONE COAT FINISHING - COL VAS RED	1.00	\$450.00	\$450.00 <i>250</i>
IL, HYD 68, 18L	2.00	\$108.00	\$216.00
Subtotal			\$4,436.00
GST (%)		7%	
GST			\$310.52
Grand Total			\$4,746.52

This is an estimated cost of repair for the vehicle reg. no. TR88889X (XB8426H) which damages caused by your insured vehicle no. SKQ5059D on 15/1/2018 along Alexandra Road, kindly arrange for survey of the above vehicle or contact me at tel: 68631728, hp: 90999979 should you need any clarification.

Trust that the above are in order and we look forward to your confirmation and job number/PO

Thank you and best regards,  
VEN

E&OE

To reply, please endorse & fax back to us.  
Confirmed and accepted by

Name / Signature and Company Stamp

Tan Jiah 97495749/62563561

17/1/18 @ 1730

6 days

Resumy new part

sent @ publictrailer.com

6 days  
Confirm with Workshop

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Jan 2018		17 Jan 2018 09:18 <a href="#">Edit Adj Rpt</a>	<b>S\$2,351.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,351.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by Insurer]

Insured:	BORNEO MOTORS (S) PTE LTD, Co. Reg. No.: 196700086Z		
Main Claimant:	VAS TRANS SERVICES PTE LTD		
Vehicle Reg. No.:	XB8426H	Date of Loss:	15/01/2018 16:00 - :59
Claim Type:	TP / 546368	Policy/Cover Note No.:	B28990449MCY (Comprehensive) Coverage: 01/07/2017 - 30/06/2018
Vehicle Reg. No. (Insured):	SKQ5059D	Policy No. (Claimant):	
		Excess:	S\$1,000.00
Repairer:	Public Trailer Equipment Suppliers Pte Ltd (HQ) 56 Tuas Road, Tuas - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wen Yao - 6643 1316]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 16/02/2018]		
Adj Asg. Remarks:	Survey today, anytime after 12pm		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



Claim Documents

\*XB8426H (546368)  
[SKQ5059D]  
TP  
VAS TRANS SERVICES PTE LTD  
Jan 15 2018 4:00PM  
[BORNEO MOTORS (S) PTE LTD]  
Public Trailer Equipment Suppliers Pte Ltd

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a> ▼		
<b>Assessment Reports</b>			1 per page ▼		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	18/01/18 08:04	<b>Accident Statement</b> From:OD - Reg. No: SKQ5059D, Claimant: BORNEO MOTORS (S) PTE LTD		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	18/01/18 18:01	<b>Adjuster Immediate Advice</b>		Load HTM	
<b>Photos/Images</b>			3 per page ▼		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	26/02/18 17:01	<b>General View</b>		Load JPG	
2	26/02/18 17:01	<b>General View</b>		Load JPG	
3	26/02/18 17:01	<b>General View</b>		Load JPG	
4	26/02/18 17:01	<b>General View</b>		Load JPG	
5	26/02/18 17:01	<b>General View</b>		Load JPG	
6	26/02/18 17:01	<b>General View</b>		Load JPG	
7	26/02/18 17:01	<b>General View</b>		Load JPG	
8	26/02/18 17:01	<b>General View</b>		Load JPG	
9	26/02/18 17:01	<b>General View</b>		Load JPG	
10	26/02/18 17:01	<b>General View</b>		Load JPG	
11	26/02/18 17:01	<b>General View</b>		Load JPG	
12	26/02/18 17:01	<b>General View</b>		Load JPG	
13	26/02/18 17:01	<b>General View</b>		Load JPG	
14	26/02/18 17:01	<b>General View</b>		Load JPG	
15	26/02/18 17:01	<b>General View</b>		Load JPG	
16	26/02/18 17:01	<b>General View</b>		Load JPG	
17	26/02/18 17:01	<b>General View</b>		Load JPG	
18	26/02/18 17:01	<b>General View</b>		Load JPG	
19	26/02/18 17:01	<b>General View</b>		Load JPG	
20	26/02/18 17:01	<b>General View</b>		Load JPG	
21	26/02/18 17:01	<b>General View</b>		Load JPG	
22	26/02/18 17:01	<b>General View</b>		Load JPG	
23	26/02/18 17:01	<b>General View</b>		Load JPG	
24	26/02/18 17:01	<b>General View</b>		Load JPG	
25	26/02/18 17:01	<b>General View</b>		Load JPG	
26	26/02/18 17:01	<b>General View</b>		Load JPG	
27	26/02/18 17:01	<b>General View</b>		Load JPG	
28	26/02/18 17:01	<b>General View</b>		Load JPG	



29	26/02/18 17:01	Chassis Number		Load JPG	
30	26/02/18 17:01	Chassis Number		Load JPG	
31	26/02/18 17:03	Replacement Part Photo		Load JPG	
32	26/02/18 17:03	Replacement Part Photo		Load JPG	
33	26/02/18 17:03	Replacement Part Photo		Load JPG	
34	26/02/18 17:03	Replacement Part Photo		Load JPG	
35	26/02/18 17:03	Replacement Part Photo		Load JPG	
36	26/02/18 17:03	Replacement Part Photo		Load JPG	
37	26/02/18 17:03	Replacement Part Photo		Load JPG	
38	26/02/18 17:03	Replacement Part Photo		Load JPG	
39	26/02/18 17:03	Replacement Part Photo		Load JPG	
40	26/02/18 17:03	Replacement Part Photo		Load JPG	
41	26/02/18 17:03	Replacement Part Photo		Load JPG	
42	26/02/18 17:03	Replacement Part Photo		Load JPG	
Documentation				1 per page ▼	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	16/01/18 16:43	Email from Public Trailer to arrange survey		Load PDF	
2	16/01/18 16:43	Estimate		Load PDF	
3	17/01/18 09:22	SKQ5059D - OI report		Load PDF	
4	12/02/18 10:30	LOD		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.



**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG18001006/T1QD3E2**Date:** 12/03/2018**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B28990449MCY
Claimant Vehicle No :	XB8426H	Insured Vehicle No :	SKQ5059D
Date of Loss:	15/01/2018	Nature of Claim:	TP
		Claim No:	546368

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>XB8426H</b>	Engine No:	6D24338903
Make & Model:	MITSUBISHI FP517DR2RDEB, 11.9 D (M)	Chassis No:	FP517DA03752
Reg. Date:	16/10/2003 (Man. Year: 2003)	Odometer:	0 km
Colour:	Red		
Engine Capacity:	11945 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	10.00 R15	Rear Tyre Size:	10.00 R15 (D)
Front Left Side:	Double Coin 8 mm	Rear Left Side:	Double Coin 8/8 mm
Front Right Side:	Double Coin 8 mm	Rear Right Side:	Double Coin 8/8 mm

The above values represent the remaining tyre treads depth

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,970.00	1,485.00	1,485.00	50.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,466.00	866.00	600.00	40.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,436.00</b>	<b>2,351.00</b>	<b>2,085.00</b>	<b>47.00</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>310.52</b>	<b>164.57</b>	<b>145.95</b>	<b>47.00</b>
<b>Nett Amount (S\$)</b>	<b>4,746.52</b>	<b>2,515.57</b>	<b>2,230.95</b>	<b>47.00</b>

**INSPECTION**

Date of Assignment:	17/01/2018	
Date Inspected:	17/01/2018	Inspected At: Public Trailer Equipment Suppliers Pte Ltd (HQ) 56 Tuas Road Singapore
Estimated Period of Repair:	6.0 days	

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:

(Last Synchronised: 12 Mar 2018)

Parts:

N/A

MITSUBISHI FP517DR2RDEB 11.9 D (M) (Model not available in database)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code:

(Unsubmitted, no print-code for XB8426H)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info:

Items/values not in reference catalogue are prefixed with an asterisk \*.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*CAR-CARRIER RAMP CYLINDER ASSY - LH & RH	N/S Not Necessary / O/S Bent	2,970.00 F	*1,485.00 F
				Total Parts (S\$)	2,970.00 1,485.00

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR & EQUIPMT - REMOVE & REFIT WORK - FOR LHS & RHS CYLINDERS	New	800.00	400.00
2	RESPRAY PAINTING - W/ ONE COAT PRIMER & ONE COAT FINISHING - COL : VAS RED	New	450.00	250.00
3	V OIL, HYD 68, 18L	New	216.00	216.00
Gross Labour Cost (S\$)			1,466.00	866.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >