	22/03/2002 -	ŧ			
	ASS. REC. BY:	REF:	Ce/ASM I	ALAAR	
•	SIMAY				
	STUM III		ASSIGN	MENT (1	
	From (Person)	onne Ang	of		
	Estimated Cost:	5	<del>-</del>	ASI	
	To Inspect Value and Inspect Value	OD RES / FV	A / INV () ST	Bill to:	
	To Inspect Vehicle No:	Ξ ΞΞΕ, ΕΥ		r-CS	
-	at Workshop m/s	TA TO	4 11366S	·	
	OT	.1 -		06.4	
	Policy Mar		gin ming	Dine 1	
				Claim	
	Sum Insured:  Make of Veh:		· <del></del>	Ехсе	
	(Client's Record)		<u> </u>		
	CA / REV / REP. / RE	U O 4 Tron -			
_	Date/Time: 17-01-2018	V 24 HRS		_	
	7,01,010	iv 15am Per	son Contacted:	Bem	
	Date/Time Action/Instru				
	SLP H36	3	) Estimate	Pend	
	17 18@ 5 18m 10	144 (A )			
	18/1/8/2 2 11	VVCV+ +D	Yvonne	Ang vi	
	18/1/8@ 3/m Yvon	ne thing !	in Anima I	2/0/1	
	コカルリカでとう カルス・ニレービ	Vared 12			
		170 De	7,000,00	-//4 X 1	
	78 3/180 11. X301	Ma mall	Sed Will	h 3 (	
	78/3/18@ 11.53m	Ma mall	Sed Will	Bernard	

.ctions.

SSIGNMENT  Stim Date  Stim Bet SLP 4366S, Feet Jun Joi -  Stim Bet SLP 4366S, Feet Jun Joi -  Stim Bet Cost  Stim Bet Cost  Stim Bet Cost  Stim Bet Stim Bet Cost  Stim Bet Stim Bet Stim Bet Stim Bet Bet Stim Bet Bet Stim Bet	- REF:	
Estimated Cost  OD ITP I WS / TP RES / OD RES / EVA / INV / INV  To Inspect Vehicle No:  At Workshop mis  At	àS:	SIGNMENT
Truck! Trailer or Truck! Truck! Trailer or Truck! T		Mention SLP4366S, Mr. Regn. JUN JOIT-
To inspect Vehicle No at Workshop mis of at Workshop mis of AC insured is 1d in If NA Sp. Reading T Sacto Insured is 1d in Insured in	Estimated Cost:	
at Workshop Pass SW SNUTION .  of Sp. Reading T. Radio Insured / Std / N1 / NA Insured  Policy No.  Claims No.  Sum insured:  (Cleims Rectro)  Make of Veh:  (Policy Condition)  Remark: The veh had commenced its repair at the time of inspection.  Ball or Market Value.  ### Consistent? Yes or No  GIA / PR Seen:  Consistent? Yes or No  Lum Sum:  % 3 Vel.: Yes or No  CA / REV / REP. / 24 HRS  Date:  Person Contacted:  Date:  Person Contacted:  Consistent? In Vehicle:  Vehicle:  IN / OUT  The UIC / Chassis frame / Body Structure affected due to collision.  REC.  CUS:  A.C. Insured / Std / NI / NA  T. Reading  T. Rea	OD / TP / WS / TP RES / OD RES / EVA / INV / MV	
Sp. Reading Tead of Insured / Std / NE / NA Insured: Policy No. Claims No. Sum Insured Excess: A Job Claims Record: Make of Veh:  (Policy Condition) Remark: The veh had commenced its rearries the time of inspection.  Ball of Market Value Record: DAC Acodent Riport: Consistent?: Yes or No Claims Receive: 4 days Res.: Yes or No CLIM Sum: CA / REV / REP. / 24 HRS Date: Person Contacted:  Sp. Reading Tead or Insured / Isted / NE / NA Eng No: CNo. QUI 3		
Insured: Policy No. Claims No. Claims No. Sum Insured: Excess: 100 Clents Record: Make of Veh:  Make of Veh:  Policy Condition) Remark: The veh had commenced its repair at the time of inspection.  Ball or Market Value.  Ball or Market Value.  Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Lum Sum:  % 3 Vall: Yes or No Lum Sum:  CA / REV / REP. / 24 HRS  Vehicle: IN / OUT  Date: Person Contacted:  Person Contacted:  Policy No. C. No: QUI 3 12 H5 2 H4  Gen. Cops Good / Fair / Poor / Burnt Steering directer / Burnt or Steering directer / Burnt or Modi: NIJ SRigh / STD AJRIm or Tyre Size F:  BS / QUIV EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM! / TOVO / YOKO or  Front Rear R. Bal.  Mm R. Bal.  Mm R. Bal.  Mm R. Bal.  D.O.A. World St.  Do.A. World St.  The U/C / Chassis frame / Body Structure affected due to collision.  REC.  C. 140	at Workshop mis SW Solution.	Colour Colour A/C. Insured / Std / NI / NA
Cours No.  Claims No.  Sum Insured Excess: \$\frac{1}{2}\text{OP}\$  (Client's Record)  Make of Velt:  Make of Velt:  Make of Velt:  Make of Velt:  Modi: Nij SRijh / STD A/Rim or  Tyre Sizs F: \$\frac{1}{2}\text{SUM} \( \) PIR / SUMI /  TOYO / YOKO or  Front Reser:  DAC Accident Roon:  Consistent? : Yes or No  GLA / PR Seen:  Consistent? : Yes or No  Lum Sum:  % 3 Val. Yes or No  CA / REV / REP. / 24 HRS  Date: Person Contacted:  Date: Time Action / Instruction  CRA : Time Action / Instruction  CRA : Copd Gadd / Fair / Poor / Burnt  Steering digder / Jammed / Leaked / Burnt or  Brake: (floyder / Jammed / Leaked / Burnt or  Brake: (floyder / Jammed / Leaked / Burnt or  Brake: (floyder / Jammed / Leaked / Burnt or  Brake: (floyder / Jammed / Leaked / Burnt or  Brake: (floyder / Jammed / Leaked / Burnt or  Brake: (floyder / Jammed / Leaked / Burnt or  Brake: (floyder / Jammed / Leaked / Burnt or  Brake: (floyder / Jammed / Leaked / Burnt or  Brake: (floyder / Jammed / Leaked / Burnt or  Brake: (floyder / Jammed / Leaked / Burnt or  Brake: (floyder / Jammed / Leaked / Burnt or  Modi: Nij 'SRijh / STD A/Rim or  Tyre Sizs F: \$\frac{1}{2} SULVA / SULVA	ef	Sp.Reading T.Radio Insured / Std / NI / NA
Clams No.  Sum Insured: Excess:	Insured:	
Steering_morder / Jammed / Leaked / Burnt or Prake of Veh.    Steering_morder / Jammed / Leaked / Burnt or Prake of Veh.	Policy No.	
Collent's Record   Brake:   Modi: Nij/SRijn / STD A/Rim or	Claims No.	Gen. Copd: Good / Fair / Poor / Burnt
Make of Vehi:  (Policy Condition)  Remark: The veh had commenced its repair at the time of inspection.  Sal. or Market Value.  Consistent?: Yes or No  Est. Repairs:  Gla / PR Seen:  Consistent?: Yes or No  Lum Sum:  % 3 Val.: Yes or No  Currey held at  Des. of Demages (Ft.): Rear / O/S / N/S / U/C / Rooftop or  The U/C / Chassis frame / Body Structure affected due to collision.  REG.  Currey held at  Date: Person Contacted:  The U/C / Chassis frame / Body Structure affected due to collision.	Sum Insured: Excess: 47 400	Steering Inorder / Jammed / Leaked / Burnt or
Tyre Size: F: DIS ( PL6 Remark: The veh had commenced its repair at the time of inspection.  Bal. or Market Value. Remark: Yes or No GIA / PR Seen: Consistent?: Yes or No Est. Repairs: U days Res.: Yes or No Lum Sum: % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Date: Person Contacted: Vehicle: IN / OUT  Date: Person Contacted: Time Action / Instruction  Tyre Size: F: DIS ( DIS) ( PL6 Re) R: BS / DUN/EXNOVA / GY / FS / LiZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or  Front Rear R. Bal. mm R. Bal. mm R. Bal. mm L. Bal. mm L	(Client's Record)	Brake: dnorder / Jammed / Leaked / Burnt or
Remark: The veh had commenced its repair at the time of inspection.  Bal. or Market Value. Reser: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Lum Sum: % 3 Val.: Yes or No CA / REV / REP. / 24 HRS  Date: Person Contacted: Vehicle: IN / OUT  Date: Person Contacted: Vehicle: IN / OUT  Date: Action / Instruction  RE:  DOJ: PR Sel.  Rear  N.S. O.S  BS / DUN) / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM! / TOYO / YOKO or  Front Rear  R.Bal.  mm R.Bal.  mm R.Bal.  mm L.Bal.  mm L.Bal.  DoJ. 1 7 Old 2018 Of .  Date / Time Action / Instruction  RECT.  Date / Time Action / Instruction	Make of Veh:	1
Remark: The veh had commenced its repair at the time of inspection.  Bal. or Market Value. Rescription Consistent? : Yes or No GIA / PR Seen: Consistent? : Yes or No Est. Repairs: Judays Rescription available of the Call Repairs: Judays Rescription available of the Call Repairs: Judays Rescription available of the Call Repairs and the Call Repairs are person Contacted:  Date / Time Action / Instruction  Bal. or Market Value. Rear / Ois / Rear / Ois / Nis / U/C / Recoftop or Rear / Ois /		Tyre Size: F: \$15\60\P\6
repair at the time of inspection.  Bal. or Market Value. RPC  IDAC Accident Rport: Consistent?: Yes or No  GIA / PR Seen: Consistent?: Yes or No  Est. Repairs: 4 days Res.: Yes or No  Lum Sum: % 3 Val.: Yes or No  CA / REV / REP. / 24 HRS  Date: Person Contacted: Des. of Damages Ft.// Rear / O/S / N/S / U/C / Rcoftop or  The U/C / Chassis frame / Body Structure affected due to collision.	(Policy Condition)	] R:
Ball or Market Value. The Consistent?: Yes or No  GIA / PR Seen: Consistent?: Yes or No  Est Repairs: U days Res.: Yes or No  Lum Sum: % 3 Val.: Yes or No  CA / REV / REP. / 24 HRS  Date: Person Contacted: Vehicle: IN / OUT  Date: Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision.  Rear mm R.Bal. mm R.Bal. mm L.Bal. mm L.Bal. mm L.Bal. mm D.O.I. 1 Hot Dot R. Gr.  Survey held at:  Des. of Damages Fr.// Rear / O/S / N/S / U/C / Rooftop or  The U/C / Chassis frame / Body Structure affected due to collision.	Remark: The veh had commenced its N/S O/S	BS (DUN) EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
IDAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Est Repairs: U days Res.: Yes or No Lum Sum: % 3 Val.: Yes or No CA / REV / REP. / 24 HRS  Date: Person Contacted: Vehicle: IN / OUT Date / Time Action / Instruction  REal. mm R.Bal. mm R.Bal. mm L.Bal. mm L.Bal. mm  CD.O.A. L.	repair at the time of inspection.	$\neg$ $\mid$ $\bigcirc$
IDAC Accident Rport: Consistent?: Yes or No  GIA / PR Seen: Consistent?: Yes or No  Est. Repairs: 4 days Res.: Yes or No  Lum Sum: % 3 Val.: Yes or No  CA / REV / REP. / 24 HRS  Date: Person Contacted: Vehicle: IN / OUT  Date / Time Action / Instruction  REal. mm R.Bal. mm R.Bal. mm LBal. mm  CA / REV / REP. / 24 HRS  Vehicle: IN / OUT  The U/C / Chassis frame / Body Structure affected due to collision.	Bal. or Market Value: \$\frac{1}{2}\$, \$\text{Ps}\$	Front Rear
GIA / PR Seen: Consistent?: Yes or No  Est Repairs: U days Res.: Yes or No  Lum Sum: % 3 Val.: Yes or No  CA / REV / REP. / 24 HRS  Des. of Damages Frt./ Rear / O/S / N/S / U/C / Rooftop or  The U/C / Chassis frame / Body Structure affected due to collision.  RECC: CA / REV / REP. / CA / Rear / O/S / N/S / U/C / Rooftop or  RECC: CA / REV / Rear / O/S / N/S / U/C / Rooftop or  RECC: CA / Rev / Rear / O/S / N/S / U/C / Rooftop or  RECC: CA / Rev / Rear / O/S / N/S / U/C / Rooftop or  RECC: CA / Rev / Rear / O/S / N/S / U/C / Rooftop or  RECC: CA / Rev / Rear / O/S / N/S / U/C / Rooftop or  RECC: CA / Rev / Rear / O/S / N/S / U/C / Rooftop or  RECC: CA / Rev / Rear / O/S / N/S / U/C / Rooftop or  RECC: CA / Rev / Rear / O/S / N/S / U/C / Rooftop or  RECC: CA / Rev / Rear / O/S / N/S / U/C / Rooftop or  RECC: CA / Rev / Rear / O/S / N/S / U/C / Rooftop or  Recc: CA / Rev / Rear / O/S / N/S / U/C / Rooftop or  Recc: CA / Rev / Rear / O/S / N/S / U/C / Rooftop or  The U/C / Chassis frame / Body Structure affected due to collision.		R/Bal. mm R.Bal. mm
Est Repairs:		L/Bal. mm L/Bal. mm
Lum Sum: % 3 Val.: Yes or No  CA / REV / REP. / 24 HRS  Date: Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision.  Date / Time		10.0 gradio17 1 10.0 - Section 17 10.00
Des. of Damages Frt // Rear / O/S / N/S / U/C / Rooftop or  The U/C / Chassis frame / Body Structure affected due to collision.		Survey held at
Date: Person Contacted: Vehicle: IN / OUT  Date / Time	<del></del> -	Des. of Damages Frt / Rear / O/S / N/S / U/C / Rooftop or
Date / Time Action / Instruction		
REC (1)	Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
	Date / Time Action / Instruction	
	•	
Cate/Time: File Pass to? : Preli. Report Days Of Repair:	REU	
. Fren. Report Bays Of Repair	Care/Time File Pass to? Prolit Poport	Days Of Renair:
: Final Report Resurvey No. of Trip:   Survey Fee: 290	1	
Cate. Time File Return to?		
Add Fee: Site Insc (\$3-755)		<del></del>
The second secon		
	Report Format: Smart Ckain	
Report Format: Smart Claim Lump Sum /1.B.h. 5 4/68.50 Learners S	Lump Sum /1.B.1: 5 4168.52	
250		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

<b>4</b>	Commission of Maria Congression	Affiliated to Federation internation	nale Des Experts En Automob			
AXA	INSURANCE PTE	ELTD	Ref : CS/ASM18001023	3/M1qb		
	ENTON WAY #24 TOWERSINGAP		Date: 17-01-2018  Code: ASM			
1		Policy Particula	ars :- OWN DAMAGE			
	Insured Veh.		Veh. Inspected	SLP 4366S		
	Policy No.		Coverage (\$)	0.00		
	Claim No.	S8M00728	Excess (\$)	700.00		
	Assign From	SMART CLAIM (YVONNE ANG)	Assign Date	17/01/2018		
2.	g ( ) militar de magni gan Amar	Vehicle Partic	culars & Condition	The experience of the experience of the		
	Make & Model		c.c	0		
	Engine No.	HIDDEN	Year of Reg.	,		
	Chassis No.		Colour	, , , , , , , , , , , , , , , , , , ,		
	Odometer -		Steering			
	Brakes		Modification	· · · · · · · · · · · · · · · · · · ·		
	General					
3.		Condition	ons of Tyres			
		Size	Make	Balance		
	R/H Front Tyre			mm		
	L/H Front Tyre			mm		
	R/H Rear Tyre			mm		
	L/H Rear Tyre			mm		
4.7		√ Descriptio	on of Damages (in a			
5.		· · · · · · · · · · · · · · · · · · ·	Information			
	Accident Date	11/01/2018	Inspection Date	17/01/2018		
	Survey held at	EM SOLUTION PTE LTD  160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722	,			
5a.	A)THE MARKET V. B)IN ACCORDANC		AGE)	AIRS.		

Menu



# **Service Request Details**

Claim

S8M00728

Reference

None 🥒

Loss Date

January 11, 2018

Request Date

January 17, 2018

Due Date

January 24, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Incident Only

Services

Accelerated workshop survey

### **Actions**

Next Step

Agree to perform service

Decline Work

Accept Work

### Vehicle Information

Incident Vehicle Registration # SLP4366S

Make

**HONDA** 

Menu

Service Address

, , ,

Primary Contact/Insured

YIXIU CHEN
BLK 461 CHOA CHU KANG AVENUE 4, #03-81, 680461, Singapore, Singapore 97596619
BLUEMOON\_YX@HOTMAIL.COM

Claim Handler

Default Owner

Additional Instructions
EXCESS \$700 PENDING DRIVING LICENSE

Messages	Invoices	History	Documents	Assessment	Metrics	Notes

New Message

# Ma C.F (LKKAuto)

From:

EM Auto <emautosolution@singnet.com.sg>

Sent:

Wednesday, 28 March, 2018 11:53 AM

To:

Ma C.F (LKKAuto)

Subject:

**RE: FINALIZATION SLP 4366S** 

Mr. Ma,

Ok Agreed.

Thanks & regards,

Bernard

HP: 91018302

From: Ma C.F (LKKAuto) [mailto:MaCF@lkkauto.com]

Sent: Friday, 19 January, 2018 5:36 PM

To: EM Auto < emautosolution@singnet.com.sg>

Subject: FINALIZATION SLP 4366S

Dear Bernard,

**SLP 4366S** 

P/P REPAIR

\$4168.52 (BEFORE EXCESS)

4 W/DAYS

Warmest Regards, Ma Chin Fook LKK Auto Consultants Pte Ltd

HP: 84028474 FAX: 6741 4108

EMAIL: macf@lkkauto.com



# SUPPLEMENTARY LIST OF VEHICLE SLP 4366S UPLOADED

Type

Question

### Message

Dear Yvonne, we have received supplementary of \$316.16 from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair. - Shiau Chan

Reply

### Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Thursday, 18 January 2018 3:04 PM

To:

'emautosolution@singnet.com.sg'

Cc:

SUR

Subject:

VEHICLE SLP 4366S (DOA: 11/01/2018)

Dear Bernard,

As spoken with you.

As instructed by our client, please proceed to repair the insured vehicle SLP 4366S (Excess \$700/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

### Shiau Chan (LKKAuto)

From:

ANG Yvonne < yvonne.ang@axa.com.sg>

Sent:

Thursday, 18 January 2018 3:00 PM

To:

Shiau Chan (LKKAuto)

Subject:

RE: VEHICLE SLP 4366S (YOUR REF: S8M00728)

Please proceed to authorize repair

Yvonne Ang Assistant Manager Motor (Property) Claims

AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg

Email: yvonne.ang@axa.com.sg

DID: 1800 880 4888



# redefining / insurance

### **AXA's Values at Work:**









ONE AXA

Please consider the environment before printing this email

This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]

Sent: Thursday, January 18, 2018 2:43 PM To: ANG Yvonne < yvonne.ang@axa.com.sg>

Subject: VEHICLE SLP 4366S (YOUR REF: S8M00728)

Dear Yvonne,

Kindly advise on authorisation as the driver's driving license copy uploaded.

Best Regards,

Shiau Chan (Ms) | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email:  $\underline{siewsc@lkkauto.com} \mid fax: 6256-4315$ 

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

#### ----Disclaimer----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: <u>S8M00728</u> Date: <u>17<sup>th</sup> January 2018</u>

Our Ref: CS/ASM18001023/M1qb

The Motor Claims Department AXA Insurance Singapore Pte L td

Attn: Yvonne Ang

Dear Sirs/Mdm

# PRELIMINARY ADVICE OF VEHICLE NO. SLP 4366S .

We thank you for the instruction on 17/01/2018.


Please be informed that we had conducted the inspection of the abovementioned vehicle on 17/01/2018 (1.41pm) at the premises of M/s \_\_\_\_\_ EM SOLUTION \_\_\_\_ and have the following to report:-

Workshop Estimate Amount	: <u>S\$</u> _	<u>9,998.60</u> .
Revised Estimate Amount	: S\$	<u>3,852.36</u>
"Check" Items Amount	: <u>S\$</u>	380.32
Total	: S\$	4,232.68
Market Value	: <del>S\$</del>	95,000.00
LTA Reimbursement Value	: <u>S\$</u>	54,413.00
	: S\$	40,587.00
Nett Value	. <u>Ou</u>	10,00

Description of Damage:

The vehicle sustained damages at the

front portion.



Comments/ Present Status:

Damages consistent.

Repair cost economical.

Estimated normal period for repairs: 4 working days.

We have NOT authorised the repairs.

Yours faithfully

MA C.F.

Automobile Assessor

# Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 4621A

Vehicle Details

Vehicle No.: SLP4366S

Vehicle to be Exported:

Intended De-registration Date: 17 Jan 2018

Vehicle Make: HONDA

Vehicle Model: VEZEL HYBRID 1.5X AUTO

Primary Colour: Blue

Manufacturing Year: 2017

Engine No.: LEB5945266

Chassis No.: RU31245249

Maximum Power Output: 112.0 kW (150 bhp)

Open Market Value: \$26,159.00

Original Registration Date: 05 Jun 2017

First Registration Date: 05 Jun 2017

Transfer Count: 0

Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date: 04 Jun 2027

PARF Rebate Amount: \$3,750.00

Intended COE Rebate Details

COE Expiry Date: 04 Jun 2027

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$54,000.00

COE Rebate Amount: \$50,663.00

Total Rebate Amount: \$54,413.00

The information contained herein is correct as at 17 Jan 2018

MKKH18005702 / K Kim Hin Auto Pte Ltd - HQ ENTRY DATÉ & TIME: 11/01/2018 18:08 SUBMITTED BY: Wong Shu Man

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful</u> and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACC	DENT	STAT	EMENT

 Date Of Report
 11/01/2018 18:08

 Date Of Accident
 11/01/2018 13:25

Exact Location Of Accident SLIP ROAD OF QUEENSWAY AND ALEXANDRA ROAD

Country/State of Loss SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number SLP4366S

Insured/Policyholder

Name Of Registered Owner CHEN YIXIU
NRIC No S8124621A

Email Address BLUEMOON\_YX@HOTMAIL.COM

Mobile Phone No (LOCAL) +65-97596619
Alternative Phone No OFFICE-97596619

Vehicle Particulars

Manufacturer HONDA

Model VEZEL-1.5 (A)

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

YES

If No, Please state action to be taken

Vehicle Category PRIVATE CAR

#### Insurance Company

Name of Insurance Company AXA INSURANCE PTE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number GA216017

Cover Note Number

#### **Driver**

Name of Driver TAN CHUAN MUAN

 NRIC No
 S0136746C

 Date Of Birth
 27/11/1952

 Occupation
 INDOOR

 Date Of Driving Pass
 22/10/1970

Driving Experience 47 YEARS AND 2 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-98177822

Fax Number

Contact Number

EMail Address NOEMAIL

Address BLK 461 CHOA CHU KANG AVE 4 #03-81

Postcode 680461

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured PARENT

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

Sarahas Sampany of Elitara Sampana

### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions RAINING
Road Surface WET

#### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by

ambulance?

NO YES

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Researance (Including Driver)

Number of Passengers (Including Driver) 2

Passenger 1

NAME: : EDWARD HAN

GENDER: : MALE

### **Details of Police Action**

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes against whom?

#### **Circumstances of Accident**

PLEASE REFER TO SKETCH PLAN.

### Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Was there any audio recorded?

NO

**Details of Witness 1** 

Name EDWARD HAN
Phone Number 96706453

Email Address

### **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SLR1438C

Vehicle Make/Model/Colour SUZUKI VITARA

**Details Of Properties** 

Vehicle Category PRIVATE CAR
Name of Driver LIM SEW HUI
NRIC/Passport Number S7512789H
Contact Number 97888708

Address

Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

#### Sketch Plan Pg. 1

#### **SKETCH PLAN**

#### **IMPORTANT NOTICE**

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Oriver's Signature

Signature

(If driver is not the policyholder)

Date & Time: } (


Reporting Centre Personnel's Signature

Name:


NRIC/FIN No.:

## Sketch Plan Pg. 2

	,
SKETCH PLAN  THE FOR THE STATE OF THE STATE	
- I I I KEN I I I I I I I I I I I I I I I I I I I	
	A CIP4266S
	A: SLP 4366S
	B: SLR 1438C
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT	
	· Dia lung
Y SLP 4366S was travelling benin	N SEK 1438C
Road and Queensmay. SLP 436	between litexandra
Kand and Queensway. SEP 431	65 cirivel has
ascortained that SLR 1438C Star	teu moving head
followed. However, SLR 1429	c Stopped Suddonly
when there was no car un the	main road and
The Hipped Pact had no	"Itop" con
Due to the sudden stop b	1 JLK 143/4C,
when there was no car un the the slipped road as mad no Due to the sudden stop be circle of SLP 4366C, even and slow speed, would not This and resulted in the accident	though moring
art ston speed, varied not	stop in time-
(Mis and resulted in the accident	*
& Repai at other workshop.	
· · · · · · · · · · · · · · · · · · ·	
DECLARATION  I/We declare the foregoing particulars are true in every respect.	
11/	yil ©
X ·	up.
Policyholder's Signature Driver's Signature	Reporting Centre Personnel's Signature
Date & Time: (If driver is not the policyholder)  Company Chop (if applicable)  Date & Time:	Name: NRIC/FIN No.:
H	









160, Sin Ming Drive, #03-18/19, Sin Ming Autocity, Singapore 575722 64584500 Tel: 64560226 Fax:

Registration No: 201016308K

12.01.2018

**AXA Insurance Pte Ltd** 8, Shenton Way, #24-01 **AXA Tower** Singapore 068811

ATTENTION: MOTOR CLAIMS DEPARTMENT

### **REPAIR ESTIMATE FOR HONDA VEZEL - SLP 4366 S**

1 pc.	front bumper		-1.127.50 det
2 pcs	front bumper side retainers	43.00	> 1,127.50 det 86.00 NS 245 05 CVC
1 pc	front bumper tow hood cover		°28.50 ♥ ~ C
1 pc	front bumper lower grille		242.20 €
2 pcs	front bumper fog lamps 4	27.70	
2 pcs	front bumper fog lamp grilles	65.00	130.00 ⋉ 🍛 🨉
1 pc	front bumper lower diffuser		451.00 y que.
1 pc	front bumper reinforcement		451.00メール・ 421.20 スメジャン
2 pcs	headlamps NS CV9 OS 2NC 1,9	95.40	3,990.80
2 pcs	headlamp lower brackets $7\chi$	54.20	X 108.40 ⋙
1 pc	front grille		-350.00 € °,
1 pc	front grille emblem		~ 43.30 V
1 pc	bonnet		₹1,120.30 € ₹ 124.60 € ₹ 161.20 ₹ 161.
2 pcs	bonnet hinges	62.30	× 124.60 Rayin
1 pc	LH front fender		×680.00 Dep~
1 pc	LH front fender inner shield		×161.20 حسدا
1 pc	LH front fender arch garnish		×183.30 ↔ ×163.30 ←
1 pc	front support panel top garnish		♥163.30 <del>▼</del>
		•	10,267.00
	Less 20%		2,053.40
		•	8,213.60 8,213.60

1 set front bumper clips √------35.00 SN

1) Check electrical wirings and headlamp focus

17/1/2018

- 2) Repair damages and renew parts.
- Spray paint on affected portions 3)

-850.00 LOD 850.00 ×40.

9.998.60

LKK Auto Consultants hence notify

- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

the Repairer of the following: 10314.76 • To resurvey before/after spray painting

160, Sin Ming Drive, #03-18/19, Sin Ming Autocity, Singapore 575722 Tel: 64560226 Fax: 64584500

Registration No: 201016308K

12.01.2018

AXA Insurance Pte Ltd 8, Shenton Way, #24-01 **AXA Tower** Singapore 068811

ATTENTION: MOTOR CLAIMS DEPARTMENT

## REPAIR ESTIMATE FOR HONDA VEZEL - SLP 4366 S

1 pc.	front bumper		- 1,127.50 Art
2 pcs	front bumper side retainers	43.00	86.00 the end ex end
1 pc	front bumper tow hood cover		<b>∀28.50 &gt;∨ ⊆</b>
1 pc	front bumper lower grille		242.20 ★ 🗢 🧸 🤇
2 pcs	front bumper fog lamps	427.70	
2 pcs	front bumper fog lamp grilles	65.00	130.00 × <>>
1 pc	front bumper lower diffuser		451.00 y ave
1 pc	front bumper reinforcement		404 00 Q
2 pcs	headlamps NS CV9 OS CV9 headlamp lower brackets	,995.40	3,990.80
2 pcs	headlamp lower brackets	54.20	× 108.40
1 pc	front grille		-350.00 S
1 pc	front grille emblem		· 43.30 · · ·
1 pc	bonnet		₹1,120.30 \\\ ¬¬¬¬¬¬¬¬¬¬¬¬¬¬¬¬¬¬¬¬¬¬¬¬¬¬¬¬¬¬¬¬¬¬
2 pcs	bonnet hinges	62.30	✓1,120.30 ← ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓
1 pc	LH front fender		1680.00 x 272W
1 pc	LH front fender inner shield		ን"161.20 ሩ~ሩ <sup>\</sup>
1 pc	LH front fender arch garnish		× 183.30 ∽ ~ ~ ~
1 pc	front support panel top garnish		7163.30
₽ <sup>4</sup>			10,267.00
	Less 20%		2,053.40
		,	8.213.60 8,213.60

1 set front bumper clips 5 35.00 SN

Check electrical wirings and headlamp focus 1)

Repair damages and renew parts. 2)

3) Spray paint on affected portions

-50.00 <sup>13</sup>~ 850:007 44 \$50.3 850.00 원 역의

9,998.60

**Suto Consultants hence notify** me Remainer of the following:

- To resur by before/after spray painting
- To display carrayed part(s) during resurvey
- \*Parts pages are subject to confirmation
- \* "nire party survey is on a "Without Prejudice" basis
- \* No inegal modification spills allowed
- \* Supplementary demosition of the resurveyed and a subject to final approval her-

Acknowledged by Repairer





160, Sin Ming Drive, #03-18/19, Sin Ming Autocity, Singapore 575722 Tel: 64560226 Fax: 64584500

Registration No: 201016308K

**17**.01.2018

AXA Insurance Pte Ltd 8, Shenton Way, #24-01 AXA Tower Singapore 068811

ATTENTION: MOTOR CLAIMS DEPARTMENT

# SUPPLYMENTARY REPAIR ESTIMATE FOR HONDA VEZEL - SLP 4366 S

1 pc.

front grille top garnish

OVO.\_\_

Less 20%

395.20 79.04

316.16

316.16

17/1/2018

160, Sin Ming Drive, #03-18/19, Sin Ming Autocity, Singapore 575722

Tel: 64560226 Fax: 64584500

GST Reg. No: 201016308K

28.03.2018

Final Invoice:

TI05042

AXA Insurance Pte Ltd 8, Shenton Way, #24-01, AXA Tower Singapore 068811

# FINAL REPAIR BILL FOR HONDA VEZEL - SLP 4366 S

1 pc 1 pc 1 pc 1 pc 1 pc 1 pc	front bumper n/s front bumper side retainer n/s headlamp front grille front grille emblem front grille garnish	Less 20%	1,127.50 43.00 1,995.40 350.00 43.30 395.20 3,954.40 790.88 3,163.52	3,163.52	
1 set	front bumper clips			35.00	SN
1) 2) 3)	Check electrical wirings & headlamp Repair accident damages and renew Spray paint on affected portions	focus. v above parts	-	30.00 400.00 540.00 4,168.52	-
		Less Excess		700.00 3,468.52 242.80	_
	COLUTION		GST 7%	3,711.32	_



To:	AXA Insurance Pte Ltd
	8, Shenton Way, #24-01
	8, Shellon way, 121 si
	AXA Tower
	Singapore 068811

# **DISCHARGE VOUCHER**

I/we are the registered owner of vehicle  $\underline{SLP\ 4366\ S}$  which was damaged in the accident on  $\underline{11.01.2018}$  .

My/our vehicle had been completed to my/our satisfaction and I/we had collected the vehicle on \_\_\_\_\_\_\_\_\_.

Please accept the repair bill from my repairer M/s. EM Solution Pte Ltd and the payment by your company to my repairer M/s. EM Solution Pte Ltd will be in full and final settlement of my/our claim for losses sustained as a result of the above accident.

The above is correct and agreed by:

Name: Chen Yixiu NRIC: S8124621S

Date: 22-01.2018